

■ INSPECTION REPORT

Grafitect - Inline Quality Report

■ INSPECTION DETAILS

■ Inspection ID:	5
■ Form:	Grafitect - Inline Quality Report
■ Inspector:	inspector1
■ Status:	■ SUBMITTED
■ Created:	2025-10-13 13:37:46
■ Updated:	2025-10-13 13:37:46

■ INSPECTION RESPONSES

■ QUESTION	■ RESPONSE
■ Tanggal * [DATETIME]	2025-10-13T06:37
■ Shift * [DROPDOWN]	1
■ Inspector * [SEARCH_DROPDOWN]	— No response provided —
■ No. Doc * [TEXT]	GRA-IN-20250001
■ MESIN * [SEARCH_DROPDOWN]	KBA 2
■ Item * [TEXT]	jhbxfhbfj
■ FSC Claim * [SEARCH_DROPDOWN]	FSC Claim
■ NO SPK * [TEXT]	hxuxo4

■ Total Output * [TEXT]	456
■ Total Reject Redbin * [TEXT]	unuoroijr
■ Sampling Size * [TEXT]	bxurour
■ Kode Reject Guide * [SEARCH_DROPDOWN]	QBK 132 - Cetakan Bergaris
■ Sign Inspector * [SIGNATURE]	jrnxbnrj
■ Leader / SPV QC * [SIGNATURE]	knxbnrj
■ Final Decision * [BUTTON]	— No response provided —
■ Note: [NOTES]	— No response provided —
■ Approved Sample * [SEARCH_DROPDOWN]	— No response provided —
■ Mylar * [SEARCH_DROPDOWN]	— No response provided —
■ Shadeband * [SEARCH_DROPDOWN]	— No response provided —
■ FRA * [SEARCH_DROPDOWN]	— No response provided —
■ Pengecekan * [TIME]	— No response provided —
■ BIQ Patrol Audit * [SEARCH_DROPDOWN]	— No response provided —
■ Inserter * [SEARCH_DROPDOWN]	— No response provided —
■ Label Status * [SEARCH_DROPDOWN]	— No response provided —
■ Redbin/Pallet Reject * [SEARCH_DROPDOWN]	— No response provided —

■ INSPECTION SUMMARY

■ Total Fields:	25
■ Completed Fields:	13 (52.0%)
■ Pass Count:	0
■ Hold Count:	0
■ Flagged Abnormal:	0
■ Overall Status:	SUBMITTED

■ Generated on 2025-10-18 at 08:23:49 by InsPecPro™
Professional Inspection Management System