## **■ INSPECTION REPORT**

**GRAFITECT - INPROCESS QUALITY REPORT** 

## **■ INSPECTION DETAILS**

■ Inspection ID:	37
■ Form:	GRAFITECT - INPROCESS QUALITY REPORT
■ Inspector:	admin
■ Status:	■ SUBMITTED
■ Status: ■ Created:	■ SUBMITTED 2025-10-18 10:19:22

## **■ INSPECTION RESPONSES**

■ QUESTION	■ RESPONSE
■ Tanggal * [DATETIME]	2025-10-18T03:17
■ Shift * [DROPDOWN]	2
■ Inspector * [SEARCH_DROPDOWN]	— No response provided —
■ No. Doc * [TEXT]	GRA-INP-20252
■ MESIN * [SEARCH_DROPDOWN]	KBA 3
■ Item * [TEXT]	4321654321
■ FSC Claim * [SEARCH_DROPDOWN]	FSC Non-Claim
■ NO SPK *  [TEXT]	4321`54321

■ Total Output *  [TEXT]	543214321
■ Total Reject Redbin *  [TEXT]	321
■ Sampling Size *  [TEXT]	3
■ Kode Reject Guide *  [SUBFORM]	nunu
■ Sign Inspector * [SIGNATURE]	nunu
■ Leader / SPV QC * [SIGNATURE]	nini
■ Final Decision *  [BUTTON]	[■ HOLD]
■ Note: [NOTES]	— No response provided —
■ Approved Sample *  [SEARCH_DROPDOWN]	Compliant
■ Mylar * [SEARCH_DROPDOWN]	Compliant
■ Shadeband * [SEARCH_DROPDOWN]	Compliant
■ FRA * [SEARCH_DROPDOWN]	Yes
■ Pengecekan *  [TIME]	12:31
■ BIQ Patrol Audit *  [SEARCH_DROPDOWN]	No
■ Inserter * [SEARCH_DROPDOWN]	Yes
■ Label Status * [SEARCH_DROPDOWN]	Yes
■ Redbin/Pallet Reject *  [SEARCH_DROPDOWN]	Yes

## **■ INSPECTION SUMMARY**

■ Total Fields:	25
■ Completed Fields:	23 (92.0%)
■ Pass Count:	0
■ Hold Count:	1
■ Flagged Abnormal:	0
■ Overall Status:	SUBMITTED

■ Generated on 2025-10-18 at 10:19:28 by InsPecPro™

Professional Inspection Management System