

■ INSPECTION REPORT

GRAFITECT - INPROCESS QUALITY REPORT

■ INSPECTION DETAILS

■ Inspection ID:	35
■ Form:	GRAFITECT - INPROCESS QUALITY REPORT
■ Inspector:	admin
■ Status:	■ SUBMITTED
■ Created:	2025-10-18 09:50:36
■ Updated:	2025-10-18 09:50:36

■ INSPECTION RESPONSES

■ QUESTION	■ RESPONSE
■ Tanggal * [DATETIME]	2025-10-18T02:46
■ Shift * [DROPDOWN]	1
■ Inspector * [SEARCH_DROPDOWN]	NUNU
■ No. Doc * [TEXT]	GRA-INL-20251
■ MESIN * [SEARCH_DROPDOWN]	KBA 2
■ Item * [TEXT]	34567
■ FSC Claim * [SEARCH_DROPDOWN]	FSC Claim
■ NO SPK * [TEXT]	5432132321

<div>■ Total Output *</div> <div>[TEXT]</div>	32121
<div>■ Total Reject Redbin *</div> <div>[TEXT]</div>	21
<div>■ Sampling Size *</div> <div>[TEXT]</div>	2
<div>■ Kode Reject Guide *</div> <div>[SUBFORM]</div>	QBK - B 123
<div>■ Sign Inspector *</div> <div>[SIGNATURE]</div>	aji
<div>■ Leader / SPV QC *</div> <div>[SIGNATURE]</div>	xzfgaha
<div>■ Final Decision *</div> <div>[BUTTON]</div>	<div>■ PASS</div>
<div>■ Note:</div> <div>[NOTES]</div>	— No response provided —
<div>■ Approved Sample *</div> <div>[SEARCH_DROPDOWN]</div>	Compliant
<div>■ Mylar *</div> <div>[SEARCH_DROPDOWN]</div>	Compliant
<div>■ Shadeband *</div> <div>[SEARCH_DROPDOWN]</div>	Compliant
<div>■ FRA *</div> <div>[SEARCH_DROPDOWN]</div>	Yes
<div>■ Pengecekan *</div> <div>[TIME]</div>	12:32
<div>■ BIQ Patrol Audit *</div> <div>[SEARCH_DROPDOWN]</div>	Yes
<div>■ Inserter *</div> <div>[SEARCH_DROPDOWN]</div>	No
<div>■ Label Status *</div> <div>[SEARCH_DROPDOWN]</div>	No
<div>■ Redbin/Pallet Reject *</div> <div>[SEARCH_DROPDOWN]</div>	No

■ INSPECTION SUMMARY

■ Total Fields:	25
■ Completed Fields:	24 (96.0%)
■ Pass Count:	1
■ Hold Count:	0
■ Flagged Abnormal:	0
■ Overall Status:	SUBMITTED

■ Generated on 2025-10-18 at 10:20:33 by InsPecPro™
Professional Inspection Management System