CERTIFICATE FOR EXAMINATION OF OVERHEAD CRANE

Certificate Number: - E2026010102	**Job Number: -** EAD-5630
Name & Address of Owner of Equipment SULZER A SOS LLC	
Location: SULZER - ASOS – LLC Unit Number A2-05N & A2-05S , Metal Park - Production Hub Al Ma`Mourah - KHIA8 - 07A_08A - Abu Dhabi	**Reference Regulations** BS 7121 PART 2-7: 2012 / **Type Of Inspection** PERIODIC

Equipment Description	ELECTRICALLY OPERATED DOUBLE GIRDER, DOUBLE TROLLEY OVERHEAD TRAVELING CRANE		
Make, Model, & Year of Manufacture	ABUS, DOUBLE GIRDER, 2025		
Serial No/Company ID	36311679	**EOT ID NO**	A2-05-S
Lifting Wire Rope & Reeving Main Hook	16mm @ 4 Falls/14mm @ 4 Falls	**Max Capacity**	20.0/10.0 Ton
Length Of Span	18.4mtr	**Cut off Height**	8.0mtr
Lifting Height	8.75mtr	**Travel Length**	145mtr
Max Allowable Deflection	24.5mm	**Actual Deflection**	17.0mm

Test Equipment Ref:	Previous Inspection Ref:	Date of Inspection	Date of Next Inspection
VC,MT,AI,SL,SG	N.A	02.01.2026	01.01.2027

Result:-

SATISFACTORY AT THE TIME OF INSPECTION.

This Certificate Becomes Invalid, If Any Alteration/Repair/Modification Is Made.

THIS IS TO INFORM YOU: that the undersigned a surveyor or representative did attend to examine this machine (equipment) to assure that it is in safe working condition. Examination indicate that the said equipment has no indigenous defects or sighted deformation and in safe working condition. The said equipment is found to be satisfactory for further use, provided there is continuous maintenance applied and qualified operators employed.

This certificate is granted subject to the condition that is agreed & understood. QICIS liability shall be limited to the act or premises of its employees, subcontractors. Under no circumstances whatsoever shall QICIS be liable for any injury or damage to any person or occurring by reason of negligent operation or any defect in materials, machinery, equipment or other items other than such defects ascertainable normally.

We hereby report that all particulars in this report are correct at the time of test/inspection. Daily inspection & operational maintenance is the sole responsibility of the users.

This certificate shall not be reproduced except in full without the approval of the Quicksand the client.

Authorized Signatory
Engr. Shaheryar Khalid

DESCRIPTION	STATUS	DESCRIPTION	STATUS
Manufacturer Manual	OK	Nondestructive testing	OK
Maintenance record	OK	Cross travel buffer	OK
Certification of lifting gears	OK	Roller	OK
Operator competency (Certifications, license etc.)	OK	Hoist wire rope/ rope guide	OK
Service manual	OK	Hoist rope termination	OK
House keeping	OK	Hoist block & sheave	OK
Safe access & egress	OK	Hook – SWL marking	OK
Power supply & panel	OK	Hoist brake	OK
Power cable	OK	Safety latch	OK
Earth testing	OK	Hoist limit switch (upper & lower)	OK
Crane rail track	OK	Long travel limit switch	OK
Level of track	OK	Cross travel limit switch	OK
Rail track Bolts Condition & fastening	OK	Overload cut off switch	OK
Main support structure	OK	Anti-collision limit switch (optional)	OK
Long travel	OK	Winch drum	OK
Travel Wheels & Bearing	OK	Gantry operation light & alarm	OK
Wheels motors	OK	Fire extinguisher	TO BE PROVIDED
Operator cabin condition	N/A	General condition	OK
Seat and seat belt	N/A	Long travel brake	OK
Wind screen	N/A	Cross travel wheel	OK
Emergency stop	OK	Functional test (without load)	OK
Pendant control	OK	Performance test (equal to SWL)	OK
Control levers / button	OK	Span / deflection at SWL	OK
End carriage buffer	OK	Over Load test (10% overload)	OK
Hook block:	OK		
STATUS: OK=satisfactory; C =See comments; N/A= Not Applicable; NT =Not tested			
Recommendations:			
SATISFACTORY AT THE TIME OF INSPECTION			

This is to certify that above mentioned comments are correct and are verified by competent inspector after inspection, testing & examination of the subject equipment