# OSHA PSM 1910.119 / API RP 75 SHIFT HANDOVER REPORT

Central Processing Facility  Train 1 (V-101 Separator & K-101 Compressor)

Report Ref: SHR-8801D5AE-202610242230 | Incident: INC-8801D5AE | Generated: 2026-10-24 22:30:19

| | | | |
|---|---|---|---|
| **Outgoing Shift Lead:** | Lead Console Operator | **Incoming Shift Lead:** | Incoming Shift Lead |
| **Operational Status:** | **ACTIVE INCIDENT / ABNORMAL** | **Supervisory Mode:** | Level-2 Advisory (Zero DCS Write) |

## 1. Executive Summary & Live DCS Telemetry

Process conditions monitored under Level-2 Supervisory advisory envelope:

| Instrument Tag | Current Reading | Operating Envelope | Alarm State |
|---|---|---|---|
| **DPIT-101** | `0.27 bar` | 0.010 - 0.050 bar | **TRIP (HIGH-HIGH)** |
| **FT-101** | `90000.00 Sm3/h` | 50,000 - 80,000 Sm3/h | **HIGH ALARM** |
| **LT-101** | `50.00 %` | 40.0 - 65.0 % | **NORMAL** |
| **LT-102** | `25.00 %` | 40.0 - 65.0 % | **NORMAL** |
| **LT-103** | `5.00 %` | 5.0 - 20.0 % | **NORMAL** |
| **PT-101** | `30.00 barg` | 28.0 - 34.0 barg | **NORMAL** |
| **PT-102** | `29.30 barg` | 27.0 - 33.0 barg | **NORMAL** |
| **PT-103** | `72.00 barg` | 70.0 - 80.0 barg | **NORMAL** |
| **VT-101** | `5.31 mm/s` | 0.50 - 3.80 mm/s | **TRIP (HIGH-HIGH)** |

**Active Symptoms: SYM_HIGH_DEMISTER_DP, SYM_HIGH_VIBRATION**

## 2. Diagnosed Root Causes & Bayesian Posterior Beliefs

**1. Separator Foaming & Demister Carryover (H03) - 40.1% confidence**

2. Compressor K-101 Aerodynamic Surge (H04) - 38.9% confidence

3. Wellhead Transient Slug Influx (H06) - 18.5% confidence

## 3. Actions Executed & Active Remediation Sequence

No corrective actions executed during this shift.

**Outstanding Plan Sequence:**

- [ ] Step 1: Start Antifoam Dosing Pump P-105 (ACT_02_INJECT_ANTIFOAM_CHEMICAL)
  Target: V-101 | Estimated Time: 3 min

## 4. Field Verification Checks (Completed vs. Pending for Incoming Crew)

No field checks completed yet during this shift.

**Pending Checks for Incoming Shift Lead:**

- [ ] CHK_03_DEMISTER_DP_DRAIN: Check Demister Differential Pressure Gauge & Drain Lines
  Target: V-101 | Priority: 1 | Mandatory Verification
- [ ] CHK_06_SCRUBBER_BOOT_DRAIN: Inspect V-102 Suction Scrubber Boot Auto-Drain Valve
  Target: V-102 | Priority: 2 | Mandatory Verification

## 5. Grounded Technical References (SOPs & HAZOP Safeguards)

**[SOP-V101 Section 2]: Section 2. Demister Fouling, Carryover & Foaming Mitigation**

Excerpt: - **Normal Clean Demister DP (DPIT-101):** 0.015 - 0.035 bar - **Fouling Warning Threshold:** > 0.050 bar...

**[HAZOP-SEP Node 2]: Node 2. Liquid Carryover from V-101 to Compressor (Parameter: Phase Distribution / Liquid in Gas)**

Excerpt: - **Deviation:** MORE Liquid in Vapor Outlet (Carryover) - **Direct Causes:**...

## 6. Formal Shift Handover Sign-off & Regulatory Endorsement

**OUTGOING SHIFT OPERATOR**

Name / Role: Lead Console Operator

Signature: _____

Timestamp: 2026-10-24 22:30:19

**INCOMING SHIFT SUPERVISOR**

Name / Role: Incoming Shift Lead

Signature: _____

Timestamp: _____-_____-_____ ____:____