MTK

MEDIANTEK KILN · MANUFACTURING SOLUTIONS

DUT TEST REPORT

Report No. DUT-FAIL-SN95308-000124-20261017-000622

1 · PRODUCT & TRACEABILITY

SERIAL NO.	**SN95308-000124**	PROJECT PART#	FRDM-MCXL255
CORE ID	95308	BATCH #	B20261016-01
STATION / OPERATOR	STN-01 / op01	REPORT TIME	2026-10-16T17:02:11

2 · TEST SUMMARY

5	4	1	FAIL
ITEMS	PASS	FAIL	OVERALL

3 · TEST DETAIL

3.1 · IMPEDANCE (ICT)

#	TEST	MEASURED / DURATION	LOW	HIGH	UNIT	RESULT
1	Imp VDD_3V3	3.21	1.00		kΩ	PASS


3.2 · VOLTAGE (ICT)

#	TEST	MEASURED / DURATION	LOW	HIGH	UNIT	RESULT
1	VDD_3V3	3.302	3.20	3.40	V	PASS
2	V8_F4232_1	7.42	7.80	8.20	V	FAIL

3.3 · CLOCK (ICT)

#	TEST	MEASURED / DURATION	LOW	HIGH	UNIT	RESULT
1	CLK_24M	24.001	23.90	24.10	MHz	PASS

3.4 · POWER RAILS UP SEQUENCE (DAQ AI) Power Rails Up Sequence — PASS



RAIL	NOMINAL V	FINAL V	RISE 10-90% s	PEAK V	OVERSHOOT	SETTLE ±5% s	NOTE
VDD_3V3	3.300	3.300	1.215	3.399	3.0%	1.182	in regulation (±5%)
V8_F4232	8.000	6.400	—	6.480	0.0%	—	final outside ±5% band — review

4 · INSPECTION SEAL



5 · SIGN-OFF

TESTED BY	REVIEWED BY	AUTHORIZED BY MTK
opol		*MTK2A*

Electronically sealed by MTK GUI — this seal is bound to the report data by trace hash
sha256 · 6e4914b16642aa0d9eef4e49b978711c7e9ddde0d172e2bdca69dab97ef895cd

Console Log

```
[17:00:01] V8_F4232_1 FAIL: measured 7.42 V
```