

VEHICLE SERVICE REPORT

Comprehensive Maintenance Report

Vehicle Information

Registration Number: **191-D-12345**

VIN: **WF0XXXXXXXXXXXXX1**

Make/Model: **Toyota Camry 2023**

Service Date: *15 January 2025*

Current Mileage: **45,230 km**

Owner Information

Owner: John Murphy

Contact: +353 86 123 4567

Email: john.murphy@example.ie

Address: 15 Main Street, Dublin 2, Ireland

Service Overview

This comprehensive service report documents all maintenance activities performed on the vehicle during the scheduled 45,000 km service interval. All work was completed in accordance with Toyota manufacturer specifications and European Union vehicle safety standards.

Services Performed

- Full engine oil and filter replacement
- Brake system inspection and pad replacement
- Tire rotation and pressure adjustment
- Air conditioning system service
- Battery health check and terminal cleaning
- Fluid level inspection (coolant, brake, power steering)
- Lighting system check (all bulbs and indicators)
- Windscreen wiper blade replacement

Complete Service History

The following table shows the complete maintenance history for this vehicle. This data is critical for warranty validation and resale value assessment.

Date	Mileage	Service Type	Parts Replaced	Cost (€)	Technician
15/01/2025	45,230 km	Full Service	Oil filter, Air filter, Wiper blades	€285.00	John Smith
10/12/2024	44,100 km	Tire Service	Tire rotation, Pressure adjustment	€45.00	Mary Jones
05/11/2024	43,000 km	Brake Inspection	Brake pads (front), Brake fluid	€320.00	John Smith
20/10/2024	42,500 km	NCT Preparation	NCT inspection, Emissions test	€95.00	Mary Jones
15/09/2024	41,800 km	Oil Change	Engine oil, Oil filter	€120.00	Tom Brown
10/08/2024	40,200 km	Air Conditioning	AC service, Refrigerant refill	€150.00	John Smith
05/07/2024	39,100 km	Tire Replacement	Front tires (2x Michelin)	€380.00	Mary Jones
15/06/2024	38,500 km	Battery Service	Battery replacement, Terminal cleaning	€180.00	Tom Brown
10/05/2024	37,200 km	Brake Service	Brake pads (rear), Brake disc machining	€340.00	John Smith
05/04/2024	36,000 km	Major Service	Oil, filters, spark plugs, coolant	€450.00	John Smith
15/03/2024	35,100 km	Suspension Check	Suspension inspection, Alignment	€110.00	Mary Jones
10/02/2024	34,500 km	Light Repair	Headlight bulb replacement	€45.00	Tom Brown
05/01/2024	33,800 km	Oil Change	Engine oil, Oil filter	€120.00	John Smith
20/12/2023	32,500 km	Winter	Antifreeze	€65.00	Mary Jones

		Check	top-up, Battery check		
15/11/2023	31,200 km	Tire Service	Winter tire installation	€80.00	Tom Brown
TOTAL				€2,785.00	

Note: This table should remain intact during chunking. HybridChunker should not split table rows across chunks.

Vehicle Identification

The Vehicle Identification Number (VIN) is located on the dashboard visible through the windscreen, and also on the vehicle registration certificate.



(Note: Replace this with actual VIN plate image for OCR testing)

VIN Breakdown

- WFO - World Manufacturer Identifier (Toyota Europe)
- XXXXXXXX - Vehicle Descriptor Section

- XXX1 - Vehicle Identifier Section (Sequential Number)

Detailed Parts and Labor Breakdown

Engine Components

Oil System

Engine oil (5W-30 synthetic, 4.5L): **€45.00**

Oil filter (OEM Toyota): **€18.00**

Air Intake

Air filter (high-performance): **€25.00**

Cabin air filter (activated carbon): **€22.00**

Brake System

Front Brakes

Brake pads (ceramic, set of 4): **€120.00**

Brake disc machining (front): **€60.00**

Brake Fluids

DOT 4 brake fluid (1L): **€15.00**

Service Cost Summary

Item	Amount (€)
Parts Total	€305.00
Labor (3.5 hours @ €65/hr)	€227.50
Subtotal	€532.50
VAT (23%)	€122.48
TOTAL	€654.98

Total Service Cost: **€654.98**

Payment and Warranty

Payment received in full on 15/01/2025 via credit card. **All parts and labor are covered by a 12-month warranty** in accordance with EU consumer protection regulations. This warranty covers defects in materials and workmanship.

Service Certification

Certified by: **John Smith, Senior Technician**

Certification Number: **TC-2025-001234**

Date: *15 January 2025*