

Roof and Gutter cleaning report

Sample completed site report for client New reports

Report ID	NR-2026-0908-0142	Status	Completed
Date	08/09/2026 11:40	Template	New Report
Client	Bayside Council	Site	Tonbridge Reserve
Service	Reactive/Adhoc Maintenance Works	Submitted by	Field Staff

Work summary

Roof and gutter cleaning completed at Tonbridge Reserve. Gutters were cleared of leaves and silt, downpipes were checked and flushed, and roof debris was removed from accessible areas. Site left tidy with no standing water observed at the entry path.

Checklist

Item	Result	Notes
Gutter clear-out	Complete	Leaves and silt removed along full run
Downpipe flush	Complete	Flow restored; no blockage remaining
Roof debris removal	Complete	Loose debris cleared from accessible roof edge
Overflow / pooling check	Pass	No pooling near entry after clean
Photo evidence	Attached	Before/after site photos on file

Materials / notes

No replacement parts required. Recommend seasonal inspection before next storm season. This PDF is a sample marketing document mirroring a completed New Report download for client review.