




Path: U:\Coding\Python\Budding-GDB\GIS\Reports\Benzene\MXDs\Report 1 - Figure 4.mxd




Legend

 Property Boundary

Sample Locations

-  No Sample (1)
-  Above (11)
-  Below (9)

 Extent of Benzene Contamination

NOTES:
* The random data generated for sample locations and contamination boundary drawn does not reflect the current state of soil. Data was produced for sample report figures.
* NJ Soil remediation standards for Benzene is 2 mg/kg.

**AREA 12 OVERVIEW
WITH SAMPLE LOCATIONS**

BENZENE SOIL CONTAMINATION

ACME
Environmental Cleanup Unit
Highland Park, NJ

PROJECT #:	DATE:	DWN:	CHKD:	FIG NO.:
#####-####	9/23/2016	sdochert2	sdochert2	4