

Assam Flood Report as on 15-06-2026										
Particulars	Assam Flood Report as on 15-06-2026									
Rivers flowing above Danger Level (as per CWC bulletin issued at 8 AM)	Rivers flowing above danger level					Nil				
	Rivers flowing above highest flood level					Nil				
District Affected	No. of Districts Affected	Name of Affected Districts								
	1	Dhemaji								
No. Of Revenue Circles Affected	2									
Name Of Revenue Circle Affected	District	Total	Revenue Circle							
	Dhemaji	2	Dhemaji, Gogamukh							
	Total	2								
Villages Affected	District	Total	Revenue Circle							
	Dhemaji	10	(Dhemaji 2), (Gogamukh 8)							
	Total	10								
Population And Crop Area Submerged	District	Male	Female	Children	Total Population	Total Crop Area (in Hect.)	Population and Crop Area Details			
	Dhemaji	26	22	7	55	17	(Dhemaji Population Affected: 55 Crop Area Submerged: 4), (Gogamukh Population Affected: 0 Crop Area Submerged: 13)			
	Total	26	22	7	55	17				
Relief Camps / Centres Opened	District	Total	Relief Camp				Relief Distribution Centres			
	Dhemaji	0	0 (Dhemaji 0), (Gogamukh 0)				0 (Dhemaji 0), (Gogamukh 0)			
	Total	0	0				0			
Inmates In Relief Camps	District	Total	Revenue Circlewise			Male	Female	Children	Pregnant / Lactating Mother	Person with Disability
	Dhemaji	0	(Dhemaji 0), (Gogamukh 0)			0	0	0	0	0
	Total	0				0	0	0	0	0
Non Camp Inmates in Relief Distribution Centers	District	Total	Revenue Circlewise			Male	Female	Children	Animals	
	Dhemaji	0	(Dhemaji 0), (Gogamukh 0)			0	0	0	Big	Small
	Total	0				0	0	0	0	0
Human Lives Lost - Confirmed	District	Total	Flood Death	General Drowning (Non Flood)	Male	Female	Children		Others	Revenue Circlewise
	Dhemaji	0	0	0	0	0	Male	Female		
	Total	0	0	0	0	0	0	0	0	
Human Lives Lost - Missing	District	Total	Male	Female	Children		Others	Revenue Circlewise		
	Dhemaji	0	0	0	Male	Female				
	Total	0	0	0	0	0	0	0 (Dhemaji 0), (Gogamukh 0)		
Animals Affected	District	Total	Big	Small	Poultry					
	Dhemaji	0	0	0	0					
	Total	0	0	0	0					
Animals Washed Away	District	Total	Big	Small	Poultry					
	Dhemaji	0	0	0	0					
	Total	0	0	0	0					

Houses Damaged	District	Fully Kuccha	Fully Pukka	Fully Total		Partially Kuccha	Partially Pukka	Partially Total				
	Dhemaji	0	0	0		0	0	0				
	Total	0	0	0		0	0	0				
Houses Damaged Others	District	Others Huts			Others Cattle Shed			Others Total				
	Dhemaji	0			0			0				
	Total	0			0			0				
Rescue Operation	District	Agency			Other Agencies Involved		Medical Team Deployed	Boats Deployed	Person Evacuated By Boats	Animal Evacuated By Boats	Helicopters Deployed	Person Evacuated By Helicopters
	Dhemaji						0	0	0	0	0	0
	Total						0	0	0	0	0	0
Relief Distributed	District	Rice (in Q)	Dal (in Q)	Salt (in Q)	M. Oil (in L)	Cattle Feed - Green Fooder (in Q)	Cattle Feed - Wheat Bran (in Q)	Cattle Feed - Rice Bran (in Q)				
	Dhemaji	0	0	0	0	0	0	0				
	Total	0	0	0	0	0	0	0				
Relief Distributed - Others	District	Baby Food Liquid		Baby Food Solid		Others						
	Dhemaji											
Infrastructure Damaged - Road	District	Number	Revenue Circle	Road Name		Department	Village	Location	Longitude	Latitude	Remarks	
	Dhemaji	7	(Dhemajih 2)	Bengenagarh Dighalgarah to Bengenagarah Dhani Mandir via Nepalibari PWD road		PWD (Roads)	Benganagorah Gaon	Bengenagarh Dighalgarah to Bengenagarah Dhani Mandir via Nepalibari PWD road	94.533337	27.374077	Today on 15/06/2026, Due to heavy rainfall, erosion of side shoulder,potholes, depression and waterlogging occurred at road connecting Bengenagarh Dighalgarah to Bengenagarah Dhani Mandir via Nepalibari PWD road from Ch.0.00Km to 5.00Km,	
				Basudev tiniali to 5 No Tekjuri PWD road		PWD (Roads)	No. 5 Tekjuri	Basudev tiniali to 5 No Tekjuri PWD road	94.516414	27.52441	Today on 15/06/2026, Due to heavy rainfall rain cut occurred at various places along the road connecting Basudev tiniali to 5 No Tekjuri PWD road from Ch.0.00 m to Ch.5000.00m.	
				(Gogamukh 5)		Joyrampur to 1 No. Baijantipur road via Kalbari and Nolatol Gaon erosion of side berms from Ch.1.5 KM to Ch.1.63KM, 130 meters length washout due to heavy rainfall followed by flash floods on 15-06-2026	PWD (Roads)	Narayanpur 1/2	Joyrampur to 1 No. Baijantipur road via Kalbari and Nolatol Gaon			

				Chenia to Hiloimari khat Road Side berm along with Carriageway of the road damaged due to overtop at multiple stretches due to heavy rainwater runoff at Chainage 2520.00m to Chainage 3020.00 m of 500 meters on 15-06-2026.	PWD (Roads)	Hiloimari Khat	Chenia to Hiloimari khat			
				Kamalpur to Dhamapur road at several locations, 100 meters side berms along with Bamboo Bridge of 30meters damaged due to heavy rainfall and flashfloods from the foothills areas of Arunachal Pradesh on 15-06-2026	PWD (Roads)	No. 1 Dharmapur	Kamalpur to Dhamapur			
				Sankarpur LP School to Cheniachuck Road Side berm along with Carriageway of the road damaged at multiple stretches due to erosion from heavy rainwater runoff at Ch 5295.00m, 7510.00 m, 7540.00 m for a stretch of 40 meters damaged on 15-06-2026	PWD (Roads)	Chenia Deori	Sankarpur LP School to Chenaichuck			
				Bordoloni Chariali to Khaliamari Tiniali road side berms eroded at several location from Ch. 2.0 Km to Ch. 2.5 Km 500 meters roads has been damaged due to raincut on 15-06-2026	PWD (Roads)	Moralchuk	Bordoloni Chariali to Khaliamari Tiniali			
	Total	7								
Infrastructure Damaged - Bridge	District	Number	Revenue Circle	Bridge Name	Department	Village	Location	Longitude	Latitude	Remarks
	Dhemaji	0	(Dhemaji 0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
			(Gogamukh 0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil
	Total	0								
Infrastructure Damaged - Embankment Breached	District	Number	Revenue Circle	Embankment Breached Name	Department	Village	Location	Longitude	Latitude	Remarks
	Dhemaji	0	(Dhemaji 0)	Nil	Nil	Nil	Nil	Nil	Nil	Nil

			(Gogamukh 0)	Nil		Nil	Nil	Nil	Nil	Nil	Nil
	Total	0									
Infrastructure Damaged - Embankment Affected	District	Number	Revenue Circle	Embankment Affected Name		Department	Village	Location	Longitude	Latitude	Remarks
	Dhemaji	1	(Dhemaji 0)	Nil		Nil	Nil	Nil	Nil	Nil	Nil
			(Gogamukh 1)	Kumotiya Right Bank Embankment from NH-15 to Hatigarh at Sapekhati, Chutiakari, Moralchuk 10 meters rain cuts due to heavy rainfall followed by flash floods on 15-06-2026.		Water Resource Deptt.	Sapaekhathi N.C.	Sapekhati, Chutiakari, Moralchuk			
	Total	1									
Infrastructure Damaged - Others	District	Revenue Circle	Damages	Number	Name	Department	Village	Location	Longitude	Latitude	Remarks
	Dhemaji	Dhemaji	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
		Gogamukh	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil	Nil
Wildlife affected under protected areas description	District	Details									
	Dhemaji										
Remarks	District	Details									
	Dhemaji	(Dhemaji - Infrastructure damages submitted as per report received from PWD road Deptment.)									
	Report Generated On: 15-06-2026 04:51 PM										