Halward Inspection Services Ltd.

Transmittal

Site: Hamilton Plant

No.	Status	Date
HIS-TR-2007-026	Issued	2007-09-18

Transmittal - HIS-2007-0388

DISTRIBUTION

To: QSCP Hamilton Inspection Department

Attn: Inspection Manager

From: Halward Inspection Services Ltd.

TRANSMITTAL DETAILS

Document No: HIS-TR-2007-026

Date: 2007-09-18

Unit: ATU-100

Purpose: For review

ENCLOSURES

1 x HIS-2007-0388: UT Thickness Survey and Fitting Scans - Regenerator Overhead Circuit

1 x HIS-2007-0388-DS-3-RV-101: UT Thickness Data Sheet - 3-RV-101

1 x HIS-2007-0388-DS-2-RV-102: UT Thickness Data Sheet - 2-RV-102

ACKNOWLEDGEMENT

Please acknowledge receipt of this transmittal and the enclosed documents.