Larkhall NDE Services Inc.

Transmittal

Site: Hamilton Plant

No.	Status	Date
LNDE-TRN-2026-049	Issued	2026-08-03

Transmittal - LNDE-RPT-20260803-034-R0

Recipient and Sender

To: QSCP Hamilton Inspection Department

Attn: Inspection Department

From: Larkhall NDE Services Inc.

Transmission Details

Purpose: Review of UT baseline for replacement spools in ATU-100

Date: 2026-08-03

Enclosures

LNDE-RPT-20260803-034-R0: Report - UT Baseline - Replacement Spools on 4-RA-101 and 2-RF-102

LNDE-RPT-20260803-034-DS-4-RA-101: UT Thickness Data Sheet - 4-RA-101

LNDE-RPT-20260803-034-DS-2-RF-102: UT Thickness Data Sheet - 2-RF-102

Acknowledgement

Please acknowledge receipt of this transmittal and the enclosed documents.