No.	Status	Date
LNDE-JSA-20241202-036	Issued	2024-12-10

Job Safety Analysis - PAUT Corrosion Mapping, ATU-100

General Information

Document ID: LNDE-JSA-20241202-036

Date: 2024-12-10

Location: Hamilton Plant

Unit: ATU-100

Author: Marcus Chen, Larkhall NDE Services Inc.

Task Description

Activity: Phased Array Ultrasonic Testing (PAUT) for corrosion mapping.

Scope: Automated and manual encoded scanning of pressure boundary surfaces.

Objective: Identification of wall loss and localized thinning.

Hazard Identification and Controls

Surface Temperature: Verify against couplant and wedge specifications.

Access: Scaffolding and elevated work platforms required for overhead piping.

Chemical Exposure: Amine and sour gas hazards associated with ATU-100 process streams.

Equipment: Use of water-based couplant and electrical NDE instruments.

Site Compliance and Reporting

Acceptance: Readings below t-min require immediate NCR issuance.

Material: A312 TP316 components require stainless-steel velocity calibration.

Intervals: RBI and Class maxima apply based on service fluid and remaining life calculations.

Sign-off	Name	Function	Date	Signature
Prepared	Marcus Chen	lead UT technician, SNT-TC-1A UT/MT/PT/VT Level II; CAN/CGSB-48.9712 UT Level II	2024-12-10	_____