

# Service Report Details

## Service Information

**Name:** Madhu

**Date of Visit:** 2025-03-19

**Zone:** Mangaluru (MNG-KA)

**Phone No:** 9901245511

**Reason of Visit:** Service

**In Time:** 5:30 p.m.

**Out Time:** 12:07 p.m.

## Customer Information

**Customer Name:** Provident housing

**Contact Number:** 9742528379

**Location:** Mangalore

**State:** Karnataka

**Date of Complaint:** 2025-03-17

**Status of Call:** Amc

## Electronic Items

Item Name	Checked	Repair	Replacement	Remark
Supply Voltage	Yes	-	-	
Current Load	Yes	-	-	
Load Break Switch	Yes	-	-	
MCB	Yes	-	-	
Surge Protector	Yes	-	-	
SMPS	Yes	-	-	
AC Contactors	Yes	-	-	
DC Contactors	Yes	-	-	
SSR	Yes	-	-	
AMPV	Yes	-	-	
Timers	Yes	-	-	
Relay Module	Yes	-	-	
PLC/ Controller Board	Yes	-	-	
HMI	Yes	-	-	

### **Electronic Panel Status**

<b>Panel Name</b>	<b>Checked</b>	<b>Repair</b>	<b>Replacement</b>	<b>Remark</b>
Water DRS Sensors	Yes	-	-	
Current Sensors	-	-	-	
Ultrasonic Sensors	-	-	-	

### **Chemical Item Status**

<b>Item Name</b>	<b>Checked</b>	<b>Repair</b>	<b>Replacement</b>	<b>Remark</b>
A1000	-	-	-	None
EC Cell	Yes	-	-	None
2300	-	-	-	None
EC 1000	-	-	-	None

### **Pump Status**

<b>Pump Name</b>	<b>Checked</b>	<b>Repair</b>	<b>Replacement</b>	<b>Remark</b>
FFP	-	-	-	None
LSP	Yes	-	-	None
Dosing Pump	-	-	-	None
Air Blower	Yes	-	-	None
Drain Valve	Yes	-	-	None
UV	Yes	-	-	None
Bag Filter	-	-	-	None
Candle Filter	-	-	-	None
FRP Filter	-	-	-	None
Agri Filter	-	-	-	None
Cyclone Filter	-	-	-	None

### **Miscellaneous Item Status**

<b>Item Name</b>	<b>Checked</b>	<b>Repair</b>	<b>Replacement</b>	<b>Remark</b>
MTA-FTA	Yes	-	-	None
Union	Yes	-	-	None
Collar	Yes	-	-	None

Item Name	Checked	Repair	Replacement	Remark
Tee	Yes	-	-	None
Drain Valve	Yes	-	-	None
Elbow	Yes	-	-	None
Pipe	Yes	-	-	None
End Cap	Yes	-	-	None
Reducer	Yes	-	-	None
Ball Valve	Yes	-	-	None
Tank Nipple	Yes	-	-	None
NRV Valve	Yes	-	-	None
Brass 3-way Ball Valve	-	-	-	None

#### **Wastewater Parameter Status**

Parameter Name	Checked	Repair	Replacement	Remark
Oil & Grease	-	-	-	None
Ph Value	Yes	-	-	None

#### **Machine Run Times**

Run Type	Run Time	End Time	Checked	Pass Status	Fail Status	Remark
No machine run times available.						

#### **Tool Status**

Tool Name	Quantity	Taken Status	Remark
Wrench	1	Yes	None
Screwdriver Sets	1	Yes	None
Multimeter	1	Yes	None
Clamp Meter	1	Yes	None
Litmus Paper	1	Yes	None
TDS Meter	1	Yes	None
Drill M/C Cardless	1	Yes	None
Drill Bits	1	-	None
Fasteners	1	Yes	None

Tool Name	Quantity	Taken Status	Remark
Teflon Tape	1	Yes	None
Jack Sets	1	-	None
Caster Wheel	1	-	None
Hand Gloves	1	Yes	None
Chemical	1	-	None
Glass Beaker	1	-	None
Insulation Tape	1	-	None
UnderWaterTape	1	-	None

### Service Report Details


#### Other Remarks:

Hosa box torsi replace madh math haledh box avrig bekh ambr use maduke koth bidh Elbow 2 nos damaged replacement done Brass valve changed 1nos lbc tank cleaning Intermediate settler cleaning Cbt cleaning Venturimeter all checked Ec cell lifted and checked All machines checked Bar screen box replacement done Liquid mixing done

#### Spares Details:


#### Attachments





























**Service Person Name:**

MADHu S

**Service Person Signature:**

A handwritten signature consisting of a wavy line followed by a straight line extending upwards and to the right.**Client Name:**

Dhanraj

**Client Signature:**A small, simple handwritten mark or slash.