CARCHECK AGENT

CONDITION SCREENING REPORT

Inspection ID: insp_25e50eab73
Date: 2026-10-23 18:15 UTC

MANDATORY SCREENING DISCLAIMER: Screening tool only. Never claim certification or accident-free status. This automated report identifies possible cosmetic, paint, and panel alignment discrepancies from smartphone video. Always confirm all flagged items with an independent professional mechanic prior to purchase or settlement.

Vehicle: 2025 Honda Civic
Summary: Significant physical wear, panel misalignment, or paint differences detected.

35/100
Condition Score

VERIFIED
Trust Layer Integrity

Trust Layer Verification Details:
- Captured in-app via device camera stream.
- Video SHA-256 checksum verified against client computation.
- Single-use capture challenge successfully verified in-frame.
- Continuous video stream with no unexplained hard cuts.
- Vehicle identification and plates consistent throughout.
- Body color and vehicle appearance consistent across 360 walkaround.

Video SHA-256: `ebe2b61d3d226ee4f526a6751c75cb3e926441132a1a273cadfeb114f43fa3b9`

Flagged Findings (21)

ID	Type	Panel	Severity	Conf.	Agent Note
fnd_7bcfb6c4	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
fnd_7ca24249	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
fnd_e02d1b4b	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
fnd_bceb51f5	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
fnd_1ae65d91	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
fnd_482fe6f3	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
fnd_4504fe1a	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.
fnd_a27be416	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.

fnd_be03d30e	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.
fnd_98fb4ff8	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.
fnd_04d64b0d	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_76aa3015	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_72172f3c	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_b11ff3a7	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_d485eb59	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_dc0b82fe	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_ca30d5b5	Panel gap asymmetry	front	Moderate	88%	Panel gap asymmetry (18.46 mm) detected along front_seam.
fnd_dd000a47	Panel gap asymmetry	rear	Moderate	72%	Panel gap asymmetry (None mm) detected along rear_seam.
fnd_8ac633ab	Tyre wear	tyre (left)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_d0e15d01	Tyre wear	tyre (right)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_a860dfe4	Tyre wear	tyre (rear)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.

Recommended Questions for Seller / Inspector

- [fnd_7bcfb6c4] What was the cause of the moderate scratch on the front bumper?
- [fnd_7ca24249] What was the cause of the moderate scratch on the front bumper?
- [fnd_e02d1b4b] What was the cause of the moderate scratch on the front-left fender?
- [fnd_bceb51f5] What was the cause of the moderate scratch on the front-left fender?
- [fnd_1ae65d91] What was the cause of the moderate scratch on the left door?
- [fnd_482fe6f3] What was the cause of the moderate scratch on the left door?
- [fnd_4504fe1a] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_a27be416] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_be03d30e] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_98fb4ff8] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_04d64b0d] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_76aa3015] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_72172f3c] What was the cause of the moderate scratch on the right door?
- [fnd_b11ff3a7] What was the cause of the moderate scratch on the right door?
- [fnd_d485eb59] What was the cause of the moderate scratch on the front-right fender?

• [fnd_dc0b82fe] What was the cause of the moderate scratch on the front-right fender?
• [fnd_ca30d5b5] Has the vehicle experienced any front/side collision impacting front alignment?
• [fnd_dd000a47] Has the vehicle experienced any front/side collision impacting rear alignment?
• [fnd_8ac633ab] When were the tyres on the tyre (left) last replaced or aligned?
• [fnd_d0e15d01] When were the tyres on the tyre (right) last replaced or aligned?
• [fnd_a860dfe4] When were the tyres on the tyre (rear) last replaced or aligned?

Cryptographic Report Integrity (ECDSA P-256):
Report Digest (SHA-256): `30cfdd6e5c67e84fc294edf38c9cbe49514becc27697a1780c4fde21a6ec5d51`
ECDSA Signature: `MEYCIQDRZkuTQn5f5SswNyjVORZDNUx7OqQlVTSLzgOUzAqe...`
Public Verification URL: /reports/insp_25e50eab73/verify