CARCHECK AGENT

CONDITION SCREENING REPORT

Inspection ID: insp_7ca00428b2
Date: 2026-10-22 21:06 UTC

MANDATORY SCREENING DISCLAIMER: Screening tool only. Never claim certification or accident-free status. This automated report identifies possible cosmetic, paint, and panel alignment discrepancies from smartphone video. Always confirm all flagged items with an independent professional mechanic prior to purchase or settlement.

Vehicle: 2025 Honda Civic
Summary: Significant physical wear, panel misalignment, or paint differences detected.

35/100
Condition Score

VERIFIED
Trust Layer Integrity

Trust Layer Verification Details:
- Captured in-app via device camera stream.
- Video SHA-256 checksum verified against client computation.
- Single-use capture challenge successfully verified in-frame.
- Continuous video stream with no unexplained hard cuts.
- Vehicle identification and plates consistent throughout.
- Body color and vehicle appearance consistent across 360 walkaround.

Video SHA-256: `ebe2b61d3d226ee4f526a6751c75cb3e926441132a1a273cadfeb114f43fa3b9`

Flagged Findings (21)

ID	Type	Panel	Severity	Conf.	Agent Note
fnd_983c2d83	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
fnd_c83b590c	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
fnd_9dcb3501	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
fnd_d3c545d0	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
fnd_6093655d	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
fnd_8223568 3	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
fnd_2a3e5fa0	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.
fnd_e686bd47	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.

fnd_c68fedeb	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.
fnd_455f5ca4	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.
fnd_6f4c9049	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_72a7dadc	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_db0a6c11	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_4f1ecd83	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_7306e8b8	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_d6298cf5	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_7b599305	Panel gap asymmetry	front	Moderate	88%	Panel gap asymmetry (18.46 mm) detected along front_seam.
fnd_2d253343	Panel gap asymmetry	rear	Moderate	72%	Panel gap asymmetry (None mm) detected along rear_seam.
fnd_3c9470c7	Tyre wear	tyre (left)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_69fdcf5e	Tyre wear	tyre (right)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_68d59b6f	Tyre wear	tyre (rear)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.

Recommended Questions for Seller / Inspector

- [fnd_983c2d83] What was the cause of the moderate scratch on the front bumper?
- [fnd_c83b590c] What was the cause of the moderate scratch on the front bumper?
- [fnd_9dcb3501] What was the cause of the moderate scratch on the front-left fender?
- [fnd_d3c545d0] What was the cause of the moderate scratch on the front-left fender?
- [fnd_6093655d] What was the cause of the moderate scratch on the left door?
- [fnd_82235683] What was the cause of the moderate scratch on the left door?
- [fnd_2a3e5fa0] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_e686bd47] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_c68fedeb] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_455f5ca4] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_6f4c9049] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_72a7dadc] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_db0a6c11] What was the cause of the moderate scratch on the right door?
- [fnd_4f1ecd83] What was the cause of the moderate scratch on the right door?
- [fnd_7306e8b8] What was the cause of the moderate scratch on the front-right fender?

• [fnd_d6298cf5] What was the cause of the moderate scratch on the front-right fender?
• [fnd_7b599305] Has the vehicle experienced any front/side collision impacting front alignment?
• [fnd_2d253343] Has the vehicle experienced any front/side collision impacting rear alignment?
• [fnd_3c9470c7] When were the tyres on the tyre (left) last replaced or aligned?
• [fnd_69fdcf5e] When were the tyres on the tyre (right) last replaced or aligned?
• [fnd_68d59b6f] When were the tyres on the tyre (rear) last replaced or aligned?

Cryptographic Report Integrity (ECDSA P-256):
Report Digest (SHA-256): `958a2fafcb2d862c04277a11d04214ff9a8c7ffc9b52819d2f3b3f162e24bf8c`
ECDSA Signature: `MEUCIQD4UfrLKWGFmFBNWsAjxLGoWaue9d3ZP6jjqiAS3JzT...`
Public Verification URL: /reports/insp_7ca00428b2/verify