CARCHECK AGENT

CONDITION SCREENING REPORT

Inspection ID: insp_eeadeb8a04
Date: 2026-10-23 18:13 UTC

MANDATORY SCREENING DISCLAIMER: Screening tool only. Never claim certification or accident-free status. This automated report identifies possible cosmetic, paint, and panel alignment discrepancies from smartphone video. Always confirm all flagged items with an independent professional mechanic prior to purchase or settlement.

Vehicle: 2026 Toyota CH-R
Summary: Significant physical wear, panel misalignment, or paint differences detected.

35/100
Condition Score

VERIFIED
Trust Layer Integrity

Trust Layer Verification Details:
- Captured in-app via device camera stream.
- Video SHA-256 checksum verified against client computation.
- Single-use capture challenge successfully verified in-frame.
- Continuous video stream with no unexplained hard cuts.
- Vehicle identification and plates consistent throughout.
- Body color and vehicle appearance consistent across 360 walkaround.

Video SHA-256: `8be77e91d8baf6f9ee0fd614877601bcc773b5f0a4a51394c4db21ff0b7d0f1e`

Flagged Findings (21)

ID	Type	Panel	Severity	Conf.	Agent Note
`fnd_cfe43ae1`	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
`fnd_fd4e47f3`	Scratch	front bumper	Moderate	92%	Possible moderate scratch detected on front bumper (80% confidence). Reconciled by vision agent.
`fnd_b5718ee8`	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
`fnd_d5bba59c`	Scratch	front-left fender	Moderate	92%	Possible moderate scratch detected on front-left fender (80% confidence). Reconciled by vision agent.
`fnd_25fdef42`	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
`fnd_4ad96cb2`	Scratch	left door	Moderate	92%	Possible moderate scratch detected on left door (80% confidence). Reconciled by vision agent.
`fnd_79c5fad2`	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.
`fnd_a2085c58`	Scratch	rear-left quarter panel	Moderate	92%	Possible moderate scratch detected on rear-left quarter panel (80% confidence). Reconciled by vision agent.

fnd_a968f42c	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.
fnd_7a7d3526	Scratch	rear bumper & boot	Moderate	92%	Possible moderate scratch detected on rear bumper & boot (80% confidence). Reconciled by vision agent.
fnd_5d0dae7d	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_e24bd0dc	Scratch	rear-right quarter panel	Moderate	80%	Possible moderate scratch detected on rear-right quarter panel (80% confidence).
fnd_cf36ca94	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_5da13880	Scratch	right door	Moderate	80%	Possible moderate scratch detected on right door (80% confidence).
fnd_fa33bc12	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_b37d5350	Scratch	front-right fender	Moderate	80%	Possible moderate scratch detected on front-right fender (80% confidence).
fnd_124f8ce6	Panel gap asymmetry	front	Moderate	88%	Panel gap asymmetry (18.46 mm) detected along front_seam.
fnd_4f837362	Panel gap asymmetry	rear	Moderate	72%	Panel gap asymmetry (None mm) detected along rear_seam.
fnd_46dfbfb9	Tyre wear	tyre (left)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_9a1fd627	Tyre wear	tyre (right)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.
fnd_14ff5c4a	Tyre wear	tyre (rear)	Moderate	82%	Tyre wear noted: tread depth 1.5 to 3 mm.

Recommended Questions for Seller / Inspector

- [fnd_cfe43ae1] What was the cause of the moderate scratch on the front bumper?
- [fnd_fd4e47f3] What was the cause of the moderate scratch on the front bumper?
- [fnd_b5718ee8] What was the cause of the moderate scratch on the front-left fender?
- [fnd_d5bba59c] What was the cause of the moderate scratch on the front-left fender?
- [fnd_25fdef42] What was the cause of the moderate scratch on the left door?
- [fnd_4ad96cb2] What was the cause of the moderate scratch on the left door?
- [fnd_79c5fad2] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_a2085c58] What was the cause of the moderate scratch on the rear-left quarter panel?
- [fnd_a968f42c] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_7a7d3526] What was the cause of the moderate scratch on the rear bumper & boot?
- [fnd_5d0dae7d] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_e24bd0dc] What was the cause of the moderate scratch on the rear-right quarter panel?
- [fnd_cf36ca94] What was the cause of the moderate scratch on the right door?
- [fnd_5da13880] What was the cause of the moderate scratch on the right door?
- [fnd_fa33bc12] What was the cause of the moderate scratch on the front-right fender?

• [fnd_b37d5350] What was the cause of the moderate scratch on the front-right fender?
• [fnd_124f8ce6] Has the vehicle experienced any front/side collision impacting front alignment?
• [fnd_4f837362] Has the vehicle experienced any front/side collision impacting rear alignment?
• [fnd_46dfbfb9] When were the tyres on the tyre (left) last replaced or aligned?
• [fnd_9a1fd627] When were the tyres on the tyre (right) last replaced or aligned?
• [fnd_14ff5c4a] When were the tyres on the tyre (rear) last replaced or aligned?

Cryptographic Report Integrity (ECDSA P-256):
Report Digest (SHA-256): `54be5736e26ea55cea3f0e1612c57ef455bf12d0bce331beb8f15fb552b18573`
ECDSA Signature: `MEYCIQDNm43NXwsyD2YBceYMu2h7yG1u7ZIvDOX1IQksN39d...`
Public Verification URL: /reports/insp_eeadeb8a04/verify