



**Boral Construction Materials
Materials Technical Services**

Unit 4, 3-5 Gibbon Road
Baulkham Hills NSW 2153 Australia
PO Box 400, Winston Hills NSW 2153

T: +61 (02) 9624 9900
F: +61 (02) 9624 9999

www.boral.com.au

CONCRETE TEST REPORT

CLIENT: NEOCRETE LTD

CLIENT No: 482/19

PROJECT: Water permeability tests: 2PC Mix D5 - 2%

Request No: 87149

Sample Description: 150 x 120mm concrete cylinders

TEST METHOD: BS EN 12390-8:2009 Depth of penetration of water under pressure.

Date cast: 15.11.2019

Date commencement of test: 13.12.2019

Age of concrete: 28 days

Lab Sample Number	Sample ID. Number	Maximum depth of water penetration (mm)
229171/1	W19 428 - A	4
229171/2	W19 428 - B	5

NOTE: Direction of water pressure along vertical plane of cylinder with respect to the casting direction.

Remarks: Specimens submitted by client on 03.12.2019 in moist condition, and testing was done by our laboratory staff in accordance with BS EN 12390-8:2009.

Comments: Test results in this test report relate only to samples tested.

Z. Bazoeva, File: 7902, Ref. 87149TS



Approved Signatory

Robert Camilleri

Date 17.12.2019 Serial No. CON87149.RC.1

Accredited for compliance with ISO/IEC 17025 - Testing
This report shall not be reproduced except in full without the approval of the Boral MTS Laboratory

NATA Accredited Laboratory

Number: 547



**Boral Construction Materials
Materials Technical Services**

Unit 4, 3-5 Gibbon Road
Baulkham Hills NSW 2153 Australia
PO Box 400, Winston Hills NSW 2153

T: +61 (02) 9624 9900
F: +61 (02) 9624 9999

www.boral.com.au

CONCRETE TEST REPORT

CLIENT: NEOCRETE LTD

CLIENT No: 482/19

PROJECT: Water permeability tests: 3PC Mix D5 - 3%

Request No: 87149

Sample Description: 150 x 120mm concrete cylinders

TEST METHOD: BS EN 12390-8:2009 Depth of penetration of water under pressure.

Date cast: 15.11.2019

Date commencement of test: 13.12.2019

Age of concrete: 28 days

Lab Sample Number	Sample ID. Number	Maximum depth of water penetration (mm)
229172/1	W19 429 - A	5
229172/2	W19 429 - B	5

NOTE: Direction of water pressure along vertical plane of cylinder with respect to the casting direction.

Remarks: Specimens submitted by client on 03.12.2019 in moist condition, and testing was done by our laboratory staff in accordance with BS EN 12390-8:2009.

Comments: Test results in this test report relate only to samples tested.

Z. Bazoeva, File: 7902, Ref. 87149TS



Approved Signatory

Date 17.12.2019

Serial No.

CON87149.RC.1

Robert Camilleri

Accredited for compliance with ISO/IEC 17025 - Testing
This report shall not be reproduced except in full without the approval of the Boral MTS Laboratory

NATA Accredited Laboratory

Number: 547