Job 6 - Website form -> Zendesk -> AI email agent -> free VA

Client photos in a Zendesk ticket, booking done by our AI agent 'Bruce', video call, estimate

Property	109 Stoney Pond Ct, Stittsville, ON (house)
Client	Homeowner (returning contact)
Service	Free Virtual Inspection (video call)
Paid	Free
Booked by	Bruce - our AI email agent, inside Zendesk
Virtual inspector	Luka Markovic, MSC ME, CMI
Estimate sent by	Danica - client support
Follow-up	Close CRM SMS + Natasa (manual)

Why the client called

Website form: 'Mold on ceiling in bathroom shower and around edge of bathtub where caulking is. There is a bathroom fan that is used regularly.' The client uploaded 2 photos with the form. She had an older quote from us and in May 2026 texted that she wanted to go ahead with it.

Step by step

When (Eastern)	Step	System	What happened
Tue Sep 1, 2026 15:34	Website form	bustmold.com form -> Zendesk ticket 52925	Client fills in the form on her iPhone and uploads 2 photos. A Zendesk ticket is created by email.
Tue Sep 1, 15:41	AI reply	Zendesk (Bruce, AI email agent)	Bruce thanks her for the photos and suggests the free virtual inspection as the first step.
Tue Sep 1, 15:44-15:54	Choosing a time	Zendesk email	Client: 'Let's go ahead and book'. Bruce offers 2 slots for the next day; client picks 9:00 AM.
Tue Sep 1, 16:11	Booked	Zendesk + Google Calendar (MB - Virtual Inspections)	Bruce confirms. Calendar event created: 'Booked by Bruce Text AI Agent', with the Zendesk link. 37 minutes from form to booking, no human involved.
Wed Sep 2, 09:00	Video call	Mold Busters Virtual Inspection app	8-minute call. From about 0:40 to 6:30 the client walks the camera through the bathroom (shower ceiling, tub, toilet area).
Wed Sep 2, 11:01	App review request	Close CRM (SMS)	SMS asking the client to rate the VA app.
Wed Sep 2, 12:37-12:38	Raw notes	Telegram (MB Virtual Inspections 1)	Inspector posts the booking details and 7 photos ('Area of concern').
Fri Sep 4, 10:23-10:26	Estimate sent	FreshBooks + Asana	Estimate MO971 ($1,495 + HST) sent. No report - free VAs get an estimate only.
Sep 21 - Sep 28	Follow-up	Close CRM (SMS)	4 follow-up SMS, the last one: 'still interested... or should we close your case?'
Thu Oct 1	Manual follow-up	Asana + Dialpad	Support follows up by hand (screenshot posted in Asana) and closes the card.
Oct 5 - Oct 9	Long-term nurture	Close CRM	Lead moved to 'Monthly follow up'. An SMS signed by the inspector and an email 'A Special Gift to Thank You for Your Trust!'.

What the inspector found

- Bathroom: mold on the ceiling corner above the shower and along the tub caulking (from the photos and the video call).
- Bathroom fan is used regularly.

Recommendations in the report

- Remove the silicone sealant; treat tiles, grout and the drywall ceiling
- Keep humidity at 30-50%; make sure the fan is adequate and clean; consider a dehumidifier

Estimate MO971

Amount	$1,495 + 13% HST = $1,689.35
Project time	4 hours
Status	Viewed, not accepted. Lead moved to 'Monthly follow up'.

- Containment of the bathroom, negative pressure if possible
- Remove silicone sealant; treat tiles, grout, drywall ceiling
- HEPA vacuum + fogging; swab test; Project Clearance Report

Files in this folder

File	What it is
Zendesk_ticket_52925_redacted.pdf	The full email conversation: website form + AI agent booking
Client_photos_from_Zendesk/ (2 JPG)	The 2 photos the client uploaded with the form
Videos/VA_call_recording_8min.mp4	Full recording of the video call
Estimate_MO971.pdf	The estimate, rebuilt from FreshBooks data
Raw_notes_from_Telegram.txt	What the inspector posted after the call
Job_Story.pdf / job_timeline.json	This story, and the same data for code