Job 7 - On-site Inspection, estimate not accepted

House, Kanata ON. Inspection -> report + estimate -> follow-ups, no reply

Property	25 Bannock Crescent, Kanata, ON (house)
Client	Homeowner
Service	Visual & Diagnostic Mold Inspection (on site)
Paid	$195 + HST = $220.35 (paid)
Booked by	Danica - client support
Inspected on site by	Danica Radovic, CMI (as listed in the report)
Estimate prepared by	Luka Markovic, inspector (as listed in FreshBooks, Asana and Close)
Report written / reviewed by	Goran (admin support) / Stefan (admin support)
Follow-up	Automated SMS from Close, then Emanuel and Natasa (client support)

Why the client called

Client was worried about the basement. They saw something that looked like efflorescence and had done an ERMI test at home (score 13.2). They wanted to know how big the problem was and where it came from. Office note: 'Please do a full diagnostic inspection'.

Step by step

When (Eastern)	Step	System	What happened
Oct 1, 2026	Booking	Google Calendar (MB - Ottawa-Gatineau)	Client support (Danica) books the inspection. The calendar entry holds the client concern, price and a note for the inspector (entry created Oct 1; its note says booked Sept 5).
Tue Oct 6, 2026 11:30	Inspection	On site	Inspector visits: thermal camera, moisture meter, hygrometer, swab tests, attic and exterior check. 21 photos taken.
Wed Oct 7	Invoice	FreshBooks	Inspection invoice MU947 created: $195 + HST = $220.35. Paid.
Wed Oct 7	Estimate	FreshBooks	Remediation estimate MP291 created: $3,700 + HST.
Wed Oct 7 12:42-14:04	Report	Brain (our internal CRM) + Asana	Admin writes the report from the inspector's notes and photos; second admin reviews it. Tracked as a 'Deliverables to complete' subtask in Asana.
Wed Oct 7 14:06	Project card	Asana	Job card created automatically in 'MB Solutions: October 2026' with links to Close, FreshBooks client, invoice, estimate and report. Staff move it: Share Deliverables -> Collect Payment.
Thu Oct 8 09:05	Report sent	Email (support mailbox)	Client gets an email with a link to the report. Asana card moves to 'Follow Up'.
Fri Oct 9	Sales follow-up starts	Close CRM	Lead + opportunity ($3,700, 50%) in Close. First automated SMS: 'I sent you the estimate... text me if anything doesn't make sense.'
Mon Oct 12	Follow-up #2	Close CRM (SMS)	Automated SMS offers 10% off the remediation.
Wed Oct 14	Follow-up #3	Close CRM (SMS)	'Checking in one last time' - also offers a post-remediation clearance report.
Mon Oct 19	Follow-up #4	Close CRM (SMS)	'Still interested, or should we close your case?'
Thu Oct 22 16:02-16:33	Manual follow-up	Asana + Dialpad (SMS)	Close sequence ends, task 'assign to CSP'. Support agent sends a personal SMS from Dialpad and posts a screenshot in Asana. Card closed.
Today	Status	Close / FreshBooks	No reply from client found. Estimate viewed, not accepted. Lead still 'Potential'.

What the inspector found

- Basement: small discoloration under the sink, swab test positive for mold. No odor, no thermal anomalies, humidity and moisture normal.
- Rest of the house checked for free: thermal anomalies on the top floor, in the living room below the roof and on the laundry room ceiling.
- Both upstairs washrooms: discoloration on grout and silicone, standing water in the en-suite, failed ball-slope test in the shower, leaking tub faucet with high moisture below.
- Attic: insulation uneven and heavily disturbed, visible discoloration.
- Outside: poor drainage and a low spot (depression) by the main entrance.

Recommendations in the report

- Professional mold remediation
- Insulation company for the attic
- Roofer to check the roof above the living room

Estimate MP291

Amount	$3,700 + 13% HST = $4,181
Project time	1 day
Status	Viewed by client, not accepted yet

- Areas: two washrooms and the attic
- Containment: plastic barriers + zipper doors, negative air when possible
- Treatment: HEPA vacuum + manual cleaning, then 2 steps - stain removal, then eco fungicide (drywall ceilings, grout, tiles, attic trusses and sheathing)
- Disinfection: HEPA vacuum + fogging of the contained area
- Clearance: visual check + 3 instant swabs by the supervisor, written clearance certificate
- Terms: 40% deposit to book, estimate valid 60 days, reconstruction not included

Files in this folder

File	What it is
Report_Indoor_Environmental_Assessment_redacted.pdf	Report the client received (21 pages)
Estimate_MP291.pdf	The estimate, rebuilt from FreshBooks data
Photos/ (21 JPG)	All photos from the report, named by caption
Job_Story.pdf / job_timeline.json	This story, and the same data for code