SCANNED MAINTENANCE WORK ORDER

Work Order WO-2026-5531

Asset CH-440 Centrifugal Chiller

Location Synthetic Plant Room B

Reported issue Intermittent vibration above normal operating threshold

Inspection readings Inlet pressure 2.8 bar; outlet pressure 6.3 bar; bearing temperature 71 C

Work performed Alignment checked; coupling tightened; vibration sensor recalibrated

Technician Synthetic Technician 14

Completion status Closed after verification

This page is intentionally rasterized and slightly degraded for OCR testing.