

## FITNESS CERTIFICATE FOR SCHOOL BUILDING

1 Name of the Officer	THIMMA KUDIYA O			
2 Name of the School	Sadguru Shri Nithyananda Vidya Peeta			
3 Location with Name of Education Dist/ Sub Dist	Kodevoor, Manjeswaram, Kasargod			
Classification of building as specified in column 4 4 of the application for Fitness Certificate	<u>Permanent</u>			
6 30.38 x 2.00 x 3.60	1 No Verandah	1 6.00 x 8.00 x 3.60	4 Nos class rooms	
7 6.00 x 8.00 x 3.60	5 Nos class rooms	2 6.00 x 8.00 x 3.60	1 No Office	
8 4.05 x 11.04 x 3.60	1 No Library	3 30.38 x 2.00 x 3.60	1 No Verandah	
9 30.38 x 2.00 x 3.60	1 No Verandah	4 6.00 x 8.00 x 3.60	5 Nos class rooms	
10 40.60 x 10.00 x 3.60	1 No.	5 4.05 x 11.04 x 3.60	1 No Staff Room	
5 Period for which the certificate is issued	2022 -2023			
6 Nature of defect	N.A			
7 a) Foundation and basement b) Super Structure c) Doors and Windows d) Wood work wrought and put up e) Roof f) Flooring	RCC Framed & Laterite RCC Framed & Laterite Country Wood Country Wood RCC Cement Flooring			
8 Any major defects modified which will render the building unsafe in any manner	No Defects			
9 Whether maintenance works have been done properly	Yes			
10 Whether Structure is sound or not for Conducting class	The above mentioned buildings are Found SAFE for conducting classes in Normal wind and weather conditions			

Certified that the school building was inspected by me on 12/07/2023 and  
the above mentioned buildings only are found to be FIT to conduct class under Normal Weather  
condition

Place : Mangalpady G.P.

Date : 12/07/2023

Assistant Engineer 12/07/2023

**ASSISTANT ENGINEER**  
LSGD SECTION  
MANGALPADY

