TANZANIA MINISTRY OF WATER & TAARIFA PLATFORM

REF: TZ-WP-103642

OFFICIAL WATERPOINT INSPECTION & OPERATIONAL TRIAGE REPORT

Date: 2026-10-13 15:34:04

PREDICTED 3-CLASS FUNCTIONALITY STATUS

FUNCTIONAL

Model Confidence: 82.6%

PROBABILITY DISTRIBUTION

Functional:	**82.6%**
Functional Needs R:	**5.2%**
Non Functional:	**12.2%**

2x2 OPERATIONAL TRIAGE: ROUTINE MONITORING — No immediate dispatch required (Risk: 17.4%)

WATERPOINT FIELD SPECIFICATIONS & ATTRIBUTES (18 PARAMETERS)

Water & Geography	Value	Hardware & Governance	Value
Water Quantity	enough	**Extraction Hardware**	gravity
Water Quality	good	**Waterpoint Type**	communal standpipe
Source Class	groundwater	**Infrastructure Age**	5 years
Total Static Head (TSH)	500	**Payment Revenue Model**	annually
Administrative Region	Iringa	**Management Entity**	user-group
Water Basin	Lake Nyasa	**Scheme Management**	VWC
GPS Elevation (Height)	1,450 m	**Funder Organization**	Danida
Population Served	250 people	**Installer Entity**	DANIDA
Public Meeting Recorded	True	**Water Permit Issued**	True

PIPELINE RISK DRIVERS & DIAGNOSTICS

- [OK] Sufficient Water Supply
- [OK] Modern Installation
- [OK] Active Revenue Model

REAL-TIME FEATUREENGINEER OUTPUT VECTOR

age (imputed)	log_pop	log_tsh	age_missing	gps_zero	pop_zero	tsh_pos	same_funder
5.0	5.53	6.22	0	0	0	1	1

FIELD INSPECTOR DISPATCH AUTHORIZATION & SIGN-OFF

Inspector Name: _____ Signature: _____ Dispatch Date: _____

Action Status: [ ] Routine Inspection Completed [ ] Maintenance Ticket Issued [ ] Equipment Replaced