Home Entry Prints Edit Data Entry Reports Logout

Indent Report

Indent No: KPY01074

Vehicle Reg No :LABOURWORK Make : Model :

Driver/Operator/Vehicle KP02638
Inspector Report No:

Indent₀₁₋₀₄₋₂₀₂₂

_	Inspector Report No.			<u>c. </u>		
	S.No.	Vehicle.No.	Description of Item	Unit(LS).	Approxmate Value	Amount
	1	AP 11 X 6589	REAR TWO SPRING OPENING AND OLD AND NEW LEAF MOPING WORK AND OLD BED REMOVING AND NEW SETTING AND FITTING WORK MOPING LEAF SETTING AND FITTING WORK	1	4500	4500
					Total	4500

certified that the above spares truly required for the repair of the vehicles

A.E/A.E.E

Dy.E.E

EXECUTIVE ENGINEER S.W.M and Transport Chief Transport Officer GHMC.

Obtain Quotation and Prepare comparative Statement of rates for placing above Purchase order /work order

Site Best viewed in 1024*768 / IE7 (Designed, Developed & Maintained by IT Department.)