

# SAKTHI AUTO COMPONENT - QC REPORT

Component: new set

Batch #: B789-Cd123

Operator: SIVANANDH C C

Date: 2025-09-18 20:10:47

Parameter	Value	Status
Temperature	95	GOOD
Pressure	7	GOOD

OVERALL STATUS: PASS

AI Process Advisor Suggestion:

AI Error: Provider returned error