

Subject and assignment summary

Subject Identifier:	SYNTHETIC-INCOMPLETE-003
Synthetic Location:	303 Demonstration Way, Example, WA
Property Type:	Detached one-unit residence
Above-grade GLA:	1,760 sq ft
Condition:	C4
Quality:	Q3
Defect:	water staining at rear bedroom ceiling

Scenario narrative

Rendered report and exhibits are present, but the structured XML export is missing.
The rendered report describes the subject as C4.
All names, locations, facts, and exhibits in this file are synthetic.
No borrower, lender, client, appraiser, signature, or credential is represented.

Sales comparison overview

Item	Subject	Comparable 1	Comparable 2	Comparable 3
Identifier	SYNTHETIC-INCOMPLETE-003	SYN-COMP-01	SYN-COMP-02	SYN-COMP-03
Sale status	Subject	Closed	Closed	Closed
Condition	C4	C3	C3	C4
Quality	Q3	Q3	Q3	Q3
GLA	1,760	2,080	2,225	1,990

Comparable commentary

- Comparable 1: similar utility; verify all reported differences in the workfile.
- Comparable 2: similar market area; commentary is synthetic and requires review.
- Comparable 3: condition differs; no adjustment conclusion is represented here.

Condition and quality addendum

Rendered condition commentary: C4.

Rendered quality commentary: Q3.

Observed scenario item: water staining at rear bedroom ceiling. Review the related exhibit.

Scenario identifier: SYNTHETIC-INCOMPLETE-003.

The appraiser must reconcile all source evidence and make every final decision.

This synthetic report does not determine value, recommend an adjustment, declare USPAP compliance, or guarantee lender or GSE acceptance.

Professional boundary

Appraiser judgment is required for every finding and report decision.

This package is a controlled demonstration fixture, not assignment evidence.