

Subject and assignment summary

Subject Identifier:	SYNTHETIC-REVIEW-002
Synthetic Location:	202 Demonstration Way, Example, WA
Property Type:	Detached one-unit residence
Above-grade GLA:	2,180 sq ft
Condition:	C3
Quality:	See narrative commentary
Defect:	active roof leakage

Scenario narrative

Complete package containing intentional cross-source and commentary conflicts.
The rendered report describes the subject as C3.
All names, locations, facts, and exhibits in this file are synthetic.
No borrower, lender, client, appraiser, signature, or credential is represented.

Sales comparison overview

Item	Subject	Comparable 1	Comparable 2	Comparable 3
Identifier	SYNTHETIC-REVIEW-002	SYN-COMP-01	SYN-COMP-02	SYN-COMP-03
Sale status	Subject	Closed	Closed	Closed
Condition	C3	C3	C3	C4
Quality	See narrative	Q3	Q3	Q3
GLA	2,180	2,080	2,225	1,990

Comparable commentary

Comparable 1: similar utility; verify all reported differences in the workfile.

No individual commentary was supplied for the remaining comparable(s).

Condition and quality addendum

Rendered condition commentary: C3.

Scenario identifier: SYNTHETIC-REVIEW-002.

Observed scenario item: active roof leakage. Review the related exhibit.

The appraiser must reconcile all source evidence and make every final decision.

This synthetic report does not determine value, recommend an adjustment, declare USPAP compliance, or guarantee lender or GSE acceptance.

Professional boundary

Appraiser judgment is required for every finding and report decision.

This package is a controlled demonstration fixture, not assignment evidence.