

Subject and assignment summary

Subject Identifier:	SYNTHETIC-SUBJECT-001
Synthetic Location:	Subject A, Fictional County, WA
Property Type:	Detached one-unit residence
Above-grade GLA:	2,140 sq ft
Condition:	C4
Quality:	Q3
Defect:	Incomplete cladding at the rear enclosure is disclosed for review; no cause, repair s

Scenario narrative

The same-subject package is complete and its report narrative accounts for the visible exhibits.

The rendered report describes the subject as C4.

All assignment data, identities, locations, and conclusions in this report are synthetic.

Sanitized owner-supplied photographs are used only as controlled visual evidence.

No borrower, lender, client, appraiser, signature, or credential is represented.

Sales comparison overview

Item	Subject	Comp 1	Comp 2	Comp 3
Identifier	SYNTHETIC-SUBJECT-001	SYN-COMP-01	SYN-COMP-02	SYN-COMP-03
Sale status	Subject	Closed	Closed	Closed
Condition	C4	C3	C3	C3
Quality	Q3	Q3	Q3	Q3
GLA	2,140	2,080	2,225	1,990

Comparable commentary

- Comparable 1: condition differs from the subject; similar utility.
- Comparable 2: condition differs from the subject; similar market area.
- Comparable 3: condition differs from the subject; no adjustment conclusion is represented.

Condition and quality addendum

Rendered condition commentary: C4.

Rendered quality commentary: Q3.

Observed scenario item: Incomplete cladding at the rear enclosure is disclosed for review; no cause, repair scope, cost, or value effect is represented.. Review the related exhibit.

Rear photographs show a covered deck and an attached storage enclosure.

The storage enclosure is excluded from above-grade GLA.

Incomplete exterior cladding at the enclosure is disclosed for appraiser review.

No cause, repair scope, cost, or value effect is represented.

The appraiser must reconcile all source evidence and make every final decision.

This synthetic report does not determine value, recommend an adjustment, declare USPAP compliance, or guarantee lender or GSE acceptance.

Photo register

rear_exterior_condition.jpg - Rear exterior and storage enclosure

rear_deck_exterior.jpg - Rear exterior and covered deck

covered_deck_exterior.jpg - Covered deck detail

kitchen_interior.jpg - Kitchen interior

bathroom_interior.jpg - Bathroom interior

Professional boundary

Appraiser judgment is required for every finding and report decision.

This controlled package is not assignment evidence.