Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX328
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668732
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907PCS
		Date of Manufacture:	1/18/2026~1/21/2026	Lot ID:	9928-539898(1st lot)
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Sign-off sample:	Yes	Approved drawings	Yes	**(Drawing#:**	K1VRJNVG	**REV:**	C **)**
Ship mark	Yes	Approved ranges	Yes			Ship to	TBA

Inspection Result **Accept** **Re-inspection:** **No**

(Comment: **)**

Inspection Result Summary

Check points	Sample size	Comment	Remark
Dimension	20	Conformed	
Aesthetics	500	Conformed	
Color	500	Conformed	
Material		N/A	
Decoration	500	Conformed	
Packaging		N/A	
Labeling		N/A	
Assortment		N/A	
Ship mark	1	Conformed	
Workmanship	500	Conformed	
Function	20	Conformed	

Aesthetic Inspection

Inspection method:	ANSI/ASQ Z1.4	Sampling plan:	Single sampling normal inspection			Sampling level:	Level 2
Acceptable Quality Level (AQL):	Critical A:	0	Critical B:	0.65	Major:	1.5	Minor: 4.0
Sample size:	500		No. of carton drawn:	10			
Opened carton No.:	No carton#						

No.	Defects description	Cri. A	Cri. B	Major	Minor
1	K. Seal gap			1	1
2	J. Thread irregularity				3
3					
4					
5					
6					
7					
	Total Defectives			1	4
	Maximum Defectives	0	7	14	21

Inspection qty: >80%

Item#	XXX PO No.	Batch qty.	Inspection quantity		No. of carton	
			Packed	Unpacked	Packed	Unpacked
XX-ABC-57052-C	71662963	61,859	41,466	8,462	61	16
		Total:	41,466	8,462	61	16

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX328
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668732
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907PCS
		Date of Manufacture:	1/18/2026~1/21/2026	Lot ID:	9928-539898(1st lot)
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Carton Check

Check point		Inner carton					Outer carton				
Quantity per carton:	Part C & Insert						619				
Dimension of carton (cm):	L x W X H		x		x		47	x	32	x	43
Weight of carton (Kg):	Gross/Net			/			15.3		/		14
Scan the barcode number:	(Result: N/A)										

Dimension and Function check - Sampling level: S-2

Sample size: 13+7

Dimension chart

Measure / Standard	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
Part A Length 35.38±0.16(mm)	26.66	25.73	25.55	25.29	26.17	26.19	26.71	26.5	26.51	25.78	25.85	26.53	25	25.78	25.59	25.52	26.62	27	25.28	26.25
Part A Width 47.37±0.31(in)	25.66	25.13	25.61	25.23	26.19	26.04	25.13	25.38	25.9	25.05	26.06	25.84	25.41	25.04	26.4	25.75	26.06	25.29	25.74	26.23
Part B Thick 31.75±0.33(cm)	12.93	12.6	12.63	13.07	12.82	12.94	12.74	12.89	12.76	13.27	12.65	12.84	13.02	13.22	12.62	12.6	12.97	12.9	12.82	12.99
Part B Diam 34.58±0.3(cm)	11.08	10.93	11.18	11.46	11.23	10.84	11.34	11.26	11.29	10.99	11.03	10.9	10.76	11.25	11.24	11.41	11.28	11.13	10.84	11.21
Part C OD 47.06±0.14(in)	21.49	21.04	20.84	20.86	20	21.08	21.4	21.08	20.41	20.89	20.43	21.64	21.52	21.44	20.8	20.45	21.49	21.62	20.53	21.01
Part C ID 19.14±0.17(mm)	126.15	131.51	131.49	126.58	129.29	129.91	127.64	132.23	128.91	127.19	129.78	131.35	127.22	128.01	133.22	130.59	129.02	129.68	126.57	127.38
Part D Height 35.23±0.18(cm)	checked	by	ø4.56	and	ø4.64	pin	gauges	,	all	within	spec.									

Part D Width

46.81±0.47(mm) / Standard	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
Part E Length 25.62±0.5(mm)	4.46	5.63	5.8	3.54	4.68	5.95	5	4.53	4.71	6	4.8	4.97	4.43	5	5.15	4.72	4.99	5.9	5.12	5.19
Part E Diam 8.3±0.15(cm)	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5
Part F OD 10.96±0.21(mm)	5.42	5.19	5.64	4.37	5.54	5.09	5.44	5.88	5.62	5.16	5.4	5.61	5.87	5.71	5.12	5.32	4.46	4.18	5.42	5.07
Part F Thick 44.57±0.22(mm)	4.56	4.03	4.55	4.26	4.66	4.02	4.43	4.66	3.68	4.13	4.43	5.41	3.74	3.87	4.11	3.84	3.88	2.87	4.65	3.82
Part G Width 24.72±0.29(cm)	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5
Part G Height 32.53±0.49(in)	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
Part H Length 28.8±0.35(in)	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
Part H OD 18.47±0.35(mm)	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5
Tape test&Cross hatch 16.9±0.45(in)	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
OFC 29.9±0.17(in)	13.64	14.08	14.11	13.75	13.88	13.32	13.63	14.19	13.87	13.73	13.9	13.43	13.77	13.7	13.99	13.32	14.08	13.35	13.44	13.78

Date: 3/6/2026

Authorized QC Inspector of XXX

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5
Item#:	XX-ABC-68878-C				
Description:	Standard Component Assembly with Seal Insert				

Photos