Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX328
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668732
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907PCS
		Date of Manufacture:	1/18/2026~1/21/2026	Lot ID:	9928-539898(1st lot)

Item#: XX-ABC-68878-C

Description: Standard Component Assembly with Seal Insert

Sign-off sample: Yes Approved drawings Yes (Drawing#: K1VRJNVG REV: C)

Ship mark Yes Approved ranges Yes Ship to TBA

Inspection Result: Accept

Re-in No

(Comment:)

Inspection Result Summary

Check points	Sample size	Comment	Remark
Dimension	20	Conformed	
Aesthetics	500	Conformed	
Color	500	Conformed	
Material		N/A	
Decoration	500	Conformed	
Packaging		N/A	
Labeling		N/A	
Assortment		N/A	
Ship mark	1	Conformed	
Workmanship	500	Conformed	
Function	20	Conformed	

Aesthetic Inspection

Inspection method: ANSI/ASQ Z1.4 Sampling plan: Single sampling normal inspection Sampling level: Level 2

Acceptable Quality Level (AQL): Critical A: 0 Critical B: 0.65 Major: 1.5 Minor: 4.0

Sample size: 500 No. of carton drawn: 10

Opened carton No.: No carton#

No.	Defects description	Cri. A	Cri. B	Major	Minor
1	K. Seal gap			1	1
2	J. Thread irregularity				3
3					
4					
5					
6					
7					
	Total Defectives			1	4
	Maximum Defectives	0	7	14	21

Inspection qty: >80%

Item#	XXX PO No.	Batch qty.	Inspection quantity		No. of carton	
			Packed	Unpacked	Packed	Unpacked
XX-ABC-57052-C	71662963	61,859	41,466	8,462	61	16
		Total:	41,466	8,462	61	16

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX328
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668732
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907PCS
		Date of Manufacture:	1/18/2026~1/21/2026	Lot ID:	9928-539898(1st lot)

Item#: XX-ABC-68878-C

Description: Standard Component Assembly with Seal Insert

Carton Check

Check point		Inner carton										Outer carton				
Quantity per carton:	Part C & Insert											619				
Dimension of carton (cm):	L x W X H		x		x							47	x	32	x	43
Weight of carton (Kg):	Gross/Net			/								15.3		/		14
Scan the barcode number:	(Resul N/A)															

Dimension and Function check - Sampling level: S-2

Sample size: 13+7

Dimension chart

Measure	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
Standard																				
Part A Length	26.66	25.73	25.55	25.29	26.17	26.19	26.71	26.5	26.51	25.78	25.85	26.53	25	25.78	25.59	25.52	26.62	27	25.28	26.25
35.38±0.16(mm)																				
Part A Width	25.66	25.13	25.61	25.23	26.19	26.04	25.13	25.38	25.9	25.05	26.06	25.84	25.41	25.04	26.4	25.75	26.06	25.29	25.74	26.23
47.37±0.31(in)																				
Part B Thick	12.93	12.6	12.63	13.07	12.82	12.94	12.74	12.89	12.76	13.27	12.65	12.84	13.02	13.22	12.62	12.6	12.97	12.9	12.82	12.99
31.75±0.33(cm)																				
Part B Diam	11.08	10.93	11.18	11.46	11.23	10.84	11.34	11.26	11.29	10.99	11.03	10.9	10.76	11.25	11.24	11.41	11.28	11.13	10.84	11.21
34.58±0.3(cm)																				
Part C OD	21.49	21.04	20.84	20.86	20	21.08	21.4	21.08	20.41	20.89	20.43	21.64	21.52	21.44	20.8	20.45	21.49	21.62	20.53	21.01
47.06±0.14(in)																				
Part C ID	126.15	131.5	131.5	126.6	129.3	129.91	127.6	132.2	128.9	127.2	129.8	131.3	127.2	128.0	133.2	130.6	129.0	129.7	126.6	127.4
19.14±0.17(mm)																				
Part D Height	checked	by	ø4.56	and	ø4.64	pin	gauge	,	all	within	spec.									
35.23±0.18(cm)																				

Part D Width

46.81±0.47(mm)	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20
Standard																				
Part E Length	4.46	5.63	5.8	3.54	4.68	5.95	5	4.53	4.71	6	4.8	4.97	4.43	5	5.15	4.72	4.99	5.9	5.12	5.19
25.62±0.5(mm)																				
Part E Diam	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5
8.3±0.15(cm)																				
Part F OD	5.42	5.19	5.64	4.37	5.54	5.09	5.44	5.88	5.62	5.16	5.4	5.61	5.87	5.71	5.12	5.32	4.46	4.18	5.42	5.07
10.96±0.21(mm)																				
Part F Thick	4.56	4.03	4.55	4.26	4.66	4.02	4.43	4.66	3.68	4.13	4.43	5.41	3.74	3.87	4.11	3.84	3.88	2.87	4.65	3.82
44.57±0.22(mm)																				
Part G Width	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5	>7.5
24.72±0.29(cm)																				
Part G Height	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
32.53±0.49(in)																				
Part H Length	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
28.8±0.35(in)																				
Part H OD	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5	>5
18.47±0.35(mm)																				
Tape test&Cross hatch	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK	OK
16.9±0.45(in)																				
OFC	13.64	14.08	14.11	13.75	13.88	13.32	13.63	14.19	13.87	13.73	13.9	13.43	13.77	13.7	13.99	13.32	14.08	13.35	13.44	13.78
29.9±0.17(in)																				

Date: 03/06/2026

Authorized QC Inspector of XXX

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5

Item#:	XX-ABC-68878-C
Description:	Standard Component Assembly with Seal Insert

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5

Item#:	XX-ABC-68878-C
Description:	Standard Component Assembly with Seal Insert

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5

Item#:	XX-ABC-68878-C
Description:	Standard Component Assembly with Seal Insert

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5

Item#:	XX-ABC-68878-C
Description:	Standard Component Assembly with Seal Insert

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5

Item#:	XX-ABC-68878-C
Description:	Standard Component Assembly with Seal Insert

Photos

Final Inspection Report

Client:	Global Tech	Supplier:	Alpha Labs	Client PO#:	PO-XX
XXX office:	TX	Inspector:	Sam Davis	XXX PO#:	21668
PM:	Avery Wilson	Inspection Site:	Greenfield county, Metro city	PO Quantity:	N/A
Project#:	XXBFNO6	Inspection date:	24-Jan-2026	Batch Quantity:	88907
				Lot ID:	9928-5

Item#:	XX-ABC-68878-C
Description:	Standard Component Assembly with Seal Insert

Photos