

STATE OF TEXAS WELL REPORT for Tracking #204102

Owner:	Alonzo M Peeler Jr	Owner Well #:	61
Address:	100 La Parita Road Jourdanton, TX 78026	Grid #:	78-21-2
Well Location:	Fm 3387 Christine, TX 78012	Latitude:	28° 44' 09" N
Well County:	Atascosa	Longitude:	098° 27' 16" W
		Elevation:	264 ft. above sea level
Type of Work:	New Well	Proposed Use:	Rig Supply

Drilling Start Date: **12/12/2009** Drilling End Date: **12/19/2009**

Borehole:	Diameter (in.)	Top Depth (ft.)	Bottom Depth (ft.)
	17.5	0	625
	9.875	625	3520

Drilling Method: **Mud (Hydraulic) Rotary**

Borehole Completion: **perforated**

Annular Seal Data:	Top Depth (ft.)	Bottom Depth (ft.)	Description (number of sacks & material)
	0	3520	266 bbl cement

Seal Method: **pressure pump**

Distance to Property Line (ft.): **2200**

Sealed By: **BJ Hughes/ Evans Drilling**

Distance to Septic Field or other
concentrated contamination (ft.): **none**

Distance to Septic Tank (ft.): **No Data**

Method of Verification: **Tape Measure**

Surface Completion: **Surface Slab Installed**

Water Level: **43 ft. below land surface, and 0 GPM** Measurement Method: **Unknown**
artesian flow on **2009-12-20**

Packers: **none**

Type of Pump: **No Data** Pump Depth (ft.): **0**

Well Tests: **Jetted** Yield: **450 GPM with 200 ft. drawdown after 2 hours**

Plug Information:	Description (number of sacks & material)	Top Depth (ft.)	Bottom Depth (ft.)
	n/a		

Water Quality:

<i>Strata Depth (ft.)</i>	<i>Water Type</i>
2954	good

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which
contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Evans Drilling**
po.box 924
belmont, TX 78604

Driller Name: **1967**

License Number: **54486**

Apprentice Name: **58313**

Apprentice Number: **58313**

Comments: **good well**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Casing:
BLANK PIPE & WELL SCREEN DATA

<i>Top (ft.)</i>	<i>Bottom (ft.)</i>	<i>Description</i>
0	3	black topsoil
3	61	tan clay
61	142	gray clay
142	157	sand
157	2954	gray clay with little sand
2954	2974	sand
2974	3090	gray clay
3090	3170	sand
3170	3520	gray clay

<i>Dia. (in.)</i>	<i>New/Used</i>	<i>Type</i>	<i>Setting From/To (ft.)</i>
13 3/8	new	steel j 50	0-625
7	new	steel j50	625-3520
		shot from	2954-2974 .45
		shot from	3090-3170 .45

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

**Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540**