# WAREHOUSE SAFETY INSPECTION

## Site: Rivergate Distribution Centre

Inspection Date: 14 October 2026

The morning inspection began at 08:20. A damaged safety barrier was found near Loading Bay 3.
The barrier was marked for immediate replacement and the affected lane was temporarily closed.

Two emergency exit signs in the western aisle were partially blocked by stored cartons.
The cartons were moved and the exits were cleared before 09:10.

A small oil leak was observed beside Forklift FL-17. The forklift was removed from service
and the maintenance team was notified.

Fire extinguishers in Zones A, B and C were checked. All units were accessible and within
their inspection dates.

No employee injuries were reported. Normal loading activity resumed at 10:05.

Follow-up actions:
1. Replace the damaged barrier at Loading Bay 3.
2. Inspect Forklift FL-17 before returning it to service.
3. Recheck the western aisle during the next weekly inspection.