Numbered index of photographs recorded for this inspection. Photographs document conditions at the time they were taken; they do not by themselves establish cause, coverage, or repair necessity. Originals are preserved unchanged; annotated copies are identified.

#	Area	Shot	Component	Caption	Version	Captured
1	Main dwelling > Front elevation	Overview	Elevation	Front elevation overview with address marker	Original	10/2/2026, 2:05:00 PM
2	Main dwelling > Left elevation	Overview	Elevation	Left elevation overview	Original	10/2/2026, 2:06:30 PM
3	Main dwelling > Rear elevation	Overview	Elevation	Rear elevation overview	Original	10/2/2026, 2:08:00 PM
4	Main dwelling > Rear elevation	Close-up	Gutter	Rear gutter - dents along front face	Original	10/2/2026, 2:09:30 PM
5	Main dwelling > Right elevation	Close-up	Window / screen	Right elevation window screen	Original	10/2/2026, 2:11:00 PM
6	Main dwelling > Roof	Overview	Roof covering	Roof overview from front	Original	10/2/2026, 2:12:30 PM
7	Main dwelling > Front slope	Context	Roof covering	Front slope test square (10 ft × 10 ft) marked in chalk	Original	10/2/2026, 2:14:00 PM
8	Main dwelling > Front slope	Close-up	Roof covering	Front slope - circular mark on shingle, chalk circled	Original	10/2/2026, 2:15:30 PM
9	Main dwelling > Kitchen (Level 1)	Overview	Room	Kitchen overview	Original	10/2/2026, 2:17:00 PM
10	Unassigned	Other		(no caption)	Original	10/2/2026, 2:18:30 PM

Photographs




Photo 1 - Main dwelling > Front elevation
Front elevation overview with address marker

Overview - Elevation - 10/2/2026, 2:05:00 PM




Photo 2 - Main dwelling > Left elevation
Left elevation overview

Overview - Elevation - 10/2/2026, 2:06:30 PM




Photo 3 - Main dwelling > Rear elevation
Rear elevation overview

Overview - Elevation - 10/2/2026, 2:08:00 PM




Photo 4 - Main dwelling > Rear elevation
Rear gutter - dents along front face

Close-up - Gutter - 10/2/2026, 2:09:30 PM




Photo 5 - Main dwelling > Right elevation
Right elevation window screen

Close-up - Window / screen - 10/2/2026, 2:11:00 PM




Photo 6 - Main dwelling > Roof
Roof overview from front

Overview - Roof covering - 10/2/2026, 2:12:30 PM




Photo 7 - Main dwelling > Front slope
Front slope test square (10 ft × 10 ft) marked in chalk

Context - Roof covering - 10/2/2026, 2:14:00 PM




Photo 8 - Main dwelling > Front slope
Front slope - circular mark on shingle, chalk circled

Close-up - Roof covering - 10/2/2026, 2:15:30 PM




Photo 9 - Main dwelling > Kitchen (Level 1)
Kitchen overview

Overview - Room - 10/2/2026, 2:17:00 PM




Photo 10 - Unassigned
(no caption)

Other - 10/2/2026, 2:18:30 PM