

Inspection Report

Truck Serial Number: 7301234

Truck Model: 730

Inspection ID: 001

Inspector Name: John Doe

Inspection Employee ID: EMP123

Date & Time: 2024-08-09 10:00:00

Location: Warehouse A

Geo Coordinates: 12.3456, 78.9012

Service Meter Hours: 12345

Inspector Signature: John Doe Signature

Customer Name: ABC Corp

CAT Customer ID: CAT456

TIRES

Tire Pressure for Left Front: 32 PSI

Tire Pressure for Right Front: 32 PSI

Tire Condition for Left Front: Good

Tire Condition for Right Front: Ok

Tire Pressure for Left Rear: 30 PSI

Tire Pressure for Right Rear: 30 PSI

Tire Condition for Left Rear: Needs Replacement

Tire Condition for Right Rear: Good

Overall Tire Summary: All tires are in good condition except for the left rear tire which needs replacement.

BATTERY

Battery Make: CAT

Battery Replacement Date: 2023-06-15

Battery Voltage: 12V

Battery Water Level: Good

Condition of Battery: No damage

Any Leak/Rust: No

Overall Battery Summary: Battery is in good condition.

EXTERIOR

Rust, Dent, or Damage to Exterior: No

Oil Leak in Suspension: No

Overall Summary: Exterior is in good condition.

BRAKES

Brake Fluid Level: Good

Brake Condition for Front: Good

Brake Condition for Rear: Ok

Emergency Brake: Good

Overall Brake Summary: Brakes are functioning well.

ENGINE

Rust, Dents, or Damage in Engine: No

Engine Oil Condition: Good

Engine Oil Color: Clean

Brake Fluid Condition: Good

Brake Fluid Color: Clean

Any Oil Leak in Engine: No

Overall Summary: Engine is in good condition.

Voice of Customer

Customer Feedback: Customer is satisfied with the inspection.
