

Inspection Report

Date: 27. 05. 2026

Robot: BigChungus

Report: report01

Task: Ring Counting

Requested by: Elena

Results:

- Total number of rings detected: 4
- Detected colors:
 - red: 2
 - green: 1
 - blue: 1

Task: Barrel Inspection

Requested by: Anita


Results:

- Total number of barrels inspected: 9

Barrel ID	Colour	Orientation	Leak detected
1	green	vertical	No
2	blue	horizontal	Yes
3	black	vertical	No
4	green	vertical	No
5	red	vertical	No
6	black	vertical	No
7	yellow	vertical	No
8	green	vertical	No
9	red	horizontal	No

Leak Evidence:

ID: 0



Task: Anomaly Detection

Requested by: Robert

Station: Red


Results:

- Total number of tiles inspected: 4
- OK: 1
- DEFECT: 3


Tile ID	Status
1	DEFECT
2	DEFECT
3	OK
4	DEFECT

Anomaly Inspection Visuals:

ID: 1



ID: 2



ID: 4

