

Inspection Report

Date: 26. 05. 2026

Robot: BigChungus

Report: report07

Task: Ring Counting

Requested by: Bobert

Results:

- Total number of rings detected: 6
- Detected colors:
 - red: 3
 - green: 2
 - blue: 1

Task: Barrel Inspection

Requested by: Bobert


Results:

- Total number of barrels inspected: 2


Barrel ID	Colour	Orientation	Leak detected
1	red	vertical	No
2	green	horizontal	Yes

Leak Evidence:

ID: 3



ID: 2



ID: 1



ID: 0



Task: Anomaly Detection

Requested by: Bobert

Station: Green


Results:

- Total number of tiles inspected: 3
- OK: 2
- DEFECT: 1

Tile ID	Status
1	OK
2	DEFECT
3	OK

Anomaly Inspection Visuals:

ID: 2



Task: Anomaly Detection

Requested by: Bobert

Station: Red

Results:

- Total number of tiles inspected: 3
- OK: 2
- DEFECT: 1

Tile ID	Status
1	OK
2	DEFECT
3	OK

Anomaly Inspection Visuals:

ID: 2

