

In-Process QC CheckList for Onboard Kavach Installation

QC Engineer Name: surya

v1.1

Station ID	Station Name	Zone	Division	Section Name	Initial Date	Updated Date
7845	wedscx	CR	Mumbai	werfvv	2025-09-05	2025-09-05

Total Points	Closed Points	Open Points
177	66	111

Start Date & Time	Completed Date & Time	Total Time
2025-09-05 12:21:16	2025-09-05 12:43:01	0h 21m 45sec

Completion Status	☐ Completed	☒ Not Completed
-------------------	------------------------------------	---

1.0 VERIFICATION OF SERIAL NUMBERS OF EQUIPMENT AS PER IC

S.No	Description	Status	Remarks	Image
1.1	Stationary TCAS Unit	Present		
1.2	Peripheral Processing Card - 1	Matching		
1.3	Peripheral Processing Card - 2	Matching		
1.4	Vital Computer Card - 1	Matching		

S.No	Description	Status	Remarks	Image
1.5	Vital Computer Card - 2	Matching		
1.6	Vital Computer Card - 3	Matching		
1.7	Voter Card - 1	Matching		
1.8	Voter Card - 2	Matching		
1.9	Vital Gateway Card - 1	Matching		
1.10	Vital Gateway Card - 2	Matching		
1.11	Integrated Data Logger Card (IDL)	Matching		
1.12	Dual GSM Card	Matching		

S.No	Description	Status	Remarks	Image
1.13	Field Scanner Card - 1	Matching		
1.14	Field Scanner Card - 2	Matching		
1.15	Field Scanner Card - 3	Matching		
1.16	Field Scanner Card - 4	Matching		
1.17	Field Scanner Card - 5	Matching		
1.18	Field Scanner Card - 6	Matching		
1.19	Field Scanner Card - 7	Matching		
1.20	Field Scanner Card - 8	Matching		

S.No	Description	Status	Remarks	Image
1.21	SMOCIP Unit	Matching		
1.22	Station Radio Power Supply card-1	Matching		
1.23	Next Gen/. Cal Amp Radio Modem-1	Matching		
1.24	Station Radio Power Supply card-2	Matching		
1.25	Next Gen/. Cal Amp Radio Modem-2	Matching		
1.26	GPS & GSM Antenna - 1	Matching		
1.27	GPS & GSM Antenna - 2	Matching		
1.28	DPS Card - 1	Matching		

S.No	Description	Status	Remarks	Image
1.29	DPS Card - 2	Matching		
1.30	EMI Filter - 1	Matching		
1.31	EMI Filter - 2	Matching		
1.32	Media Converter - 1	Matching		
1.33	Media Converter - 2	Matching		
1.34	Media Converter - 3	Matching		
1.35	Cable Extender	Matching		
1.36	RIU-COM - 1	Matching		

S.No	Description	Status	Remarks	Image
1.37	RIU-COM - 2	Matching		
1.38	FIU Termination Card - 1	Matching		
1.39	FIU Termination Card - 2	Matching		
1.40	FIU Termination Card - 3	Matching		
1.41	FIU Termination Card - 4	Matching		
1.42	FIU Termination Card - 5	Matching		
1.43	FIU Termination Card - 6	Matching		
1.44	FIU Termination Card - 7	Matching		

S.No	Description	Status	Remarks	Image
1.45	FIU Termination Card - 8	Matching		
1.46	PDU Box	Matching		
1.47	RTU - 1	Matching		
1.48	RTU - 2	Matching		
1.49	RADIO - 1	Matching		

2.0 Tower and RTU

Start Date & Time	Completed Date & Time	Total Time
5/9/2025, 12:31:30 pm	5/9/2025, 12:31:31 pm	0h 0m 1sec

S.No	Description	Status	Remarks	Image
2.1	Visual Checks	Found Ok		
2.2	Verification of RF Antenna Fixing and LMR Cable Routing:Verification of Antenna Fixing	Fixed		
2.3	Verification of RF Antenna Fixing and LMR Cable Routing:Verify the RF Cable joining to Antenna	Joined		
2.4	Verification of RF Antenna Fixing and LMR Cable Routing:Tie the cables to die pole antenna by using stainless steel cable tie at four locations.	Cable ties implemented		
2.5	Verification of RF Antenna Fixing and LMR Cable Routing:LMR 600 cables routing by using feeder clamps.	Routing done		
2.6	Installation of RTU Box and connections with identification:Visual inspection, Identification and Radios functioning	Functioning		
2.7	Installation of RTU Box and connections with identification:LMR cable fixing	Fixed		
2.8	Installation of RTU Box and connections with identification:Verification of RTU box Fixing on platform.	Fixed		

S.No	Description	Status	Remarks	Image
2.9	Installation of RTU Box and connections with identification:Tie the cables to structure by using stainless steel cable ties.	Cable ties implemented		
2.10	Installation of RTU Box and connections with identification:Radios power supply 110V	Voltage found Ok		
2.11	Installation of RTU Box and connections with identification:Verification of RTU Earthing	Earth Connected		
2.12	Verification of Tower:Tower Foundation & Fencing	Done		
2.13	Verification of Tower:Ladder Fixing	Fixed		
2.14	Verification of Tower:GI Earthing strip routing	Routing done		
2.15	Verification of Tower and RTU Earth pit arrangement with brazing.	Done		
2.16	Earthing for Tower as per Spec. &	Ok		

S.No	Description	Status	Remarks	Image
2.17	Verification of Aviation Warning Lamp, Functioning and power supply 110V	Voltage found Ok		

3.0 Station TCAS

Start Date & Time	Completed Date & Time	Total Time
5/9/2025, 12:33:49 pm	5/9/2025, 12:33:49 pm	0h 0m 0sec

S.No	Description	Status	Remarks	Image
3.1	Visual Checks (Ex.Equipment labels, External appearance, Dents, Shade, Rust, Cable entries at STCAS to be closed properly with rubber gaskets/grommets in STCAS)	Found Ok		
3.2	Verification of equipment placement and cable routing as per Relay Room Layout.	Routing Done		
3.3	Verification of Connections as per Power Supply Diagram cum Load Calculation:Verification of Cable size and connectivity as per diagram	Found Ok		
3.4	Verification of Connections as per Power Supply Diagram cum Load Calculation:Implementation of Ferrule Lug 0.75mm	Implemented		
3.5	Verification of Connections as per Power Supply Diagram cum Load Calculation:Implementation of Lug 2.5Sqmm	Implemented		
3.6	Verification of Connections as per Power Supply Diagram cum Load Calculation:Implementation of Media Converter	Implemented		

S.No	Description	Status	Remarks	Image
3.7	Verification of Connections as per Power Supply Diagram cum Load Calculation:Verification of 48V SMPS Charger & Battery Installation	Installed		
3.8	Verification of Connections as per Power Supply Diagram cum Load Calculation:MCB 2P Installed in IPS room	Rating as per Diagram:		
3.9	TCAS system I/P110V DC supply	Voltage found Ok		
3.10	Cards Functional Checking as per ATR	Voltage found Ok		
3.11	Review of PCCL Report	PCCL Done		
3.12	Earth Resistance of STCAS is "d 1!& (to be	Found Ok		
3.13	Verification of PDU Box fixing and wiring:Identification for Fuse, MCB's etc.	Identification Done		
3.14	Verification of PDU Box fixing and wiring:Verification of cable routing	Routing Done		

S.No	Description	Status	Remarks	Image
3.15	 Verification of PDU Box fixing and wiring: Implementation of glands/ grommets.	Implemented		
3.16	 Verification of PDU Box fixing and wiring: Earthing	Connected		
3.17	 Verification of PDU Box fixing and wiring: Verification of Voltage	Found Ok		
3.18	 Verification of PDU Box fixing and wiring: Verification of Fuse Ratings as per PSD Rating Table	Found Ok		
3.19	 Verification of PDU Box fixing and wiring: 	Found Ok		
3.20	 Verification of DC-DC Converter installation: Identification	Done		
3.21	 Verification of DC-DC Converter installation: Earthing	Connected		
3.22	 Verification of DC-DC Converter installation: Implementation of glands/ grommets.	Implemented		

S.No	Description	Status	Remarks	Image
3.23	Verification of DC-DC Converter installation:Voltage Input and Output	Found Ok		
3.24	Verification of GPS / GSM Antenna Fixing & Wiring	Found Ok		

4.0 Relay installation and wiring

Start Date & Time	Completed Date & Time	Total Time
5/9/2025, 12:36:31 pm	5/9/2025, 12:36:31 pm	0h 0m 0sec

S.No	Description	Status	Remarks	Image
4.1	Visual Checks (Ferrules/ Sticking to be done for easily identification of cables).	Found Ok		
4.3	Verification of Relay rack and interfaces are connected as per relay wiring drawing.	Connected		
4.4	Verify slow blowing fuse placement and Fuse rating (2A)	Found Ok		
4.5	Verification of Relay Contact 24V supply (18VDA to 26VDA)	Found Ok		
4.6	Verification of Data Logger connectivity	Connected		

5.0 SMOCIP

Start Date & Time	Completed Date & Time	Total Time
5/9/2025, 12:37:11 pm	5/9/2025, 12:37:12 pm	0h 0m 1sec

S.No	Description	Status	Remarks	Image
5.1	Visual Checks	Found Ok		
5.2	Verification of SMOCIP Unit fixing, Connectivity & Fibre Splicing and Key on off position	Found Ok		
5.3	SMOCIP Health Status	Found Ok		
5.4	SMOCIP Earthing	Connected		
5.5	Checksum verification as per FAT Report.	Matching		

6.0 RFID tags

Start Date & Time	Completed Date & Time	Total Time
5/9/2025, 12:38:29 pm	5/9/2025, 12:38:29 pm	0h 0m 0sec

S.No	Description	Status	Remarks	Image
6.1	Visual Checks (Cracks, Shade, No oil, Center Placement, Play and Tag Number & ABS location on TAG)	Torquing done		
6.2	Verification of RFID TAG fixing Fixing proper Brackets (Point sleeper Bracket & Normal Sleeper Bracket) as per drawing no 5 16 67 0490,106, CC Apran TCAS/2021_02_15 & RDSO Drawing No. SDO/S&T/TCAS/008	Yes		
6.3	Verification of Tag Program as per RFID Tag layout	Routing Done		
6.4	Verification of RFID Tag Placement	Locked		

Note : This QC report is generated by the system and does not need a physical signature.