Employee project and field notes

FICTIONAL HIRING EXERCISE ONLY - NOT FOR PROPERTY OR SAFETY DECISIONS

Project Id: ORTAM-DEMO-001

Client: Example Property Group fictional

Building: Fictional Training Building A

Address: Training Site A - no real address

Inspection Date: 2026-10-01

Currency: CAD

Jurisdiction: Unspecified - no regulatory compliance conclusion permitted

Scope: Accessible areas only; illustration for hiring assessment

Renovation: Ground corridor floor and office ceiling replacement planned

Employee material and sample register

M01 Pipe insulation

Floor and location: Basement | B01 mechanical room

Sample IDs: S01 | Quantity: 24 linear_m

Condition: poor | Planned disturbance: No | Rate reference: R_PIPE

Visible damage recorded; quantity is an exercise input.

M02 Floor tile and adhesive

Floor and location: Ground | G01 corridor

Sample IDs: S02 | Quantity: 90 m2

Condition: intact | Planned disturbance: Yes | Rate reference: R_FLOOR

Tile and underlying adhesive are distinct lab layers.

M03 Textured ceiling

Floor and location: Ground | G02 office

Sample IDs: S03|S07 | Quantity: 140 m2

Condition: damaged | Planned disturbance: Yes | Rate reference: R_CEILING

Two samples represent one material zone; count 140 m2 only once.

M04 Wall plaster

Floor and location: Ground | G03 meeting room

Sample IDs: S04 | Quantity: 65 m2

Condition: intact | Planned disturbance: No | Rate reference: Not assigned

Result applies only to sampled material.

M05 Cement panel

Floor and location: Exterior | E01 east elevation

Sample IDs: S05 | Quantity: UNKNOWN m2

Condition: intact | Planned disturbance: No | Rate reference: R_PANEL

Quantity not measured. Do not treat blank as zero.

M06 Insulation fragment

Floor and location: Basement | B02 service room

Sample IDs: S06 | Quantity: 8 m2

Condition: unknown | Planned disturbance: No | Rate reference: Not assigned

Inconclusive laboratory result; do not classify as negative.

M07 Uninspected riser material

Floor and location: Basement | B03 locked riser

Sample IDs: None | Quantity: UNKNOWN m2

Condition: unknown | Planned disturbance: No | Rate reference: Not assigned

No access and no sample. No conclusion about asbestos presence.