Inspection and Testing Plan
for
Instrumentation and Fire Fighting System
Installation and Testing

(Doc No. CT8-ITP-EI-001)

USA PROJECT UNIT 1 - TALLGRASS

REVISION HISTORY				
REVISION	**DATE**	**DESCRIPTIONS**	**PREPARED BY**	**APPROVED BY**
0	10 Apr 26	First Issue	Miss Michelle Wilrutstien	Mr. Phisit Pew-La-Or
1	20 Apr 26	Revised as mark	Miss Michelle Wilrutstien	Mr. Phisit Pew-La-Or
2	24 Jul 26	Revised as mark	Miss Michelle Wilrutstien	Mr. Phisit Pew-La-Or

Prepared by (QA Engineer):	Miss Michelle Wilrutstien	**Approved by (QAQC Manager):**	Mr. Phisit Pew-La-Or	**Approved by (Customer):**	Digitally signed by Suriya Lamor
Date:	24-Jul-26	**Date:**	24-Jul-26	**Date:**	Date: 2026.07.25 07:47:55 +07'00'
Signature:		**Signature:**		**Signature:**	

Job/Project No.:	CT8	Project Name:	USA PROJECT UNIT 1 - TALLGRASS	Location:	☑ Shop ☐ Site

No.	Production and Inspection Items	Specifications and Procedures			Inspection & Test Equipment	Inspection Marking	Verifying Control Records	Inspection Points											
								BJC			CIMTAS			Mitsubishi Power			AI/NOBO		
		CODE	BJC / CIMTAS	MPW-A				IP	Date	Sign	IP	Date	Sign	IP	Date	Sign	IP	Date	Sign
1	**SPECIFICATIONS**																		
1.1	Verify that all relevant documents have been received	-	-	Project Spec.	-	-	-	-			-			-			-		
2	**ENGINEERING**																		
2.1	Engineering Documents	-	Technical Specification	LU-00130 Latest rev.	-	-	-	-			-			-			-		
2.2	AFC Drawings	-	Drawings/ Part Lists		-	-	-	-			-			-			-		
3	**WELDING QUALITY CONTROL AND NDT**																		
3.1	WPS/PQR	AWS D1.1	CT8-PRO-ST-001 (WPS/PQR List for Structure)	LU-00130 Latest rev.	-	-	-	H			R			R			-		
3.2	Welder Qualification Register		CT8-PRO-ST-002 (Welder List and Certificates for Module Structure)		-	-	-	H			R			R			-		
4	**INSPECTION MEASUREMENT AND TEST EQUIPMENT**																		
4.1	Verify calibration of inspection measurement & test equipment	Manufacturer Standard	-	-	-	Calibration sticker	Calibration certificate & control log	R			R			R			-		
5	**MATERIAL RECEIVING INSPECTION**																		
5.1	**RECEIVING INSPECTION FOR MATERIAL SUPPLIED BY CLIENT**																		
5.1.1	Review material list / certificate	Material Certificates / Packing list	CT8-PRO-CM-009 Material Handling and Storage Procedure / MRR & RIR	LU-00130 Latest rev.	Visual inspection & measuring tools	Accepted stamp and sign	Material Receiving Report (MAR) and Receiving Inspection Reccord (RIR)	H / R			R			R			-		
5.1.2	Check condition of packing & quantity of material							H			R			R			-		
5.1.3	Check tag numbers of material (if any)							H			R			R			-		
5.1.4	Cable test on drum							H			R			R			-		
5.2	**RECEIVING INSPECTION FOR MATERIAL SUPPLIED BY BJCHI**																		
5.2.1	**DOCUMENT REVIEW BEFORE ORDERING**																		
5.2.1.1	Review project specification for material requisition compliance spec.	Relevant design code & project specification	CT8-PRO-CM-009 Material Handling and Storage Procedure / MRR & RIR	LU-00130 Latest rev.	-	Review stamp and sign	Material Receiving Report (MAR)	R			R			R			-		
5.2.1.2	Review material certificate							R			R			R			-		
5.2.1.3	Material Approval Request (MAR)							R			R			R			-		
5.2.2	**RECEIVING INSPECTION**																		
5.2.2.1	Review material list / certificate	Relevant design code & project specification	CT8-PRO-CM-009 Material Handling and Storage Procedure / MRR & RIR	LU-00130 Latest rev.	Visual inspection & measuring tools	Accepted stamp and sign	Approved MAR , Material Certificates &Packing list	H / R			R			R			-		
5.2.2.2	Check condition of packing & quantity of material							H			R			R			-		
5.2.2.3	Check tag numbers of material (if any)							H			R			R			-		
6	BEFORE EXECUTION																		
6.1	Method Statement approved	-	-	LU-00130 Latest rev.	-	-	Method Statement	H			R			R			-		

Legend: A: Approve H: Hold Point M: Monitoring Activity R: Document Review V: Verify W: Witness N/A: Not Applicable
Note: The reference documents or procedures if revision is not specified, use latest revision.

Job/Project No.:	CT8	Project Name:	USA PROJECT UNIT 1 - TALLGRASS	Location:	☑ Shop ☐ Site

No.	Production and Inspection Items	Specifications and Procedures			Inspection & Test Equipment	Inspection Marking	Verifying Control Records	Inspection Points											
								BJC			CIMTAS			Mitsubishi Power			AI/NOBO		
		CODE	BJC / CIMTAS	MPW-A				IP	Date	Sign	IP	Date	Sign	IP	Date	Sign	IP	Date	Sign
7	**DURING EXECUTION**																		
7.1	Instrument Conduit and Cable Tray Installation	Drawing and P&ID	CT8-PRO-CM-017 Method Statement for Cable Receway Installation and Inspection / AFC Drawings	*LU-00130 Latest rev. / MDL-301 Engineering Design Standards for Electrical Installations*	Visual Inspection, Measuring, Tools,	Contruction scope	-	H			M			M			-		
7.2	Instrument Junction box, Panal Installation		AFC Drawings				-	H			M			M			-		
7.3	Field Instrument Installation		AFC, P&ID Drawings				-	H			M			M			-		
7.4	Instrument piping and tubing Installation		AFC, P&ID , HOOK UP Drawings				-	H			M			M			-		
7.5	Instrument Cable Installation, Internal Continuity Check		AFC Drawings				-	H			M			M			-		
7.6	Cable Cut Length Verification		AFC Drawings				Cable Cut Length Record	H			M			M			-		
8	**AFTER EXECUTION**																		
8.1	Instrument Conduit and Cable Tray Installation Inspection	Drawing and P&ID	CT8-PRO-CM-017 Method Statement for Cable Receway Installation and Inspection / AFC Drawings	LU-00130 Latest rev. / MDL-301 Engineering Design Standards for Electrical Installations	Inspection & Test report	Accepted stamp and sign	FIC-INS-001 / FIC-FF-001	H			W/R			R			-		
8.2	Instrument Junction box, Panal Installation Inspection		AFC Drawings				FIC-INS-002 / FIC-FF-002	H			W/R			R			-		
8.3 △2	***Field Instrument and Fire Fighting System Installation Inspection***		AFC, P&ID Drawings				FIC-INS-003 / FIC-FF-003	H			W/R			R			-		
8.4	Instrument piping and tubing Installation Inspection		AFC, P&ID , HOOK UP Drawings				FIC-INS-004	H			W/R			R			-		
8.5	Instrument Pressure Testing Inspection (Impulse lines, Air Supplier, Signal Tubing)		CT8-PRO-CM-018_Method Statement for Air Supply & Impulse Line Testing / AFC Drawings				FIC-INS-005	H			W/R			R			-		
8.6	Instrument Cable Installation Inspection		AFC Drawings				△2 FIC-INS-006 / ***FIC-FF-004***	H			W/R			R			-		
8.7	Cable Length Verification at Test Package as applicable		AFC Drawings				Cable Cut Length Record	H			W/R			R			-		
8.8	Power and Control Cable Testing Inspection (Instrument)		AFC Drawings				△2 FIC-INS-007 / FIC-INS-008 / ***FIC-FF-005***	H			W/R			R			-		
8.9	Final punch list		-				F-QA-026	H			W/R			R			-		
8.10	As built document		-				AFC Drawings	H			R			R			-		

Legend: A: Approve H: Hold Point M: Monitoring Activity R: Document Review V: Verify W: Witness N/A: Not Applicable
Note: The reference documents or procedures if revision is not specified, use latest revision.

INSTRUMENT FOR CONDUIT AND CABLE TRAY INSTALLATION INSPECTION REPORT

BJCHI

cimtas | ningbo

Inspection Date :	**Project Name :**	**Report No:**
System / Subsystem :	**Unit :**	
TAG No.:	**Module :**	
Procedure / Specification :	**Drawing No. :**	**Revision:**

Installation

The following have been inspected and verified:	YES	N/A	NO
Supports installation according to the latest Drawings and Specifications	☐	☐	☐
Size and type according to the latest Drawing and Specifications	☐	☐	☐
Route and location according to the latest Drawing and Specifications	☐	☐	☐
Depth is according to the latest Drawing and Specifications	☐	☐	☐
Spacing from hot pipes and heat surface maintained	☐	☐	☐
Proper fittings installed with threads fully engaged proper sealing compound used	☐	☐	☐
Fittings used as per area classification	☐	☐	☐
Connections have been firmly fixed	☐	☐	☐
Earth is completed	☐	☐	☐
Cable tray cover installed	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

BJCHI	**INSTRUMENT FOR JUNCTION BOX INSTALLATION INSPECTION REPORT**	cimtas | ningbo
		Report No:

Inspection Date :	**Project Name :**		
System / Subsystem :	**Unit :**		
TAG No.:	**Module :**		
Procedure / Specification :	**Drawing No. :**	**Revision:**	

The following have been inspected and verified:	YES	N/A	NO
Junction box installation correct	☐	☐	☐
Trunking to junction box correct	☐	☐	☐
Cable markers installed	☐	☐	☐
Cables correctly strapped / fixed in junction box	☐	☐	☐
Lead sheath taped	☐	☐	☐
All cores connected correctly	☐	☐	☐
Crimp-on lugs properly installed (multistrand)	☐	☐	☐
Junction box sealed correctly	☐	☐	☐
Installation of cable tray and conduit correct	☐	☐	☐
Supporting of cable tray and conduit correct	☐	☐	☐
Earthing of junction box correct	☐	☐	☐
Terminals are free of defects and are of the correct type	☐	☐	☐
Thermal numbering is complete	☐	☐	☐
Threads are adequately lubricated	☐	☐	☐
Cable is not unduly stressed inside the junction box (mechanical tension)	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

INSTRUMENT FOR FIELD INSTRUMENT INSTALLATION INSPECTION REPORT

BJCHI

cimtas | ningbo

Report No:		
Inspection Date :	**Project Name :**	
System / Subsystem :	**Unit :**	
TAG No.:	**Module :**	
Procedure / Specification :	**Drawing No. :**	**Revision:**

Mechanical Check:	YES	N/A	NO
Instrument location correct	☐	☐	☐
Instrument installed correctly	☐	☐	☐
Instrument mounting robust and vibration free	☐	☐	☐
Tray and racking installation sheet completed (by area)	☐	☐	☐
Instrument piping inspection sheet completed	☐	☐	☐
Read for test	☐	☐	☐
Instrument piping test certificate completed	☐	☐	☐
Local label fitted	☐	☐	☐
Temperature element can easily be removed from well	☐	☐	☐
Instrument is local indication only	☐	☐	☐

Confirm Electrical Equipment Area Classification

Non-Hazardous		Hazardous ■	Non-Hazardous	

Non-Hazardous Check:	YES	N/A	NO
Instrument earth bonding correct to philosophy drawing	☐	☐	☐
Cables installed correctly	☐	☐	☐
Cable glands correct	☐	☐	☐
Cable core identification correct	☐	☐	☐
Instrument covers fitted, bolts tight and correct	☐	☐	☐
Screwed covers lubricated with correct grease			
Hazardous:	YES	N/A	NO
Electrical equipment in hazardous area sheet completed	☐	☐	☐
Intrinsically safe system inspection sheet completed	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

INSTRUMENTATION FOR INSTRUMENT PIPING INSTALLATION INSPECTION REPORT

BJCHI

cimtas | ningbo

Report No:

Inspection Date :	**Project Name :**		
System / Subsystem :	**Unit :**		
TAG No.:	**Module :**		
Procedure / Specification :	**Drawing No. :**	**Revision:**	

IMPULSE LINES (or other, specify)	**YES**	**N/A**	**NO**
Hook-up Drawing No. & Revision: _____			
Tappings correct to isometric drawing no: _____	☐	☐	☐
Installed with correct slope and to hook-up	☐	☐	☐
Materials correct to hook-up	☐	☐	☐
All connections made	☐	☐	☐
Lines supported correctly	☐	☐	☐
NDT tests completed	☐	☐	☐
NDT records attached	☐	☐	☐
AIR SUPPLIES	**YES**	**N/A**	**NO**
Hook-up Drawing No. & Revision: _____	☐	☐	☐
Main isolation valve installed	☐	☐	☐
Local isolation valve installed	☐	☐	☐
Installed correct to hook-up	☐	☐	☐
Materials correct to hook-up	☐	☐	☐
All connections made	☐	☐	☐
Lines supported correctly	☐	☐	☐
Lines identified	☐	☐	☐
NDT tests completed	☐	☐	☐
NDT records attached	☐	☐	☐
SIGNAL TUBING	**YES**	**N/A**	**NO**
Hook-up Drawing No. & Revision: _____			
Installed correct to hook-up	☐	☐	☐
Materials correct to hook-up	☐	☐	☐
All connections made	☐	☐	☐
Lines supported correctly	☐	☐	☐
Lines identified	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

PRESSURE LEAK TEST FOR INSTRUMENT PIPING INSPECTION REPORT

BJCHI

cimtas | ningbo

Report No:

Inspection Date :	**Project Name :**
System / Subsystem :	**Unit :**
TAG No.:	**Module :**
Procedure / Specification :	**Drawing No. :** **REV.:**

	YES	N/A	NO
Instrument Piping Inspection Report Completed FIC-INS-004	☐	☐	☐

IMPULSE LINES

	YES	N/A	NO
Lines disconnected & end connections checked	☐	☐	☐
Lines blown clean	☐	☐	☐
Lines reconnected and leak checked	☐	☐	☐

Test Pressure _____

Test Fluid _____

Test Duration _____

AIR SUPPLIES

	YES	N/A	NO
Lines disconnected & end connections checked	☐	☐	☐
Lines blown clean	☐	☐	☐
Lines reconnected and leak checked	☐	☐	☐

Test Pressure _____

Test Fluid _____

Test Duration _____

SIGNAL TUBING

	YES	N/A	NO
Lines disconnected & end connections checked	☐	☐	☐
Lines blown clean	☐	☐	☐
Lines reconnected and leak checked	☐	☐	☐

Test Pressure _____

Test Fluid _____

Test Duration _____

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

BJCHI	**INSTRUMENT FOR CABLE INSTALLATION INSPECTION REPORT**	cimtas | ningbo
		Report No:

Inspection Date :	**Project Name :**		
System / Subsystem :	**Unit :**		
TAG No.:	**Module :**		
Procedure / Specification :	**Drawing No. :**	**Revision:**	

The following have been inspected and verified:	YES	N/A	NO
Cable size and type as per approved cable schedule and drawing	☐	☐	☐
Cable installation neat and spaced	☐	☐	☐
Cable tag provided and properly labelled according to specification	☐	☐	☐
Cable bending radius is as per procedure and bend free of deformities	☐	☐	☐
Cable sheath free of damage	☐	☐	☐
Correct size and type of crimping lug used	☐	☐	☐
Check if single core power cable laying arrangement is in trefoil formation	☐	☐	☐
Cables are properly fixed with cable tie wrap	☐	☐	☐
Check if single core cable armoured and metalic shield are bonded to Earth at one end only	☐	☐	☐
Cables dressing and glanding done correctly	☐	☐	☐
Cable properly supported	☐	☐	☐
Cable segregation checked	☐	☐	☐
Cable termination done properly	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

INSTRUMENTATION FOR CONTROL CABLE TESTED INSPECTION REPORT

cimtas | ningbo

Report No:

Inspection Date :	**Project Name :**
System / Subsystem :	**Unit :**
TAG No.:	**Module :**
Procedure / Specification :	**Drawing No. :** **REV.:**

CABLE TESTING

Record lowest test results for each cable multicore and each signal cable within the cable.

Number of Pairs/ Triads/ Quads/ Others: _____

Pair _____ Triad _____

Quad _____ Other _____

Cable Length _____

Cable No. _____ From _____ To _____

An insulation resistance test is carried out on cables listed after completion of glanding using a Megger tester (voltage) : _____

Test Equipment Reference

TEST EQUIPMENT REFERENCE: _____ S. No.: _____

CERTIFICATION TRACE NO.: _____ ISSUE DATE: _____ DUE DATE: _____

TEST EQUIPMENT REFERENCE: _____ S. No.: _____

CERTIFICATION TRACE NO.: _____ ISSUE DATE: _____ DUE DATE: _____

Insulation Resistance in MegOhms.

Core Colour	Core to Core	Core to Screen	Core to Earth	Screen to Earth	Continuity	Installation Date

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

BJCHI	**INSTRUMENTATION FOR POWER CABLE TEST/ACCEPTANCE INSPECTION REPORT**	cimtas | ningbo
		Report No:

Inspection Date :	**Project Name :**
System / Subsystem :	**Unit :**
TAG No.:	**Module :**
Procedure / Specification :	**Drawing No. :** **REV.:**

Cable Length: _____

Cable No.: _____ From: _____ To: _____

An insulation resistance test is carried out on cables listed after completion of glanding using a Megger tester (voltage): _____

Test Equipment reference

TEST EQUIPMENT REFERENCE : _____ S. No.: _____

CERTIFICATION TRACE NO. : _____ ISSUE DATE: _____ DUE DATE: _____

TEST EQUIPMENT REFERENCE : _____ S. No.: _____

CERTIFICATION TRACE NO. : _____ ISSUE DATE: _____ DUE DATE: _____

CABLE No.	MEGGER TEST (MEGOHMS)										CONTINUITY
	C1-C2	C1-C3	C1-C4	C1-C5	C1-C6	C1-C7	C1-C8	C2-C3	C2-C4	C2-C5	

Remarks:

Completed By	QC Eng'r/Inspector	Client	Owner
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

FIRE FIGHTING FOR CONDUIT AND CABLE TRAY INSTALLATION INSPECTION REPORT

Report No:

Inspection Date :	**Project Name :**		
System / Subsystem :	**Unit :**		
TAG No.:	**Module :**		
Procedure / Specification :	**Drawing No. :**	**Revision:**	

Installation

The following have been inspected and verified:	YES	N/A	NO
Supports installation according to the latest Drawings and Specifications	☐	☐	☐
Size and type according to the latest Drawing and Specifications	☐	☐	☐
Route and location according to the latest Drawing and Specifications	☐	☐	☐
Depth is according to the latest Drawing and Specifications	☐	☐	☐
Spacing from hot pipes and heat surface maintained	☐	☐	☐
Proper fittings installed with threads fully engaged proper sealing compound used	☐	☐	☐
Fittings used as per area classification	☐	☐	☐
Connections have been firmly fixed	☐	☐	☐
Earth is completed	☐	☐	☐
Cable tray cover installed	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

BJCHI	**FIRE FIGHTING FOR JUNCTION BOX INSTALLATION INSPECTION REPORT**	cimtas | ningbo
		Report No:

Inspection Date :	**Project Name :**		
System / Subsystem :	**Unit :**		
TAG No.:	**Module :**		
Procedure / Specification :	**Drawing No. :**	**Revision:**	

The following have been inspected and verified:	YES	N/A	NO
Junction box installation correct	☐	☐	☐
Trunking to junction box correct	☐	☐	☐
Cable markers installed	☐	☐	☐
Cables correctly strapped / fixed in junction box	☐	☐	☐
Lead sheath taped	☐	☐	☐
All cores connected correctly	☐	☐	☐
Crimp-on lugs properly installed (multistrand)	☐	☐	☐
Junction box sealed correctly	☐	☐	☐
Installation of cable tray and conduit correct	☐	☐	☐
Supporting of cable tray and conduit correct	☐	☐	☐
Earthing of junction box correct	☐	☐	☐
Terminals are free of defects and are of the correct type	☐	☐	☐
Thermal numbering is complete	☐	☐	☐
Threads are adequately lubricated	☐	☐	☐
Cable is not unduly stressed inside the junction box (mechanical tension)	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

BJCHI	**FIRE FIGHTING FOR EQUIPMENT INSTALLATION INSPECTION REPORT**	cimtas | ningbo
		Report No:

Inspection Date :	**Project Name :**
System / Subsystem :	**Unit :**
TAG No.:	**Module :**
Procedure / Specification :	**Drawing No. :** **REV.:**

The following have been inspected and verified:	YES	N/A	NO
Area classification is conformed	☐	☐	☐
Devices properly mounted and located according to latest drawings and specifications	☐	☐	☐
Conform elevation of light as per the site condition and according to latest drawings and specifications	☐	☐	☐
Fixture/JB type and rating according to latest drawings and specifications	☐	☐	☐
Proper orientation of lighting fixtures and not obscured by pipes or structures	☐	☐	☐
The location of emergency and exit lights according to latest drawings and specifications	☐	☐	☐
Devices are free of damage	☐	☐	☐
Circuit identification number according to lalest drawings and specifications	☐	☐	☐
Device identification number according to latest drawings and specifications	☐	☐	☐
Cable colour coding and sizing are verified	☐	☐	☐
Termination and connection of lighting cables verified	☐	☐	☐
Fixture pole / supports checked	☐	☐	☐
Check the lighting pole / support grouding connection	☐	☐	☐
Grounding connection done properly	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

BJCHI	**FIRE FIGHTING FOR CABLE INSTALLATION INSPECTION REPORT**	cimtas | ningbo
		Report No:

Inspection Date :	**Project Name :**		
System / Subsystem :	**Unit :**		
TAG No.:	**Module :**		
Procedure / Specification :	**Drawing No. :**	**Revision:**	

The following have been inspected and verified:	YES	N/A	NO
Cable size and type as per approved cable schedule and drawing	☐	☐	☐
Cable installation neat and spaced	☐	☐	☐
Cable tag provided and properly labelled according to specification	☐	☐	☐
Cable bending radius is as per procedure and bend free of deformities	☐	☐	☐
Cable sheath free of damage	☐	☐	☐
Correct size and type of crimping lug used	☐	☐	☐
Check if single core power cable laying arrangement is in trefoil formation	☐	☐	☐
Cables are properly fixed with cable tie wrap	☐	☐	☐
Check if single core cable armoured and metalic shield are bonded to Earth at one end only	☐	☐	☐
Cables dressing and glanding done correctly	☐	☐	☐
Cable properly supported	☐	☐	☐
Cable segregation checked	☐	☐	☐
Cable termination done properly	☐	☐	☐

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

FIRE FIGHTINGL FOR
POWER CABLE TEST/ACCEPTANCE INSPECTION REPORT

BJCHI

cimtas | ningbo

Report No:

Inspection Date :	**Project Name :**
System / Subsystem :	**Unit :**
TAG No.:	**Module :**
Procedure / Specification :	**Drawing No. :** **REV.:**

Cable Length: _____

Cable No.: _____ From: _____ To: _____

An insulation resistance test is carried out on cables listed after completion of glanding using a Megger tester (voltage): _____

Test Equipment reference

TEST EQUIPMENT REFERENCE: _____ S. No.: _____

CERTIFICATION TRACE NO.: _____ ISSUE DATE: _____ DUE DATE: _____

TEST EQUIPMENT REFERENCE: _____ S. No.: _____

CERTIFICATION TRACE NO.: _____ ISSUE DATE: _____ DUE DATE: _____

CABLE No.	MEGGER TEST (MEGOHMS)									CONTINUITY
	C1-C2	C1-C3	C1-C4	C2-C3	C3-C4	C1-E	C2-E	C3-E	C4-E	

Remarks:

Completed By	**QC Eng'r/Inspector**	**Client**	**Owner**
Company	BJCHI	CIMTAS	MPW-A
Signature			
Name			
Date			

PUNCH LIST

CLIENT:	**MODULE NO.:**
PROJECT NO:	**SYSTEM.:**
PROJECT NAME:	**DRAWING NO.:**
UNIT NO.:	**INSPECTION DATE.:**

Category:	**Discipline:**	
A1: Shall stop any test (such us hydraulic test, loop test, motor run…) or any activity that would result in HSE issue or in any risk for the integrity of the plant.	01 - Civil / UG Piping	07 - Instrumentation
	02 - Buildings / HVAC	08 - Fire fighting
A: Items must be completed before Turnover.	03 - Steel Structure	09 - Coating
	04 - Mechanical Equipment	10 - Insulation
B: Items can be completed after Turnover but before Start-up of the Facility.	05 - Piping	11 - As-Built
	06 - Electrical	12 - Others
C: Items can be completed anytime, but are required before Acceptance of Facility.		

Item No.	Module / Tag no.	Punch item Description	Category	Originator (Company)	Open Date	Closed Date	Action by	Sign Clear Date (BJCHI)		Sign Clear Date (CIMTAS)		Sign Clear Date (MPW-A)	

WITNESSED / REVIEWED BY:	**CHECKED / REVIEWED BY (BJCHI)**	**REVIEWED / APPROVED BY (CIMTAS)**	**REVIEWED / APPROVED BY (MPW-A)**
PRINT NAME:			
SIGNATURE:			
DATE:			