

DOCUMENT TYPE: Site Photograph Log (text description, no images in this fictional dataset)

LOG REF: PHOTO-DMV7-P42-JUL2019

DATE RANGE: 02-Jul-2019 to 10-Jul-2019

LOCATION: Pier P-42

ENTRIES:

- PH-114 (02-Jul-2019): Additional rebar fixing in progress at pier base, lower shaft.
- PH-115 (03-Jul-2019): Completed additional reinforcement cage prior to joint measurement.
- PH-116 (10-Jul-2019): Joint measurement in progress, Contractor and Engineer's Representative present.

Logged by: Site Office