

InfraCrackNet - Inspection Report

Inspection ID: 6a0164e9391644f9ad973c70

Date: 11/05/2026, 10:11:05 am

Summary

Crack Severity: Minor


Crack Count: 1

Confidence Score: 81%

Recommendation:

Monitor the crack and schedule routine inspections.

Original Image



Processed Overlay

