

InfraCrackNet - Inspection Report

Inspection ID: 6a00c030e4319a12830c7404

Date: 10/05/2026, 10:28:16 pm

Summary

Crack Severity: Minor


Crack Count: 4

Confidence Score: 99.6%

Recommendation:

Monitor the crack and schedule routine inspections.

Original Image



Processed Overlay

