

Report Type: {'rooms': 0, 'halls': 0, 'kitchens': 2, 'bathrooms': 3, 'rooms_detail': [{'label':

```
[
{
"label": "bathroom",
"score": 0.9960892200469971,
"bbox": [
225.88365173339844,
90.77445220947266,
319.3827819824219,
148.25169372558594
]
},
{
"label": "kitchen",
"score": 0.9899068474769592,
"bbox": [
223.09251403808594,
304.934814453125,
336.17376708984375,
506.64581298828125
]
},
{
"label": "porch",
"score": 0.9895882606506348,
"bbox": [
34.630950927734375,
505.3842468261719,
224.4612274169922,
614.0599365234375
]
},
{
"label": "garage",
"score": 0.9889650344848633,
"bbox": [
349.8504638671875,
103.60420989990234,
584.9411010742188,
501.5235290527344
]
},
{
"label": "bathroom",
"score": 0.9813678860664368,
"bbox": [
333.1422119140625,
177.9398651123047,
365.58001708984375,
241.1849822998047
]
},
{
"label": "bedroom",
"score": 0.9362871050834656,
"bbox": [
108.70110321044922,
```

```
90.2605209350586,  
216.9442138671875,  
218.93399047851562  
]  
},  
{  
  "label": "kitchen",  
  "score": 0.927820086479187,  
  "bbox": [  
    110.62166595458984,  
    332.3127136230469,  
    209.9985809326172,  
    500.10675048828125  
  ]  
},  
{  
  "label": "laundry",  
  "score": 0.9021267890930176,  
  "bbox": [  
    226.3800048828125,  
    160.07432556152344,  
    322.7405090332031,  
    213.47874450683594  
  ]  
},  
{  
  "label": "bathroom",  
  "score": 0.767353355884552,  
  "bbox": [  
    224.500732421875,  
    220.0500030517578,  
    261.03253173828125,  
    266.1244812011719  
  ]  
}  
]
```