

Report Type: {'rooms': 1, 'halls': 0, 'kitchens': 1, 'bathrooms': 1, 'rooms_detail': [{'label':

```
[
{
"label": "porch",
"score": 0.9982293248176575,
"bbox": [
400.7684326171875,
479.4430236816406,
599.3863525390625,
560.4625854492188
]
},
{
"label": "bathroom",
"score": 0.9819349050521851,
"bbox": [
401.82598876953125,
158.4649200439453,
478.9146423339844,
204.10935974121094
]
},
{
"label": "garage",
"score": 0.923884391784668,
"bbox": [
241.8646240234375,
171.65699768066406,
352.35980224609375,
468.84918212890625
]
},
{
"label": "kitchen",
"score": 0.9217439293861389,
"bbox": [
404.1828308105469,
338.9716491699219,
562.11279296875,
480.08990478515625
]
},
{
"label": "garage",
"score": 0.7393800020217896,
"bbox": [
45.158477783203125,
88.4215087890625,
234.69834899902344,
553.1730346679688
]
},
{
"label": "laundry",
"score": 0.7125772833824158,
"bbox": [
405.96099853515625,
```

```
211.1422882080078,  
474.9584655761719,  
249.34288024902344  
]  
},  
{  
  "label": "room",  
  "score": 0.7106466889381409,  
  "bbox": [  
    46.155757904052734,  
    99.39485168457031,  
    215.4939422607422,  
    532.6666870117188  
  ]  
}  
]
```