

Detailed Discrepancy Report

Discrepancy 1

STATE	Tamil Nadu
DISTRICT	Ariyalur
BLOCK	Andimadam
SANCTION YEAR	2015-2016
PACKAGE NUMBER	TN3090
ROAD NAME	L060-Silambur to Thirukonam road (VR2180)
ROAD LENGTH	5.4

NQM Inspection count	1
NQM Grading	Unsatisfactory
NQM Name	Dange Pradeep Bhaskar rao
NQM Inspection date	24-09-2016
NQM Status	In Progress
NQM Start Chainage	1
NQM End Chainage	4.0

SQM Inspection count	11
SQM Grading	satisfactory
SQM Name	Durairaj Kumaraswamy
SQM Inspection date	23-02-2016
SQM Status	In Progress
SQM Start Chainage	0
SQM End Chainage	5.4

Detailed Discrepancy Report

Discrepancy Items:

Geometrics
Base Course-Water Bound Macadam
Cross Drainage Works

Detailed Discrepancy Report

Discrepancy 2

STATE	Tamil Nadu
DISTRICT	Ariyalur
BLOCK	Ariyalur
SANCTION YEAR	2016-2017
PACKAGE NUMBER	TN1165
ROAD NAME	poyyathanallur - illupaiyur
ROAD LENGTH	5.52

NQM Inspection count	2
NQM Grading	Unsatisfactory
NQM Name	Sharma Deputy Lal
NQM Inspection date	26-08-2018
NQM Status	Maintenance
NQM Start Chainage	0
NQM End Chainage	5.5

SQM Inspection count	7
SQM Grading	satisfactory
SQM Name	C Duraisamy
SQM Inspection date	17-02-2018
SQM Status	Maintenance
SQM Start Chainage	0
SQM End Chainage	5.5

Detailed Discrepancy Report

Discrepancy Items:

Maintenance
Shoulders

Detailed Discrepancy Report

Discrepancy 3

STATE	Tamil Nadu
DISTRICT	Ariyalur
BLOCK	Ariyalur
SANCTION YEAR	2015-2016
PACKAGE NUMBER	TN3082
ROAD NAME	L073-AS road to Ameenabath road (VR2041)
ROAD LENGTH	1.325

NQM Inspection count	1
NQM Grading	Unsatisfactory
NQM Name	Dange Pradeep Bhaskar rao
NQM Inspection date	23-09-2016
NQM Status	In Progress
NQM Start Chainage	0
NQM End Chainage	1.325

SQM Inspection count	2
SQM Grading	satisfactory
SQM Name	Y CHRISTDHAS
SQM Inspection date	24-08-2016
SQM Status	In Progress
SQM Start Chainage	0
SQM End Chainage	1.325

Detailed Discrepancy Report

Discrepancy Items:

Base Course-Water Bound Macadam
Cross Drainage Works

Detailed Discrepancy Report

Discrepancy 4

STATE	Tamil Nadu
DISTRICT	Ariyalur
BLOCK	Ariyalur
SANCTION YEAR	2015-2016
PACKAGE NUMBER	TN3083
ROAD NAME	L063-AA road to Kayarlabad road (VR2066)
ROAD LENGTH	1.25

NQM Inspection count	1
NQM Grading	Unsatisfactory
NQM Name	Suresh Chandra Sharma
NQM Inspection date	14-12-2018
NQM Status	Maintenance
NQM Start Chainage	0
NQM End Chainage	1.25

SQM Inspection count	6
SQM Grading	satisfactory
SQM Name	Thiruppathy Chithan
SQM Inspection date	29-08-2017
SQM Status	Maintenance
SQM Start Chainage	0
SQM End Chainage	1.25

Detailed Discrepancy Report

Discrepancy Items:

Geometrics
Base Course-Water Bound Macadam
Road Furnitures And Markings
Maintenance
Shoulders
pavement

Detailed Discrepancy Report

Discrepancy 5

STATE	Tamil Nadu
DISTRICT	Ariyalur
BLOCK	Ariyalur
SANCTION YEAR	2014-2015
PACKAGE NUMBER	TN3086
ROAD NAME	L047-Karuppur Poiyyur - Oriyur - Nanangur road to Puthur road (VR2067)
ROAD LENGTH	1.125

NQM Inspection count	1
NQM Grading	Unsatisfactory
NQM Name	Suresh Chandra Sharma
NQM Inspection date	14-12-2018
NQM Status	Maintenance
NQM Start Chainage	0
NQM End Chainage	1.125

SQM Inspection count	5
SQM Grading	satisfactory
SQM Name	Muthuvalliappan M
SQM Inspection date	22-02-2017
SQM Status	Maintenance
SQM Start Chainage	0
SQM End Chainage	1.125

Detailed Discrepancy Report

Discrepancy Items:

Geometrics
Base Course-Water Bound Macadam
Road Furnitures And Markings
Maintenance
Shoulders
pavement

Detailed Discrepancy Report

Discrepancy 6

STATE	Tamil Nadu
DISTRICT	Ariyalur
BLOCK	Jayamkondam
SANCTION YEAR	2016-2017
PACKAGE NUMBER	TN1166
ROAD NAME	Meensurity - Kuttakkarai
ROAD LENGTH	1.0

NQM Inspection count	2
NQM Grading	Unsatisfactory
NQM Name	Sharma Deputy Lal
NQM Inspection date	26-04-2018
NQM Status	Maintenance
NQM Start Chainage	0
NQM End Chainage	1.0

SQM Inspection count	7
SQM Grading	satisfactory
SQM Name	Thangaraj D
SQM Inspection date	25-11-2017
SQM Status	Maintenance
SQM Start Chainage	0
SQM End Chainage	1.0

Detailed Discrepancy Report

Discrepancy Items:

Shoulders

Detailed Discrepancy Report

Discrepancy 7

STATE	Tamil Nadu
DISTRICT	Ariyalur
BLOCK	Jayamkondam
SANCTION YEAR	2014-2015
PACKAGE NUMBER	TN30105
ROAD NAME	MRL12-Meikavalputhur-Veeracholapuram (via) Mendevanallur road
ROAD LENGTH	3.0

NQM Inspection count	1
NQM Grading	Satisfactory
NQM Name	Prakash Anugrah
NQM Inspection date	16-09-2018
NQM Status	Maintenance
NQM Start Chainage	0
NQM End Chainage	3.0

SQM Inspection count	4
SQM Grading	Unsatisfactory
SQM Name	Muthuvalliappan M
SQM Inspection date	11-08-2018
SQM Status	Maintenance
SQM Start Chainage	0
SQM End Chainage	3.0

Detailed Discrepancy Report

Discrepancy Items:

Base Course-Water Bound Macadam
