INCOMING INSPECTION

Queue Court Q1 · 2026-08-01 · INS-419f1429

Bathroom

Basin and taps	DAMAGED
Cracked during clicking	
Bath or shower	GOOD
Extractor or window	GOOD
Geyser access	GOOD
Tiling and grout	GOOD
Toilet	GOOD

Bedroom 1

Built-in cupboards	GOOD
Flooring	GOOD
Plugs and switches	GOOD
Walls and paint	GOOD
Windows and latches	GOOD

Bedroom 2

Built-in cupboards	GOOD
Flooring	GOOD
Plugs and switches	GOOD
Walls and paint	GOOD
Windows and latches	GOOD

Entrance

Door and lock	GOOD
Flooring	GOOD
Light fittings	GOOD
Walls and paint	GOOD

Exterior

Boundary and gate	GOOD
Front door	GOOD
Garden or yard	GOOD
Post box	GOOD
Prepaid meter reading	GOOD

Kitchen

Counter tops	GOOD
Cupboards	GOOD
Flooring	GOOD
Plugs and switches	GOOD
Sink and taps	GOOD
Stove and oven	GOOD

Lounge

Curtain rails	GOOD
Flooring	GOOD

Plugs and switches	GOOD
Walls and paint	GOOD
Windows and latches	GOOD

Signed jointly