


Scrap Form

DATE	P/N SAP	QTD	Name	DESCRIPTION OF THE DEFECT	CAUSE	Nº VIN	Production Order	UNIT PRICE	TOTAL VALUE	CLASS
9/22/2026	11272431-00	2	UNID DE CONTROLE ELETR EBS 5S	Apresentou fuga de tensão durante a depuração	A	901	19000002701	R\$1,233.89	R\$2,467.78	B
9/22/2026	17120732-00	1	CONTROL DE GERENCIAMENTO DE BATERIA	Não passa corrente do chicote para o modulo	C	901	19000002701	R\$1,000.19	R\$1,000.19	B

CAPTION

Damaged during assembly	(B) Improper Handling	Malfunction	(D) Deteriorated	(E) Supplier Defect	(F) Broken	(G) Contaminated	(H) Wrong Application
-------------------------	-------------------------	-------------	--------------------	-----------------------	--------------	--------------------	-------------------------

Approval

Responsible	1ª . Production Supervisor	2ª . Responsible for Quality	3ª . Logistics Supervisor	4ª .Finance Department (If Class A or B)
Name	Pessoa Producao	Pessoa Qualidade	Pessoa Logistica	Pessoa Financeiro
DATE:				
Signature	 Digitally signed by Pessoa Producao. Timestamp: 2026-10-02 09:32:42 -03.	 Digitally signed by Pessoa Qualidade. Timestamp: 2026-10-02 09:32:42 -03.	 Digitally signed by Pessoa Logistica. Timestamp: 2026-10-02 09:32:42 -03.	 Digitally signed by Pessoa Financeiro. Timestamp: 2026-10-02 09:32:42 -03.