

Pretty-print

```
[  
  {  
    "latitude": 13.052965400000001,  
    "longitude": 77.5933773,  
    "signal_strength_dBm": -67  
  },  
  {  
    "latitude": 13.05323255,  
    "longitude": 77.59338795,  
    "signal_strength_dBm": -70  
  },  
  {  
    "latitude": 13.05576925,  
    "longitude": 77.5932128,  
    "signal_strength_dBm": -100  
  },  
  {  
    "latitude": 13.0560861,  
    "longitude": 77.5932019,  
    "signal_strength_dBm": -61  
  },  
  {  
    "latitude": 13.05738955,  
    "longitude": 77.5932542,  
    "signal_strength_dBm": -97  
  },  
  {  
    "latitude": 13.05739145,  
    "longitude": 77.59328314999999,  
    "signal_strength_dBm": -90  
  },  
  {  
    "latitude": 13.057362600000001,  
    "longitude": 77.59340420000001,  
    "signal_strength_dBm": -93  
  },  
  {  
    "latitude": 13.0572718,  
    "longitude": 77.59325100000001,  
    "signal_strength_dBm": -83  
  },  
  {  
    "latitude": 13.057372650000001,  
    "longitude": 77.5932267,  
    "signal_strength_dBm": -54  
  },  
  {  
    "latitude": 13.05766485,  
    "longitude": 77.59138734999999,  
    "signal_strength_dBm": -97  
  },  
  {  
    "latitude": 13.0576778,  
    "longitude": 77.59149625,  
    "signal_strength_dBm": -75  
  },  
  {  
    "latitude": 13.05763615,  
    "longitude": 77.5914788,  
    "signal_strength_dBm": -66  
  },  
  {  
    "latitude": 13.0578509,  
    "longitude": 77.59146455,  
    "signal_strength_dBm": -110  
  },  
]
```

```
Pretty-print
{
    "longitude": 77.59128505000001,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.057567500000001,
    "longitude": 77.59106460000001,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0574999,
    "longitude": 77.59082294999999,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.05740745,
    "longitude": 77.59089585000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0574949,
    "longitude": 77.5906979,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.05750975,
    "longitude": 77.5905998,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.05790305,
    "longitude": 77.58798245,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05793785,
    "longitude": 77.58775815,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.058176,
    "longitude": 77.58786090000001,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.05787649999999,
    "longitude": 77.58790235000001,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.05841495,
    "longitude": 77.58393555,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.05851165,
    "longitude": 77.5840627,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.05856415,
    "longitude": 77.58370185000001,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0587383,
    "longitude": 77.58219075,
    "signal_strength_dBm": -76
},
```

```
Pretty-print
{
    "latitude": 13.05878545,
    "longitude": 77.58178104999999,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0586395,
    "longitude": 77.5820405,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0591525,
    "longitude": 77.58214,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.05983345,
    "longitude": 77.57671694999999,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.05984715,
    "longitude": 77.57673085,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.062459,
    "longitude": 77.5734368,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.06252395,
    "longitude": 77.57334975,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.06331755,
    "longitude": 77.57230995,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.06347214999999,
    "longitude": 77.5721212,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0636388,
    "longitude": 77.57192825,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06375215,
    "longitude": 77.5718436,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.065473,
    "longitude": 77.5708505,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.06577895,
    "longitude": 77.57067035,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.066702849999999,
    "longitude": 77.57011904999999,
    "signal_strength_dBm": -99
```

Pretty-print

```
{  
    "latitude": 13.0674135,  
    "longitude": 77.56983299999999,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.0689899,  
    "longitude": 77.56924774999999,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.06913025,  
    "longitude": 77.56918705,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.070130299999999,  
    "longitude": 77.56861685,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.070499949999999,  
    "longitude": 77.5684033,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.07158505,  
    "longitude": 77.56775775,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.07192665,  
    "longitude": 77.56755290000001,  
    "signal_strength_dBm": -75  
},  
{  
    "latitude": 13.072641,  
    "longitude": 77.5671193,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.0728436,  
    "longitude": 77.5669988,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.0730065,  
    "longitude": 77.5669206,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.0732892,  
    "longitude": 77.5668306,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.0735054,  
    "longitude": 77.5667977,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.0658034,  
    "longitude": 77.60086905,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.065691650000002,  
    "longitude": 77.60070565000001,  
    "signal_strength_dBm": -90  
}
```

Pretty-print

```
},
{
  "latitude": 13.0657005,
  "longitude": 77.60078114999999,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.06586714999999,
  "longitude": 77.60003234999999,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.065732950000001,
  "longitude": 77.6004974,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.065987100000001,
  "longitude": 77.59964345,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.0659758,
  "longitude": 77.59971695,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.065978300000001,
  "longitude": 77.5989887,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0659925,
  "longitude": 77.5993534,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.0659559,
  "longitude": 77.59879505,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.06595655,
  "longitude": 77.59885265,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.0660125,
  "longitude": 77.598375,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.065965550000001,
  "longitude": 77.59863014999999,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.0661981,
  "longitude": 77.59766145,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.06609165,
  "longitude": 77.59806085,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.0663295,
```

```
Pretty-print
-----
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06663155,
    "longitude": 77.59581650000001,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06651795,
    "longitude": 77.59630295,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.067213800000001,
    "longitude": 77.5936556,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.067147649999999,
    "longitude": 77.5940051,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0671869,
    "longitude": 77.59293339999999,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.0673155,
    "longitude": 77.59292049999999,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.067247850000001,
    "longitude": 77.59296855,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.069026449999999,
    "longitude": 77.5930767,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.06815555,
    "longitude": 77.59314549999999,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.06646525,
    "longitude": 77.59328945,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.066074050000001,
    "longitude": 77.59332795,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06178655,
    "longitude": 77.59350305000001,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0612542,
    "longitude": 77.5935271,
    "signal_strength_dBm": -99
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.59355565,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.05969605,
    "longitude": 77.59357309999999,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.057381549999999,
    "longitude": 77.5935381,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0573568,
    "longitude": 77.5935959,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05722965,
    "longitude": 77.59359355000001,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0545887,
    "longitude": 77.5937309,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.05455375,
    "longitude": 77.59373339999999,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.05310265,
    "longitude": 77.5938017,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.052770800000001,
    "longitude": 77.59377825,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.05633075,
    "longitude": 77.61145139999999,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0561889,
    "longitude": 77.6112364,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.0559961,
    "longitude": 77.61107355,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.055856649999999,
    "longitude": 77.6109329,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05580175,
    "longitude": 77.61081465000001,
    "signal_strength_dBm": -57
},
```

```
Pretty-print
{
    "latitude": 13.0556988,
    "longitude": 77.6105658,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05560365,
    "longitude": 77.61033665,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.05555725,
    "longitude": 77.61020705,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.05553265,
    "longitude": 77.61009179999999,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.055374350000001,
    "longitude": 77.6027383,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.0552609,
    "longitude": 77.60257345,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.05517505,
    "longitude": 77.60232715000001,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.055117450000001,
    "longitude": 77.6003739,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.05511479999998,
    "longitude": 77.60020005,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.05514235,
    "longitude": 77.59974065,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.05516785,
    "longitude": 77.5995485,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0552969,
    "longitude": 77.59914814999999,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.055348649999999,
    "longitude": 77.59901909999999,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0558222,
    "longitude": 77.59812895,
    "signal_strength_dBm": -62
```

Pretty-print

```
{  
    "latitude": 13.0558955,  
    "longitude": 77.59781695000001,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.05586545,  
    "longitude": 77.59763665,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.0558189,  
    "longitude": 77.5975165,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.05563885,  
    "longitude": 77.5973869,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.0554697,  
    "longitude": 77.5973079,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.055448,  
    "longitude": 77.5972616,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.0555927,  
    "longitude": 77.59604010000001,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.05567915,  
    "longitude": 77.59522079999999,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.05439975,  
    "longitude": 77.57142495,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.05434749999999,  
    "longitude": 77.57216975,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.0551949,  
    "longitude": 77.5760855,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.05494849999998,  
    "longitude": 77.57595705,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.05526385,  
    "longitude": 77.5757601,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.05445969999999,  
    "longitude": 77.5694331,  
    "signal_strength_dBm": -109  
}
```

Pretty-print

```
},
{
  "latitude": 13.06737305,
  "longitude": 77.59320955,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.06716295,
  "longitude": 77.5932272,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.067252100000001,
  "longitude": 77.59311435000001,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.0672573,
  "longitude": 77.5932851,
  "signal_strength_dBm": -63
},
{
  "latitude": 13.0636635,
  "longitude": 77.58684310000001,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0635132,
  "longitude": 77.58656535,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.06374955,
  "longitude": 77.58682265,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.06372145,
  "longitude": 77.58708755,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.0652811,
  "longitude": 77.58310155,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.0641585,
  "longitude": 77.58464635,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.06485185,
  "longitude": 77.5840243,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.0644655,
  "longitude": 77.583714,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.06326855,
  "longitude": 77.5858627,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.062734899999999,
```

```
Pretty-print
-----
    "signal_strength_dBm": -44
},
{
    "latitude": 13.0632166,
    "longitude": 77.58617770000001,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.07032085,
    "longitude": 77.5789517,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.07036625,
    "longitude": 77.57915854999999,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.07039599999999,
    "longitude": 77.57896355,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0704617,
    "longitude": 77.5789877,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0684714,
    "longitude": 77.57834865,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0681476,
    "longitude": 77.5785371,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06863909999999,
    "longitude": 77.57851445,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.06811095,
    "longitude": 77.57834399999999,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.06728375,
    "longitude": 77.5779752,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.06655295,
    "longitude": 77.57762345,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.05584255,
    "longitude": 77.5936783,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0558951,
    "longitude": 77.59363300000001,
    "signal_strength_dBm": -77
},
{
```

```
Pretty-print
{
    "longitude": 77.5936438,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.05815045,
    "longitude": 77.5951091,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0581995,
    "longitude": 77.5949161,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.058809799999999,
    "longitude": 77.59356635,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.05801,
    "longitude": 77.59354975,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05825595,
    "longitude": 77.5946939,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.05221175,
    "longitude": 77.57647940000001,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.052525,
    "longitude": 77.57894715,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.05263435,
    "longitude": 77.57874035,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.05253425,
    "longitude": 77.57498269999999,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.052076249999999,
    "longitude": 77.57491525,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0551216,
    "longitude": 77.60000915,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.055130949999999,
    "longitude": 77.59983865000001,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0577598,
    "longitude": 77.59661625,
    "signal_strength_dBm": -46
},
```

```
Pretty-print
{
    "latitude": 13.057894650000001,
    "longitude": 77.59611634999999,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05544695,
    "longitude": 77.5988376,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.055498,
    "longitude": 77.60467990000001,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.05548365,
    "longitude": 77.60447355,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.055631949999999,
    "longitude": 77.59850595,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.05547365,
    "longitude": 77.59335189999999,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.055763500000001,
    "longitude": 77.5933426,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.08285495,
    "longitude": 77.59346425000001,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.083269699999999,
    "longitude": 77.5935984,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0836761,
    "longitude": 77.59375085,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.08459425,
    "longitude": 77.59411080000001,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.08151095,
    "longitude": 77.59317415000001,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.081769600000001,
    "longitude": 77.593211,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.05442225,
    "longitude": 77.5934161,
    "signal_strength_dBm": -51
```

Pretty-print

```
{  
    "latitude": 13.0552299,  
    "longitude": 77.59336575,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.0784825,  
    "longitude": 77.5929173,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.080583950000001,  
    "longitude": 77.59309745,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.07493135,  
    "longitude": 77.59261125,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.07521525,  
    "longitude": 77.592625,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.066928650000001,  
    "longitude": 77.59324649999999,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.0601018,  
    "longitude": 77.59326055,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.06042425,  
    "longitude": 77.5932476,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.0823724,  
    "longitude": 77.5933374,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.06553175,  
    "longitude": 77.5930855,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.0657143,  
    "longitude": 77.5930714,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.0729613,  
    "longitude": 77.59264495,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.073619950000001,  
    "longitude": 77.59261889999999,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.076240949999999,  
    "longitude": 77.59271335,  
    "signal_strength_dBm": -42  
}
```

Pretty-print

```
},
{
  "latitude": 13.06626465,
  "longitude": 77.59315000000001,
  "signal_strength_dBm": -79
},
{
  "latitude": 13.06680235,
  "longitude": 77.59310145,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.07011645,
  "longitude": 77.59283435,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.0716049,
  "longitude": 77.59273685,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.0534465,
  "longitude": 77.59348055,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.053591399999998,
  "longitude": 77.59347255,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.05274435,
  "longitude": 77.5934585,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.0529258,
  "longitude": 77.59348095,
  "signal_strength_dBm": -55
},
{
  "latitude": 13.0674203,
  "longitude": 77.59303765,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.06812615,
  "longitude": 77.59297335,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06364285,
  "longitude": 77.5932502,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.0645574,
  "longitude": 77.5932235,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.06159155,
  "longitude": 77.59336005,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.0626012,
```

```
Pretty-print
-----
{"signal_strength_dBm": -94
},
{
  "latitude": 13.05307935,
  "longitude": 77.59348625,
  "signal_strength_dBm": -99
},
{
  "latitude": 13.0518865,
  "longitude": 77.5936035,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.051686100000001,
  "longitude": 77.59355545,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.08573155,
  "longitude": 77.5945526,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.05985,
  "longitude": 77.5934089,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.0602756,
  "longitude": 77.59340025,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.06905885,
  "longitude": 77.59290555000001,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.05687805,
  "longitude": 77.59335775,
  "signal_strength_dBm": -41
},
{
  "latitude": 13.05853275,
  "longitude": 77.5933874,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.05237955,
  "longitude": 77.5933967,
  "signal_strength_dBm": -55
},
{
  "latitude": 13.0564507,
  "longitude": 77.58786599999999,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.07006305,
  "longitude": 77.5804478,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.07030145,
  "longitude": 77.57955475,
  "signal_strength_dBm": -46
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.57963325,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0729585,
    "longitude": 77.58268835000001,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.07235415,
    "longitude": 77.5822165,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0700916,
    "longitude": 77.58123665,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.069651499999999,
    "longitude": 77.58103065,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.05519505,
    "longitude": 77.57538464999999,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0554566,
    "longitude": 77.57531234999999,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.07284665,
    "longitude": 77.586048,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.05380415,
    "longitude": 77.57481215,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0537739,
    "longitude": 77.57425085,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.053550349999998,
    "longitude": 77.5749978,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0722399,
    "longitude": 77.59286639999999,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.07061375,
    "longitude": 77.59297935000001,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.0524612,
    "longitude": 77.5937314,
    "signal_strength_dBm": -88
},
```

```
Pretty-print
{
    "latitude": 13.05396575,
    "longitude": 77.59376955,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0534577,
    "longitude": 77.5937968,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.052281950000001,
    "longitude": 77.59369749999999,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0521364,
    "longitude": 77.59366424999999,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0532524,
    "longitude": 77.59383345,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.05247174999999,
    "longitude": 77.59331040000001,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0527226,
    "longitude": 77.5933514,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.06116685,
    "longitude": 77.593215,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.061792950000001,
    "longitude": 77.5931943,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06800945,
    "longitude": 77.59285955,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.06833945,
    "longitude": 77.5928351,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06910485,
    "longitude": 77.5927665,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.06955245,
    "longitude": 77.5927279,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.06946095,
    "longitude": 77.5926796,
    "signal_strength_dBm": -87
```

Pretty-print

```
{  
    "latitude": 13.0633144,  
    "longitude": 77.59314334999999,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.063998949999998,  
    "longitude": 77.5931162,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.0521783,  
    "longitude": 77.5932453,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.0534248,  
    "longitude": 77.5933847,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.071254499999998,  
    "longitude": 77.5926031,  
    "signal_strength_dBm": -44  
},  
{  
    "latitude": 13.071880199999999,  
    "longitude": 77.59255925,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.087256700000001,  
    "longitude": 77.5952044,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.0881011,  
    "longitude": 77.59557825,  
    "signal_strength_dBm": -91  
},  
{  
    "latitude": 13.08880015,  
    "longitude": 77.59586985,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.0894762,  
    "longitude": 77.5961459,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.0743697,  
    "longitude": 77.59261175,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.0864486,  
    "longitude": 77.5948413,  
    "signal_strength_dBm": -51  
},  
{  
    "latitude": 13.05517335,  
    "longitude": 77.6019769,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.05517165,  
    "longitude": 77.60190754999999,  
    "signal_strength_dBm": -99  
}
```

Pretty-print

```
},
{
  "latitude": 13.050650399999999,
  "longitude": 77.57503485000001,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.05043595,
  "longitude": 77.5751044,
  "signal_strength_dBm": -77
},
{
  "latitude": 13.05165275,
  "longitude": 77.57486850000001,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.0514631,
  "longitude": 77.5748578,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.0535409,
  "longitude": 77.5753119,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.0533863,
  "longitude": 77.57518160000001,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0534556,
  "longitude": 77.5752521,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.05751665,
  "longitude": 77.57677165,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.0575682,
  "longitude": 77.57676169999999,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.058658699999999,
  "longitude": 77.57689595,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0585852,
  "longitude": 77.57687675,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.058694299999999,
  "longitude": 77.5768827,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.059488,
  "longitude": 77.57670035,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.059604400000001,
```

```
Pretty-print
-----
    "signal_strength_dBm": -56
},
{
    "latitude": 13.0596602,
    "longitude": 77.57664374999999,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.05966905,
    "longitude": 77.5766796,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06081475,
    "longitude": 77.57643675,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0608801,
    "longitude": 77.57640995,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0609763,
    "longitude": 77.5763693,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0616929,
    "longitude": 77.57607974999999,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0615338,
    "longitude": 77.57612995,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0627014,
    "longitude": 77.5758864,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0626748,
    "longitude": 77.57587555,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0627217,
    "longitude": 77.57585795,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0662513,
    "longitude": 77.581162,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.066346,
    "longitude": 77.581628,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0665076999999999,
    "longitude": 77.5815538,
    "signal_strength_dBm": -40
},
```

```
Pretty-print
{
    "longitude": 77.5819384,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.07116915,
    "longitude": 77.5817064,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06952,
    "longitude": 77.57563285,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.06949225,
    "longitude": 77.57578705,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.0694085,
    "longitude": 77.5756891,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0712646,
    "longitude": 77.57688795,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.0648311,
    "longitude": 77.5734932,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.065289400000001,
    "longitude": 77.57347734999999,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0650607,
    "longitude": 77.5731946,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0663933,
    "longitude": 77.5747915,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06648725,
    "longitude": 77.5744794,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.06702525,
    "longitude": 77.57482295,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0660135,
    "longitude": 77.57454290000001,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06668425,
    "longitude": 77.5738248,
    "signal_strength_dBm": -91
},
```

```
Pretty-print
{
    "latitude": 13.0668848,
    "longitude": 77.57315855,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0664505,
    "longitude": 77.5735665,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.06690125,
    "longitude": 77.57370765,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0646153,
    "longitude": 77.57347765,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.064763750000001,
    "longitude": 77.5731678,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.06472065,
    "longitude": 77.57352549999999,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.066083800000001,
    "longitude": 77.57346625,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.06973775,
    "longitude": 77.5749764,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0697452,
    "longitude": 77.5748427,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06996715,
    "longitude": 77.57497795,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0696401,
    "longitude": 77.57529685,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.07001165,
    "longitude": 77.5754539,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0638589,
    "longitude": 77.57328190000001,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.064057,
    "longitude": 77.5733309,
    "signal_strength_dBm": -76
```

Pretty-print

```
{  
    "latitude": 13.0583664,  
    "longitude": 77.59155365000001,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.05841775,  
    "longitude": 77.59161094999999,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.0581794,  
    "longitude": 77.59154050000001,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.0584794,  
    "longitude": 77.59143765,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.0587517,  
    "longitude": 77.59107975,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.058842550000001,  
    "longitude": 77.59095765000001,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.05946425,  
    "longitude": 77.590087,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.05968315,  
    "longitude": 77.58978035,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.05988505,  
    "longitude": 77.58997389999999,  
    "signal_strength_dBm": -101  
},  
{  
    "latitude": 13.05907265000001,  
    "longitude": 77.5898658,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.06038435,  
    "longitude": 77.5897657,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.06009185,  
    "longitude": 77.59015095,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.06033285,  
    "longitude": 77.59003129999999,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.06127625,  
    "longitude": 77.58856245000001,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.0607793,
  "longitude": 77.58955315,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.06169605,
  "longitude": 77.589708,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.0611017,
  "longitude": 77.58943095000001,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.06139735,
  "longitude": 77.5893049,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.061679300000002,
  "longitude": 77.58867145,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.061229650000001,
  "longitude": 77.58757045,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.06163505,
  "longitude": 77.58701235000001,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0616625,
  "longitude": 77.58722515,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.06086685,
  "longitude": 77.58737239999999,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0620327,
  "longitude": 77.58873805,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.0622699,
  "longitude": 77.58840455,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.06242945,
  "longitude": 77.58865460000001,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.06238515,
  "longitude": 77.5859636,
  "signal_strength_dBm": -63
},
{
  "latitude": 13.062517199999998,
```

```
Pretty-print
-----
    "signal_strength_dBm": -62
},
{
    "latitude": 13.063737150000001,
    "longitude": 77.58797165,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0637503,
    "longitude": 77.58871110000001,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.0637145,
    "longitude": 77.58860105,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.06401865,
    "longitude": 77.58368565,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.06431415,
    "longitude": 77.58327134999999,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.06420005,
    "longitude": 77.58349845000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06413005,
    "longitude": 77.58345295,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.065921,
    "longitude": 77.5806578,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0658836,
    "longitude": 77.5810762,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0669211,
    "longitude": 77.58127395,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0673166,
    "longitude": 77.5805732,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.066554799999999,
    "longitude": 77.58072755,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.070314,
    "longitude": 77.58625675,
    "signal_strength_dBm": -75
},
```

```
Pretty-print
{
    "longitude": 77.5859437,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.07044,
    "longitude": 77.58644785,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.06041145,
    "longitude": 77.5795799,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0605305,
    "longitude": 77.57963720000001,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.063632949999999,
    "longitude": 77.5779574,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.06385905,
    "longitude": 77.57792935,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0628386,
    "longitude": 77.57673059999999,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.06344645,
    "longitude": 77.57768215,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0633128,
    "longitude": 77.5775107,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0629461,
    "longitude": 77.57745890000001,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06286355,
    "longitude": 77.57730045,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0631126,
    "longitude": 77.57746945,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.06290835,
    "longitude": 77.5789746,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.06289245,
    "longitude": 77.57969865,
    "signal_strength_dBm": -61
},
```

```
Pretty-print
{
    "latitude": 13.0625934,
    "longitude": 77.579451,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.0631661,
    "longitude": 77.57793344999999,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06237434999999,
    "longitude": 77.5795153,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0627329,
    "longitude": 77.58004165,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.06211594999999,
    "longitude": 77.57955494999999,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.063454,
    "longitude": 77.5781762,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.06319815,
    "longitude": 77.57915815,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0630761,
    "longitude": 77.57985074999999,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0637691,
    "longitude": 77.5795034,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06324875,
    "longitude": 77.58022315,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.063237350000001,
    "longitude": 77.5799843,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.06349375,
    "longitude": 77.57936459999999,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.061184950000001,
    "longitude": 77.58184915000001,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.06152875,
    "longitude": 77.58193135,
    "signal_strength_dBm": -61
```

Pretty-print

```
{  
    "latitude": 13.060703,  
    "longitude": 77.58170785,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.06084855,  
    "longitude": 77.58176055,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.060043700000001,  
    "longitude": 77.5814287,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.0604177,  
    "longitude": 77.58159180000001,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.05958185,  
    "longitude": 77.5812873,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.06327565,  
    "longitude": 77.58161344999999,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.06353645,  
    "longitude": 77.58190214999999,  
    "signal_strength_dBm": -68  
},  
{  
    "latitude": 13.0631316,  
    "longitude": 77.58212065000001,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.0635589,  
    "longitude": 77.58151484999999,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.06263215,  
    "longitude": 77.58087275,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.062888350000001,  
    "longitude": 77.5811876,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.062842700000001,  
    "longitude": 77.58082565000001,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.06249175,  
    "longitude": 77.58135315000001,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.06262755,  
    "longitude": 77.5786046,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.06262755,  
    "longitude": 77.5786046,  
    "signal_strength_dBm": -80  
}
```

Pretty-print

```
},
{
  "latitude": 13.0638238,
  "longitude": 77.58222305,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.06343995,
  "longitude": 77.58238975,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.06409945,
  "longitude": 77.58221234999999,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.0639748,
  "longitude": 77.58166080000001,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.064337850000001,
  "longitude": 77.58217955,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.063378100000001,
  "longitude": 77.58285624999999,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.0636881,
  "longitude": 77.58310355,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.06376195,
  "longitude": 77.58268955,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.063525250000001,
  "longitude": 77.58302845,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.0630351,
  "longitude": 77.58260824999999,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.0638216,
  "longitude": 77.58114245,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.063054600000001,
  "longitude": 77.5805072,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.0633435,
  "longitude": 77.5805156,
  "signal_strength_dBm": -77
},
{
  "latitude": 13.062657999999999,
```

```
Pretty-print
-----
    "signal_strength_dBm": -85
},
{
    "latitude": 13.06270845,
    "longitude": 77.5851544,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.062078750000001,
    "longitude": 77.5846839,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.063065600000002,
    "longitude": 77.58541224999999,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.062751200000001,
    "longitude": 77.58546215,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.06289975,
    "longitude": 77.5852582,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0641178,
    "longitude": 77.58014990000001,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0646713,
    "longitude": 77.57965845000001,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06451605,
    "longitude": 77.5794335,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06340955,
    "longitude": 77.58113035,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0637928,
    "longitude": 77.58089000000001,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.063602,
    "longitude": 77.5807211,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0617336,
    "longitude": 77.58417605,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.06150214999999,
    "longitude": 77.58453175,
    "signal_strength_dBm": -101
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.58234265,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06286345,
    "longitude": 77.582493,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06284535,
    "longitude": 77.58251139999999,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06413545,
    "longitude": 77.5827685,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0638012,
    "longitude": 77.58324685,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0639515,
    "longitude": 77.58330075,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.064448200000001,
    "longitude": 77.5802541,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06491375,
    "longitude": 77.57959405,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.06492455,
    "longitude": 77.58002005,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.06562755,
    "longitude": 77.5806286,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.065362,
    "longitude": 77.58064725,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.065146850000001,
    "longitude": 77.58126924999999,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.061533749999999,
    "longitude": 77.57939465000001,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0616374,
    "longitude": 77.5789906,
    "signal_strength_dBm": -106
},
```

```
Pretty-print
{
    "latitude": 13.0617554,
    "longitude": 77.5792705,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.06144555,
    "longitude": 77.57911250000001,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.060274750000001,
    "longitude": 77.5773807,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.0609144,
    "longitude": 77.5776809,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.0602148,
    "longitude": 77.57749445,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06161715,
    "longitude": 77.5779945,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0615397,
    "longitude": 77.57774915,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0617632,
    "longitude": 77.57848755,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0617621,
    "longitude": 77.5784407,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0638283,
    "longitude": 77.578587,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.06395475,
    "longitude": 77.57856575,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.064063449999999,
    "longitude": 77.57830315000001,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06400025,
    "longitude": 77.58000469999999,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.06329675,
    "longitude": 77.58101644999999,
    "signal_strength_dBm": -98
}
```

Pretty-print

```
{  
    "latitude": 13.0627709,  
    "longitude": 77.58178255000001,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.06247145,  
    "longitude": 77.5822202,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.06225345,  
    "longitude": 77.5821297,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.0588467,  
    "longitude": 77.58749075,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.0590017,  
    "longitude": 77.5877092,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.05854095,  
    "longitude": 77.5877933,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.06029975,  
    "longitude": 77.58631,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.060981900000002,  
    "longitude": 77.5853271,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.061039650000001,  
    "longitude": 77.5856609,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.06060265,  
    "longitude": 77.58542085,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.05955945,  
    "longitude": 77.5873684,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.05952555,  
    "longitude": 77.5876145,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.064731850000001,  
    "longitude": 77.58160000000001,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.06452705,  
    "longitude": 77.5812944,
```

Pretty-print

```
},
{
  "latitude": 13.064947,
  "longitude": 77.580978,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.06517055,
  "longitude": 77.5803751,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.0647506,
  "longitude": 77.5806915,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.06427425,
  "longitude": 77.58092555,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.064023500000001,
  "longitude": 77.58085625000001,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.063347,
  "longitude": 77.58561635000001,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.0635157,
  "longitude": 77.5855272,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.063671150000001,
  "longitude": 77.58600595,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.06321405,
  "longitude": 77.5784341,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.06380395,
  "longitude": 77.57876429999999,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.0639304,
  "longitude": 77.57874305,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.06355645,
  "longitude": 77.57859769999999,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.0621486,
  "longitude": 77.57623269999999,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.06218885,
```

```
Pretty-print
-----
    "signal_strength_dBm": -101
},
{
    "latitude": 13.062332099999999,
    "longitude": 77.5765149,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.06260725,
    "longitude": 77.5769201,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06255395,
    "longitude": 77.57710305,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.062026,
    "longitude": 77.57603879999999,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06194085,
    "longitude": 77.57645980000001,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.0619811,
    "longitude": 77.57691464999999,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.061743799999999,
    "longitude": 77.57679425,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.062427199999998,
    "longitude": 77.57665495,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.061447000000001,
    "longitude": 77.58374914999999,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.06082525,
    "longitude": 77.5846533,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06096625,
    "longitude": 77.58395905,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.06203185,
    "longitude": 77.58287555,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0613596,
    "longitude": 77.5834678,
    "signal_strength_dBm": -88
},
{
```

```
Pretty-print
{
    "longitude": 77.58385765,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.060395799999998,
    "longitude": 77.58389915000001,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06016595,
    "longitude": 77.5837842,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06122855,
    "longitude": 77.5832518,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.060694900000001,
    "longitude": 77.58337765,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.06032255,
    "longitude": 77.5831527,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.0602338,
    "longitude": 77.58351060000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0543579,
    "longitude": 77.57293440000001,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05404275,
    "longitude": 77.57332020000001,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.05406535,
    "longitude": 77.57284775,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.05742155,
    "longitude": 77.57389359999999,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.05756075,
    "longitude": 77.57393805000001,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0574827,
    "longitude": 77.57401205,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.0900338,
    "longitude": 77.59635755,
    "signal_strength_dBm": -109
},
```

```
Pretty-print
{
    "latitude": 13.09034125,
    "longitude": 77.59645284999999,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.09070535,
    "longitude": 77.59655405,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.09104905,
    "longitude": 77.59663524999999,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.08984525,
    "longitude": 77.59629095,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0681788,
    "longitude": 77.5802477,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0676926,
    "longitude": 77.5799871,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.06793385,
    "longitude": 77.58000645,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06863885,
    "longitude": 77.57879735,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0681812,
    "longitude": 77.5794598,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0694302,
    "longitude": 77.57614175,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.069193850000001,
    "longitude": 77.5766013,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06946175,
    "longitude": 77.57658004999999,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.07004585,
    "longitude": 77.577766,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.06937565,
    "longitude": 77.5782573,
    "signal_strength_dBm": -64
```

Pretty-print

```
{  
    "latitude": 13.069672,  
    "longitude": 77.577759,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.0689077,  
    "longitude": 77.57687645,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.06912355,  
    "longitude": 77.57690535,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.0681215,  
    "longitude": 77.57324890000001,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.0676558,  
    "longitude": 77.57302125,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.0698434,  
    "longitude": 77.57441804999999,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.06983535,  
    "longitude": 77.5740108,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.0700812,  
    "longitude": 77.57410945000001,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.06869925,  
    "longitude": 77.57340625,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.06900905,  
    "longitude": 77.5735073,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.0686415,  
    "longitude": 77.5739376,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.06891715,  
    "longitude": 77.57312245,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.069747849999999,  
    "longitude": 77.57387135,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.06961675,  
    "longitude": 77.57425045,  
    "signal_strength_dBm": -55  
}
```

Pretty-print

```
},
{
  "latitude": 13.06974505,
  "longitude": 77.57376905000001,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.0705661,
  "longitude": 77.57522295,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.0707784,
  "longitude": 77.57553419999999,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.0504168,
  "longitude": 77.57505384999999,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.05581035,
  "longitude": 77.57336585,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.0554504,
  "longitude": 77.57324805,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.054238999999999,
  "longitude": 77.57409675,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.0544075,
  "longitude": 77.5735375,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.05493595,
  "longitude": 77.5738916,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.0560015,
  "longitude": 77.57590214999999,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.0558267,
  "longitude": 77.57636645,
  "signal_strength_dBm": -55
},
{
  "latitude": 13.05574535,
  "longitude": 77.57630355,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.0562898,
  "longitude": 77.57647125,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.05656765,
```

```
Pretty-print
-----
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0562719,
  "longitude": 77.57653024999999,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.05619625,
  "longitude": 77.5770275,
  "signal_strength_dBm": -99
},
{
  "latitude": 13.0573508,
  "longitude": 77.57443155,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.0569992,
  "longitude": 77.57420205,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.057397949999999,
  "longitude": 77.5742054,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.054894999999998,
  "longitude": 77.573515,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.05449955,
  "longitude": 77.57317995,
  "signal_strength_dBm": -79
},
{
  "latitude": 13.05591365,
  "longitude": 77.57691205,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.05596555,
  "longitude": 77.5764409,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.05564835,
  "longitude": 77.5758086,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.0560707,
  "longitude": 77.57468994999999,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.05597865,
  "longitude": 77.5754255,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.0564962,
  "longitude": 77.5740438,
  "signal_strength_dBm": -83
},
```

```
Pretty-print
{
    "longitude": 77.5739385,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.05557465,
    "longitude": 77.5739183,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.05541785,
    "longitude": 77.57429780000001,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.056217100000001,
    "longitude": 77.5753079,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.05667665,
    "longitude": 77.57562279999999,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0561004,
    "longitude": 77.57755284999999,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0558288,
    "longitude": 77.573819,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.055488,
    "longitude": 77.57370800000001,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.054644,
    "longitude": 77.5746855,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.05404615,
    "longitude": 77.5746863,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0557679,
    "longitude": 77.5745191,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.05608935,
    "longitude": 77.57368065,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.054993150000001,
    "longitude": 77.57311680000001,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.054760250000001,
    "longitude": 77.57219825,
    "signal_strength_dBm": -64
},
```

```
Pretty-print
{
    "latitude": 13.0552487,
    "longitude": 77.57469875000001,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0551468,
    "longitude": 77.57494059999999,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0555327,
    "longitude": 77.57625055,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.05537905,
    "longitude": 77.5761758,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0554395,
    "longitude": 77.5763621,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0553132,
    "longitude": 77.5773989,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.054996800000001,
    "longitude": 77.5775376,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0550219,
    "longitude": 77.577904,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.056741500000001,
    "longitude": 77.57367085,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0562231,
    "longitude": 77.57325835,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05742575,
    "longitude": 77.5745748,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.05694345,
    "longitude": 77.5766967,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.05709895,
    "longitude": 77.5767711,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.056823399999999,
    "longitude": 77.57669085,
    "signal_strength_dBm": -98
```

Pretty-print

```
{  
    "latitude": 13.057494349999999,  
    "longitude": 77.57462625,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.057525949999999,  
    "longitude": 77.574607600000001,  
    "signal_strength_dBm": -59  
},  
{  
    "latitude": 13.0573974,  
    "longitude": 77.57681124999999,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.0574399,  
    "longitude": 77.57679585,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.05739115,  
    "longitude": 77.59300755,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.05743785,  
    "longitude": 77.59281265,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.07334295,  
    "longitude": 77.5925005,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.0640652,  
    "longitude": 77.5761728,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.064362299999999,  
    "longitude": 77.57664535,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.064503649999999,  
    "longitude": 77.57647655,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.0651872,  
    "longitude": 77.57824554999999,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.06486055,  
    "longitude": 77.5782155,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0651951,  
    "longitude": 77.57871225,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.068193749999999,  
    "longitude": 77.5823973,  
    "signal_strength_dBm": -80  
}
```

Pretty-print

```
},
{
  "latitude": 13.0682546,
  "longitude": 77.58199265,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.067849299999999,
  "longitude": 77.5822845,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.072700600000001,
  "longitude": 77.58517599999999,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.0717739,
  "longitude": 77.58456515,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.0702777,
  "longitude": 77.58219815,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.0705604,
  "longitude": 77.581691,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.07064775,
  "longitude": 77.58196914999999,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.071106449999998,
  "longitude": 77.58263790000001,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.07104825,
  "longitude": 77.58212935,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.07143505,
  "longitude": 77.58228410000001,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.06683525,
  "longitude": 77.58005895,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.0671296,
  "longitude": 77.5798541,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.0668337,
  "longitude": 77.5797751,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.069922949999999,
```

```
Pretty-print
-----
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0695943,
    "longitude": 77.5814542,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.0693056,
    "longitude": 77.58223815,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.066377750000001,
    "longitude": 77.57965745000001,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0658454,
    "longitude": 77.57886260000001,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.06617305,
    "longitude": 77.57907035,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.07155105,
    "longitude": 77.58257415,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0714137,
    "longitude": 77.58299965,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.06880285,
    "longitude": 77.58306605000001,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.07026785,
    "longitude": 77.58513605,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0701079,
    "longitude": 77.58560510000001,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.069802249999999,
    "longitude": 77.5848253,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0728932,
    "longitude": 77.58553945,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0729389,
    "longitude": 77.58503974999999,
    "signal_strength_dBm": -42
},
{
```

```
Pretty-print
{
    "longitude": 77.5832263,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.070708549999999,
    "longitude": 77.5828996,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0667026,
    "longitude": 77.57921834999999,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.0700278,
    "longitude": 77.58264080000001,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0702803,
    "longitude": 77.58262005,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.06685145,
    "longitude": 77.57947135,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06662125,
    "longitude": 77.579458,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.069600000000001,
    "longitude": 77.5833734,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0693982,
    "longitude": 77.58367715,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.070026,
    "longitude": 77.5839007,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.06652365,
    "longitude": 77.58027580000001,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.06614735,
    "longitude": 77.580118,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0695852,
    "longitude": 77.5851775,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.070178349999999,
    "longitude": 77.58602590000001,
    "signal_strength_dBm": -104
},
```

```
Pretty-print
{
    "latitude": 13.068602850000001,
    "longitude": 77.58046064999999,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06827345,
    "longitude": 77.5805705,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.07296165,
    "longitude": 77.5838317,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.072745000000001,
    "longitude": 77.58281360000001,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.06550315,
    "longitude": 77.5787612,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0657366,
    "longitude": 77.5784207,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.063721050000002,
    "longitude": 77.5758403,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.063949650000001,
    "longitude": 77.57589335,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0638807,
    "longitude": 77.575825,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06928015,
    "longitude": 77.58416489999999,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0698885,
    "longitude": 77.58457085,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.071685550000002,
    "longitude": 77.5821575,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0718569,
    "longitude": 77.582454,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0712775,
    "longitude": 77.58342155,
    "signal_strength_dBm": -64
```

Pretty-print

```
{  
    "latitude": 13.0711346,  
    "longitude": 77.5838642,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.06852065,  
    "longitude": 77.5828978,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.0689611,  
    "longitude": 77.5822176,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.06863255,  
    "longitude": 77.5830489,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.06753975,  
    "longitude": 77.58222745,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.06775155,  
    "longitude": 77.58255175,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.07059005,  
    "longitude": 77.5866775,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.070650350000001,  
    "longitude": 77.58239105000001,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.0692238,  
    "longitude": 77.58393964999999,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.06905895,  
    "longitude": 77.5841878,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.0664181,  
    "longitude": 77.57915475,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.0661808,  
    "longitude": 77.5787439,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.0694818,  
    "longitude": 77.5827549,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.0698601,  
    "longitude": 77.5821182,  
    "signal_strength_dBm": -90  
}
```

Pretty-print

```
},
{
  "latitude": 13.06977775,
  "longitude": 77.5826595,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.069535250000001,
  "longitude": 77.5830838,
  "signal_strength_dBm": -79
},
{
  "latitude": 13.06928815,
  "longitude": 77.58307074999999,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.07051245,
  "longitude": 77.58441415,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.0704066,
  "longitude": 77.58472660000001,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.06988465,
  "longitude": 77.5841906,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.0704025,
  "longitude": 77.58308065,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.0694201,
  "longitude": 77.5814508,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.06930545,
  "longitude": 77.58132175,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.064591400000001,
  "longitude": 77.5769763,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.0645373,
  "longitude": 77.5773135,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.0649906,
  "longitude": 77.57712575,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.07088075,
  "longitude": 77.5839757,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.070989149999999,
```

```
Pretty-print
-----
    "signal_strength_dBm": -//  
},  
{  
    "latitude": 13.07063355,  
    "longitude": 77.58405669999999,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.06868215,  
    "longitude": 77.5814818,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.064043850000001,  
    "longitude": 77.57699515,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.06453215,  
    "longitude": 77.5777279,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.0646839,  
    "longitude": 77.57641515,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.06496765,  
    "longitude": 77.57663869999999,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.06724405,  
    "longitude": 77.58176714999999,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.067563450000002,  
    "longitude": 77.58111794999999,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.07077885,  
    "longitude": 77.58362165,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.07020755,  
    "longitude": 77.5835294,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.0659362,  
    "longitude": 77.5781296,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.06613975,  
    "longitude": 77.57802939999999,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.06875425,  
    "longitude": 77.58194739999999,  
    "signal_strength_dBm": -68  
},  
{
```

```
Pretty-print
{
    "longitude": 77.58119174999999,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0653875,
    "longitude": 77.5771031,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0654221,
    "longitude": 77.57701660000001,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.06566035,
    "longitude": 77.57720305000001,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0648263,
    "longitude": 77.5768075,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0652601,
    "longitude": 77.57687045,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.070497,
    "longitude": 77.58141710000001,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.07021745,
    "longitude": 77.58151685,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.0674081,
    "longitude": 77.5798093,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0708712,
    "longitude": 77.58464294999999,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.06884735,
    "longitude": 77.58411695000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06905835,
    "longitude": 77.5844206,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.06547195,
    "longitude": 77.5778292,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.072312,
    "longitude": 77.58263825,
    "signal_strength_dBm": -49
},
```

```
Pretty-print
{
    "latitude": 13.06498545,
    "longitude": 77.57754015,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.068428449999999,
    "longitude": 77.58275665,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0654767,
    "longitude": 77.57912915,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.055509050000001,
    "longitude": 77.6051789,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.055510250000001,
    "longitude": 77.60502675000001,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.05545235,
    "longitude": 77.6042085,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0554232,
    "longitude": 77.6038775,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.05541935,
    "longitude": 77.6032424,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.055410949999999,
    "longitude": 77.60294765,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.055506600000001,
    "longitude": 77.6054956,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05550775,
    "longitude": 77.6053452,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0554204,
    "longitude": 77.60355915,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0555029,
    "longitude": 77.60597695,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05550515,
    "longitude": 77.6056847,
    "signal_strength_dBm": -74
```

Pretty-print

```
{  
    "latitude": 13.0555099,  
    "longitude": 77.60484550000001,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.0551744,  
    "longitude": 77.60208335,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.056466,  
    "longitude": 77.5868877,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.05680604999999,  
    "longitude": 77.58592404999999,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.05757255,  
    "longitude": 77.5888307,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.057756,  
    "longitude": 77.5889489,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.05779894999999,  
    "longitude": 77.5886495,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.05381515,  
    "longitude": 77.5922508,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.053952800000001,  
    "longitude": 77.5914036,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.05545155,  
    "longitude": 77.5876954,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.0556603,  
    "longitude": 77.5872464,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.05429535,  
    "longitude": 77.58928399999999,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.05426875,  
    "longitude": 77.58944445,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.0573158,  
    "longitude": 77.58448375,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.0555099,  
    "longitude": 77.60484550000001,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.05624155,
  "longitude": 77.58876785000001,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.056695,
  "longitude": 77.58878924999999,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.0564642,
  "longitude": 77.5885552,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.05442975,
  "longitude": 77.58909645,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.05452925,
  "longitude": 77.58906329999999,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.05409555,
  "longitude": 77.5906023,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.054712599999998,
  "longitude": 77.5890162,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.054906599999999,
  "longitude": 77.58892555,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.0548112,
  "longitude": 77.5890936,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.054335649999999,
  "longitude": 77.58918335,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.054386699999998,
  "longitude": 77.58912305,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.05415515,
  "longitude": 77.59023124999999,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.0550099,
  "longitude": 77.58878605000001,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.0551356,
```

```
Pretty-print
-----
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0555272,
    "longitude": 77.58873410000001,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.05774205,
    "longitude": 77.5836564,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0574645,
    "longitude": 77.5835417,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.055017150000001,
    "longitude": 77.58889975,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.056269799999999,
    "longitude": 77.5872756,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.056502049999999,
    "longitude": 77.58732044999999,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.055738250000001,
    "longitude": 77.5871978,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.059680100000001,
    "longitude": 77.57930859999999,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.05919905,
    "longitude": 77.5797011,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.05936825,
    "longitude": 77.5790808,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.060160750000001,
    "longitude": 77.57654514999999,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.06042145,
    "longitude": 77.57617345,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.06024795,
    "longitude": 77.57651759999999,
    "signal_strength_dBm": -69
},
{
```

```
Pretty-print
{
    "longitude": 77.57909605,
    "signal_strength_dBm": -44
},
{
    "longitude": 77.57870135,
    "signal_strength_dBm": -96
},
{
    "longitude": 77.57860865,
    "signal_strength_dBm": -40
},
{
    "longitude": 77.5783888,
    "signal_strength_dBm": -101
},
{
    "longitude": 77.5787291,
    "signal_strength_dBm": -108
},
{
    "longitude": 77.57849095,
    "signal_strength_dBm": -93
},
{
    "longitude": 77.5787029,
    "signal_strength_dBm": -56
},
{
    "longitude": 77.57886445,
    "signal_strength_dBm": -96
},
{
    "longitude": 77.57897995,
    "signal_strength_dBm": -102
},
{
    "longitude": 77.57907249999999,
    "signal_strength_dBm": -54
},
{
    "longitude": 77.57909400000001,
    "signal_strength_dBm": -56
},
{
    "longitude": 77.57909605,
    "signal_strength_dBm": -48
},
{
    "longitude": 77.57909605,
    "signal_strength_dBm": -48
}
}]]
```

```
Pretty-print
{
    "latitude": 13.059116150000001,
    "longitude": 77.5782099,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.05961355,
    "longitude": 77.57805450000001,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06170925,
    "longitude": 77.57827625,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0608874,
    "longitude": 77.57793860000001,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06014395,
    "longitude": 77.57761355,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.060679799999999,
    "longitude": 77.5785955,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.068435099999999,
    "longitude": 77.5708032,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0682154,
    "longitude": 77.57144464999999,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0665293,
    "longitude": 77.5702226,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06748775,
    "longitude": 77.57284809999999,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.067682699999999,
    "longitude": 77.5728693,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06582735,
    "longitude": 77.57209695,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.066044600000001,
    "longitude": 77.57224655,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.0660246,
    "longitude": 77.57148355,
    "signal_strength_dBm": -97
```

Pretty-print

```
{  
    "latitude": 13.06588745,  
    "longitude": 77.5719347,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.0661352,  
    "longitude": 77.5708138,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.066165699999999,  
    "longitude": 77.57098669999999,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0583971,  
    "longitude": 77.57853700000001,  
    "signal_strength_dBm": -59  
},  
{  
    "latitude": 13.058026250000001,  
    "longitude": 77.57821770000001,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.0578506,  
    "longitude": 77.57864115000001,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.057679100000001,  
    "longitude": 77.57905465,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.05923215,  
    "longitude": 77.578905,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.063029,  
    "longitude": 77.58507655,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.062593,  
    "longitude": 77.58704184999999,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.0621636,  
    "longitude": 77.58734534999999,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.06211245,  
    "longitude": 77.5871339,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.0621644,  
    "longitude": 77.57597505,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.06189015,  
    "longitude": 77.57603144999999,  
    "signal_strength_dBm": -71  
}
```

Pretty-print

```
},
{
  "latitude": 13.06213945,
  "longitude": 77.5818827,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.0620051,
  "longitude": 77.5820846,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.06181275,
  "longitude": 77.58200645,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.06223065,
  "longitude": 77.57701055,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.062480950000001,
  "longitude": 77.57590975,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.0631043,
  "longitude": 77.58142570000001,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.0642771,
  "longitude": 77.5815289,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.0641034,
  "longitude": 77.5779566,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.063376250000001,
  "longitude": 77.57686545,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.064092599999999,
  "longitude": 77.57878815000001,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.0643241,
  "longitude": 77.57913765,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.064610049999999,
  "longitude": 77.5791392,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.06473265,
  "longitude": 77.58190379999999,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.06454015,
```

```
Pretty-print
-----
    "signal_strength_dBm": -82
},
{
    "latitude": 13.06490805,
    "longitude": 77.57916180000001,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.064487249999999,
    "longitude": 77.5785271,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06496935,
    "longitude": 77.58195715,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.065425300000001,
    "longitude": 77.57993045,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0648984,
    "longitude": 77.58245415,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0652029,
    "longitude": 77.5820282,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0546589,
    "longitude": 77.59213095000001,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.05478695,
    "longitude": 77.5922785,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.06370785,
    "longitude": 77.59018505,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.063630100000001,
    "longitude": 77.590453,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.06369675,
    "longitude": 77.59032255,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.06352665,
    "longitude": 77.59081025,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0634246,
    "longitude": 77.5911403,
    "signal_strength_dBm": -67
},
{
```

```
Pretty-print
{
    "longitude": 77.5910392,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.063426549999999,
    "longitude": 77.59102135,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0548575,
    "longitude": 77.59240995,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.054873,
    "longitude": 77.59235035,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.062958850000001,
    "longitude": 77.5921207,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0630224,
    "longitude": 77.59204174999999,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.062937699999999,
    "longitude": 77.5922135,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0548576,
    "longitude": 77.59255555,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0541002,
    "longitude": 77.59198575,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.054022400000001,
    "longitude": 77.59228835,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.05408705,
    "longitude": 77.59167400000001,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0544399,
    "longitude": 77.59203769999999,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.055132050000001,
    "longitude": 77.60073695,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05512335,
    "longitude": 77.60053845,
    "signal_strength_dBm": -62
},
```

```
Pretty-print
{
    "latitude": 13.0551604,
    "longitude": 77.60157344999999,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05515344999999,
    "longitude": 77.60137854999999,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0551435,
    "longitude": 77.60105580000001,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.05522399999999,
    "longitude": 77.59932814999999,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.0551663,
    "longitude": 77.60173689999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0674968,
    "longitude": 77.58554280000001,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06731175,
    "longitude": 77.5854238,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0677762,
    "longitude": 77.5850571,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.06823465,
    "longitude": 77.58442055,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0686937,
    "longitude": 77.5846892,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.0682593,
    "longitude": 77.58409595,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06757245,
    "longitude": 77.5855698,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0661397,
    "longitude": 77.58191345,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.065952500000002,
    "longitude": 77.58217264999999,
    "signal_strength_dBm": -43
```

Pretty-print

```
{  
    "latitude": 13.0661615,  
    "longitude": 77.58223075000001,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.0667206,  
    "longitude": 77.58310080000001,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.0664993,  
    "longitude": 77.5837118,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.067667,  
    "longitude": 77.5846402,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.067100400000001,  
    "longitude": 77.58526995,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.065879299999999,  
    "longitude": 77.58353865000001,  
    "signal_strength_dBm": -75  
},  
{  
    "latitude": 13.065377699999999,  
    "longitude": 77.58442925,  
    "signal_strength_dBm": -101  
},  
{  
    "latitude": 13.065266600000001,  
    "longitude": 77.58434505,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.065732050000001,  
    "longitude": 77.58469715,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.06559165,  
    "longitude": 77.5843499,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.06700275,  
    "longitude": 77.58425285,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.06663865,  
    "longitude": 77.58474724999999,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.066559049999999,  
    "longitude": 77.58448415000001,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.06750165,  
    "longitude": 77.58359045,
```

Pretty-print

```
},
{
  "latitude": 13.06784725,
  "longitude": 77.58348275,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.06759465,
  "longitude": 77.5831156,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.06637945,
  "longitude": 77.5825672,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0665484,
  "longitude": 77.5828312,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0674309,
  "longitude": 77.5843773,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0680643,
  "longitude": 77.58380825,
  "signal_strength_dBm": -94
},
{
  "latitude": 13.0661308,
  "longitude": 77.5845345,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.065809049999999,
  "longitude": 77.5840593,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.066857500000001,
  "longitude": 77.58512865,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.06673905,
  "longitude": 77.58529265,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.0664365,
  "longitude": 77.5850157,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.0660429,
  "longitude": 77.5840422,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.066264199999999,
  "longitude": 77.5834312,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.0661546,
```

```
Pretty-print
-----
    "signal_strength_dBm": -69
},
{
    "latitude": 13.066102149999999,
    "longitude": 77.58545459999999,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.06648615,
    "longitude": 77.5852873,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.066763550000001,
    "longitude": 77.58550185,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0665336,
    "longitude": 77.5855823,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0669666,
    "longitude": 77.58566025,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.06628505,
    "longitude": 77.5842543,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.06368875,
    "longitude": 77.58340609999999,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06329405,
    "longitude": 77.58397345,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0634262,
    "longitude": 77.58339409999999,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.0611417,
    "longitude": 77.5868687,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.061612400000001,
    "longitude": 77.5867925,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.06160185,
    "longitude": 77.5865048,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.06194855,
    "longitude": 77.58385435,
    "signal_strength_dBm": -69
},
```

```
Pretty-print
{
    "longitude": 77.58434729999999,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.059757900000001,
    "longitude": 77.58525145,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.058977599999999,
    "longitude": 77.58517255,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.059125850000001,
    "longitude": 77.5850037,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06160075,
    "longitude": 77.58546605000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0612528,
    "longitude": 77.5849241,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0623527,
    "longitude": 77.5832494,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06274175,
    "longitude": 77.58266645,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0627651,
    "longitude": 77.58288515000001,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.062167200000001,
    "longitude": 77.58378959999999,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0612011,
    "longitude": 77.5864504,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06166125,
    "longitude": 77.5860865,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.061379800000001,
    "longitude": 77.58589215,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0621313,
    "longitude": 77.5801414,
    "signal_strength_dBm": -97
},
```

```
Pretty-print
{
    "latitude": 13.06224445,
    "longitude": 77.5803022,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.06200085,
    "longitude": 77.5851815,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06144755,
    "longitude": 77.57989334999999,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06173195,
    "longitude": 77.57997044999999,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.06144255,
    "longitude": 77.580051,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0610371,
    "longitude": 77.58288915,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.06114605,
    "longitude": 77.5830574,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.06065525,
    "longitude": 77.58301044999999,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.071181750000001,
    "longitude": 77.5769585,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0707,
    "longitude": 77.5773049,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0709801,
    "longitude": 77.5768291,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.059958349999999,
    "longitude": 77.5903257,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0598213,
    "longitude": 77.59027574999999,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0601165,
    "longitude": 77.59031934999999,
    "signal_strength_dBm": -68
```

Pretty-print

```
{  
    "latitude": 13.062435650000001,  
    "longitude": 77.58058460000001,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.062228300000001,  
    "longitude": 77.58056504999999,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.0616693,  
    "longitude": 77.58258935,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.06011255,  
    "longitude": 77.5870353,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.06067375,  
    "longitude": 77.58694445,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.06085245,  
    "longitude": 77.58638619999999,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.06056755,  
    "longitude": 77.58411945,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.0589198,  
    "longitude": 77.59202884999999,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.0589577,  
    "longitude": 77.59185794999999,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.05915765,  
    "longitude": 77.59204249999999,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.0592617,  
    "longitude": 77.58078119999999,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.0589163,  
    "longitude": 77.58089000000001,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.05899775,  
    "longitude": 77.5804809,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.05972375,  
    "longitude": 77.59059915,
```

Pretty-print

```
},
{
  "latitude": 13.05986955,
  "longitude": 77.59058315,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.05969035,
  "longitude": 77.58456705,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.05908195,
  "longitude": 77.58466975,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.05904145,
  "longitude": 77.58436185,
  "signal_strength_dBm": -99
},
{
  "latitude": 13.061608499999998,
  "longitude": 77.5813986,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0612914,
  "longitude": 77.58143075000001,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.0617202,
  "longitude": 77.58154110000001,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.0707633,
  "longitude": 77.57803625,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.060402400000001,
  "longitude": 77.5828437,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.05899595,
  "longitude": 77.58379694999999,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.059044,
  "longitude": 77.58376865,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.062221950000001,
  "longitude": 77.5811642,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.06208155,
  "longitude": 77.5816446,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.06208985,
```

```
Pretty-print
-----
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0604029,
    "longitude": 77.58446325,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0602305,
    "longitude": 77.5847613,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.058959699999999,
    "longitude": 77.58381295000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05897835,
    "longitude": 77.58386275000001,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0590012,
    "longitude": 77.58405590000001,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.05924855,
    "longitude": 77.5903891,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.0594527,
    "longitude": 77.59024704999999,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.05891605,
    "longitude": 77.59017035,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.062216750000001,
    "longitude": 77.5859047,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.060362600000001,
    "longitude": 77.58101775,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06064325,
    "longitude": 77.58114675,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.060714350000001,
    "longitude": 77.5804162,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.059344549999999,
    "longitude": 77.58378865,
    "signal_strength_dBm": -79
},
```

```
Pretty-print
{
    "longitude": 77.58370260000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0630658,
    "longitude": 77.5831122,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06070245,
    "longitude": 77.58144495,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.06061905,
    "longitude": 77.5817031,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.060076,
    "longitude": 77.5809102,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.06041635,
    "longitude": 77.5803186,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.05975400000002,
    "longitude": 77.58425805,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.05940444999999,
    "longitude": 77.58714995,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.05976115,
    "longitude": 77.58084265,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0601411,
    "longitude": 77.5802102,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.0593065,
    "longitude": 77.58683085000001,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.06086105,
    "longitude": 77.57974540000001,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.06106705,
    "longitude": 77.57979015000001,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06020535,
    "longitude": 77.58553545000001,
    "signal_strength_dBm": -47
},
```

```
Pretty-print
{
    "latitude": 13.06193995,
    "longitude": 77.5859942,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.0603004,
    "longitude": 77.58773195,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0599896,
    "longitude": 77.5875315,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.062451450000001,
    "longitude": 77.58401574999999,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0628055,
    "longitude": 77.58428195,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.059041050000001,
    "longitude": 77.59156175000001,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.0592077,
    "longitude": 77.59125325,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.05931595,
    "longitude": 77.59144075,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0588219,
    "longitude": 77.59137720000001,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06027675,
    "longitude": 77.5889305,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0606986,
    "longitude": 77.58832375,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06036955,
    "longitude": 77.58877385,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.061112600000001,
    "longitude": 77.5811441,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.06098225,
    "longitude": 77.5815758,
    "signal_strength_dBm": -102
```

Pretty-print

```
{  
    "latitude": 13.06288555,  
    "longitude": 77.58454875000001,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.0693442,  
    "longitude": 77.5790736,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.06896025,  
    "longitude": 77.57940825,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.05172715,  
    "longitude": 77.59338525,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.053492899999998,  
    "longitude": 77.5935968,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.05442525,  
    "longitude": 77.59353595,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.0548191,  
    "longitude": 77.5930148,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.05476185,  
    "longitude": 77.59324434999999,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.05514445,  
    "longitude": 77.59323245,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.056909950000001,  
    "longitude": 77.59348195,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.056270600000001,  
    "longitude": 77.5934726,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.08190085,  
    "longitude": 77.5933471,  
    "signal_strength_dBm": -51  
},  
{  
    "latitude": 13.08150025,  
    "longitude": 77.59328719999999,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.0530532,  
    "longitude": 77.59360634999999,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.0530532,  
    "longitude": 77.59360634999999,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.0527457,
  "longitude": 77.59358119999999,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0845744,
  "longitude": 77.59421955,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.08364915,
  "longitude": 77.59385685000001,
  "signal_strength_dBm": -77
},
{
  "latitude": 13.08536025,
  "longitude": 77.59452885,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.07311325,
  "longitude": 77.59275205,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.07151845,
  "longitude": 77.59285625,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.08605354999999,
  "longitude": 77.5947998,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.0903213,
  "longitude": 77.5965588,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.08994165,
  "longitude": 77.59643785,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.0893406,
  "longitude": 77.59621335,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.05366005,
  "longitude": 77.59341445,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.05372525,
  "longitude": 77.5929175,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.05356795,
  "longitude": 77.59337024999999,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.0541924,
```

```
Pretty-print
-----
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0674519,
    "longitude": 77.59314445,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0665488,
    "longitude": 77.5932328,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.074311,
    "longitude": 77.59271910000001,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.073713,
    "longitude": 77.5927271,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.0645131,
    "longitude": 77.5933308,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.063646550000001,
    "longitude": 77.59335305,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0557601,
    "longitude": 77.59347005000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0554796,
    "longitude": 77.59347650000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.05814985,
    "longitude": 77.59350015000001,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.05757185,
    "longitude": 77.59349,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.088601950000001,
    "longitude": 77.59591545,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.06243285,
    "longitude": 77.59317304999999,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.062495550000001,
    "longitude": 77.59317095,
    "signal_strength_dBm": -59
},
{
```

```
Pretty-print
{
    "longitude": 77.5929732,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.08242525,
    "longitude": 77.59346310000001,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.052375999999999,
    "longitude": 77.5935291,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.08789455,
    "longitude": 77.59561339999999,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.065519949999999,
    "longitude": 77.5933031,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0829414,
    "longitude": 77.59360465,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.086960049999998,
    "longitude": 77.5951955,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0805827,
    "longitude": 77.59321015,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.07858055,
    "longitude": 77.59303495,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0762083,
    "longitude": 77.5928242,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.07486545,
    "longitude": 77.59272555,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.090966850000001,
    "longitude": 77.59673155,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06935185,
    "longitude": 77.5930011,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.06813075,
    "longitude": 77.59308064999999,
    "signal_strength_dBm": -58
},
```

```
Pretty-print
{
    "latitude": 13.051732999999999,
    "longitude": 77.59325425,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0626083,
    "longitude": 77.5934084,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.061599999999999,
    "longitude": 77.5934614,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.058729750000001,
    "longitude": 77.5928864,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0584238,
    "longitude": 77.59325355,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.05877605,
    "longitude": 77.5932568,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.06046325,
    "longitude": 77.59351475,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.060086850000001,
    "longitude": 77.59352150000001,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0906789,
    "longitude": 77.59665975,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.05196535,
    "longitude": 77.5931913,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.066399050000001,
    "longitude": 77.5968276,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06189855,
    "longitude": 77.5725823,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.06170805,
    "longitude": 77.57290975000001,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06269065,
    "longitude": 77.57312529999999,
    "signal_strength_dBm": -73
```

Pretty-print

```
{  
    "latitude": 13.06211495,  
    "longitude": 77.57227565,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.06204975,  
    "longitude": 77.5739304,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.06210575,  
    "longitude": 77.5738645,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.062429999999999,  
    "longitude": 77.57424655,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.062836449999999,  
    "longitude": 77.5745484,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.062967350000001,  
    "longitude": 77.57459385,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.06298765,  
    "longitude": 77.57443045,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.0621057,  
    "longitude": 77.57417475,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.0621838,  
    "longitude": 77.5743104,  
    "signal_strength_dBm": -56  
},  
{  
    "latitude": 13.0624003,  
    "longitude": 77.57467425,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.062722950000001,  
    "longitude": 77.57515315,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.06291005,  
    "longitude": 77.57516095,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.062874449999999,  
    "longitude": 77.5753688,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.0629662,  
    "longitude": 77.57490295,  
    "signal_strength_dBm": -74  
}
```

Pretty-print

```
},
{
  "latitude": 13.0630338,
  "longitude": 77.57415415,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.06321494999999,
  "longitude": 77.5742814,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.0628657,
  "longitude": 77.5742707,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.06296365,
  "longitude": 77.57471945,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.0628358,
  "longitude": 77.57481329999999,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.0626528,
  "longitude": 77.57488545,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.06771309999999,
  "longitude": 77.5892729,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.06777604999999,
  "longitude": 77.58921495,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.0679754,
  "longitude": 77.58880740000001,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.06829965,
  "longitude": 77.5882132,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.0701295,
  "longitude": 77.58673435,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.0698005,
  "longitude": 77.58628089999999,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.0669061,
  "longitude": 77.59070235,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.06698725,
```

```
Pretty-print
-----
{"signal_strength_dBm": -56
},
{
  "latitude": 13.06680265,
  "longitude": 77.5909,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.0664269,
  "longitude": 77.59071635000001,
  "signal_strength_dBm": -41
},
{
  "latitude": 13.0587499,
  "longitude": 77.5916795,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.0592391,
  "longitude": 77.591749,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.070386599999999,
  "longitude": 77.5872602,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.070399649999999,
  "longitude": 77.58719245,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.0703198,
  "longitude": 77.58740205000001,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.0703691,
  "longitude": 77.5873113,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.068475750000001,
  "longitude": 77.5879961,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.068432999999999,
  "longitude": 77.58785295,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.07016745,
  "longitude": 77.58752515,
  "signal_strength_dBm": -41
},
{
  "latitude": 13.069942000000001,
  "longitude": 77.58762680000001,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.0662849,
  "longitude": 77.5919107,
  "signal_strength_dBm": -93
},
```

```
Pretty-print
{
    "longitude": 77.59183825,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.06625605,
    "longitude": 77.5918409,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.06648435,
    "longitude": 77.59176590000001,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.066499199999999,
    "longitude": 77.5917015,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.066411200000001,
    "longitude": 77.59180075,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.06666225,
    "longitude": 77.59183535,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.06625245,
    "longitude": 77.59206275,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0703709,
    "longitude": 77.5870798,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.07023845,
    "longitude": 77.5868871,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0685898,
    "longitude": 77.58797229999999,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.068832449999999,
    "longitude": 77.58791515,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0704268,
    "longitude": 77.5871102,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.07043875,
    "longitude": 77.58718855000001,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0694053,
    "longitude": 77.5877686,
    "signal_strength_dBm": -48
},
```

```
Pretty-print
{
    "latitude": 13.0661927,
    "longitude": 77.59272795,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.06619865,
    "longitude": 77.592596,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0671955,
    "longitude": 77.59020724999999,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0674587,
    "longitude": 77.58974825,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.066538399999999,
    "longitude": 77.591503,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06663145,
    "longitude": 77.5912438,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.066189399999999,
    "longitude": 77.5929825,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.066188050000001,
    "longitude": 77.59288705,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.06597545,
    "longitude": 77.59304425,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.066613400000001,
    "longitude": 77.5929841,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.067642,
    "longitude": 77.589387,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.05417175,
    "longitude": 77.58201635,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.05437145,
    "longitude": 77.58199715,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.05430205,
    "longitude": 77.58181264999999,
    "signal_strength_dBm": -65
```

Pretty-print

```
{  
    "latitude": 13.05191305,  
    "longitude": 77.58011335,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.052029950000001,  
    "longitude": 77.579871,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.0523957,  
    "longitude": 77.5791839,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.0524406,  
    "longitude": 77.5791007,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.052681849999999,  
    "longitude": 77.57827850000001,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.05323295,  
    "longitude": 77.57894455,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.05275565,  
    "longitude": 77.57849870000001,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.052875449999998,  
    "longitude": 77.57507555000001,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.05348705,  
    "longitude": 77.57869005,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.0529165,  
    "longitude": 77.57749895,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.05342235,  
    "longitude": 77.5763681,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.053347500000001,  
    "longitude": 77.57650849999999,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.0542787,  
    "longitude": 77.5791033,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.0544953,  
    "longitude": 77.57902155,  
    "signal_strength_dBm": -43  
}
```

Pretty-print

```
},
{
  "latitude": 13.0542377,
  "longitude": 77.57958325,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.05420475,
  "longitude": 77.57559095,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.053776899999999,
  "longitude": 77.57543815,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.0537075,
  "longitude": 77.57589405,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.053982900000001,
  "longitude": 77.57824600000001,
  "signal_strength_dBm": -58
},
{
  "latitude": 13.053909,
  "longitude": 77.5779687,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.05422205,
  "longitude": 77.57785475,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.0549092,
  "longitude": 77.57669634999999,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0576203,
  "longitude": 77.5900879,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.057643899999999,
  "longitude": 77.58994275,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.06893385,
  "longitude": 77.57858345,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.06530185,
  "longitude": 77.59320405,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.065724849999999,
  "longitude": 77.5931846,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.066985899999999,
```

```
Pretty-print
-----
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0669191,
    "longitude": 77.58511179999999,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.05709055,
    "longitude": 77.59011305,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.06669995,
    "longitude": 77.59111745,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.066743800000001,
    "longitude": 77.59102715,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.066412750000001,
    "longitude": 77.5909849,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05328965,
    "longitude": 77.5934876,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06093265,
    "longitude": 77.5933832,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.059511350000001,
    "longitude": 77.59340365,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0819832,
    "longitude": 77.59325095,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.060936649999999,
    "longitude": 77.5934935,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0657756,
    "longitude": 77.59333985,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.06544625,
    "longitude": 77.59334935,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0514965,
    "longitude": 77.59351079999999,
    "signal_strength_dBm": -106
},
{
```

```
Pretty-print
{
    "longitude": 77.5930169,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.049335150000001,
    "longitude": 77.5928743,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.050102899999999,
    "longitude": 77.59273934999999,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.051093999999999,
    "longitude": 77.59298265,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0553035,
    "longitude": 77.58225955,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.055270199999999,
    "longitude": 77.58246455,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0551212,
    "longitude": 77.5823933,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.055368600000001,
    "longitude": 77.58185925000001,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0553361,
    "longitude": 77.5817605,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05539305,
    "longitude": 77.58198155,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.055594150000001,
    "longitude": 77.58194445000001,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0563742,
    "longitude": 77.57899985,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.05642855,
    "longitude": 77.57888695,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.05670755,
    "longitude": 77.57908685000001,
    "signal_strength_dBm": -110
},
```

```
Pretty-print
{
    "latitude": 13.05663365,
    "longitude": 77.57846119999999,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.0566789,
    "longitude": 77.57836485,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.056861900000001,
    "longitude": 77.57850400000001,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0566774,
    "longitude": 77.57786999999999,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.056776849999999,
    "longitude": 77.5781478,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0569663,
    "longitude": 77.57772795,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.0575538,
    "longitude": 77.57845405,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.05757505,
    "longitude": 77.57885715,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.0572414,
    "longitude": 77.57869305,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.05820205,
    "longitude": 77.5791264,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0581172,
    "longitude": 77.57995735,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.05830465,
    "longitude": 77.57948035,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.057610350000001,
    "longitude": 77.57948055,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0584265,
    "longitude": 77.57983325000001,
    "signal_strength_dBm": -62
```

Pretty-print

```
{  
    "latitude": 13.06607025,  
    "longitude": 77.5981458,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.0666745,  
    "longitude": 77.59565094999999,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.062631450000001,  
    "longitude": 77.59277560000001,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.0626885,  
    "longitude": 77.5927189,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.062062050000002,  
    "longitude": 77.5927901,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.0627988,  
    "longitude": 77.59244050000001,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.06285905,  
    "longitude": 77.59237305,  
    "signal_strength_dBm": -44  
},  
{  
    "latitude": 13.06277125,  
    "longitude": 77.59255110000001,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.0626572,  
    "longitude": 77.5924514,  
    "signal_strength_dBm": -68  
},  
{  
    "latitude": 13.0621209,  
    "longitude": 77.59247640000001,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.06242595,  
    "longitude": 77.59214815,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.06202885,  
    "longitude": 77.59216194999999,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.06239785,  
    "longitude": 77.59183164999999,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.06205395,  
    "longitude": 77.59163665,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.06205395,  
    "longitude": 77.59163665,  
    "signal_strength_dBm": -71  
}
```

Pretty-print

```
},
{
  "latitude": 13.0625945,
  "longitude": 77.5911764,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.06217915,
  "longitude": 77.5910771,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.0629675,
  "longitude": 77.5910901,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.06308525,
  "longitude": 77.59129375,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.0632184,
  "longitude": 77.5914863,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.0633318,
  "longitude": 77.59117555,
  "signal_strength_dBm": -99
},
{
  "latitude": 13.06330425,
  "longitude": 77.59134614999999,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.0633607,
  "longitude": 77.59130185000001,
  "signal_strength_dBm": -100
},
{
  "latitude": 13.06327625,
  "longitude": 77.5914992,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.0631904,
  "longitude": 77.59163935000001,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0632442,
  "longitude": 77.5916494,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.063139199999998,
  "longitude": 77.59180420000001,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06301155,
  "longitude": 77.5916026,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.062706850000001,
```

```
Pretty-print
-----
    "signal_strength_dBm": -63
},
{
    "latitude": 13.06273495,
    "longitude": 77.5918565,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06277205,
    "longitude": 77.5921315,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0635507,
    "longitude": 77.59057965,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.063466049999999,
    "longitude": 77.59055665,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.063326199999999,
    "longitude": 77.5905199,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.06274775,
    "longitude": 77.59041665000001,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0622081,
    "longitude": 77.59054015000001,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06230115,
    "longitude": 77.5902042,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0631346,
    "longitude": 77.5907136,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.06259495,
    "longitude": 77.5908371,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.06321405,
    "longitude": 77.5909719,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0621092,
    "longitude": 77.5908964,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06237165,
    "longitude": 77.5899493,
    "signal_strength_dBm": -102
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.58993495,
    "signal_strength_dBm": -96
},
{
    "longitude": 77.58970625,
    "signal_strength_dBm": -79
},
{
    "longitude": 77.5892154,
    "signal_strength_dBm": -41
},
{
    "longitude": 77.58943500000001,
    "signal_strength_dBm": -109
},
{
    "longitude": 77.59325955,
    "signal_strength_dBm": -110
},
{
    "longitude": 77.5932602,
    "signal_strength_dBm": -60
},
{
    "longitude": 77.5927614,
    "signal_strength_dBm": -46
},
{
    "longitude": 77.59268335,
    "signal_strength_dBm": -66
},
{
    "longitude": 77.59260230000001,
    "signal_strength_dBm": -83
},
{
    "longitude": 77.5927815,
    "signal_strength_dBm": -103
},
```

```
Pretty-print
{
    "latitude": 13.0593362,
    "longitude": 77.59250305,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.059258750000001,
    "longitude": 77.59305085,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.05923455,
    "longitude": 77.5932206,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05956145,
    "longitude": 77.59299095,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.059371200000001,
    "longitude": 77.59325885000001,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.05937655,
    "longitude": 77.59218680000001,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0594259,
    "longitude": 77.5920691,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0593586,
    "longitude": 77.59232755,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0591078,
    "longitude": 77.5923272,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0588365,
    "longitude": 77.59240464999999,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0588879,
    "longitude": 77.5921728,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.059479,
    "longitude": 77.59205195000001,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.05962514999999,
    "longitude": 77.5914491,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05962845,
    "longitude": 77.59208165000001,
    "signal_strength_dBm": -72
```

Pretty-print

```
{  
    "latitude": 13.0633718,  
    "longitude": 77.5880064,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.0633751,  
    "longitude": 77.5891245,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.0635273,  
    "longitude": 77.58860179999999,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.06320975,  
    "longitude": 77.58860304999999,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.06353395,  
    "longitude": 77.58967385,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.0632089,  
    "longitude": 77.58961769999999,  
    "signal_strength_dBm": -44  
},  
{  
    "latitude": 13.06304355,  
    "longitude": 77.58909625,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.06304515,  
    "longitude": 77.5883671,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.0628852,  
    "longitude": 77.58860435,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.062882250000001,  
    "longitude": 77.58956135,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.0627237,  
    "longitude": 77.58849025,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.0627245,  
    "longitude": 77.58865655,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.062723550000001,  
    "longitude": 77.5893917,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.06272435,  
    "longitude": 77.58885005,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.062724,
  "longitude": 77.58912075,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.0623276,
  "longitude": 77.5889335,
  "signal_strength_dBm": -55
},
{
  "latitude": 13.06184815,
  "longitude": 77.58898485,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.062244549999999,
  "longitude": 77.5891721,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.0589104,
  "longitude": 77.5925388,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.05896585,
  "longitude": 77.59286225,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.059066900000001,
  "longitude": 77.59325815,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.058913350000001,
  "longitude": 77.59321084999999,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.059673199999999,
  "longitude": 77.59237485,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.058680800000001,
  "longitude": 77.5920071,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0584784,
  "longitude": 77.5918042,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.0583517,
  "longitude": 77.59244050000001,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06003175,
  "longitude": 77.59091315,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.0594205,
```

```
Pretty-print
-----
  "signal_strength_dBm": -79
},
{
  "latitude": 13.05961935,
  "longitude": 77.59086525000001,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.05948035,
  "longitude": 77.59113155,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.063738,
  "longitude": 77.5855408,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.06360355,
  "longitude": 77.585373,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.063885599999999,
  "longitude": 77.58573045,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06399195,
  "longitude": 77.5858676,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.064157250000001,
  "longitude": 77.5860807,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.0645688,
  "longitude": 77.5852898,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.064261550000001,
  "longitude": 77.5862152,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.064104100000002,
  "longitude": 77.5862912,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.064490150000001,
  "longitude": 77.58619239999999,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.06405335,
  "longitude": 77.58653269999999,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0649406,
  "longitude": 77.58610145,
  "signal_strength_dBm": -68
},
{
```

```
Pretty-print
{
    "longitude": 77.58556594999999,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0653593,
    "longitude": 77.58602395,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.065471,
    "longitude": 77.58562245,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0655609,
    "longitude": 77.58623134999999,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06553745,
    "longitude": 77.58591150000001,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.0656397,
    "longitude": 77.58508695,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.065388200000001,
    "longitude": 77.58487765,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0658754,
    "longitude": 77.58503999999999,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.06516255,
    "longitude": 77.5846899,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.064751000000001,
    "longitude": 77.5854808,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0651285,
    "longitude": 77.58423825,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.065159600000001,
    "longitude": 77.58447215000001,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.06479875,
    "longitude": 77.58443865,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.065642650000001,
    "longitude": 77.58327765,
    "signal_strength_dBm": -95
},
```

```
Pretty-print
{
    "latitude": 13.063943049999999,
    "longitude": 77.58558595,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.064145199999999,
    "longitude": 77.58532745,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0643601,
    "longitude": 77.5850419,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.06452535,
    "longitude": 77.58482029999999,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0652601,
    "longitude": 77.5865235,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0639803,
    "longitude": 77.58676704999999,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0642625,
    "longitude": 77.5867055,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.06378315,
    "longitude": 77.58882295000001,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.06405835,
    "longitude": 77.588843,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.06444905,
    "longitude": 77.58889005,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.064711899999999,
    "longitude": 77.5889584,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.06461385,
    "longitude": 77.58851419999999,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.064844,
    "longitude": 77.58900285,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06484745,
    "longitude": 77.58904715,
    "signal_strength_dBm": -48
```

Pretty-print

```
{  
    "latitude": 13.0637029,  
    "longitude": 77.58734684999999,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.06352475,  
    "longitude": 77.58738084999999,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.063205750000002,  
    "longitude": 77.58744175,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.062531750000002,  
    "longitude": 77.5875523,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.063042450000001,  
    "longitude": 77.58763859999999,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.0630439,  
    "longitude": 77.5879673,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.062801499999999,  
    "longitude": 77.58802415,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.062444855,  
    "longitude": 77.58786965,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.0622403,  
    "longitude": 77.58794535000001,  
    "signal_strength_dBm": -68  
},  
{  
    "latitude": 13.06218025,  
    "longitude": 77.5877265,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.0620014,  
    "longitude": 77.58761915,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.06227375,  
    "longitude": 77.58813860000001,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.06256415,  
    "longitude": 77.58829175,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.0601787,  
    "longitude": 77.59061355,  
    "signal_strength_dBm": -99  
}
```

Pretty-print

```
},
{
  "latitude": 13.065474049999999,
  "longitude": 77.59417575,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.065480749999999,
  "longitude": 77.59433525,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.0653058,
  "longitude": 77.5949611,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.0653035,
  "longitude": 77.59501230000001,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.06531685,
  "longitude": 77.59507135,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.0653695,
  "longitude": 77.5951216,
  "signal_strength_dBm": -79
},
{
  "latitude": 13.0653385,
  "longitude": 77.5953895,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.06526135,
  "longitude": 77.5957338,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.0651665,
  "longitude": 77.59609835,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.06508165,
  "longitude": 77.59643885,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06494345,
  "longitude": 77.59337495,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.0642613,
  "longitude": 77.59339845,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.0644867,
  "longitude": 77.59384705,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.0643897,
```

```
Pretty-print
-----
    "signal_strength_dBm": -73
},
{
    "latitude": 13.06437175,
    "longitude": 77.59476325,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.0644045,
    "longitude": 77.59486874999999,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05689465,
    "longitude": 77.57088329999999,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.05670784999999,
    "longitude": 77.57081554999999,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.07174465,
    "longitude": 77.57431685,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0714907,
    "longitude": 77.5745518,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.068787050000001,
    "longitude": 77.56965615,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0687087,
    "longitude": 77.56992435000001,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0711912,
    "longitude": 77.5744525,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.07090655,
    "longitude": 77.57436115,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0706266,
    "longitude": 77.57427305,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.0707593,
    "longitude": 77.57352005,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.07036074999999,
    "longitude": 77.57419795,
    "signal_strength_dBm": -100
},
```

```
Pretty-print
{
    "longitude": 77.57457095000001,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0705046,
    "longitude": 77.5723292,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0706279,
    "longitude": 77.57248385,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.070745599999999,
    "longitude": 77.57268385,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.07048315,
    "longitude": 77.57347379999999,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.07021495,
    "longitude": 77.57416025,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.069407649999999,
    "longitude": 77.57102205000001,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.06892165,
    "longitude": 77.57231615,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.069858100000001,
    "longitude": 77.5718573,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.06974645,
    "longitude": 77.57215565,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.06933315,
    "longitude": 77.57327955,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.06935485,
    "longitude": 77.5736292,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06911735,
    "longitude": 77.5738828,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.06899295,
    "longitude": 77.57424950000001,
    "signal_strength_dBm": -53
},
```

```
Pretty-print
{
    "latitude": 13.06953795,
    "longitude": 77.5735449,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06936415,
    "longitude": 77.57406069999999,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06959995,
    "longitude": 77.57371705,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.069342500000001,
    "longitude": 77.572008,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.069241250000001,
    "longitude": 77.5728947,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.06910555,
    "longitude": 77.57262879999999,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0684109,
    "longitude": 77.57465245,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.06827945,
    "longitude": 77.57501780000001,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0685258,
    "longitude": 77.57491805000001,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.068501300000001,
    "longitude": 77.57529335000001,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.06815315,
    "longitude": 77.57515205,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.070104149999999,
    "longitude": 77.5726409,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.069797300000001,
    "longitude": 77.57351295000001,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.069986,
    "longitude": 77.5729843,
    "signal_strength_dBm": -57
```

Pretty-print

```
{  
    "latitude": 13.06991135,  
    "longitude": 77.57319465,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0695158,  
    "longitude": 77.57279235,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.0696351,  
    "longitude": 77.5730447,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.06964015,  
    "longitude": 77.5724508,  
    "signal_strength_dBm": -68  
},  
{  
    "latitude": 13.0692307,  
    "longitude": 77.57230085,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.06975255,  
    "longitude": 77.57267064999999,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.0693801,  
    "longitude": 77.57252645,  
    "signal_strength_dBm": -44  
},  
{  
    "latitude": 13.069139,  
    "longitude": 77.57090009999999,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.06861335,  
    "longitude": 77.56939075,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.0688575,  
    "longitude": 77.56939915,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.0680405,  
    "longitude": 77.5719391,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.0679765,  
    "longitude": 77.57205909999999,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.06788725,  
    "longitude": 77.5722197,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.0678334,  
    "longitude": 77.57232235000001,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.06779055,
  "longitude": 77.5724488,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.06773235,
  "longitude": 77.5726758,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.067852250000001,
  "longitude": 77.57257154999999,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06805345,
  "longitude": 77.57264825,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.068213,
  "longitude": 77.5725591,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.06791785,
  "longitude": 77.5728705,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0683531,
  "longitude": 77.57297925,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.06863255,
  "longitude": 77.57220025,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.0721727,
  "longitude": 77.5674034,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0723284,
  "longitude": 77.5673089,
  "signal_strength_dBm": -94
},
{
  "latitude": 13.07090175,
  "longitude": 77.56816425,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.071285,
  "longitude": 77.56793625,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.06952595,
  "longitude": 77.56896145,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.069749250000001,
```

```
Pretty-print
-----
    "signal_strength_dBm": -47
},
{
    "latitude": 13.06929685,
    "longitude": 77.56909205,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.068036450000001,
    "longitude": 77.56960985,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.064584700000001,
    "longitude": 77.57136375,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.06493015,
    "longitude": 77.57116435,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.06319025,
    "longitude": 77.57312085000001,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0634848,
    "longitude": 77.5731918,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.063258300000001,
    "longitude": 77.57323815000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.06342535,
    "longitude": 77.57262030000001,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.06356095,
    "longitude": 77.57206235000001,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06357955,
    "longitude": 77.57199685,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.06222241,
    "longitude": 77.5737212,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.062385299999999,
    "longitude": 77.57352605,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0628445,
    "longitude": 77.57375965,
    "signal_strength_dBm": -64
},
{
```

```
Pretty-print
[{"longitude": 77.57379470000001, "signal_strength_dBm": -45}, {"longitude": 77.57269314999999, "signal_strength_dBm": -100}, {"longitude": 77.57375715, "signal_strength_dBm": -109}, {"longitude": 77.57444505000001, "signal_strength_dBm": -54}, {"longitude": 77.57463494999999, "signal_strength_dBm": -95}, {"longitude": 77.57463469999999, "signal_strength_dBm": -75}, {"longitude": 77.5747976, "signal_strength_dBm": -62}, {"longitude": 77.5727804, "signal_strength_dBm": -72}, {"longitude": 77.5733827, "signal_strength_dBm": -50}, {"longitude": 77.57396270000001, "signal_strength_dBm": -82}, {"longitude": 77.57288335, "signal_strength_dBm": -80}, {"longitude": 77.5734457, "signal_strength_dBm": -75}, {"longitude": 77.5740519, "signal_strength_dBm": -95}, {"longitude": 77.5723912, "signal_strength_dBm": -88}],
```

```
Pretty-print
{
    "latitude": 13.065166900000001,
    "longitude": 77.57257734999999,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.06514415,
    "longitude": 77.57281785,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.06528555,
    "longitude": 77.57275849999999,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.06499335,
    "longitude": 77.57286920000001,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0664898,
    "longitude": 77.57242855000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06621625,
    "longitude": 77.57252435000001,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.06591635,
    "longitude": 77.5734519,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0660387,
    "longitude": 77.57324704999999,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.065613899999999,
    "longitude": 77.57239765,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.06573545,
    "longitude": 77.57266375,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.066113,
    "longitude": 77.57287275,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.06601475,
    "longitude": 77.57269529999999,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.066204249999998,
    "longitude": 77.5730589,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.065759700000001,
    "longitude": 77.57301720000001,
    "signal_strength_dBm": -48
```

Pretty-print

```
{  
    "latitude": 13.06686595,  
    "longitude": 77.57258820000001,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.0665954,  
    "longitude": 77.5728976,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.06717115,  
    "longitude": 77.57271515,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.06725865,  
    "longitude": 77.57304819999999,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.0673623,  
    "longitude": 77.5726205,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.06715045,  
    "longitude": 77.57366859999999,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.06710495000001,  
    "longitude": 77.5737381,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.06718504999999,  
    "longitude": 77.57347014999999,  
    "signal_strength_dBm": -101  
},  
{  
    "latitude": 13.0678383,  
    "longitude": 77.573498,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.0677673,  
    "longitude": 77.57377414999999,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.066586699999998,  
    "longitude": 77.5741489,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.0669527,  
    "longitude": 77.57406929999999,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.066199099999999,  
    "longitude": 77.573858,  
    "signal_strength_dBm": -56  
},  
{  
    "latitude": 13.067692350000002,  
    "longitude": 77.574272,
```

Pretty-print

```
},
{
  "latitude": 13.0678144,
  "longitude": 77.57440915,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.066763850000001,
  "longitude": 77.57436985,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.06611,
  "longitude": 77.57418684999999,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.06702385,
  "longitude": 77.5744266,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.06563625,
  "longitude": 77.57425035,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.0655654,
  "longitude": 77.57456255,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.06571325,
  "longitude": 77.57345185,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0657979,
  "longitude": 77.57358535,
  "signal_strength_dBm": -79
},
{
  "latitude": 13.0657224,
  "longitude": 77.57389595,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.0662984,
  "longitude": 77.57510669999999,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0665805,
  "longitude": 77.5754092,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0658694,
  "longitude": 77.57515595,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.065528950000001,
  "longitude": 77.57490870000001,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.06537825,
```

```
Pretty-print
-----
    "signal_strength_dBm": -102
},
{
    "latitude": 13.065607,
    "longitude": 77.5747442,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.06557134999999,
    "longitude": 77.57476510000001,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.06599359999999,
    "longitude": 77.57483855000001,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0667803,
    "longitude": 77.57504180000001,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.06728915,
    "longitude": 77.5751743,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0676363,
    "longitude": 77.57528195,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06730285,
    "longitude": 77.5754995,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0671564,
    "longitude": 77.57618595,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0670997,
    "longitude": 77.576358,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.067209250000001,
    "longitude": 77.57594309999999,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.06747975,
    "longitude": 77.576231,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.06789805,
    "longitude": 77.57624805,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.06765169999999,
    "longitude": 77.57651055,
    "signal_strength_dBm": -64
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.5770007,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0669485,
    "longitude": 77.57557765,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0669818,
    "longitude": 77.5756636,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06695824999999,
    "longitude": 77.5757799,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.07057805,
    "longitude": 77.57625195,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.07045335,
    "longitude": 77.5757667,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0703879,
    "longitude": 77.57535734999999,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.07068405,
    "longitude": 77.5758053,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.07103215,
    "longitude": 77.57651845000001,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.07104625,
    "longitude": 77.5763464,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.070894,
    "longitude": 77.57660974999999,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.07067485,
    "longitude": 77.5767628,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0700209,
    "longitude": 77.5772316,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06939225,
    "longitude": 77.57766665,
    "signal_strength_dBm": -108
},
```

```
Pretty-print
[{"latitude": 13.0694615, "longitude": 77.5774284, "signal_strength_dBm": -96}, {"latitude": 13.0672236, "longitude": 77.57836855, "signal_strength_dBm": -101}, {"latitude": 13.06786174999999, "longitude": 77.57874484999999, "signal_strength_dBm": -93}, {"latitude": 13.07041165, "longitude": 77.57675094999999, "signal_strength_dBm": -44}, {"latitude": 13.06984634999999, "longitude": 77.57594929999999, "signal_strength_dBm": -89}, {"latitude": 13.070226250000001, "longitude": 77.57648165, "signal_strength_dBm": -68}, {"latitude": 13.06985225, "longitude": 77.57694774999999, "signal_strength_dBm": -65}, {"latitude": 13.069296600000001, "longitude": 77.5771563, "signal_strength_dBm": -93}, {"latitude": 13.07002395, "longitude": 77.57641335, "signal_strength_dBm": -71}, {"latitude": 13.069391450000001, "longitude": 77.5768841, "signal_strength_dBm": -52}, {"latitude": 13.06974479999999, "longitude": 77.57660725, "signal_strength_dBm": -81}, {"latitude": 13.06971325, "longitude": 77.57616895000001, "signal_strength_dBm": -75}, {"latitude": 13.06877275, "longitude": 77.57811935, "signal_strength_dBm": -96}, {"latitude": 13.0682116, "longitude": 77.57766004999999, "signal_strength_dBm": -83}]
```

Pretty-print

```
{  
    "latitude": 13.0679136,  
    "longitude": 77.57696394999999,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.067726,  
    "longitude": 77.57719335,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.06850235,  
    "longitude": 77.57630325,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.0682467,  
    "longitude": 77.5765602,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.06850065,  
    "longitude": 77.57658255000001,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.068762,  
    "longitude": 77.57583045,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.06892615,  
    "longitude": 77.57548105000001,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.06883975,  
    "longitude": 77.57544075,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.06805065,  
    "longitude": 77.57678885,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.0685381,  
    "longitude": 77.5773423,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.0691025,  
    "longitude": 77.57786665,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.0690115,  
    "longitude": 77.57736564999999,  
    "signal_strength_dBm": -59  
},  
{  
    "latitude": 13.06870105000001,  
    "longitude": 77.57686365,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.06740765,  
    "longitude": 77.5767897,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.06733195,
  "longitude": 77.57655425,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.06775635,
  "longitude": 77.57675655,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.063175099999999,
  "longitude": 77.57573224999999,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0633828,
  "longitude": 77.57579229999999,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.06323235,
  "longitude": 77.57580145,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.06408295,
  "longitude": 77.5759619,
  "signal_strength_dBm": -94
},
{
  "latitude": 13.06437875,
  "longitude": 77.57617995,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.065966849999999,
  "longitude": 77.5773645,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.066256599999999,
  "longitude": 77.57748405000001,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.06613535,
  "longitude": 77.57736205,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.06537345,
  "longitude": 77.57690170000001,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.0657361,
  "longitude": 77.5763264,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.0657297,
  "longitude": 77.57616619999999,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.0653475,
```

```
Pretty-print
-----
    "signal_strength_dBm": -94
},
{
    "latitude": 13.065535,
    "longitude": 77.57537740000001,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.065622699999999,
    "longitude": 77.5752979,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.065976299999999,
    "longitude": 77.57540115,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.066526249999999,
    "longitude": 77.57559605,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.069998049999999,
    "longitude": 77.57887124999999,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0700333,
    "longitude": 77.5790928,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.06939165,
    "longitude": 77.57959805,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.06916635,
    "longitude": 77.57963434999999,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06897275,
    "longitude": 77.57951829999999,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0688747,
    "longitude": 77.58004775,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0690769,
    "longitude": 77.58072495,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.06959205,
    "longitude": 77.58050375,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.0696533,
    "longitude": 77.57937815,
    "signal_strength_dBm": -76
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.57608915,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0596496,
    "longitude": 77.57532789999999,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.05991505,
    "longitude": 77.5753814,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0597906,
    "longitude": 77.576011,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0581602,
    "longitude": 77.57266625,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0580255,
    "longitude": 77.5728454,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0588439,
    "longitude": 77.5728876,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05921125,
    "longitude": 77.5732529,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.05926475,
    "longitude": 77.5735399,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0590846,
    "longitude": 77.57344225,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0592663,
    "longitude": 77.57351135,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.05930725,
    "longitude": 77.57370515,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.059372750000001,
    "longitude": 77.5739126,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0594219,
    "longitude": 77.57402504999999,
    "signal_strength_dBm": -71
},
```

```
Pretty-print
{
    "latitude": 13.05948175,
    "longitude": 77.57423055,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0594872,
    "longitude": 77.57453709999999,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.05935745,
    "longitude": 77.57523345,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0592138,
    "longitude": 77.575187,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.059388049999999,
    "longitude": 77.57495275,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0587082,
    "longitude": 77.57420175,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.05859155,
    "longitude": 77.57471045,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.058155150000001,
    "longitude": 77.5743052,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.058742800000001,
    "longitude": 77.57448055,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.059348499999999,
    "longitude": 77.57465335,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.059578949999999,
    "longitude": 77.5747034,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.06014155,
    "longitude": 77.57479295,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.0600493,
    "longitude": 77.5747069,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.059911249999999,
    "longitude": 77.574757,
    "signal_strength_dBm": -60
```

Pretty-print

```
{  
    "latitude": 13.05999785,  
    "longitude": 77.57503009999999,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.05948385,  
    "longitude": 77.57655299999999,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.05914305,  
    "longitude": 77.57645195,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.05896699999999,  
    "longitude": 77.576401,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.05909475,  
    "longitude": 77.57615215000001,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.05898025,  
    "longitude": 77.57649230000001,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.05881164999999,  
    "longitude": 77.57632955,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.0586806,  
    "longitude": 77.5762675,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.058743400000001,  
    "longitude": 77.57619215,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0585945,  
    "longitude": 77.5762416,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.05880195,  
    "longitude": 77.57505425,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.05869925,  
    "longitude": 77.57502105,  
    "signal_strength_dBm": -56  
},  
{  
    "latitude": 13.05877239999999,  
    "longitude": 77.5747659,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.05841865,  
    "longitude": 77.57587075,  
}
```

Pretty-print

```
},
{
  "latitude": 13.058380150000001,
  "longitude": 77.57602325,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.0583741,
  "longitude": 77.57612735000001,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0583922,
  "longitude": 77.576165,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0584204,
  "longitude": 77.57656665,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.058289649999999,
  "longitude": 77.576845,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.058456849999999,
  "longitude": 77.5768664,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.05839345,
  "longitude": 77.57492400000001,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.0581807,
  "longitude": 77.5751449,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.05809215,
  "longitude": 77.57544379999999,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.0581695,
  "longitude": 77.5756184,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.058265800000001,
  "longitude": 77.57574869999999,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.05822705,
  "longitude": 77.57581834999999,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.05845325,
  "longitude": 77.57575065,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.0583957,
```

```
Pretty-print
-----
    "signal_strength_dBm": -89
},
{
    "latitude": 13.05794765,
    "longitude": 77.57602589999999,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05792939999999,
    "longitude": 77.5760815,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.057894600000001,
    "longitude": 77.57618595,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.057862700000001,
    "longitude": 77.57626335,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.057931100000001,
    "longitude": 77.5767685,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.05806875,
    "longitude": 77.57680265,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0579952,
    "longitude": 77.5768579,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.05794064999999,
    "longitude": 77.57653955,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.05760864999999,
    "longitude": 77.57655955,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.05756729999999,
    "longitude": 77.576617,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.05752935,
    "longitude": 77.576675,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05928845,
    "longitude": 77.57556835,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.05933385,
    "longitude": 77.5762805,
    "signal_strength_dBm": -105
},
```

```
Pretty-print
-----
{
    "longitude": 77.57588665,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.05913275,
    "longitude": 77.57588665,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0593112,
    "longitude": 77.5759028,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.05906865,
    "longitude": 77.5758812,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.0588988,
    "longitude": 77.57593184999999,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0588457,
    "longitude": 77.57592844999999,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.058738850000001,
    "longitude": 77.57590615000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.058797250000001,
    "longitude": 77.57601070000001,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0586631,
    "longitude": 77.57588735,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.05864485,
    "longitude": 77.57582790000001,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.05864395,
    "longitude": 77.57581845,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0587697,
    "longitude": 77.5760985,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.058997,
    "longitude": 77.57511695,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.0590632,
    "longitude": 77.5752793,
    "signal_strength_dBm": -102
},
```

```
Pretty-print
{
    "latitude": 13.05917425,
    "longitude": 77.57488760000001,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0593884,
    "longitude": 77.5740391,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.05930955,
    "longitude": 77.57436085,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.059135,
    "longitude": 77.57459245000001,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0592114,
    "longitude": 77.57380789999999,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05908845,
    "longitude": 77.57430585,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05895775,
    "longitude": 77.5748218,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0589282,
    "longitude": 77.57453345,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05905045,
    "longitude": 77.57402395,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.059263000000001,
    "longitude": 77.57407425,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.0588556,
    "longitude": 77.57397275,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0588364,
    "longitude": 77.57365905,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0585721,
    "longitude": 77.5739077,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0588902,
    "longitude": 77.57425155,
    "signal_strength_dBm": -107
```

Pretty-print

```
{  
    "latitude": 13.0589655,  
    "longitude": 77.57394099999999,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.058431800000001,  
    "longitude": 77.57322835,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.058606600000001,  
    "longitude": 77.57499075000001,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.0579584,  
    "longitude": 77.57306750000001,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.0579046,  
    "longitude": 77.57322945,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.05774305,  
    "longitude": 77.5737097,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.057673699999999,  
    "longitude": 77.5738552,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.0580149,  
    "longitude": 77.57393005,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.05762155,  
    "longitude": 77.5739194,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.057622349999999,  
    "longitude": 77.57395555,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.05781865,  
    "longitude": 77.57348495,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.0581012,  
    "longitude": 77.57344484999999,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.05935585,  
    "longitude": 77.57347684999999,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.05962515,  
    "longitude": 77.57351935,
```

Pretty-print

```
},
{
  "latitude": 13.05989205,
  "longitude": 77.57357830000001,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.060322450000001,
  "longitude": 77.57368825,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0606045,
  "longitude": 77.5737653,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.060549349999999,
  "longitude": 77.57339935,
  "signal_strength_dBm": -100
},
{
  "latitude": 13.061379200000001,
  "longitude": 77.57398825,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.06154495,
  "longitude": 77.57403525000001,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.0616208,
  "longitude": 77.57420295,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.06137515,
  "longitude": 77.5741449,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.061618150000001,
  "longitude": 77.57421695,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.06162435,
  "longitude": 77.57421665,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.0609021,
  "longitude": 77.57400855,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.06082885,
  "longitude": 77.57425649999999,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06056005,
  "longitude": 77.57430705,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06044625,
```

```
Pretty-print
-----
    "signal_strength_dBm": -62
},
{
    "latitude": 13.06078175,
    "longitude": 77.5749045,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06037135,
    "longitude": 77.57480145,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.0611678,
    "longitude": 77.57502165,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0612389,
    "longitude": 77.57506534999999,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.06116805,
    "longitude": 77.57508659999999,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06140909999999,
    "longitude": 77.57471785,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.060499,
    "longitude": 77.5745322,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.06093999999999,
    "longitude": 77.57453555000001,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0608435,
    "longitude": 77.57475885,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0608516,
    "longitude": 77.5738381,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06106795,
    "longitude": 77.57390215000001,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06102050000001,
    "longitude": 77.57367135,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.06004245000001,
    "longitude": 77.57361675,
    "signal_strength_dBm": -76
},
{
```

```
Pretty-print
{
    "longitude": 77.5733931,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.06078525,
    "longitude": 77.573544,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.059959150000001,
    "longitude": 77.5733931,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0598727,
    "longitude": 77.5737199,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0600949,
    "longitude": 77.5727887,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06003875,
    "longitude": 77.57303865,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0596327,
    "longitude": 77.57279955,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0596384,
    "longitude": 77.57312195,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.053372150000001,
    "longitude": 77.5758012,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.053106750000001,
    "longitude": 77.57628335,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0532885,
    "longitude": 77.57664804999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0532185,
    "longitude": 77.57681074999999,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.05296925,
    "longitude": 77.57661024999999,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0526533,
    "longitude": 77.57655249999999,
    "signal_strength_dBm": -41
},
```

```
Pretty-print
{
    "latitude": 13.0531599,
    "longitude": 77.5751784,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.05445525,
    "longitude": 77.577457,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.054426249999999,
    "longitude": 77.5771972,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0546712,
    "longitude": 77.57734135,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.053808400000001,
    "longitude": 77.576841,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0532716,
    "longitude": 77.5781025,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.0540028,
    "longitude": 77.57849845,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05542015,
    "longitude": 77.57935739999999,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.055609149999999,
    "longitude": 77.5794499,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.05604845,
    "longitude": 77.57968869999999,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0561291,
    "longitude": 77.57950844999999,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.05585795,
    "longitude": 77.57953995,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0544774,
    "longitude": 77.57880115,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.05460505,
    "longitude": 77.57888654999999,
    "signal_strength_dBm": -91
```

Pretty-print

```
{  
    "latitude": 13.05479665,  
    "longitude": 77.577417,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.05425635,  
    "longitude": 77.57865435,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.054472650000001,  
    "longitude": 77.57800044999999,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.053999300000001,  
    "longitude": 77.5801509,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.05429485,  
    "longitude": 77.5804414,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.05387305,  
    "longitude": 77.58046350000001,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.054786,  
    "longitude": 77.58061615,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.05493985,  
    "longitude": 77.5805223,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.05505825,  
    "longitude": 77.5799435,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.0551946,  
    "longitude": 77.57949205,  
    "signal_strength_dBm": -87  
},  
{  
    "latitude": 13.05509045,  
    "longitude": 77.57917810000001,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.054473300000002,  
    "longitude": 77.5802041,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.054826550000001,  
    "longitude": 77.58033535,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.051753699999999,  
    "longitude": 77.5748788,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.051210300000001,
  "longitude": 77.57485525000001,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.0509397,
  "longitude": 77.5749167,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.05802785,
  "longitude": 77.58717835,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.05774405,
  "longitude": 77.5875643,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.0667347,
  "longitude": 77.59541875,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.06681925,
  "longitude": 77.5951323,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.0654205,
  "longitude": 77.59455065,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.0599794,
  "longitude": 77.5940264,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.05990275,
  "longitude": 77.5946505,
  "signal_strength_dBm": -41
},
{
  "latitude": 13.0597695,
  "longitude": 77.59533175,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.0596153,
  "longitude": 77.5958172,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.05454885,
  "longitude": 77.59399694999999,
  "signal_strength_dBm": -100
},
{
  "latitude": 13.054463850000001,
  "longitude": 77.59454525,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.0554957,
```

```
Pretty-print
-----
    "signal_strength_dBm": -78
},
{
    "latitude": 13.066819500000001,
    "longitude": 77.59118375,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.06756165,
    "longitude": 77.59141020000001,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.06736045,
    "longitude": 77.5914746,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06717355,
    "longitude": 77.5912918,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06692295,
    "longitude": 77.59134829999999,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.06799309999999,
    "longitude": 77.5924857,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.06804575,
    "longitude": 77.5924198,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.0681943,
    "longitude": 77.59258885,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.06833085,
    "longitude": 77.5926211,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.06857975,
    "longitude": 77.5928137,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0683058,
    "longitude": 77.59243335,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.068493449999998,
    "longitude": 77.5924621,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0685922,
    "longitude": 77.59257025,
    "signal_strength_dBm": -78
},
```

```
Pretty-print
-----
{
    "longitude": 77.5927303,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0673932,
    "longitude": 77.5925083,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.06739675,
    "longitude": 77.59227365000001,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06739385,
    "longitude": 77.59221765000001,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.06736435,
    "longitude": 77.59213255,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0668761,
    "longitude": 77.5920289,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0670082,
    "longitude": 77.59191425,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0669187,
    "longitude": 77.5922748,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.066987000000001,
    "longitude": 77.59240835,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0670423,
    "longitude": 77.592472,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06708075,
    "longitude": 77.59294274999999,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0670422,
    "longitude": 77.59272315,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06622125,
    "longitude": 77.59237195,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0662339,
    "longitude": 77.5922466,
    "signal_strength_dBm": -51
},
```

```
Pretty-print
{
    "latitude": 13.0658356,
    "longitude": 77.5922544,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.06549245,
    "longitude": 77.59195645,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.065328449999999,
    "longitude": 77.59216585,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.06563895,
    "longitude": 77.59172835000001,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.065802300000001,
    "longitude": 77.59172025000001,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.066036,
    "longitude": 77.5917642,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.0655699,
    "longitude": 77.5915367,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.0656213,
    "longitude": 77.5912494,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0656683,
    "longitude": 77.5910375,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.065702550000001,
    "longitude": 77.59088365,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06573395,
    "longitude": 77.5907442,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0657437,
    "longitude": 77.59055955,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.0656261,
    "longitude": 77.59042005,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.06545365,
    "longitude": 77.59034224999999,
    "signal_strength_dBm": -55
}
```

Pretty-print

```
{  
    "latitude": 13.06531255,  
    "longitude": 77.590589,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.06534925,  
    "longitude": 77.59029095,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.065205299999999,  
    "longitude": 77.5909637,  
    "signal_strength_dBm": -69  
},  
{  
    "latitude": 13.065077299999999,  
    "longitude": 77.59136335,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.0649756,  
    "longitude": 77.59169955,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.065057549999999,  
    "longitude": 77.5916596,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.06494945,  
    "longitude": 77.5918444,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.0649157,  
    "longitude": 77.59197535,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.06486605,  
    "longitude": 77.59206925000001,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.0647508,  
    "longitude": 77.59219300000001,  
    "signal_strength_dBm": -56  
},  
{  
    "latitude": 13.064642500000001,  
    "longitude": 77.59227925,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.0645641,  
    "longitude": 77.59236875,  
    "signal_strength_dBm": -101  
},  
{  
    "latitude": 13.0644829,  
    "longitude": 77.5925722,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.065299249999999,  
    "longitude": 77.5930954,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.065205299999999,  
    "longitude": 77.5909637,  
    "signal_strength_dBm": -69  
},  
{  
    "latitude": 13.06534925,  
    "longitude": 77.59029095,  
    "signal_strength_dBm": -60  
},  
}
```

Pretty-print

```
},
{
  "latitude": 13.0654016,
  "longitude": 77.59297095,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.0652966,
  "longitude": 77.5928237,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.065138600000001,
  "longitude": 77.5927916,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.065098899999999,
  "longitude": 77.59275985,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.06513185,
  "longitude": 77.59261285,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.06517095,
  "longitude": 77.59241465,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.065197000000001,
  "longitude": 77.5922438,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.066207599999998,
  "longitude": 77.59250735,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.066215,
  "longitude": 77.592434,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.066081650000001,
  "longitude": 77.5924446,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.06588475,
  "longitude": 77.59243615,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.0657761,
  "longitude": 77.5924277,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.06566495,
  "longitude": 77.59243275,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.06554645,
```

Pretty-print

```
    "signal_strength_dBm": -90
},
{
    "latitude": 13.065435149999999,
    "longitude": 77.5924316,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0652996,
    "longitude": 77.59237235,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.0652081,
    "longitude": 77.5923471,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0657988,
    "longitude": 77.5926081,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06576815,
    "longitude": 77.59292605,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06498075,
    "longitude": 77.59271225,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.06546325,
    "longitude": 77.59171345,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.065339049999999,
    "longitude": 77.59169215,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.06521155,
    "longitude": 77.59167405,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.06532455,
    "longitude": 77.59156655000001,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06530385,
    "longitude": 77.59109715,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0644622,
    "longitude": 77.5905842,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.064449100000001,
    "longitude": 77.59080935,
    "signal_strength_dBm": -79
},
```

```
Pretty-print
-----
{
    "longitude": 77.59131005,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0637086,
    "longitude": 77.59117069999999,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06363765,
    "longitude": 77.5910826,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.0644619,
    "longitude": 77.59166139999999,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.06365905,
    "longitude": 77.5917827,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.0641196,
    "longitude": 77.59173659999999,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.064095949999999,
    "longitude": 77.59196585,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.062799349999999,
    "longitude": 77.5931609,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0629339,
    "longitude": 77.59279040000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06273805,
    "longitude": 77.59267595,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0630761,
    "longitude": 77.59240779999999,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0629162,
    "longitude": 77.59232035,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.06341045,
    "longitude": 77.5912771,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.06344295,
    "longitude": 77.5913106,
    "signal_strength_dBm": -49
},
```

```
Pretty-print
{
    "latitude": 13.0634752,
    "longitude": 77.5913386,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0645074,
    "longitude": 77.59224465,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0642722,
    "longitude": 77.5921015,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0644498,
    "longitude": 77.59206705,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.059871699999999,
    "longitude": 77.58951454999999,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.05917295,
    "longitude": 77.58955325,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0584778,
    "longitude": 77.58947570000001,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0598975,
    "longitude": 77.58878305,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.059727299999999,
    "longitude": 77.58843440000001,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0601296,
    "longitude": 77.58914490000001,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.05986425,
    "longitude": 77.58909295000001,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.06002015,
    "longitude": 77.58930235,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.059759849999999,
    "longitude": 77.58940275,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.06020385,
    "longitude": 77.5887765,
    "signal_strength_dBm": -85
```

Pretty-print

```
{  
    "latitude": 13.06002919999999,  
    "longitude": 77.58840635,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.060159500000001,  
    "longitude": 77.58800995,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.059859,  
    "longitude": 77.58805770000001,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.06033415,  
    "longitude": 77.5883801,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.0606632,  
    "longitude": 77.58793,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.059007600000001,  
    "longitude": 77.59072649999999,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.058982050000001,  
    "longitude": 77.59051595,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.0587154,  
    "longitude": 77.59050504999999,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.0583582,  
    "longitude": 77.59047465,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.05850605,  
    "longitude": 77.59083655,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.0576653,  
    "longitude": 77.58975154999999,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.05779744999999,  
    "longitude": 77.58988675,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.057991000000001,  
    "longitude": 77.5895,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.0578912,  
    "longitude": 77.58907640000001,  
    "signal_strength_dBm": -95  
}
```

Pretty-print

```
},
{
  "latitude": 13.05773705,
  "longitude": 77.58911180000001,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0597023,
  "longitude": 77.5878328,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.05772395,
  "longitude": 77.58922855,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.057568,
  "longitude": 77.58914870000001,
  "signal_strength_dBm": -99
},
{
  "latitude": 13.05593875,
  "longitude": 77.5890143,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.0557295,
  "longitude": 77.5889977,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.055817900000001,
  "longitude": 77.58910965000001,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.057263899999999,
  "longitude": 77.5891169,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0573661,
  "longitude": 77.58952805,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.05731845,
  "longitude": 77.5899704,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0572269,
  "longitude": 77.5899134,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.05726855,
  "longitude": 77.59022245,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.057075900000001,
  "longitude": 77.5898948,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.05698585,
```

```
Pretty-print
-----
    "signal_strength_dBm": -89
},
{
    "latitude": 13.057074,
    "longitude": 77.58949475,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.056986349999999,
    "longitude": 77.59003799999999,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0567059,
    "longitude": 77.58906825,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05678465,
    "longitude": 77.5895963,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.056749100000001,
    "longitude": 77.5901365,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.056417199999999,
    "longitude": 77.58904795000001,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0565134,
    "longitude": 77.58958725,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.056459199999999,
    "longitude": 77.59027325,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.05645905,
    "longitude": 77.5905173,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.05647435,
    "longitude": 77.59070375,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.0564979,
    "longitude": 77.5908236,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.0565174,
    "longitude": 77.5908694,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.05651855,
    "longitude": 77.59104690000001,
    "signal_strength_dBm": -43
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.59125825,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0563629,
    "longitude": 77.59113685,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.05684875,
    "longitude": 77.5913377,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.057159,
    "longitude": 77.5914105,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.05741105,
    "longitude": 77.5914895,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.05755055,
    "longitude": 77.59152555,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0575774,
    "longitude": 77.591794,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0561529,
    "longitude": 77.58902935,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.056258499999998,
    "longitude": 77.589226,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.056229049999999,
    "longitude": 77.58964575,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.056206,
    "longitude": 77.58994340000001,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.056192800000002,
    "longitude": 77.5900752,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0561599,
    "longitude": 77.59036215,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0561276,
    "longitude": 77.59062685,
    "signal_strength_dBm": -67
},
```

```
Pretty-print
{
    "latitude": 13.05611835,
    "longitude": 77.590704,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.055997699999999,
    "longitude": 77.5891706,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.05591335,
    "longitude": 77.58959055,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05575755,
    "longitude": 77.58983330000001,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0556787,
    "longitude": 77.5896772,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.05571085,
    "longitude": 77.58953564999999,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0557532,
    "longitude": 77.58936715,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.0555187,
    "longitude": 77.5889794,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.055593250000001,
    "longitude": 77.58910295,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.05556035,
    "longitude": 77.5893086,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0555904,
    "longitude": 77.58946085,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.055669349999999,
    "longitude": 77.58953564999999,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0552481,
    "longitude": 77.5897227,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0550465,
    "longitude": 77.58975575,
    "signal_strength_dBm": -95
```

Pretty-print

```
{  
    "latitude": 13.0552503,  
    "longitude": 77.5898578,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.05530215,  
    "longitude": 77.58951335,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.05532805,  
    "longitude": 77.58941010000001,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.0553497,  
    "longitude": 77.58931715,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.0553955,  
    "longitude": 77.5891015,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.05523005,  
    "longitude": 77.58895435,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.055016349999999,  
    "longitude": 77.5890577,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.05496425,  
    "longitude": 77.58930799999999,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.0549141,  
    "longitude": 77.58951504999999,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.05488445,  
    "longitude": 77.58963335,  
    "signal_strength_dBm": -68  
},  
{  
    "latitude": 13.0548659,  
    "longitude": 77.5897497,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.05481479999999,  
    "longitude": 77.5896588,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.0552679,  
    "longitude": 77.58991895,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.0554038,  
    "longitude": 77.58990449999999,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.0551943,
  "longitude": 77.59011910000001,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.05525155,
  "longitude": 77.59033675,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.0550158,
  "longitude": 77.59024605,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.0554724,
  "longitude": 77.59046445000001,
  "signal_strength_dBm": -100
},
{
  "latitude": 13.05565485,
  "longitude": 77.59059540000001,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.055751950000001,
  "longitude": 77.59066204999999,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.05582455,
  "longitude": 77.59068439999999,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.055996449999999,
  "longitude": 77.59071929999999,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.05611305,
  "longitude": 77.59079555,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.05479495,
  "longitude": 77.58930755,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.054774349999999,
  "longitude": 77.589495,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.05482885,
  "longitude": 77.58958229999999,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.0547592,
  "longitude": 77.58960775,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.05524185,
```

```
Pretty-print
-----
    "signal_strength_dBm": -103
},
{
    "latitude": 13.055144599999998,
    "longitude": 77.589349,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.05440625,
    "longitude": 77.5892075,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0544042,
    "longitude": 77.58943735,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.05449225,
    "longitude": 77.5895873,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.0543291,
    "longitude": 77.58956,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0545913,
    "longitude": 77.58939805,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.054563900000002,
    "longitude": 77.5896712,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.0546672,
    "longitude": 77.58962410000001,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.054605299999999,
    "longitude": 77.58911685,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.05452975,
    "longitude": 77.58981610000001,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0544949,
    "longitude": 77.58999854999999,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.054331,
    "longitude": 77.59006975,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05446095,
    "longitude": 77.5901731,
    "signal_strength_dBm": -77
},
```

```
Pretty-print
{
    "longitude": 77.5901097,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.054218599999999,
    "longitude": 77.5897943,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0548844,
    "longitude": 77.59035755,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0554319,
    "longitude": 77.59056724999999,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.05552825,
    "longitude": 77.5907213,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.05562155,
    "longitude": 77.59080965,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0557306,
    "longitude": 77.59082035,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05575365,
    "longitude": 77.59073409999999,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.055923499999999,
    "longitude": 77.59082675,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.05677205,
    "longitude": 77.59029645000001,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.05678395,
    "longitude": 77.59044804999999,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.0567912,
    "longitude": 77.59056515,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.05682125,
    "longitude": 77.5906854,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.0575452,
    "longitude": 77.59043565,
    "signal_strength_dBm": -95
},
```

```
Pretty-print
{
    "latitude": 13.056999600000001,
    "longitude": 77.59072689999999,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.057130749999999,
    "longitude": 77.5908135,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.05721475,
    "longitude": 77.5908848,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.057067499999999,
    "longitude": 77.5908699,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0568057,
    "longitude": 77.59083975,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.05654275,
    "longitude": 77.5908092,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.056109,
    "longitude": 77.59000275,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.055937700000001,
    "longitude": 77.5899938,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.055768650000001,
    "longitude": 77.58997465,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.055602749999998,
    "longitude": 77.5899438,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0535201,
    "longitude": 77.59230865,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.053463449999999,
    "longitude": 77.5927001,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0535533,
    "longitude": 77.59188714999999,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05324395,
    "longitude": 77.591485650000001,
    "signal_strength_dBm": -88
```

Pretty-print

```
{  
    "latitude": 13.0528788,  
    "longitude": 77.59162885,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.0526737,  
    "longitude": 77.59180125,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.052765650000001,  
    "longitude": 77.5923896,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.0519712,  
    "longitude": 77.591666,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.05172515,  
    "longitude": 77.59162755,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.05113199999999,  
    "longitude": 77.59156795,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.050475,  
    "longitude": 77.59150635,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.0500413,  
    "longitude": 77.59145755,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.04979554999999,  
    "longitude": 77.59147805,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.04973235,  
    "longitude": 77.59158310000001,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0496543,  
    "longitude": 77.59165525,  
    "signal_strength_dBm": -59  
},  
{  
    "latitude": 13.049237,  
    "longitude": 77.59157395,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.0489353,  
    "longitude": 77.59118065,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.05115565,  
    "longitude": 77.58620715,
```

Pretty-print

```
},
{
  "latitude": 13.053041499999999,
  "longitude": 77.58684650000001,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.05398,
  "longitude": 77.587168,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.0538116,
  "longitude": 77.5864029,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.054336,
  "longitude": 77.5874154,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.054593149999999,
  "longitude": 77.58683205,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.054162949999998,
  "longitude": 77.58773715000001,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.0552672,
  "longitude": 77.58815865,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.055244550000001,
  "longitude": 77.58809235000001,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.055077449999999,
  "longitude": 77.58567585,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.05544065,
  "longitude": 77.58454935,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.0557973,
  "longitude": 77.58376475,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0556517,
  "longitude": 77.5846474,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.055724900000001,
  "longitude": 77.58280690000001,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.056861949999998,
```

```
Pretty-print
-----
{"signal_strength_dBm": -43
},
{
  "latitude": 13.05655285,
  "longitude": 77.58455765,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.0563413,
  "longitude": 77.58502175000001,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.05607285,
  "longitude": 77.58490725,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.0553128,
  "longitude": 77.5847261,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.055353799999999,
  "longitude": 77.58460529999999,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.0548503,
  "longitude": 77.58238324999999,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0550218,
  "longitude": 77.58345415,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.0541369,
  "longitude": 77.5822981,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.05372214999999,
  "longitude": 77.58266850000001,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.0533364,
  "longitude": 77.58321775,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.05392265,
  "longitude": 77.58391825000001,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.05504614999999,
  "longitude": 77.58443675000001,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.05437225,
  "longitude": 77.58502605000001,
  "signal_strength_dBm": -94
},
```

```
Pretty-print
{
    "longitude": 77.58521139999999,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.055625150000001,
    "longitude": 77.58686005000001,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.0555017,
    "longitude": 77.5871563,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.05525025,
    "longitude": 77.58696225,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.05540825,
    "longitude": 77.5874006,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.05572055,
    "longitude": 77.5849878,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.05525685,
    "longitude": 77.58613075,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.05516395,
    "longitude": 77.58635975,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.054681850000001,
    "longitude": 77.58757095,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.05450395,
    "longitude": 77.5877999,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.05473705,
    "longitude": 77.58788805,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.05523855,
    "longitude": 77.5878033,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.05501225,
    "longitude": 77.58799885,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0551665,
    "longitude": 77.58806095,
    "signal_strength_dBm": -95
},
```

```
Pretty-print
{
    "latitude": 13.0550645,
    "longitude": 77.58743835,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.054875299999999,
    "longitude": 77.587085,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.055059,
    "longitude": 77.5866235,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.05581025,
    "longitude": 77.58641255,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0554339,
    "longitude": 77.5865213,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.05599915,
    "longitude": 77.5859424,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.05561965,
    "longitude": 77.58605605,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.055425549999999,
    "longitude": 77.58570155000001,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.0561467,
    "longitude": 77.58556605,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.05580505,
    "longitude": 77.58558790000001,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05557065,
    "longitude": 77.58533635,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.054742999999998,
    "longitude": 77.58830495000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.05538385,
    "longitude": 77.5815922,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.05543535,
    "longitude": 77.58140585000001,
    "signal_strength_dBm": -90
```

Pretty-print

```
{  
    "latitude": 13.0555464,  
    "longitude": 77.58153254999999,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.05603455,  
    "longitude": 77.5816753,  
    "signal_strength_dBm": -44  
},  
{  
    "latitude": 13.05630635,  
    "longitude": 77.5817692,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.056742,  
    "longitude": 77.58191554999999,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.056862,  
    "longitude": 77.5821664,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.05693935,  
    "longitude": 77.581952,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.05673645,  
    "longitude": 77.5825243,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.05662045,  
    "longitude": 77.58229355,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.05665765,  
    "longitude": 77.58274815,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.05657319999999,  
    "longitude": 77.58297565,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.056905400000002,  
    "longitude": 77.58331064999999,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.056341,  
    "longitude": 77.58306744999999,  
    "signal_strength_dBm": -51  
},  
{  
    "latitude": 13.05611065,  
    "longitude": 77.582953,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.05594575,  
    "longitude": 77.5828602,
```

Pretty-print

```
},
{
  "latitude": 13.0554193,
  "longitude": 77.58255745,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.054734700000001,
  "longitude": 77.58220855,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.0543391,
  "longitude": 77.5816775,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.0537298,
  "longitude": 77.5815619,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.05440555,
  "longitude": 77.58147015,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.05448395,
  "longitude": 77.58119755,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0545789,
  "longitude": 77.58140415,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.05454995,
  "longitude": 77.58094305,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.05461485,
  "longitude": 77.58070430000001,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.054814350000001,
  "longitude": 77.58151975,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.055005399999999,
  "longitude": 77.58160029999999,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.05518165,
  "longitude": 77.58164930000001,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.055312449999999,
  "longitude": 77.58168265,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.054356850000001,
```

```
Pretty-print
-----
    "signal_strength_dBm": -50
},
{
    "latitude": 13.0543505,
    "longitude": 77.58159205,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0545302,
    "longitude": 77.5817639,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0548189,
    "longitude": 77.58192015,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.055033850000001,
    "longitude": 77.58198785,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.055253650000001,
    "longitude": 77.5820444,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0684753,
    "longitude": 77.5836931,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06869005,
    "longitude": 77.58404920000001,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.0686883,
    "longitude": 77.5839657,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.06925595,
    "longitude": 77.5848505,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0696396,
    "longitude": 77.5857262,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.069254950000001,
    "longitude": 77.5854909,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.062567999999999,
    "longitude": 77.5755455,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06270285,
    "longitude": 77.5757275,
    "signal_strength_dBm": -78
},
{
```

```
Pretty-print
{
    "longitude": 77.575965,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0627228,
    "longitude": 77.57541235,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.062840049999998,
    "longitude": 77.57544475,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.061819400000001,
    "longitude": 77.57418150000001,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.0554997,
    "longitude": 77.6063852,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.05546035,
    "longitude": 77.60806815000001,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0554733,
    "longitude": 77.60778260000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.0554879,
    "longitude": 77.6074663,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.055495,
    "longitude": 77.60698740000001,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.05545785,
    "longitude": 77.6083712,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0554786,
    "longitude": 77.6088522,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.05546585,
    "longitude": 77.60864985,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0555262,
    "longitude": 77.60989345,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.055521,
    "longitude": 77.6097082,
    "signal_strength_dBm": -60
},
```

```
Pretty-print
{
    "latitude": 13.055516,
    "longitude": 77.6095428,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.055497599999999,
    "longitude": 77.60917384999999,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.060931100000001,
    "longitude": 77.57923155,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0611389,
    "longitude": 77.57904475000001,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.06321325,
    "longitude": 77.57244455,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.059805099999998,
    "longitude": 77.57708635,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.05980955,
    "longitude": 77.57699355,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.0596818,
    "longitude": 77.57773660000001,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0597898,
    "longitude": 77.57720495000001,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.059756199999999,
    "longitude": 77.57738635000001,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.05884795,
    "longitude": 77.5813553,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.059076600000001,
    "longitude": 77.58154744999999,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.05875595,
    "longitude": 77.5814915,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0581396,
    "longitude": 77.58645875,
    "signal_strength_dBm": -100
```

Pretty-print

```
{  
    "latitude": 13.0581271,  
    "longitude": 77.58675455,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.057708850000001,  
    "longitude": 77.5893631,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.0576896,  
    "longitude": 77.58953475,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.05758765,  
    "longitude": 77.59023905000001,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.057547,  
    "longitude": 77.59212005,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.0573733,  
    "longitude": 77.59313975,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.057483000000001,  
    "longitude": 77.59256145,  
    "signal_strength_dBm": -90  
},  
{  
    "latitude": 13.0656027,  
    "longitude": 77.58146909999999,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.06539295,  
    "longitude": 77.5817624,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.064575349999998,  
    "longitude": 77.58290600000001,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.0636639,  
    "longitude": 77.58418420000001,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.0632998,  
    "longitude": 77.58469595,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.0629607,  
    "longitude": 77.57547305,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.0630266,  
    "longitude": 77.5755527,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.0630266,  
    "longitude": 77.5755527,  
    "signal_strength_dBm": -50  
}
```

Pretty-print

```
},
{
  "latitude": 13.0633764,
  "longitude": 77.5759996,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.06360665,
  "longitude": 77.57633555000001,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.0657715,
  "longitude": 77.5795638,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.068063299999999,
  "longitude": 77.5830349,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06289915,
  "longitude": 77.57284845,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.0627597,
  "longitude": 77.57295554999999,
  "signal_strength_dBm": -63
},
{
  "latitude": 13.06283055,
  "longitude": 77.57299409999999,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.06305135,
  "longitude": 77.57308739999999,
  "signal_strength_dBm": -55
},
{
  "latitude": 13.06293305,
  "longitude": 77.57304245,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.063184499999998,
  "longitude": 77.5735315,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.06322575,
  "longitude": 77.57336765,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.06312965,
  "longitude": 77.57374949999999,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.063090599999999,
  "longitude": 77.57260099999999,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.0629207,
```

```
Pretty-print
-----
    "signal_strength_dBm": -58
},
{
    "latitude": 13.062600150000002,
    "longitude": 77.57308044999999,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.056930300000001,
    "longitude": 77.58740449999999,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.057315899999999,
    "longitude": 77.58748015,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.057351449999999,
    "longitude": 77.58661905,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05752905,
    "longitude": 77.58728195,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.0576743,
    "longitude": 77.58646375000001,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.05671825,
    "longitude": 77.58736285,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.05701675,
    "longitude": 77.5865733,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.05475315,
    "longitude": 77.5899808,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.054774049999999,
    "longitude": 77.5901652,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.0548556,
    "longitude": 77.58983425,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.05817375,
    "longitude": 77.5774718,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05818095,
    "longitude": 77.5775405,
    "signal_strength_dBm": -52
},
```

```
Pretty-print
{
    "longitude": 77.57849399999999,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.054384200000001,
    "longitude": 77.59455935,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.05755895,
    "longitude": 77.5935389,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.05770305,
    "longitude": 77.59387204999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0577142,
    "longitude": 77.59391915,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.072185099999999,
    "longitude": 77.58852595,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0724612,
    "longitude": 77.58869595,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.072847849999999,
    "longitude": 77.58961465,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.072785849999999,
    "longitude": 77.5898909,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.072044250000001,
    "longitude": 77.59255005,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.072288350000001,
    "longitude": 77.59253860000001,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0721281,
    "longitude": 77.59236935,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0725923,
    "longitude": 77.5887856,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0727095,
    "longitude": 77.588911,
    "signal_strength_dBm": -44
},
```

```
Pretty-print
{
    "latitude": 13.0727551,
    "longitude": 77.5890215,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.07098045,
    "longitude": 77.58766514999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.07112585,
    "longitude": 77.58779315000001,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0714408,
    "longitude": 77.58803445000001,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.07183214999999,
    "longitude": 77.5883053,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.07069995,
    "longitude": 77.58740230000001,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0708884,
    "longitude": 77.5875803,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.072623,
    "longitude": 77.59050845,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.07240455,
    "longitude": 77.5913295,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.07223105,
    "longitude": 77.59197599999999,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.07046975,
    "longitude": 77.57865584999999,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.07056075,
    "longitude": 77.5782615,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.05715925000002,
    "longitude": 77.57728345,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.05729795,
    "longitude": 77.57694805,
    "signal_strength_dBm": -51
```

Pretty-print

```
{  
    "latitude": 13.057258650000001,  
    "longitude": 77.5770919,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.05696165,  
    "longitude": 77.5819114,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.05700895,  
    "longitude": 77.5818783,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.0570371,  
    "longitude": 77.58187845,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.05735665,  
    "longitude": 77.58200245,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.05771925,  
    "longitude": 77.58194284999999,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.0576073,  
    "longitude": 77.58225375,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.05789044999999,  
    "longitude": 77.5822038,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.0569887,  
    "longitude": 77.58188835,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.057017,  
    "longitude": 77.58282325,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.0574087,  
    "longitude": 77.5828052,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.0576583,  
    "longitude": 77.5830717,  
    "signal_strength_dBm": -87  
},  
{  
    "latitude": 13.0580861,  
    "longitude": 77.58186965,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.05761985,  
    "longitude": 77.58170415000001,  
    "signal_strength_dBm": -58  
}
```

Pretty-print

```
},
{
  "latitude": 13.05846085,
  "longitude": 77.58200175,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.05848735,
  "longitude": 77.58234195,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.057489449999998,
  "longitude": 77.58155740000001,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.057356949999999,
  "longitude": 77.59389905,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.0574818,
  "longitude": 77.5938832,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.05704115,
  "longitude": 77.59455679999999,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.05729285,
  "longitude": 77.59394599999999,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.05680135,
  "longitude": 77.59515695,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.0568001,
  "longitude": 77.5951546,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.05724315,
  "longitude": 77.5952722,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.057010649999999,
  "longitude": 77.59524015,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.057497349999998,
  "longitude": 77.5946084,
  "signal_strength_dBm": -41
},
{
  "latitude": 13.0577263,
  "longitude": 77.5939569,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.05772775,
```

```
Pretty-print
-----
    "signal_strength_dBm": -55
},
{
    "latitude": 13.057649900000001,
    "longitude": 77.59391174999999,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.05772385,
    "longitude": 77.59394185,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.05857705,
    "longitude": 77.58513295,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.05833335,
    "longitude": 77.5852113,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0584241,
    "longitude": 77.5846266,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0597788,
    "longitude": 77.57670214999999,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.059798050000001,
    "longitude": 77.57670205,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0597602,
    "longitude": 77.5767074,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05974355,
    "longitude": 77.5767174,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.059736399999998,
    "longitude": 77.5767026,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.05973,
    "longitude": 77.57673145,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.05972045,
    "longitude": 77.5767486,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.05971555,
    "longitude": 77.5767677,
    "signal_strength_dBm": -50
},
{
```

```
Pretty-print
{
    "longitude": 77.576875,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.05972075,
    "longitude": 77.5768066,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.05973045,
    "longitude": 77.57682365,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0597441,
    "longitude": 77.57683755,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0597608,
    "longitude": 77.57684739999999,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.05977945,
    "longitude": 77.57685244999999,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.059798749999999,
    "longitude": 77.57685235,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.059833999999999,
    "longitude": 77.57683714999999,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.05981735,
    "longitude": 77.57684714999999,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.05984755,
    "longitude": 77.5768231,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.059857099999999,
    "longitude": 77.57680595,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.059861999999999,
    "longitude": 77.57678680000001,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.059861900000001,
    "longitude": 77.57676699999999,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05985685,
    "longitude": 77.5767479,
    "signal_strength_dBm": -42
},
```

```
Pretty-print
{
    "latitude": 13.059816699999999,
    "longitude": 77.5767071,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.059916399999999,
    "longitude": 77.57666599999999,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.0667767,
    "longitude": 77.576018,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.066809249999999,
    "longitude": 77.57571835,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.066625850000001,
    "longitude": 77.57624955,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.066433,
    "longitude": 77.5765866,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.06646995,
    "longitude": 77.57615999999999,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06622975,
    "longitude": 77.57712825,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.060709750000001,
    "longitude": 77.5797237,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06077085,
    "longitude": 77.57973645,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0606005,
    "longitude": 77.5796759,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06064915,
    "longitude": 77.57969969999999,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.056373449999999,
    "longitude": 77.5712417,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.056465849999999,
    "longitude": 77.5709291,
    "signal_strength_dBm": -44
```

Pretty-print

```
{  
    "latitude": 13.0560437,  
    "longitude": 77.57240475,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.0560925,  
    "longitude": 77.57297550000001,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.055707550000001,  
    "longitude": 77.57285325000001,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.055432750000001,  
    "longitude": 77.57276494999999,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.05634735,  
    "longitude": 77.57281895,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.056890800000001,  
    "longitude": 77.57320870000001,  
    "signal_strength_dBm": -51  
},  
{  
    "latitude": 13.0609106,  
    "longitude": 77.58181195,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.0549745,  
    "longitude": 77.58028200000001,  
    "signal_strength_dBm": -101  
},  
{  
    "latitude": 13.05517205,  
    "longitude": 77.5802243,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.054883700000001,  
    "longitude": 77.58012640000001,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.0555663,  
    "longitude": 77.58032370000001,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.055398100000001,  
    "longitude": 77.58013445,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.05519695,  
    "longitude": 77.58073525,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.05569345,  
    "longitude": 77.58059259999999,
```

Pretty-print

```
},
{
  "latitude": 13.055833100000001,
  "longitude": 77.580237,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.05632525,
  "longitude": 77.58258000000001,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.056283650000001,
  "longitude": 77.58217164999999,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.055690949999999,
  "longitude": 77.58271640000001,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.0556537,
  "longitude": 77.58231535,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.05594395,
  "longitude": 77.5820562,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.0559812,
  "longitude": 77.58245725,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.0541977,
  "longitude": 77.59067505,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.05420625,
  "longitude": 77.59066975,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.05403635,
  "longitude": 77.5926037,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.054244350000001,
  "longitude": 77.59231915,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.05427905,
  "longitude": 77.59263285,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.05414025,
  "longitude": 77.59261645,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.0547607,
```

```
Pretty-print
-----
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0546852,
    "longitude": 77.5927026,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.054593,
    "longitude": 77.59266880000001,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0547004,
    "longitude": 77.59275915,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0547127,
    "longitude": 77.59301965,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0557254,
    "longitude": 77.57202735,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0562592,
    "longitude": 77.57164470000001,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06691515,
    "longitude": 77.57598435,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.06690405000002,
    "longitude": 77.57619825,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.0669576,
    "longitude": 77.5763364,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0670354,
    "longitude": 77.5764112,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0671033,
    "longitude": 77.57644675,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06143905,
    "longitude": 77.57976295,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0616486,
    "longitude": 77.57970285,
    "signal_strength_dBm": -93
},
```

```
Pretty-print
-----
{
    "longitude": 77.57759859999999,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.05818755,
    "longitude": 77.57759859999999,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0582618,
    "longitude": 77.577731,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0583758,
    "longitude": 77.57777795,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.05859465,
    "longitude": 77.57782940000001,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.058518,
    "longitude": 77.57781455,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0586416,
    "longitude": 77.578039,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.05863755,
    "longitude": 77.57801485,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.06106855,
    "longitude": 77.5752282,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0619325,
    "longitude": 77.5753939,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.061918599999998,
    "longitude": 77.57575535,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.06215015,
    "longitude": 77.57526784999999,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.061393599999999,
    "longitude": 77.57659100000001,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.06113775,
    "longitude": 77.5764331,
    "signal_strength_dBm": -96
},
```

```
Pretty-print
{
    "latitude": 13.0616044,
    "longitude": 77.57671135,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0615422,
    "longitude": 77.5766748,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.06149095,
    "longitude": 77.57688594999999,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.06123715,
    "longitude": 77.57625425,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.057566099999999,
    "longitude": 77.5731859,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0574092,
    "longitude": 77.57362119999999,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.05702265,
    "longitude": 77.57279615,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0576897,
    "longitude": 77.57284295,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.056454500000001,
    "longitude": 77.57243995,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.05712155,
    "longitude": 77.57248675,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.05654095,
    "longitude": 77.5721341,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.05771185,
    "longitude": 77.588142,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.057522899999999,
    "longitude": 77.5883825,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.05771155,
    "longitude": 77.5884155,
    "signal_strength_dBm": -53
```

Pretty-print

```
{  
    "latitude": 13.0571223,  
    "longitude": 77.58749655,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.0568558,  
    "longitude": 77.58786459999999,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.0570937,  
    "longitude": 77.5883195,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.05604135,  
    "longitude": 77.58852665,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.05564975,  
    "longitude": 77.5882516,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.0661228,  
    "longitude": 77.57046514999999,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.065970100000001,  
    "longitude": 77.570595,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.06598565,  
    "longitude": 77.57068100000001,  
    "signal_strength_dBm": -51  
},  
{  
    "latitude": 13.06602745,  
    "longitude": 77.5707621,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.063225,  
    "longitude": 77.58692665000001,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.063074700000001,  
    "longitude": 77.5866489,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.05461705,  
    "longitude": 77.5757682,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.0548797,  
    "longitude": 77.57558159999999,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.0544852,  
    "longitude": 77.57509245,  
    "signal_strength_dBm": -80  
}
```

Pretty-print

```
},
{
  "latitude": 13.05505805,
  "longitude": 77.57515095,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.06666999999999,
  "longitude": 77.58614639999999,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.0666719,
  "longitude": 77.5865051,
  "signal_strength_dBm": -41
},
{
  "latitude": 13.06644994999999,
  "longitude": 77.5864452,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.065850900000001,
  "longitude": 77.5861889,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.0658774,
  "longitude": 77.58646885,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.066692450000001,
  "longitude": 77.587048,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.06662715,
  "longitude": 77.58732995,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06671025,
  "longitude": 77.5866785,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.06665825,
  "longitude": 77.5858463,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.06666205,
  "longitude": 77.58585285000001,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.06588204999999,
  "longitude": 77.58590385,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.0658674,
  "longitude": 77.58582805,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06417885,
```

```
Pretty-print
-----
    "signal_strength_dBm": -87
},
{
    "latitude": 13.06430435,
    "longitude": 77.57152495,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.06595925,
    "longitude": 77.5987379,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.0721035,
    "longitude": 77.56744555,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0688538,
    "longitude": 77.5833571,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.06910005,
    "longitude": 77.5833584,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.06884735,
    "longitude": 77.5837344,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0613299,
    "longitude": 77.5804244,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.06122075,
    "longitude": 77.5807858,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.06131465,
    "longitude": 77.58067539999999,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.05716955,
    "longitude": 77.57587129999999,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.05734019999999,
    "longitude": 77.5752158,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.05635105,
    "longitude": 77.5749275,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.056432000000001,
    "longitude": 77.5746972,
    "signal_strength_dBm": -95
},
```

```
Pretty-print
-----
{
    "longitude": 77.58945735,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.066315249999999,
    "longitude": 77.59008,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.06632045,
    "longitude": 77.59035025,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0661676,
    "longitude": 77.5903053,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0669197,
    "longitude": 77.5893211,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0667388,
    "longitude": 77.58973474999999,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0666075,
    "longitude": 77.59000359999999,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.06649385,
    "longitude": 77.59024835,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0667154,
    "longitude": 77.5904648,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.06018275,
    "longitude": 77.57949275,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0598028,
    "longitude": 77.5801252,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0540202,
    "longitude": 77.58215615,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.053948349999999,
    "longitude": 77.58220575,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.05370495,
    "longitude": 77.58214645000001,
    "signal_strength_dBm": -81
},
```

```
Pretty-print
{
    "latitude": 13.0537305,
    "longitude": 77.58241905,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.051402150000001,
    "longitude": 77.58145075,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.051462,
    "longitude": 77.581266,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.06483475,
    "longitude": 77.57358615,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0650588,
    "longitude": 77.57429124999999,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.065021600000001,
    "longitude": 77.5736539,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06499345,
    "longitude": 77.5749068,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.065135000000001,
    "longitude": 77.5749518,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.052321899999999,
    "longitude": 77.59173195,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.048584649999999,
    "longitude": 77.59258265,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0482122,
    "longitude": 77.59240489999999,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.04902765,
    "longitude": 77.59277785,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.04890345,
    "longitude": 77.59272884999999,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.05584555,
    "longitude": 77.58161949999999,
    "signal_strength_dBm": -82
```

Pretty-print

```
{  
    "latitude": 13.0557829,  
    "longitude": 77.5812433,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.055747,  
    "longitude": 77.58086105,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.0560549,  
    "longitude": 77.5809797,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.05611755,  
    "longitude": 77.5813559,  
    "signal_strength_dBm": -44  
},  
{  
    "latitude": 13.05553385,  
    "longitude": 77.58106325,  
    "signal_strength_dBm": -87  
},  
{  
    "latitude": 13.065177649999999,  
    "longitude": 77.57560584999999,  
    "signal_strength_dBm": -68  
},  
{  
    "latitude": 13.06514405,  
    "longitude": 77.57549395,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.0651079,  
    "longitude": 77.57563984999999,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.06523945,  
    "longitude": 77.57508089999999,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.06131175,  
    "longitude": 77.5798565,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0625434,  
    "longitude": 77.58029435,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.0620188,  
    "longitude": 77.57987555,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.061870200000001,  
    "longitude": 77.5797855,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.0619984,  
    "longitude": 77.58004585,  
    "signal_strength_dBm": -83  
}
```

Pretty-print

```
},
{
  "latitude": 13.05455905,
  "longitude": 77.57846190000001,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.05380165,
  "longitude": 77.5737232,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.053529600000001,
  "longitude": 77.57363459999999,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.053373650000001,
  "longitude": 77.57355749999999,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.053956,
  "longitude": 77.57494915000001,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.05439315,
  "longitude": 77.56975365,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.054328550000001,
  "longitude": 77.57080505,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.0705675,
  "longitude": 77.57901294999999,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.0656023,
  "longitude": 77.5765697,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.0655051,
  "longitude": 77.57672285000001,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.06544515,
  "longitude": 77.57681275,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.0705043,
  "longitude": 77.57816385000001,
  "signal_strength_dBm": -58
},
{
  "latitude": 13.070551850000001,
  "longitude": 77.57818865,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.07013615,
```

```
Pretty-print
-----
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0704831,
    "longitude": 77.57811365,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.0704739,
    "longitude": 77.57809415,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.0704875,
    "longitude": 77.57805795,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.070513550000001,
    "longitude": 77.5780236,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.07050115,
    "longitude": 77.5779867,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0704268,
    "longitude": 77.57788745,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.07037349999999,
    "longitude": 77.5777869,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.07036975,
    "longitude": 77.57772965,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.07034919999999,
    "longitude": 77.57767755,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.07031275,
    "longitude": 77.57762460000001,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0578357,
    "longitude": 77.58841665,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.05786705,
    "longitude": 77.58821499999999,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.057945100000001,
    "longitude": 77.58835635,
    "signal_strength_dBm": -65
},
```

```
Pretty-print
{
    "longitude": 77.58758209999999,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0577709,
    "longitude": 77.58775415,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.06326465,
    "longitude": 77.58555315000001,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0623151,
    "longitude": 77.58680575,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.06202865,
    "longitude": 77.58700225,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.053135699999999,
    "longitude": 77.5944724,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.05298975,
    "longitude": 77.59532455,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.05469015,
    "longitude": 77.59396634999999,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05476655,
    "longitude": 77.59395905,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.05472495,
    "longitude": 77.59394355,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.05509025,
    "longitude": 77.5943554,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.05494675,
    "longitude": 77.5939456,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.05479705,
    "longitude": 77.59477625,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.05457715,
    "longitude": 77.59437374999999,
    "signal_strength_dBm": -50
},
```

```
Pretty-print
{
    "latitude": 13.0550852,
    "longitude": 77.59368685000001,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.05476675,
    "longitude": 77.593716,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.05480575,
    "longitude": 77.5937673,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.0564492,
    "longitude": 77.59321095,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.056478649999999,
    "longitude": 77.59321165,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.056619699999999,
    "longitude": 77.59239665000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05657385,
    "longitude": 77.5926819,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.056855800000001,
    "longitude": 77.5927146,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0568889,
    "longitude": 77.59244695000001,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.056675949999999,
    "longitude": 77.5932166,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.05695335,
    "longitude": 77.59322549999999,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05447655,
    "longitude": 77.59069885,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0526974,
    "longitude": 77.5930023,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.053063250000001,
    "longitude": 77.5930345,
    "signal_strength_dBm": -85
```

Pretty-print

```
{  
    "latitude": 13.0532819,  
    "longitude": 77.59219780000001,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.058222,  
    "longitude": 77.58385475,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.05799705,  
    "longitude": 77.5837618,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.05826315,  
    "longitude": 77.5828985,  
    "signal_strength_dBm": -90  
},  
{  
    "latitude": 13.05837335,  
    "longitude": 77.58327324999999,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.0596221,  
    "longitude": 77.58486400000001,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.05886645,  
    "longitude": 77.5836972,  
    "signal_strength_dBm": -91  
},  
{  
    "latitude": 13.05890945,  
    "longitude": 77.58380120000001,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.05882005,  
    "longitude": 77.58496345,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.057811000000001,  
    "longitude": 77.58845235,  
    "signal_strength_dBm": -101  
},  
{  
    "latitude": 13.0581702,  
    "longitude": 77.58885839999999,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.0580964,  
    "longitude": 77.58855105,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.058174600000001,  
    "longitude": 77.58831655,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.05690615,  
    "longitude": 77.5944574,
```

Pretty-print

```
},
{
  "latitude": 13.05655995,
  "longitude": 77.59426095,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.05615865,
  "longitude": 77.59428729999999,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.0562525,
  "longitude": 77.59389805,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.0562995,
  "longitude": 77.5936734,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.0564699,
  "longitude": 77.59364285000001,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.0561778,
  "longitude": 77.5936385,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.05862185,
  "longitude": 77.59125045,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.05770845,
  "longitude": 77.5924661,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.057818600000001,
  "longitude": 77.59249415,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.05780795,
  "longitude": 77.59217425,
  "signal_strength_dBm": -94
},
{
  "latitude": 13.057912349999999,
  "longitude": 77.59219379999999,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.058079750000001,
  "longitude": 77.592539,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.057732399999999,
  "longitude": 77.5921601,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.0578951,
```

```
Pretty-print
-----
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0577504,
    "longitude": 77.5918873,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05812245,
    "longitude": 77.59168525,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0581884,
    "longitude": 77.59197234999999,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.05804745,
    "longitude": 77.5922191,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.057152,
    "longitude": 77.58386955,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.05443504999999,
    "longitude": 77.59265070000001,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.05439725,
    "longitude": 77.59236815,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.05454205,
    "longitude": 77.59246715,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.05411415,
    "longitude": 77.5923011,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05421825,
    "longitude": 77.5920038,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0533559,
    "longitude": 77.59101749999999,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.05302695,
    "longitude": 77.59063115000001,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.05309505,
    "longitude": 77.59029125,
    "signal_strength_dBm": -47
},
{
```

```
Pretty-print
{
    "longitude": 77.5882906,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.051640599999999,
    "longitude": 77.5878695,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.053733300000001,
    "longitude": 77.58880055,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0539516,
    "longitude": 77.58859675,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0538581,
    "longitude": 77.58847205000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.0542495,
    "longitude": 77.5881931,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0559941,
    "longitude": 77.58722495,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.0563158,
    "longitude": 77.58584055,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.05844885,
    "longitude": 77.58758710000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.058900999999999,
    "longitude": 77.58661505,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05859205,
    "longitude": 77.58642169999999,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05824225,
    "longitude": 77.58651674999999,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0584256,
    "longitude": 77.5871259,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.058183450000001,
    "longitude": 77.5869285,
    "signal_strength_dBm": -84
},
```

```
Pretty-print
{
    "latitude": 13.058214150000001,
    "longitude": 77.5867135,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0581832,
    "longitude": 77.58676299999999,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.05928895,
    "longitude": 77.5864057,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.0596695,
    "longitude": 77.58630115,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.059427849999999,
    "longitude": 77.58611379999999,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0599101,
    "longitude": 77.58595245000001,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.05958835,
    "longitude": 77.5857096,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0508868,
    "longitude": 77.5933628,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.05037695,
    "longitude": 77.59322850000001,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.0499545,
    "longitude": 77.59311174999999,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.05629585,
    "longitude": 77.59467705,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05609005,
    "longitude": 77.59453339999999,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.05686955,
    "longitude": 77.59457275,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0555512,
    "longitude": 77.5964191,
    "signal_strength_dBm": -96
```

Pretty-print

```
{  
    "latitude": 13.05528175,  
    "longitude": 77.59389924999999,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.05519419999999,  
    "longitude": 77.59431835000001,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.0556003,  
    "longitude": 77.59432054999999,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.055518150000001,  
    "longitude": 77.59390345,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.0556287,  
    "longitude": 77.5947339,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.05539144999998,  
    "longitude": 77.59473675,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.0556984,  
    "longitude": 77.5947329,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.05575474999998,  
    "longitude": 77.59450100000001,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.05770289999999,  
    "longitude": 77.59375105,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.054728050000001,  
    "longitude": 77.59377595,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.0547269,  
    "longitude": 77.59385945,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.07281199999999,  
    "longitude": 77.59251935,  
    "signal_strength_dBm": -91  
},  
{  
    "latitude": 13.0731385,  
    "longitude": 77.59251105000001,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.06869125,  
    "longitude": 77.59562265,
```

Pretty-print

```
},
{
  "latitude": 13.06859455,
  "longitude": 77.59557434999999,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.0669825,
  "longitude": 77.5946052,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.066973350000001,
  "longitude": 77.59513055,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.06714245,
  "longitude": 77.595254,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.067256100000002,
  "longitude": 77.59531035,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.06737365,
  "longitude": 77.59536805,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.067503,
  "longitude": 77.59540290000001,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.06763495,
  "longitude": 77.5954069,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.06781655,
  "longitude": 77.59543375,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.06799425,
  "longitude": 77.5954619,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.0681066,
  "longitude": 77.5954699,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.06836,
  "longitude": 77.5955115,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.0688068,
  "longitude": 77.59568725,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0689335,
```

```
Pretty-print
-----
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0690537,
    "longitude": 77.59572205,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.06918435,
    "longitude": 77.595714,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0693594,
    "longitude": 77.59573549999999,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.069541000000001,
    "longitude": 77.59576235,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.069631099999999,
    "longitude": 77.5957422,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0696389,
    "longitude": 77.5956644,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0696729,
    "longitude": 77.59558530000001,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0697343,
    "longitude": 77.5954753,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0697591,
    "longitude": 77.59535994999999,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0697957,
    "longitude": 77.59526745,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.06992505,
    "longitude": 77.5949094,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.07004915,
    "longitude": 77.59449365,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.07011445,
    "longitude": 77.59424150000001,
    "signal_strength_dBm": -86
},
{
```

```
Pretty-print
{
    "longitude": 77.5939679,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.07015625,
    "longitude": 77.5936554,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.070077600000001,
    "longitude": 77.5933069,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.0696215,
    "longitude": 77.59304305,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.063512,
    "longitude": 77.593421,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.06289345,
    "longitude": 77.5934443,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.0632777,
    "longitude": 77.59358284999999,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0631828,
    "longitude": 77.59405860000001,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.06307635,
    "longitude": 77.59452915,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0630308,
    "longitude": 77.59460235,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.062949799999998,
    "longitude": 77.59463199999999,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.0630417,
    "longitude": 77.59428025,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.063033399999998,
    "longitude": 77.59429779999999,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.06281865,
    "longitude": 77.59374120000001,
    "signal_strength_dBm": -71
},
```

```
Pretty-print
{
    "latitude": 13.0631307,
    "longitude": 77.5936963,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.063086349999999,
    "longitude": 77.59399495,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.06250775,
    "longitude": 77.59371745,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0624896,
    "longitude": 77.59393495,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.06221115,
    "longitude": 77.5934749,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.061985400000001,
    "longitude": 77.57403885,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.06197805,
    "longitude": 77.57389180000001,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0621905,
    "longitude": 77.5736098,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.06241385,
    "longitude": 77.5733165,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.053421799999999,
    "longitude": 77.5934319,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.070609600000001,
    "longitude": 77.5867775,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.070529650000001,
    "longitude": 77.586948,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.072664450000001,
    "longitude": 77.58885315,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.072810050000001,
    "longitude": 77.58926410000001,
    "signal_strength_dBm": -46
```

Pretty-print

```
{  
    "latitude": 13.072845749999999,  
    "longitude": 77.5894944,  
    "signal_strength_dBm": -90  
},  
{  
    "latitude": 13.05280325,  
    "longitude": 77.58008615,  
    "signal_strength_dBm": -70  
},  
{  
    "latitude": 13.053284099999999,  
    "longitude": 77.58032775,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.052291050000001,  
    "longitude": 77.57980975000001,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.0522424,  
    "longitude": 77.5794719,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.065165,  
    "longitude": 77.59309569999999,  
    "signal_strength_dBm": -68  
},  
{  
    "latitude": 13.05754315,  
    "longitude": 77.5932427,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.0579361,  
    "longitude": 77.59324785000001,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.053992699999998,  
    "longitude": 77.5880037,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.053917349999999,  
    "longitude": 77.58822155,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.053369,  
    "longitude": 77.5896355,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.06794385,  
    "longitude": 77.5872943,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.0678423,  
    "longitude": 77.58691845,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.0681764,  
    "longitude": 77.58742505000001,  
    "signal_strength_dBm": -60  
}
```

Pretty-print

```
},
{
  "latitude": 13.068324,
  "longitude": 77.5875101,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.0682777,
  "longitude": 77.58711149999999,
  "signal_strength_dBm": -79
},
{
  "latitude": 13.0683856,
  "longitude": 77.58711819999999,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.068168499999999,
  "longitude": 77.587122,
  "signal_strength_dBm": -63
},
{
  "latitude": 13.0681053,
  "longitude": 77.58725345,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.05928745,
  "longitude": 77.5935738,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.059201850000001,
  "longitude": 77.59385535,
  "signal_strength_dBm": -41
},
{
  "latitude": 13.0590952,
  "longitude": 77.59441375,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.065601950000001,
  "longitude": 77.5894239,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.06537985,
  "longitude": 77.59000755,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.0691944,
  "longitude": 77.5935846,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.058071850000001,
  "longitude": 77.59541855,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.05809215,
  "longitude": 77.59533875,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.05484395,
```

```
Pretty-print
-----
    "signal_strength_dBm": -106
},
{
    "latitude": 13.05494565,
    "longitude": 77.59266364999999,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0551141,
    "longitude": 77.592509,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0550139,
    "longitude": 77.592832,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.055341850000001,
    "longitude": 77.59226045,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0552218,
    "longitude": 77.59229755,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0551973,
    "longitude": 77.59232505,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.04806114999999,
    "longitude": 77.5923316,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.05649925,
    "longitude": 77.59274165,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0565623,
    "longitude": 77.59225895,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.05682725,
    "longitude": 77.59181674999999,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0566011,
    "longitude": 77.59201455,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.058371300000001,
    "longitude": 77.5941326,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0560412,
    "longitude": 77.5937289,
    "signal_strength_dBm": -104
},
```

```
Pretty-print
{
    "longitude": 77.5936343,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.054406799999999,
    "longitude": 77.59374245000001,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.0510776,
    "longitude": 77.59340710000001,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05104205,
    "longitude": 77.5933988,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0638529,
    "longitude": 77.59340685000001,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0638538,
    "longitude": 77.5941602,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0639395,
    "longitude": 77.59355310000001,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.059624150000001,
    "longitude": 77.58164855,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.059394900000001,
    "longitude": 77.5815977,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0600226,
    "longitude": 77.58173975,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06028915,
    "longitude": 77.58177595000001,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.060244,
    "longitude": 77.58183935,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.060380949999999,
    "longitude": 77.58170955,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.05617095,
    "longitude": 77.5783016,
    "signal_strength_dBm": -60
},
```

```
Pretty-print
{
    "latitude": 13.05653275,
    "longitude": 77.57867064999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0576065,
    "longitude": 77.5812589,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0576822,
    "longitude": 77.5810638,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.05691745,
    "longitude": 77.58091289999999,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.056273950000001,
    "longitude": 77.58045784999999,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.05611355,
    "longitude": 77.5801968,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0570387,
    "longitude": 77.58060875,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.057776350000001,
    "longitude": 77.58082429999999,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.055954700000001,
    "longitude": 77.5799274,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.057838799999999,
    "longitude": 77.5806654,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.057947500000001,
    "longitude": 77.580389,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0572543,
    "longitude": 77.58032320000001,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0563331,
    "longitude": 77.57990104999999,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.05626675,
    "longitude": 77.5792228,
    "signal_strength_dBm": -64
```

Pretty-print

```
{  
    "latitude": 13.056501050000001,  
    "longitude": 77.57953205,  
    "signal_strength_dBm": -103  
},  
{  
    "latitude": 13.0574256,  
    "longitude": 77.57992085000001,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.058187199999999,  
    "longitude": 77.58023655,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.05889465,  
    "longitude": 77.59350955,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.05961325,  
    "longitude": 77.59351925,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.05492705,  
    "longitude": 77.5772356,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.055100249999999,  
    "longitude": 77.57695035,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.0692907,  
    "longitude": 77.5904545,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.06989625,  
    "longitude": 77.59114655,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.070042749999999,  
    "longitude": 77.5906718,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.07003695,  
    "longitude": 77.590599550000001,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.069601599999999,  
    "longitude": 77.5923377,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.0696872,  
    "longitude": 77.5919727,  
    "signal_strength_dBm": -51  
},  
{  
    "latitude": 13.07001865,  
    "longitude": 77.5911739,
```

Pretty-print

```
},
{
  "latitude": 13.07010155,
  "longitude": 77.5906852,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.07028055,
  "longitude": 77.59013264999999,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.06982264999999,
  "longitude": 77.59198125,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.06974525,
  "longitude": 77.5923255,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.0685139,
  "longitude": 77.59022205,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.06843234999998,
  "longitude": 77.59013995000001,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.0684759,
  "longitude": 77.58989270000001,
  "signal_strength_dBm": -100
},
{
  "latitude": 13.06922829999999,
  "longitude": 77.59030585,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.068461450000001,
  "longitude": 77.58966369999999,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.06865475,
  "longitude": 77.589434,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.06775405,
  "longitude": 77.5896816,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.0675363,
  "longitude": 77.58995695,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.06730145,
  "longitude": 77.59061735,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.0674377,
```

```
Pretty-print
-----
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0676573,
    "longitude": 77.591101,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0687624,
    "longitude": 77.5913749,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0698383,
    "longitude": 77.59164095,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06506895,
    "longitude": 77.57577777,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06501435,
    "longitude": 77.57588985,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0649211,
    "longitude": 77.57592614999999,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0648198,
    "longitude": 77.5759476,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0647442,
    "longitude": 77.57605165000001,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06465755,
    "longitude": 77.57624955,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.06555215,
    "longitude": 77.5747386,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.07011515,
    "longitude": 77.5744881,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.0589453,
    "longitude": 77.578779,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0589453,
    "longitude": 77.57914435,
    "signal_strength_dBm": -104
},
```

```
Pretty-print
-----
{
    "longitude": 77.57875785,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.058677549999999,
    "longitude": 77.5790704,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.05991535,
    "longitude": 77.57812279999999,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.05984915,
    "longitude": 77.577756,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.05971165,
    "longitude": 77.57759425,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0572919,
    "longitude": 77.5781618,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05636475,
    "longitude": 77.57769815,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.056605300000001,
    "longitude": 77.57756069999999,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0564413,
    "longitude": 77.57788425,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.05671235,
    "longitude": 77.57734314999999,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.0567244,
    "longitude": 77.57663174999999,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.05684445,
    "longitude": 77.5766376,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0563439,
    "longitude": 77.57739975,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0556277,
    "longitude": 77.5767722,
    "signal_strength_dBm": -74
},
```

```
Pretty-print
{
    "latitude": 13.05553373,
    "longitude": 77.57655915,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.05396425,
    "longitude": 77.5765523,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.054373,
    "longitude": 77.57697150000001,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0530704,
    "longitude": 77.5771483,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.0535761,
    "longitude": 77.57711395000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.05347935,
    "longitude": 77.5777399,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0534523,
    "longitude": 77.58037955,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.05348785,
    "longitude": 77.58034375,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0537592,
    "longitude": 77.5797968,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.0540798,
    "longitude": 77.5791545,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05485295,
    "longitude": 77.57856945,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.054674250000001,
    "longitude": 77.5788588,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.054923200000001,
    "longitude": 77.5811631,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05524895,
    "longitude": 77.5812597,
    "signal_strength_dBm": -47
```

Pretty-print

```
{  
    "latitude": 13.05466465,  
    "longitude": 77.58108805,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.05571584999999,  
    "longitude": 77.5792793,  
    "signal_strength_dBm": -59  
},  
{  
    "latitude": 13.0555408,  
    "longitude": 77.5797299,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.054565,  
    "longitude": 77.57995455,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.0705734,  
    "longitude": 77.58550555,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.070639100000001,  
    "longitude": 77.58823665,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.070776200000001,  
    "longitude": 77.58783,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.06718225,  
    "longitude": 77.59195199999999,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.06581995,  
    "longitude": 77.5908457,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.066020250000001,  
    "longitude": 77.5908618,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.063963900000001,  
    "longitude": 77.59041214999999,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.06430595,  
    "longitude": 77.59053025,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.0640798,  
    "longitude": 77.591475,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0646417,  
    "longitude": 77.58663255,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.0646417,  
    "longitude": 77.58663255,  
    "signal_strength_dBm": -50  
}
```

Pretty-print

```
},
{
  "latitude": 13.0643526,
  "longitude": 77.58708865,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.062801,
  "longitude": 77.58786094999999,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.0625796,
  "longitude": 77.58342535,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.06121695,
  "longitude": 77.58259225,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.060784250000001,
  "longitude": 77.5827224,
  "signal_strength_dBm": -63
},
{
  "latitude": 13.0598815,
  "longitude": 77.58218815,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.0602157,
  "longitude": 77.58227635,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.0601862,
  "longitude": 77.58206955,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.05832685,
  "longitude": 77.58122845,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.05851835,
  "longitude": 77.5810066,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.05830505,
  "longitude": 77.5809319,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.05800715,
  "longitude": 77.58080799999999,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.05815355,
  "longitude": 77.5810127,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.0578012,
```

```
Pretty-print
-----
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0575553,
    "longitude": 77.5813898,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0583904,
    "longitude": 77.5819511,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.057355600000001,
    "longitude": 77.5823067,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.05751135,
    "longitude": 77.58252025,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.057819,
    "longitude": 77.5824824,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.0572324,
    "longitude": 77.58257180000001,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0577527,
    "longitude": 77.5827627,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.057176349999999,
    "longitude": 77.58131610000001,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.06180015,
    "longitude": 77.57469165,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0616306,
    "longitude": 77.57503325,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0616013,
    "longitude": 77.57480195,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.061848999999999,
    "longitude": 77.5749119,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.06167255,
    "longitude": 77.57527295,
    "signal_strength_dBm": -60
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.575135,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0614857,
    "longitude": 77.57532515,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.061890949999999,
    "longitude": 77.5751516,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.06201605,
    "longitude": 77.57489165,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.06167689999998,
    "longitude": 77.57559655,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.056614150000001,
    "longitude": 77.5718753,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.05676755,
    "longitude": 77.5713328,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.06556945,
    "longitude": 77.57366445,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.06638775,
    "longitude": 77.57030705,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.06744405,
    "longitude": 77.57239845000001,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0692859,
    "longitude": 77.57564249999999,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.06920255,
    "longitude": 77.5756091,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.06938725,
    "longitude": 77.57509445,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.0503,
    "longitude": 77.5914919,
    "signal_strength_dBm": -75
},
```

```
Pretty-print
{
    "latitude": 13.05715675,
    "longitude": 77.58881105,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.05694705,
    "longitude": 77.5886624,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06534895,
    "longitude": 77.59480665,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.06713815,
    "longitude": 77.58370595,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0671067,
    "longitude": 77.58338735000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06669445,
    "longitude": 77.58393725,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.06734285,
    "longitude": 77.58308955,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.06672785,
    "longitude": 77.5825121,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.067014,
    "longitude": 77.58228165,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.06156505,
    "longitude": 77.5802511,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.06175155,
    "longitude": 77.58031215,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.06183015,
    "longitude": 77.5803564,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0618672,
    "longitude": 77.5803901,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0620318,
    "longitude": 77.5789431,
    "signal_strength_dBm": -96
}
```

Pretty-print

```
{  
    "latitude": 13.06099594999999,  
    "longitude": 77.5805207,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.06139615,  
    "longitude": 77.57718385000001,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.05784285,  
    "longitude": 77.57629639999999,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.057728000000001,  
    "longitude": 77.5764273,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.0570938,  
    "longitude": 77.57619299999999,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.057122199999998,  
    "longitude": 77.57607189999999,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.05734615,  
    "longitude": 77.57625515,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.0566894,  
    "longitude": 77.57610125,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.05841645,  
    "longitude": 77.57620035,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.06909345,  
    "longitude": 77.57556109999999,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.0689834,  
    "longitude": 77.575510500000001,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.069153,  
    "longitude": 77.57503795,  
    "signal_strength_dBm": -91  
},  
{  
    "latitude": 13.06891825,  
    "longitude": 77.57492925,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.070286,  
    "longitude": 77.5729983,
```

Pretty-print

```
},
{
  "latitude": 13.0685322,
  "longitude": 77.57049125,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.068623200000001,
  "longitude": 77.57019890000001,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.05837855,
  "longitude": 77.57273695,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.05859925,
  "longitude": 77.5725611,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.0610632,
  "longitude": 77.5924632,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.0610678,
  "longitude": 77.59230500000001,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.061092599999998,
  "longitude": 77.59237675,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06116635,
  "longitude": 77.59233309999999,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.06123165,
  "longitude": 77.5922573,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.06126305,
  "longitude": 77.59216140000001,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.0612474,
  "longitude": 77.592089,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.061172249999998,
  "longitude": 77.59203535,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.061097799999999,
  "longitude": 77.5921118,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.061103,
```

```
Pretty-print
-----  
{"signal_strength_dBm": -97},  
{ "latitude": 13.061144550000002, "longitude": 77.59297175, "signal_strength_dBm": -82},  
{ "latitude": 13.061027800000002, "longitude": 77.5932211, "signal_strength_dBm": -91},  
{ "latitude": 13.0611478, "longitude": 77.59316229999999, "signal_strength_dBm": -51},  
{ "latitude": 13.06403274999999, "longitude": 77.59155575, "signal_strength_dBm": -73},  
{ "latitude": 13.0531219, "longitude": 77.57504595, "signal_strength_dBm": -102},  
{ "latitude": 13.05272405, "longitude": 77.57492819999999, "signal_strength_dBm": -50},  
{ "latitude": 13.05244285, "longitude": 77.57486265, "signal_strength_dBm": -89},  
{ "latitude": 13.05180689999999, "longitude": 77.57478825000001, "signal_strength_dBm": -73},  
{ "latitude": 13.05213124999999, "longitude": 77.5748238, "signal_strength_dBm": -66},  
{ "latitude": 13.051447750000001, "longitude": 77.5747678, "signal_strength_dBm": -108},  
{ "latitude": 13.051644150000001, "longitude": 77.5747734, "signal_strength_dBm": -78},  
{ "latitude": 13.051039150000001, "longitude": 77.57478705, "signal_strength_dBm": -108},  
{ "latitude": 13.05120995, "longitude": 77.57477145, "signal_strength_dBm": -58}
```

```
Pretty-print
{
    "longitude": 77.57489659999999,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0533611,
    "longitude": 77.5752368,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.0528436,
    "longitude": 77.57475475000001,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.05318765,
    "longitude": 77.5747887,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0533473,
    "longitude": 77.57431905,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.05341065,
    "longitude": 77.57384365,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.068770350000001,
    "longitude": 77.5765773,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.05722655,
    "longitude": 77.59364845,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.057044600000001,
    "longitude": 77.59364579999999,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.055824699999999,
    "longitude": 77.59384275,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.067387100000001,
    "longitude": 77.59281465000001,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.06725205,
    "longitude": 77.59340935,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.067174649999998,
    "longitude": 77.59335915,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0673573,
    "longitude": 77.5933438,
    "signal_strength_dBm": -109
},
```

```
Pretty-print
{
    "latitude": 13.07104765,
    "longitude": 77.5930524,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06971225,
    "longitude": 77.59271655,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0696373,
    "longitude": 77.59270430000001,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.06985405,
    "longitude": 77.59270615,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.0697837,
    "longitude": 77.5926939,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.072153,
    "longitude": 77.59199185,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.07253265,
    "longitude": 77.59252665,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0696375,
    "longitude": 77.59315815,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06835125,
    "longitude": 77.59325960000001,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06533525,
    "longitude": 77.59010795,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0653128,
    "longitude": 77.59021365000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.067345249999999,
    "longitude": 77.59033195,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06826015,
    "longitude": 77.589592,
    "signal_strength_dBm": -79
}
```

Pretty-print

```
{  
    "latitude": 13.06799135,  
    "longitude": 77.5895969,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.056670650000001,  
    "longitude": 77.58737074999999,  
    "signal_strength_dBm": -69  
},  
{  
    "latitude": 13.05664305,  
    "longitude": 77.58742425,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.05666495,  
    "longitude": 77.5877466,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.06971245,  
    "longitude": 77.57880134999999,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.06929755,  
    "longitude": 77.57869285000001,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.06680235,  
    "longitude": 77.59238735,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.07050705,  
    "longitude": 77.58724715,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.0704782,  
    "longitude": 77.5872818,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.072415750000001,  
    "longitude": 77.5910147,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.072644050000001,  
    "longitude": 77.5901394,  
    "signal_strength_dBm": -104  
},  
{  
    "latitude": 13.07276655,  
    "longitude": 77.58964655,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.072770049999999,  
    "longitude": 77.58955975,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.072737799999999,  
    "longitude": 77.58931565,
```

Pretty-print

```
},
{
  "latitude": 13.07267685,
  "longitude": 77.58904204999999,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.07263485,
  "longitude": 77.58894395,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.07259305,
  "longitude": 77.5888912,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.07250705,
  "longitude": 77.58881675,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.07228725,
  "longitude": 77.58867405000001,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.071967950000001,
  "longitude": 77.5884722,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.071791300000001,
  "longitude": 77.5883622,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.071765150000001,
  "longitude": 77.5883458,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.071618950000001,
  "longitude": 77.58824974999999,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.0713688,
  "longitude": 77.588083,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.071225649999999,
  "longitude": 77.5879791,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.07114005,
  "longitude": 77.58790429999999,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.070982449999999,
  "longitude": 77.5877651,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.0706814,
```

```
Pretty-print
-----
    "signal_strength_dBm": -93
},
{
    "latitude": 13.070856599999999,
    "longitude": 77.58770154999999,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0639139,
    "longitude": 77.58336589999999,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.063638350000002,
    "longitude": 77.58317174999999,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0634045,
    "longitude": 77.58298675,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.063071149999999,
    "longitude": 77.5827205,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.062642700000001,
    "longitude": 77.58238895,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0622231,
    "longitude": 77.5821751,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.06178465,
    "longitude": 77.5820508,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.061441250000001,
    "longitude": 77.58222195,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.0612398,
    "longitude": 77.5819182,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.0607559,
    "longitude": 77.58178355000001,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.060159899999999,
    "longitude": 77.5815316,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0605263,
    "longitude": 77.58169265000001,
    "signal_strength_dBm": -84
},
{
```

```
Pretty-print
{
    "longitude": 77.58134485,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.059249900000001,
    "longitude": 77.5812641,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0592517,
    "longitude": 77.5812329,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0590451,
    "longitude": 77.5812233,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.06408575,
    "longitude": 77.58340845000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06407015,
    "longitude": 77.58344205,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.060258900000001,
    "longitude": 77.57480435,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.060236249999999,
    "longitude": 77.57480555000001,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.0605568,
    "longitude": 77.57557890000001,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.06069215,
    "longitude": 77.57560185,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.060712800000001,
    "longitude": 77.57572095,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.06086695,
    "longitude": 77.57550605,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0597926,
    "longitude": 77.5739692,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.059282549999999,
    "longitude": 77.57661715,
    "signal_strength_dBm": -79
},
```

```
Pretty-print
[{"latitude": 13.0592483,
 "longitude": 77.57675334999999,
 "signal_strength_dBm": -51},
 {"latitude": 13.0593486,
 "longitude": 77.57672844999999,
 "signal_strength_dBm": -62},
 {"latitude": 13.0594146,
 "longitude": 77.5767844,
 "signal_strength_dBm": -81},
 {"latitude": 13.0594038,
 "longitude": 77.57694699999999,
 "signal_strength_dBm": -88},
 {"latitude": 13.05914544999999,
 "longitude": 77.57687849999999,
 "signal_strength_dBm": -51},
 {"latitude": 13.0590486,
 "longitude": 77.57681935,
 "signal_strength_dBm": -66},
 {"latitude": 13.0591823,
 "longitude": 77.57677625,
 "signal_strength_dBm": -103},
 {"latitude": 13.058931000000001,
 "longitude": 77.57703535,
 "signal_strength_dBm": -76},
 {"latitude": 13.05892804999999,
 "longitude": 77.57685430000001,
 "signal_strength_dBm": -96},
 {"latitude": 13.05878565,
 "longitude": 77.57698095,
 "signal_strength_dBm": -51},
 {"latitude": 13.0587602,
 "longitude": 77.57688300000001,
 "signal_strength_dBm": -47},
 {"latitude": 13.058850499999998,
 "longitude": 77.57686975,
 "signal_strength_dBm": -72},
 {"latitude": 13.05876845,
 "longitude": 77.5771498,
 "signal_strength_dBm": -49},
 {"latitude": 13.058634900000001,
 "longitude": 77.577053,
 "signal_strength_dBm": -42}]
```

Pretty-print

```
{  
    "latitude": 13.058951050000001,  
    "longitude": 77.5765817,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.0588894,  
    "longitude": 77.5766643,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.0588921,  
    "longitude": 77.5766899,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.05890195,  
    "longitude": 77.57678225000001,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.060154950000001,  
    "longitude": 77.5761883,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.0601032,  
    "longitude": 77.57651279999999,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.06006275,  
    "longitude": 77.5765936,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.060115150000001,  
    "longitude": 77.57675255,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.06041125,  
    "longitude": 77.5764991,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.06029165,  
    "longitude": 77.57653859999999,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.0602827,  
    "longitude": 77.57675745,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.06058795,  
    "longitude": 77.5773194,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.06006095,  
    "longitude": 77.57744794999999,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.0574915,  
    "longitude": 77.57724440000001,  
    "signal_strength_dBm": -106  
}
```

Pretty-print

```
},
{
  "latitude": 13.05740265,
  "longitude": 77.5764734,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.0573196,
  "longitude": 77.57601665,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.0568092,
  "longitude": 77.5758725,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.0577037,
  "longitude": 77.57466690000001,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.0579222,
  "longitude": 77.57364125,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.05789185,
  "longitude": 77.57302659999999,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.0583081,
  "longitude": 77.57245094999999,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.0553196,
  "longitude": 77.57507865,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.05527354999999,
  "longitude": 77.5744959,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.05514785,
  "longitude": 77.57444468,
  "signal_strength_dBm": -55
},
{
  "latitude": 13.05502149999999,
  "longitude": 77.57456020000001,
  "signal_strength_dBm": -94
},
{
  "latitude": 13.05513945,
  "longitude": 77.57424785,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.05486979999999,
  "longitude": 77.5746637,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.05451435,
```

```
Pretty-print
-----
    "signal_strength_dBm": -107
},
{
    "latitude": 13.054374,
    "longitude": 77.57411155,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.0547465,
    "longitude": 77.57389864999999,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.055103800000001,
    "longitude": 77.57403825,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.055276450000001,
    "longitude": 77.5741057,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.05528485,
    "longitude": 77.57430465,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0551669,
    "longitude": 77.57462290000001,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.05488684999999,
    "longitude": 77.5743119,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.05369395,
    "longitude": 77.57365755000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.05391375,
    "longitude": 77.5726549,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.0537039,
    "longitude": 77.57249715,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0534202,
    "longitude": 77.57300285,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.05634865,
    "longitude": 77.57807165,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0565041,
    "longitude": 77.57823619999999,
    "signal_strength_dBm": -72
},
{
```

```
Pretty-print
{
    "longitude": 77.5787475,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.05592105,
    "longitude": 77.5776923,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.056918750000001,
    "longitude": 77.57944405,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.056732400000001,
    "longitude": 77.57985504999999,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.05843314999999,
    "longitude": 77.577878,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.05837264999999,
    "longitude": 77.57823024999999,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0585828,
    "longitude": 77.578337,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.058856250000002,
    "longitude": 77.578473,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05912395,
    "longitude": 77.57867315,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.05918195,
    "longitude": 77.57854789999999,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0587554,
    "longitude": 77.58107365000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0585894,
    "longitude": 77.58118830000001,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.058399600000001,
    "longitude": 77.58184775000001,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.05870885,
    "longitude": 77.58272235,
    "signal_strength_dBm": -100
},
```

```
Pretty-print
{
    "latitude": 13.05872175,
    "longitude": 77.58251329999999,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0588113,
    "longitude": 77.5831079,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.05928865,
    "longitude": 77.5828382,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.0588093,
    "longitude": 77.58276255,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0587673,
    "longitude": 77.5834449,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.05795835,
    "longitude": 77.58324250000001,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05789980000001,
    "longitude": 77.58355845,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.0584743,
    "longitude": 77.5841568,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.058359150000001,
    "longitude": 77.58420875,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.0581983,
    "longitude": 77.58469995,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.05820855,
    "longitude": 77.58521815,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.05826355,
    "longitude": 77.5856607,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.05830345,
    "longitude": 77.58529845,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.051706249999999,
    "longitude": 77.58064185,
    "signal_strength_dBm": -40
```

Pretty-print

```
{  
    "latitude": 13.05267195,  
    "longitude": 77.5818344,  
    "signal_strength_dBm": -72  
},  
{  
    "latitude": 13.0519241,  
    "longitude": 77.58160845,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.0530297,  
    "longitude": 77.58194245,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.053317400000001,  
    "longitude": 77.58202935,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.05320805,  
    "longitude": 77.58175845,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.05354095,  
    "longitude": 77.5818706,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.05791405,  
    "longitude": 77.5925096,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.0585512,  
    "longitude": 77.5867101,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.0583802,  
    "longitude": 77.58603815000001,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.05845245,  
    "longitude": 77.58613260000001,  
    "signal_strength_dBm": -65  
},  
{  
    "latitude": 13.05835435,  
    "longitude": 77.5861974,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.05819715,  
    "longitude": 77.58608815,  
    "signal_strength_dBm": -57  
},  
{  
    "latitude": 13.0582271,  
    "longitude": 77.58617525,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.05779495,  
    "longitude": 77.58788925,  
    "signal_strength_dBm": -50  
}
```

Pretty-print

```
},
{
  "latitude": 13.06011895,
  "longitude": 77.58922154999999,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.060302,
  "longitude": 77.58934675,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0605752,
  "longitude": 77.5892875,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.06043635,
  "longitude": 77.58947739999999,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.06073795,
  "longitude": 77.58906055,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.0607858,
  "longitude": 77.5889887,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.0607893,
  "longitude": 77.5889653,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.06078115,
  "longitude": 77.58894015,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.06064874999999,
  "longitude": 77.58884195,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.0605128,
  "longitude": 77.5887521,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.0604877,
  "longitude": 77.5887521,
  "signal_strength_dBm": -77
},
{
  "latitude": 13.060463200000001,
  "longitude": 77.58876885000001,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.060300250000001,
  "longitude": 77.58901195,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.06006045,
```

```
Pretty-print
-----
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0599661,
    "longitude": 77.58956605,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.059962,
    "longitude": 77.5895936,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.05999935,
    "longitude": 77.58963315,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.06011605,
    "longitude": 77.58972,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.060207049999999,
    "longitude": 77.5897805,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.060223950000001,
    "longitude": 77.5897799,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0602362,
    "longitude": 77.58976609999999,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06024265,
    "longitude": 77.58972415,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.06024905,
    "longitude": 77.58966724999999,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06026245,
    "longitude": 77.58962715,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06029805,
    "longitude": 77.5895918,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0603704,
    "longitude": 77.5895367,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.05925585,
    "longitude": 77.59078145000001,
    "signal_strength_dBm": -68
},
{
```

```
Pretty-print
{
    "longitude": 77.5907679,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.05924394999999,
    "longitude": 77.59075595,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05923239999999,
    "longitude": 77.5907474999999,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0593875,
    "longitude": 77.59054710000001,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05921875,
    "longitude": 77.59074355,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.0592046,
    "longitude": 77.59074455000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.059173,
    "longitude": 77.5907879,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05917579999998,
    "longitude": 77.59080165,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.05918255,
    "longitude": 77.59081330000001,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.059192500000002,
    "longitude": 77.5908222,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.059091850000002,
    "longitude": 77.590949,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0592047,
    "longitude": 77.59082745,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0592179,
    "longitude": 77.59082855,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05919159999998,
    "longitude": 77.5907504,
    "signal_strength_dBm": -49
},
```

```
Pretty-print
{
    "latitude": 13.05918125,
    "longitude": 77.5907604,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.059174800000001,
    "longitude": 77.59077339999999,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0591305,
    "longitude": 77.59073575,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.059230750000001,
    "longitude": 77.5908253,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.0592422,
    "longitude": 77.59081835,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.059250599999999,
    "longitude": 77.5908079,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0592943,
    "longitude": 77.59084625,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.059255149999998,
    "longitude": 77.590795,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0592334,
    "longitude": 77.59102335,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.05940735,
    "longitude": 77.59080069999999,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0590613,
    "longitude": 77.59112385,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.0590817,
    "longitude": 77.59122335,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.058934350000001,
    "longitude": 77.59103625,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.05897795,
    "longitude": 77.59084915,
    "signal_strength_dBm": -57
```

Pretty-print

```
{  
    "latitude": 13.0587947,  
    "longitude": 77.5911031,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.059226299999999,  
    "longitude": 77.59051235000001,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.0594523,  
    "longitude": 77.5903315,  
    "signal_strength_dBm": -52  
},  
{  
    "latitude": 13.05954015,  
    "longitude": 77.59031759999999,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.0596466,  
    "longitude": 77.59036130000001,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.059602949999999,  
    "longitude": 77.59025875,  
    "signal_strength_dBm": -86  
},  
{  
    "latitude": 13.0595471,  
    "longitude": 77.59027315,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.059615350000001,  
    "longitude": 77.59055105,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.05887765,  
    "longitude": 77.59124575,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.058457950000001,  
    "longitude": 77.5911074,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.0565706,  
    "longitude": 77.5904227,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.056685850000001,  
    "longitude": 77.5902768,  
    "signal_strength_dBm": -76  
},  
{  
    "latitude": 13.05668645,  
    "longitude": 77.59051009999999,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.0559123,  
    "longitude": 77.58531450000001,  
    "signal_strength_dBm": -80  
}
```

Pretty-print

```
},
{
  "latitude": 13.055055,
  "longitude": 77.58989170000001,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.056322999999999,
  "longitude": 77.5927518,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.056196,
  "longitude": 77.59320464999999,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.056353999999999,
  "longitude": 77.5932086,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.0592293,
  "longitude": 77.5945788,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.0559334,
  "longitude": 77.59428940000001,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.055965149999999,
  "longitude": 77.59424440000001,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.055844449999999,
  "longitude": 77.5942775,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.055785149999998,
  "longitude": 77.59422155,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.0559441,
  "longitude": 77.59419270000001,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.05600175,
  "longitude": 77.59400945,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.05585305,
  "longitude": 77.59418174999999,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.0558012,
  "longitude": 77.59406775,
  "signal_strength_dBm": -48
},
{
  "latitude": 13.0704525,
```

```
Pretty-print
-----
    "signal_strength_dBm": -103
},
{
    "latitude": 13.0623739,
    "longitude": 77.5768379,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.06279575,
    "longitude": 77.57580845000001,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.0682018,
    "longitude": 77.5847268,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.06841825,
    "longitude": 77.58502250000001,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0681798,
    "longitude": 77.58499445000001,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.06317275,
    "longitude": 77.5733175,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0630846,
    "longitude": 77.57392859999999,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.06302825,
    "longitude": 77.5738248,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06292665,
    "longitude": 77.57399394999999,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0630873,
    "longitude": 77.5756261,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0630876,
    "longitude": 77.57573719999999,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0630898,
    "longitude": 77.57539915000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0643071,
    "longitude": 77.57536605,
    "signal_strength_dBm": -96
},
```

```
Pretty-print
{
    "longitude": 77.57529174999999,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.06395885,
    "longitude": 77.57529174999999,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.06393905,
    "longitude": 77.57530765,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.063907149999999,
    "longitude": 77.57545454999999,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0638787,
    "longitude": 77.57563504999999,
    "signal_strength_dBm": -58
},
{
    "latitude": 13.063875549999999,
    "longitude": 77.5757333,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.06409335,
    "longitude": 77.57573235,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.06368135,
    "longitude": 77.57565539999999,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.06345035,
    "longitude": 77.57561734999999,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.06338745,
    "longitude": 77.57557929999999,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.063350400000001,
    "longitude": 77.57550764999999,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.063342599999999,
    "longitude": 77.57536255,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.0652092,
    "longitude": 77.575212,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.06518415,
    "longitude": 77.57532035,
    "signal_strength_dBm": -92
},
```

```
Pretty-print
{
    "latitude": 13.0653161,
    "longitude": 77.57526855,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.061251949999999,
    "longitude": 77.5738223,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0611959,
    "longitude": 77.57393985,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.06097305,
    "longitude": 77.57535809999999,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.0608015,
    "longitude": 77.5753556,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.061163950000001,
    "longitude": 77.57539259999999,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.0613383,
    "longitude": 77.5754679,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.060781500000001,
    "longitude": 77.57590955,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0611213,
    "longitude": 77.57605495,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.061388350000001,
    "longitude": 77.5761353,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0616858,
    "longitude": 77.5765815,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.061556249999999,
    "longitude": 77.57654205,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.060773000000001,
    "longitude": 77.5764475,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.060635399999999,
    "longitude": 77.5764707,
    "signal_strength_dBm": -52
```

Pretty-print

```
{ "latitude": 13.0607749,
  "longitude": 77.5767312,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.06118535,
  "longitude": 77.57757235,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.0614297,
  "longitude": 77.58111195000001,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.061773599999999,
  "longitude": 77.58117625,
  "signal_strength_dBm": -98
},
{
  "latitude": 13.061153449999999,
  "longitude": 77.582438,
  "signal_strength_dBm": -94
},
{
  "latitude": 13.061240699999999,
  "longitude": 77.5793046,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.05930185,
  "longitude": 77.57349765000001,
  "signal_strength_dBm": -99
},
{
  "latitude": 13.0680676,
  "longitude": 77.58074715000001,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.06826085,
  "longitude": 77.580844,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.067106500000001,
  "longitude": 77.57684395,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.06630465,
  "longitude": 77.5759144,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.0664008,
  "longitude": 77.576026,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.065951049999999,
  "longitude": 77.57579785,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.06566125,
  "longitude": 77.57584990000001,
```

Pretty-print

```
},
{
  "latitude": 13.066104450000001,
  "longitude": 77.57608139999999,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.06603065,
  "longitude": 77.57631125,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.0660601,
  "longitude": 77.5763755,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.06612265,
  "longitude": 77.5764292,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.0660587,
  "longitude": 77.5764935,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.06594785,
  "longitude": 77.57839805,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.06774074999999,
  "longitude": 77.5789715,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.0676274,
  "longitude": 77.57939445,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.067541,
  "longitude": 77.57978825000001,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.0650882,
  "longitude": 77.57516115,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.065032,
  "longitude": 77.57538059999999,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.06498675,
  "longitude": 77.5756672,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.06740885,
  "longitude": 77.57418899999999,
  "signal_strength_dBm": -85
},
{
  "latitude": 13.06750585,
```

```
Pretty-print
-----
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06723,
    "longitude": 77.57429640000001,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.067124,
    "longitude": 77.57443275,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.0688951,
    "longitude": 77.57414945,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.068658500000002,
    "longitude": 77.57449539999999,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.06437715,
    "longitude": 77.5910267,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.0643009,
    "longitude": 77.59121475,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0641182,
    "longitude": 77.5913552,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.06406475,
    "longitude": 77.59112855,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06424745,
    "longitude": 77.5909881,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.0640953,
    "longitude": 77.59216225,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.063087249999999,
    "longitude": 77.59197715,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.063239549999999,
    "longitude": 77.59205605,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0664354,
    "longitude": 77.5921923,
    "signal_strength_dBm": -110
},
```

```
Pretty-print
[{"longitude": 77.59243455000001, "signal_strength_dBm": -58}, {"latitude": 13.06639914999999, "longitude": 77.5925677, "signal_strength_dBm": -70}, {"latitude": 13.06636945, "longitude": 77.5928323999999, "signal_strength_dBm": -83}, {"latitude": 13.06756005, "longitude": 77.58954855, "signal_strength_dBm": -85}, {"latitude": 13.0674909, "longitude": 77.58941845000001, "signal_strength_dBm": -74}, {"latitude": 13.06757, "longitude": 77.59289509999999, "signal_strength_dBm": -109}, {"latitude": 13.0677543, "longitude": 77.59262635, "signal_strength_dBm": -68}, {"latitude": 13.0684055, "longitude": 77.5876436, "signal_strength_dBm": -54}, {"latitude": 13.06838069999999, "longitude": 77.58754735, "signal_strength_dBm": -98}, {"latitude": 13.0684185, "longitude": 77.5870999, "signal_strength_dBm": -42}, {"latitude": 13.06842635, "longitude": 77.5870214, "signal_strength_dBm": -97}, {"latitude": 13.06843024999999, "longitude": 77.58686985, "signal_strength_dBm": -93}, {"latitude": 13.0647832, "longitude": 77.59309655, "signal_strength_dBm": -98}, {"latitude": 13.06515415000001, "longitude": 77.59294825, "signal_strength_dBm": -74}]
```

```
Pretty-print
{
    "latitude": 13.0622754,
    "longitude": 77.57380645,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.062102450000001,
    "longitude": 77.574039,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.06258375,
    "longitude": 77.57369315,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.06262795,
    "longitude": 77.57332679999999,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0647555,
    "longitude": 77.58929330000001,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.062637299999999,
    "longitude": 77.59467135,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.0627079,
    "longitude": 77.59464650000001,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.065338050000001,
    "longitude": 77.59509919999999,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0707474,
    "longitude": 77.5751374,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0705052,
    "longitude": 77.57478845,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06722355,
    "longitude": 77.5919502,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.06725655,
    "longitude": 77.591931,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.067285250000001,
    "longitude": 77.5918519,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.067236900000001,
    "longitude": 77.59176605,
    "signal_strength_dBm": -102
```

Pretty-print

```
{  
    "latitude": 13.05887715,  
    "longitude": 77.58115645000001,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.05888945,  
    "longitude": 77.58107285,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.06250425,  
    "longitude": 77.59362875,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.05559735,  
    "longitude": 77.5762986,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.05560685,  
    "longitude": 77.57626884999999,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.055720350000001,  
    "longitude": 77.57636274999999,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.0573436,  
    "longitude": 77.57681579999999,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.05736059999999,  
    "longitude": 77.5768164,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.05702065,  
    "longitude": 77.57643809999999,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.057115750000001,  
    "longitude": 77.57671805,  
    "signal_strength_dBm": -91  
},  
{  
    "latitude": 13.05658349999999,  
    "longitude": 77.5769161,  
    "signal_strength_dBm": -66  
},  
{  
    "latitude": 13.06541155,  
    "longitude": 77.59406394999999,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.0653782,  
    "longitude": 77.59374399999999,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.0595653,  
    "longitude": 77.58233874999999,
```

Pretty-print

```
},
{
  "latitude": 13.0587387,
  "longitude": 77.58275035,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.0597381,
  "longitude": 77.58383,
  "signal_strength_dBm": -91
},
{
  "latitude": 13.0592995,
  "longitude": 77.58176255,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.060299350000001,
  "longitude": 77.58232749999999,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.0602558,
  "longitude": 77.58254525000001,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.060080899999999,
  "longitude": 77.5836759,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.0601731,
  "longitude": 77.58369210000001,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.05964475,
  "longitude": 77.58363655,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0596226,
  "longitude": 77.5837874,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.0589436,
  "longitude": 77.5823442,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.0628823,
  "longitude": 77.5776883,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.06280065,
  "longitude": 77.577886,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.062736950000001,
  "longitude": 77.57786535,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.06267395,
```

```
Pretty-print
-----
  "signal_strength_dBm": -58
},
{
  "latitude": 13.06271345,
  "longitude": 77.5777877,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.0623078,
  "longitude": 77.57800005,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.0619902,
  "longitude": 77.57781785,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.06182155,
  "longitude": 77.577677,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.06156255,
  "longitude": 77.57752905,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.062113,
  "longitude": 77.57756885,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.0606019,
  "longitude": 77.5766742,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.0605443,
  "longitude": 77.57659635,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.06053255,
  "longitude": 77.57650465,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.06142295,
  "longitude": 77.57709965000001,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.06087995,
  "longitude": 77.57662785,
  "signal_strength_dBm": -62
},
{
  "latitude": 13.060903849999999,
  "longitude": 77.57686275,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.061305149999999,
  "longitude": 77.5770604,
  "signal_strength_dBm": -85
},
```

```
Pretty-print
-----
{
    "longitude": 77.57457015,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.060061650000002,
    "longitude": 77.57434380000001,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.060378199999999,
    "longitude": 77.57568015,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.065229500000001,
    "longitude": 77.57099099999999,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0658927,
    "longitude": 77.57249085000001,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.05379225,
    "longitude": 77.57320915,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05392255,
    "longitude": 77.57280234999999,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0678497,
    "longitude": 77.57506344999999,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.06763385,
    "longitude": 77.57491815,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.06764845,
    "longitude": 77.57481365,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.06763565,
    "longitude": 77.57477925,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.067566,
    "longitude": 77.5747559,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.067423250000001,
    "longitude": 77.57471925,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.0635008,
    "longitude": 77.58526764999999,
    "signal_strength_dBm": -50
},
```

```
Pretty-print
{
    "latitude": 13.070126349999999,
    "longitude": 77.58676,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.070072249999999,
    "longitude": 77.58678185,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0699784,
    "longitude": 77.58677705,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.07316825,
    "longitude": 77.5929419,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.06988195,
    "longitude": 77.58718915,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.0703639,
    "longitude": 77.58727114999999,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0700787,
    "longitude": 77.57929965,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0705715,
    "longitude": 77.5801731,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.070504750000001,
    "longitude": 77.57983965,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0704954,
    "longitude": 77.57981240000001,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0705574,
    "longitude": 77.57977865000001,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0707271,
    "longitude": 77.5797372,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.0547809,
    "longitude": 77.5789952,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.0552314,
    "longitude": 77.57848824999999,
    "signal_strength_dBm": -95
```

Pretty-print

```
{  
    "latitude": 13.0554077,  
    "longitude": 77.5777935,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.0564639,  
    "longitude": 77.5746059,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.05650675,  
    "longitude": 77.57452945,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.05681955,  
    "longitude": 77.57465175,  
    "signal_strength_dBm": -98  
},  
{  
    "latitude": 13.05697455,  
    "longitude": 77.58178495,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.05680265,  
    "longitude": 77.58163435,  
    "signal_strength_dBm": -106  
},  
{  
    "latitude": 13.05394735,  
    "longitude": 77.5814931,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.0535315,  
    "longitude": 77.58133855,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.05350485,  
    "longitude": 77.5811898,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.05319475,  
    "longitude": 77.57568975,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.05322275,  
    "longitude": 77.5824816,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.0528782,  
    "longitude": 77.5823016,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.052723,  
    "longitude": 77.5822291,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.05252665,  
    "longitude": 77.58219685,
```

Pretty-print

```
},
{
  "latitude": 13.0524038,
  "longitude": 77.58220265,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.05224835,
  "longitude": 77.5821784,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.05629755,
  "longitude": 77.57515749999999,
  "signal_strength_dBm": -82
},
{
  "latitude": 13.05636674999999,
  "longitude": 77.57518329999999,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0635422,
  "longitude": 77.59105295,
  "signal_strength_dBm": -74
},
{
  "latitude": 13.066066150000001,
  "longitude": 77.58646055,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.06628075,
  "longitude": 77.58587195,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.05777185,
  "longitude": 77.58843784999999,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.0576431,
  "longitude": 77.5921453,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.05768835,
  "longitude": 77.59215185,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.068829000000001,
  "longitude": 77.59220705,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.0694018,
  "longitude": 77.5923351,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.0680955,
  "longitude": 77.59215675,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.06774275,
```

```
Pretty-print
-----
    "signal_strength_dBm": -105
},
{
    "latitude": 13.06760425,
    "longitude": 77.5919643,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0677277,
    "longitude": 77.59183955,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06787075,
    "longitude": 77.59170545,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.068114399999999,
    "longitude": 77.59151705,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0689518,
    "longitude": 77.59159414999999,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.06951025,
    "longitude": 77.59204945,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.069445550000001,
    "longitude": 77.5924792,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0554263,
    "longitude": 77.59369319999999,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.055395650000001,
    "longitude": 77.59365805,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.055396850000001,
    "longitude": 77.59390055,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0554262,
    "longitude": 77.59381604999999,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0553658,
    "longitude": 77.59369705,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.055367100000002,
    "longitude": 77.59381669999999,
    "signal_strength_dBm": -80
},
{
```

```
Pretty-print
{
    "longitude": 77.59346314999999,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0611474,
    "longitude": 77.57400255,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.06109865,
    "longitude": 77.5741946,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.06127955,
    "longitude": 77.57436824999999,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.07001585,
    "longitude": 77.59267804999999,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.07001275,
    "longitude": 77.5926217,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.070383249999999,
    "longitude": 77.5926351,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0699678,
    "longitude": 77.59266375,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.07038335,
    "longitude": 77.59266790000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.070644999999999,
    "longitude": 77.592472,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.070465850000001,
    "longitude": 77.59234585,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.070541,
    "longitude": 77.5922795,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.070365,
    "longitude": 77.59225534999999,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0701625,
    "longitude": 77.5922715,
    "signal_strength_dBm": -61
},
```

```
Pretty-print
{
    "latitude": 13.0700024,
    "longitude": 77.5924339,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.06999145,
    "longitude": 77.59223515,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.070651999999999,
    "longitude": 77.59181245,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.070254550000001,
    "longitude": 77.59170979999999,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.07035155,
    "longitude": 77.59173665,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.070136000000002,
    "longitude": 77.59164885,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.070178850000001,
    "longitude": 77.59169399999999,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.069998349999999,
    "longitude": 77.59209795000001,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.0699697,
    "longitude": 77.59269835,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.069921650000001,
    "longitude": 77.59268405,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0700368,
    "longitude": 77.59189185,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0700132,
    "longitude": 77.59150295,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0699551,
    "longitude": 77.5918516,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.061179,
    "longitude": 77.57493645,
    "signal_strength_dBm": -53
```

Pretty-print

```
{  
    "latitude": 13.0612845,  
    "longitude": 77.5747622,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.061420349999999,  
    "longitude": 77.57453795,  
    "signal_strength_dBm": -83  
},  
{  
    "latitude": 13.0615484,  
    "longitude": 77.574326500000001,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.0616105,  
    "longitude": 77.5742249,  
    "signal_strength_dBm": -44  
},  
{  
    "latitude": 13.0616309,  
    "longitude": 77.5742197,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.061639799999998,  
    "longitude": 77.5742273,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.0616825,  
    "longitude": 77.57427805,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.0617202,  
    "longitude": 77.5743344,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.0615977,  
    "longitude": 77.57455669999999,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.061382,  
    "longitude": 77.57492005,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.06171655,  
    "longitude": 77.57435459999999,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.05279355,  
    "longitude": 77.573655,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.05249685,  
    "longitude": 77.57908255000001,  
    "signal_strength_dBm": -101  
},  
{  
    "latitude": 13.052594899999999,  
    "longitude": 77.57913655,  
}
```

Pretty-print

```
},
{
  "latitude": 13.0526534,
  "longitude": 77.5791801,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.05264985,
  "longitude": 77.57919855,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.0526556,
  "longitude": 77.579218,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.0531019,
  "longitude": 77.57946559999999,
  "signal_strength_dBm": -75
},
{
  "latitude": 13.05355284999999,
  "longitude": 77.57970445000001,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.0535694,
  "longitude": 77.579701,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0536359,
  "longitude": 77.57957945,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.05463855,
  "longitude": 77.57890724999999,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.05602145,
  "longitude": 77.57860905000001,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.05670724999999,
  "longitude": 77.57732845,
  "signal_strength_dBm": -43
},
{
  "latitude": 13.05657935,
  "longitude": 77.57724759999999,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.069889,
  "longitude": 77.57325705,
  "signal_strength_dBm": -52
},
{
  "latitude": 13.060827150000001,
  "longitude": 77.57646865000001,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.0608581,
```

```
Pretty-print
-----
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0593505,
    "longitude": 77.5937159,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.0593054,
    "longitude": 77.59402324999999,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.0676339,
    "longitude": 77.5855557,
    "signal_strength_dBm": -64
},
{
    "latitude": 13.06800715,
    "longitude": 77.5854353,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.068399,
    "longitude": 77.5875697,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0646563,
    "longitude": 77.58733079999999,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.064982050000001,
    "longitude": 77.58793675,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.0625014,
    "longitude": 77.59297545,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.062852500000002,
    "longitude": 77.59228164999999,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.06304865,
    "longitude": 77.5918776,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.0634506,
    "longitude": 77.59079075,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.06358265,
    "longitude": 77.59033435,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.0636641,
    "longitude": 77.5900708,
    "signal_strength_dBm": -45
},
{
```

```
Pretty-print
-----
{
    "longitude": 77.59002495,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.06368965,
    "longitude": 77.58985444999999,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.06368615,
    "longitude": 77.58915114999999,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.06368025,
    "longitude": 77.58797625,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06364495,
    "longitude": 77.58710239999999,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.062686500000002,
    "longitude": 77.5926092,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0626432,
    "longitude": 77.5929295,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.06285045,
    "longitude": 77.59251125,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.06302715,
    "longitude": 77.59216225,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.06319225,
    "longitude": 77.59182235,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.0633528,
    "longitude": 77.59147895,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0634804,
    "longitude": 77.59117599999999,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.063624950000001,
    "longitude": 77.5906886,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.06376855,
    "longitude": 77.59016095,
    "signal_strength_dBm": -69
},
```

```
Pretty-print
{
    "latitude": 13.0638215,
    "longitude": 77.58991549999999,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.063821650000001,
    "longitude": 77.58933145,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0637981,
    "longitude": 77.58781859999999,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06217925,
    "longitude": 77.59591895,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.06224695,
    "longitude": 77.5939568,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.062258100000001,
    "longitude": 77.59427145000001,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.062153200000001,
    "longitude": 77.5942148,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0616765,
    "longitude": 77.5940611,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.061720300000001,
    "longitude": 77.5940363,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06180195,
    "longitude": 77.59404905,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.062020100000002,
    "longitude": 77.59575025000001,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.061633400000002,
    "longitude": 77.59551355,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.061231,
    "longitude": 77.5953989,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.061208149999999,
    "longitude": 77.5953399,
    "signal_strength_dBm": -65
```

Pretty-print

```
{  
    "latitude": 13.0612291,  
    "longitude": 77.59501535000001,  
    "signal_strength_dBm": -69  
},  
{  
    "latitude": 13.06140285,  
    "longitude": 77.5947746,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.0615805,  
    "longitude": 77.59468475,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.06164255,  
    "longitude": 77.59449765,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.061694800000001,  
    "longitude": 77.59434945000001,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.061901500000001,  
    "longitude": 77.59421975000001,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.06197205,  
    "longitude": 77.59412185,  
    "signal_strength_dBm": -59  
},  
{  
    "latitude": 13.0623363,  
    "longitude": 77.59439144999999,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.06282875,  
    "longitude": 77.5946292,  
    "signal_strength_dBm": -79  
},  
{  
    "latitude": 13.06239645,  
    "longitude": 77.5945432,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.0715449,  
    "longitude": 77.58911555,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.07040645,  
    "longitude": 77.59037169999999,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.07076865,  
    "longitude": 77.58902115000001,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.07102595,  
    "longitude": 77.58896805,  
    "signal_strength_dBm": -85  
}
```

Pretty-print

```
},
{
  "latitude": 13.070466249999999,
  "longitude": 77.5914633,
  "signal_strength_dBm": -54
},
{
  "latitude": 13.07039725,
  "longitude": 77.59171985,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0703842,
  "longitude": 77.59177825,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.07071655,
  "longitude": 77.59188015000001,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.070705700000001,
  "longitude": 77.59192010000001,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06990705,
  "longitude": 77.5924229,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.069918600000001,
  "longitude": 77.59262875,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.07071255,
  "longitude": 77.59023884999999,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.070713099999999,
  "longitude": 77.59035595,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.0706946,
  "longitude": 77.59047605,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.07062405,
  "longitude": 77.59070539999999,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0710265,
  "longitude": 77.5905915,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.0709736,
  "longitude": 77.59069675,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.0707327,
```

```
Pretty-print
-----
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0709195,
    "longitude": 77.5908472,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.07086095,
    "longitude": 77.59105199999999,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.0704995,
    "longitude": 77.59100945,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0705423,
    "longitude": 77.59090785000001,
    "signal_strength_dBm": -68
},
{
    "latitude": 13.070508400000001,
    "longitude": 77.59114819999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.07063775,
    "longitude": 77.5912662,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.07077385,
    "longitude": 77.59128165,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.070815549999999,
    "longitude": 77.59121085,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.07108345,
    "longitude": 77.59047534999999,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0711331,
    "longitude": 77.5903399,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0711651,
    "longitude": 77.5901944,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0711762,
    "longitude": 77.5899604,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.070065150000001,
    "longitude": 77.5916512,
    "signal_strength_dBm": -80
},
{
```

```
Pretty-print
{
    "longitude": 77.58670855,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.065093749999999,
    "longitude": 77.58669435,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0649408,
    "longitude": 77.5866685,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0649379,
    "longitude": 77.58660585000001,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.06526225,
    "longitude": 77.58730795,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.055330399999999,
    "longitude": 77.58489309999999,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.05197495,
    "longitude": 77.593625,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.05651565,
    "longitude": 77.59308490000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0565261,
    "longitude": 77.59321285,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0568117,
    "longitude": 77.5929761,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.05679355,
    "longitude": 77.59298235,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.05670205,
    "longitude": 77.5929673,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.05660965,
    "longitude": 77.59294940000001,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.05658905,
    "longitude": 77.5929529,
    "signal_strength_dBm": -62
},
```

```
Pretty-print
{
    "latitude": 13.05656775,
    "longitude": 77.5930863,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0566417,
    "longitude": 77.5923809,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.056764000000001,
    "longitude": 77.59239635,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.05687755,
    "longitude": 77.59242645,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.056217100000001,
    "longitude": 77.5872809,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.05622065,
    "longitude": 77.58735805,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.05737745,
    "longitude": 77.5886846,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.05737875,
    "longitude": 77.58853475000001,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0571154,
    "longitude": 77.59313965,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.0571247,
    "longitude": 77.5932321,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05712805,
    "longitude": 77.59298415,
    "signal_strength_dBm": -46
},
{
    "latitude": 13.057076949999999,
    "longitude": 77.5929086,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.05719915,
    "longitude": 77.592925000000001,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0570075,
    "longitude": 77.592889500000001,
    "signal_strength_dBm": -74
```

Pretty-print

```
{  
    "latitude": 13.0569908,  
    "longitude": 77.59286935,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.056984799999999,  
    "longitude": 77.5928327,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.05705605,  
    "longitude": 77.5922621,  
    "signal_strength_dBm": -53  
},  
{  
    "latitude": 13.0571305,  
    "longitude": 77.59169985,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.057137749999999,  
    "longitude": 77.59166855000001,  
    "signal_strength_dBm": -45  
},  
{  
    "latitude": 13.05715145,  
    "longitude": 77.5916407,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.057181700000001,  
    "longitude": 77.59162814999999,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.0572826,  
    "longitude": 77.59163975,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.0573721,  
    "longitude": 77.5916589,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.0573888,  
    "longitude": 77.59167550000001,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.057406,  
    "longitude": 77.5917089,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.05111995,  
    "longitude": 77.59341705,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.05743055,  
    "longitude": 77.59176360000001,  
    "signal_strength_dBm": -58  
},  
{  
    "latitude": 13.05744705,  
    "longitude": 77.5918155,
```

Pretty-print

```
},
{
  "latitude": 13.05745125,
  "longitude": 77.59186249999999,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.057449850000001,
  "longitude": 77.59193880000001,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.05743975,
  "longitude": 77.59207485,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.05745175,
  "longitude": 77.5921651,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.057413050000001,
  "longitude": 77.5922823,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.0575066,
  "longitude": 77.5921784,
  "signal_strength_dBm": -67
},
{
  "latitude": 13.0575243,
  "longitude": 77.5923032,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.05746915,
  "longitude": 77.5924124,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.057412750000001,
  "longitude": 77.5924048,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.0573747,
  "longitude": 77.5925611,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.057354149999998,
  "longitude": 77.59273185,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.05734875,
  "longitude": 77.59276795,
  "signal_strength_dBm": -50
},
{
  "latitude": 13.057341650000001,
  "longitude": 77.5928069,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.05733375,
```

```
Pretty-print
-----
    "signal_strength_dBm": -102
},
{
    "latitude": 13.057327399999998,
    "longitude": 77.59286589999999,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0573218,
    "longitude": 77.5928855,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0573133,
    "longitude": 77.59290179999999,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.05729385,
    "longitude": 77.5929187,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.057271400000001,
    "longitude": 77.59292945,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.05799695,
    "longitude": 77.59571365,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.058039650000001,
    "longitude": 77.59554539999999,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.0581142,
    "longitude": 77.59525185000001,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0583302,
    "longitude": 77.5937333,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0583241,
    "longitude": 77.5937989,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0583046,
    "longitude": 77.5938122,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05820885,
    "longitude": 77.59381925,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.0581118,
    "longitude": 77.5938171,
    "signal_strength_dBm": -98
},
{
```

```
Pretty-print
{
    "longitude": 77.59380060000001,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.058075200000001,
    "longitude": 77.59373035,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.062274649999999,
    "longitude": 77.59362725,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0600199,
    "longitude": 77.59371335,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.058025050000001,
    "longitude": 77.5915452,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0580094,
    "longitude": 77.5916224,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.05785965,
    "longitude": 77.5908447,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0577983,
    "longitude": 77.5910717,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.05774795,
    "longitude": 77.5912599,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0576588,
    "longitude": 77.5913454,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.057696400000001,
    "longitude": 77.59132355,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0577838,
    "longitude": 77.59092255,
    "signal_strength_dBm": -87
},
{
    "latitude": 13.0577101,
    "longitude": 77.5908938,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.057677349999999,
    "longitude": 77.59085595,
    "signal_strength_dBm": -81
},
```

```
Pretty-print
{
    "latitude": 13.05765765,
    "longitude": 77.59075945000001,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.06156955,
    "longitude": 77.57405335,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.061589600000001,
    "longitude": 77.57407855,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.061603550000001,
    "longitude": 77.5741092,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.061613,
    "longitude": 77.57414415,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0616187,
    "longitude": 77.5741764,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.0613502,
    "longitude": 77.5754872,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06131304999999,
    "longitude": 77.57562005,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.0612462,
    "longitude": 77.5758167,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.061188900000001,
    "longitude": 77.5757071,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0626489,
    "longitude": 77.57587365,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0627228,
    "longitude": 77.57590105,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.06274655,
    "longitude": 77.57592435000001,
    "signal_strength_dBm": -79
```

Pretty-print

```
{  
    "latitude": 13.06276375,  
    "longitude": 77.57582984999999,  
    "signal_strength_dBm": -62  
},  
{  
    "latitude": 13.05843705,  
    "longitude": 77.57625734999999,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.05853395,  
    "longitude": 77.57622294,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.0584668,  
    "longitude": 77.5762199,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.0589351,  
    "longitude": 77.5765988,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.05891685,  
    "longitude": 77.57661024999999,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.058902549999999,  
    "longitude": 77.5766168,  
    "signal_strength_dBm": -88  
},  
{  
    "latitude": 13.05889255,  
    "longitude": 77.57662705,  
    "signal_strength_dBm": -91  
},  
{  
    "latitude": 13.058888849999999,  
    "longitude": 77.5766447,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.058910149999999,  
    "longitude": 77.5763817,  
    "signal_strength_dBm": -95  
},  
{  
    "latitude": 13.058929299999999,  
    "longitude": 77.57592585,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.06030335,  
    "longitude": 77.57479705,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.06019225,  
    "longitude": 77.575144,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.060280299999999,  
    "longitude": 77.574800000000001,
```

Pretty-print

```
},
{
  "latitude": 13.05973565,
  "longitude": 77.57472865,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.05993055,
  "longitude": 77.57531555,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.0579976,
  "longitude": 77.575807,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.0581809,
  "longitude": 77.5758965,
  "signal_strength_dBm": -81
},
{
  "latitude": 13.05797345,
  "longitude": 77.57594875000001,
  "signal_strength_dBm": -65
},
{
  "latitude": 13.05815175,
  "longitude": 77.57592405,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.05811845,
  "longitude": 77.57593955,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.0580784,
  "longitude": 77.57594615,
  "signal_strength_dBm": -47
},
{
  "latitude": 13.0580489,
  "longitude": 77.5759485,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.0580262,
  "longitude": 77.5759508,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.05799785,
  "longitude": 77.57595935,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.05797705,
  "longitude": 77.5759718,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.057963149999999,
  "longitude": 77.5759941,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.05788765,
```

```
Pretty-print
-----
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0578691,
    "longitude": 77.57675760000001,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.0578019,
    "longitude": 77.5767508,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.0577252,
    "longitude": 77.5767481,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.05764345,
    "longitude": 77.5767518,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.05748595,
    "longitude": 77.57677935,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.05750254999999,
    "longitude": 77.57675645,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.05799865,
    "longitude": 77.5760372,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.058083400000001,
    "longitude": 77.57608635,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.05815985,
    "longitude": 77.5761231,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.0582761,
    "longitude": 77.57616645,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.058330250000001,
    "longitude": 77.5757274,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.0583061,
    "longitude": 77.57572875,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.058284,
    "longitude": 77.57573585,
    "signal_strength_dBm": -69
},
{
```

```
Pretty-print
{
    "longitude": 77.57620505,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.058392000000001,
    "longitude": 77.57620505,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.0584314,
    "longitude": 77.5762282,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0585711,
    "longitude": 77.57537775,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0575105,
    "longitude": 77.57671735,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.0589843,
    "longitude": 77.5759049,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0590412,
    "longitude": 77.57588465,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.058651350000002,
    "longitude": 77.57588255,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.05864225,
    "longitude": 77.57587355000001,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.058641699999999,
    "longitude": 77.57585025,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.05864,
    "longitude": 77.57580974999999,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.058632,
    "longitude": 77.57580225000001,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.05854205,
    "longitude": 77.57576935,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.058386599999999,
    "longitude": 77.5780643,
    "signal_strength_dBm": -107
},
```

```
Pretty-print
{
    "latitude": 13.0583592,
    "longitude": 77.5781883,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0583629,
    "longitude": 77.5782119,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.05861515,
    "longitude": 77.57783865,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0586309,
    "longitude": 77.5778551,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.05863705,
    "longitude": 77.5778789,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.05863725,
    "longitude": 77.57794580000001,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0586531,
    "longitude": 77.57805765,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.05867085,
    "longitude": 77.57807355,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.058965,
    "longitude": 77.578533,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.05902950000001,
    "longitude": 77.578575,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0590693,
    "longitude": 77.57860395,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.059097699999999,
    "longitude": 77.5786258,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0591152,
    "longitude": 77.57864365,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.0591212,
    "longitude": 77.57865705,
    "signal_strength_dBm": -98
```

Pretty-print

```
{  
    "latitude": 13.0580461,  
    "longitude": 77.57699395,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.058081900000001,  
    "longitude": 77.57710220000001,  
    "signal_strength_dBm": -56  
},  
{  
    "latitude": 13.058115,  
    "longitude": 77.5772012,  
    "signal_strength_dBm": -87  
},  
{  
    "latitude": 13.0581418,  
    "longitude": 77.5772959,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.0581615,  
    "longitude": 77.5773891,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.0577594,  
    "longitude": 77.5781573,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.0573146,  
    "longitude": 77.5771301,  
    "signal_strength_dBm": -73  
},  
{  
    "latitude": 13.0619971,  
    "longitude": 77.5808753,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.06174965,  
    "longitude": 77.5809596,  
    "signal_strength_dBm": -51  
},  
{  
    "latitude": 13.0614285,  
    "longitude": 77.5807373,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.06156035,  
    "longitude": 77.5808222,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.062005599999999,  
    "longitude": 77.58055485,  
    "signal_strength_dBm": -41  
},  
{  
    "latitude": 13.061791,  
    "longitude": 77.5803306,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.06204095,  
    "longitude": 77.58006635000001,
```

Pretty-print

```
},
{
  "latitude": 13.06208305,
  "longitude": 77.5800926,
  "signal_strength_dBm": -95
},
{
  "latitude": 13.05970625,
  "longitude": 77.5766881,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.059961699999999,
  "longitude": 77.5787752,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.06004295,
  "longitude": 77.57880564999999,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.0598098,
  "longitude": 77.57689350000001,
  "signal_strength_dBm": -104
},
{
  "latitude": 13.05730735,
  "longitude": 77.57679095,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.0573777,
  "longitude": 77.57681545,
  "signal_strength_dBm": -49
},
{
  "latitude": 13.0572986,
  "longitude": 77.576817,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.06850915,
  "longitude": 77.58800905,
  "signal_strength_dBm": -70
},
{
  "latitude": 13.068628749999998,
  "longitude": 77.58813169999999,
  "signal_strength_dBm": -108
},
{
  "latitude": 13.0687392,
  "longitude": 77.588245,
  "signal_strength_dBm": -103
},
{
  "latitude": 13.06875125,
  "longitude": 77.5882607,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.06875905,
  "longitude": 77.58827585,
  "signal_strength_dBm": -58
},
{
  "latitude": 13.06875655,
```

```
Pretty-print
-----
    "signal_strength_dBm": -95
},
{
    "latitude": 13.068633250000001,
    "longitude": 77.5884197,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.07312435,
    "longitude": 77.5925917,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.073346,
    "longitude": 77.5925761,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.07181525,
    "longitude": 77.59301780000001,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.071608699999999,
    "longitude": 77.59303405,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.0724996,
    "longitude": 77.59297875,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.058196250000002,
    "longitude": 77.59367420000001,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.05788525,
    "longitude": 77.5936643,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06065275,
    "longitude": 77.59368764999999,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0604158,
    "longitude": 77.5936969,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.06370465,
    "longitude": 77.59352865,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.0634676,
    "longitude": 77.5935341,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0576699,
    "longitude": 77.59365725,
    "signal_strength_dBm": -71
},
{
```

```
Pretty-print
{
    "longitude": 77.59367954999999,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.058844050000001,
    "longitude": 77.59368305,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.05929335,
    "longitude": 77.59368509999999,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.05968885,
    "longitude": 77.59368975,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.06020955,
    "longitude": 77.59369565,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0615736,
    "longitude": 77.59363479999999,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06282365,
    "longitude": 77.59356475000001,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.062388200000001,
    "longitude": 77.59358825000001,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.063327350000002,
    "longitude": 77.5935351,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0632159,
    "longitude": 77.59353985,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0642376,
    "longitude": 77.59351035,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0638933,
    "longitude": 77.59352215,
    "signal_strength_dBm": -65
},
{
    "latitude": 13.066612549999999,
    "longitude": 77.5934063,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.065753749999999,
    "longitude": 77.5934613,
    "signal_strength_dBm": -59
},
```

```
Pretty-print
{
    "latitude": 13.0645311,
    "longitude": 77.59353275000001,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.064951650000001,
    "longitude": 77.593489,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.07256975,
    "longitude": 77.59262885000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.0715978,
    "longitude": 77.5926892,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.070627850000001,
    "longitude": 77.59274615000001,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.0697513,
    "longitude": 77.59280715,
    "signal_strength_dBm": -103
},
{
    "latitude": 13.068881900000001,
    "longitude": 77.5928702,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.06811635,
    "longitude": 77.59292719999999,
    "signal_strength_dBm": -109
},
{
    "latitude": 13.06751775,
    "longitude": 77.59298290000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06718725,
    "longitude": 77.59301375000001,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.0668381,
    "longitude": 77.5930486,
    "signal_strength_dBm": -93
},
{
    "latitude": 13.066262,
    "longitude": 77.59310024999999,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.0657257,
    "longitude": 77.5931324,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.065305649999999,
    "longitude": 77.59315115000001,
    "signal_strength_dBm": -104
```

Pretty-print

```
{  
    "latitude": 13.06456035,  
    "longitude": 77.59316925,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.063774599999999,  
    "longitude": 77.5931934,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.06272755,  
    "longitude": 77.5932504,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.061536100000001,  
    "longitude": 77.5933074,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.0607588,  
    "longitude": 77.5933403,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.05969535,  
    "longitude": 77.5933584,  
    "signal_strength_dBm": -108  
},  
{  
    "latitude": 13.0586672,  
    "longitude": 77.5933537,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.05793225,  
    "longitude": 77.59332810000001,  
    "signal_strength_dBm": -43  
},  
{  
    "latitude": 13.057449649999999,  
    "longitude": 77.59353615,  
    "signal_strength_dBm": -96  
},  
{  
    "latitude": 13.05523165,  
    "longitude": 77.59348485000001,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.057159,  
    "longitude": 77.5932337,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.0575706,  
    "longitude": 77.5924239,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.0574914,  
    "longitude": 77.59282395,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.05744305,  
    "longitude": 77.59302915,  
    "signal_strength_dBm": -95  
}
```

Pretty-print

```
},
{
  "latitude": 13.0574014,
  "longitude": 77.59315050000001,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.0576542,
  "longitude": 77.5918566,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.07335385,
  "longitude": 77.59279305,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.06537005,
  "longitude": 77.5924033,
  "signal_strength_dBm": -59
},
{
  "latitude": 13.07132005,
  "longitude": 77.58905165,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06992635,
  "longitude": 77.59212385000001,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.07054655,
  "longitude": 77.58719415,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.06333805,
  "longitude": 77.59370745000001,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.06336025,
  "longitude": 77.59358075,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.063570349999999,
  "longitude": 77.59374485000001,
  "signal_strength_dBm": -109
},
{
  "latitude": 13.0638296,
  "longitude": 77.5936127,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.063788500000001,
  "longitude": 77.59389775,
  "signal_strength_dBm": -110
},
{
  "latitude": 13.06325925,
  "longitude": 77.5942576,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.063016900000001,
```

```
Pretty-print
-----
  "signal_strength_dBm": -//  
},  
{  
  "latitude": 13.06279935,  
  "longitude": 77.59492515,  
  "signal_strength_dBm": -59  
},  
{  
  "latitude": 13.06319455,  
  "longitude": 77.5952158,  
  "signal_strength_dBm": -97  
},  
{  
  "latitude": 13.0636773,  
  "longitude": 77.59486039999999,  
  "signal_strength_dBm": -46  
},  
{  
  "latitude": 13.06373934999999,  
  "longitude": 77.59445005,  
  "signal_strength_dBm": -49  
},  
{  
  "latitude": 13.06377395,  
  "longitude": 77.59430855,  
  "signal_strength_dBm": -108  
},  
{  
  "latitude": 13.0637772,  
  "longitude": 77.5941342,  
  "signal_strength_dBm": -43  
},  
{  
  "latitude": 13.070605,  
  "longitude": 77.57802985000001,  
  "signal_strength_dBm": -80  
},  
{  
  "latitude": 13.07009989999999,  
  "longitude": 77.5783973,  
  "signal_strength_dBm": -104  
},  
{  
  "latitude": 13.07082775,  
  "longitude": 77.57778885,  
  "signal_strength_dBm": -94  
},  
{  
  "latitude": 13.07073565,  
  "longitude": 77.5778978,  
  "signal_strength_dBm": -73  
},  
{  
  "latitude": 13.07100245,  
  "longitude": 77.57745625000001,  
  "signal_strength_dBm": -71  
},  
{  
  "latitude": 13.07109125,  
  "longitude": 77.5771652,  
  "signal_strength_dBm": -84  
},  
{  
  "latitude": 13.07071155,  
  "longitude": 77.57740045,  
  "signal_strength_dBm": -84  
},  
{
```

```
Pretty-print
{
    "longitude": 77.57810455,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.069394800000001,
    "longitude": 77.57861395,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.06136105,
    "longitude": 77.5942831,
    "signal_strength_dBm": -90
},
{
    "latitude": 13.0610978,
    "longitude": 77.59469949999999,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.0611853,
    "longitude": 77.59422344999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0603652,
    "longitude": 77.59386520000001,
    "signal_strength_dBm": -50
},
{
    "latitude": 13.060247050000001,
    "longitude": 77.5944571,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06075655,
    "longitude": 77.59404875,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0611858,
    "longitude": 77.59414325,
    "signal_strength_dBm": -61
},
{
    "latitude": 13.0611747,
    "longitude": 77.59413384999999,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.06119535,
    "longitude": 77.59416825,
    "signal_strength_dBm": -72
},
{
    "latitude": 13.0611928,
    "longitude": 77.59415525,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0611937,
    "longitude": 77.59418145000001,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.061002550000001,
    "longitude": 77.5951623,
    "signal_strength_dBm": -83
},
```

```
Pretty-print
{
    "latitude": 13.061013,
    "longitude": 77.5951482,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.06097255,
    "longitude": 77.59517274999999,
    "signal_strength_dBm": -85
},
{
    "latitude": 13.060988250000001,
    "longitude": 77.59517075,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.060586950000001,
    "longitude": 77.59510515,
    "signal_strength_dBm": -43
},
{
    "latitude": 13.0601816,
    "longitude": 77.59502605,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.060199749999999,
    "longitude": 77.59503495,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.06016645,
    "longitude": 77.59501245,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.060149599999999,
    "longitude": 77.5949767,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0601556,
    "longitude": 77.59499555,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.060148550000001,
    "longitude": 77.5949569,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.060392199999999,
    "longitude": 77.59372995000001,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.07141365,
    "longitude": 77.58907825,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0714884,
    "longitude": 77.5890995,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06708515,
    "longitude": 77.59341485,
    "signal_strength_dBm": -58
```

Pretty-print

```
{  
    "latitude": 13.0698513,  
    "longitude": 77.5926718,  
    "signal_strength_dBm": -89  
},  
{  
    "latitude": 13.069764500000002,  
    "longitude": 77.59251,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.06970875,  
    "longitude": 77.59268165,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.069619549999999,  
    "longitude": 77.59252185,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.0704639,  
    "longitude": 77.591965,  
    "signal_strength_dBm": -56  
},  
{  
    "latitude": 13.071463600000001,  
    "longitude": 77.58799125,  
    "signal_strength_dBm": -64  
},  
{  
    "latitude": 13.07096325,  
    "longitude": 77.5875802,  
    "signal_strength_dBm": -90  
},  
{  
    "latitude": 13.05748965,  
    "longitude": 77.59365335000001,  
    "signal_strength_dBm": -56  
},  
{  
    "latitude": 13.05371965,  
    "longitude": 77.59346255,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.058252150000001,  
    "longitude": 77.58601585,  
    "signal_strength_dBm": -85  
},  
{  
    "latitude": 13.0681252,  
    "longitude": 77.56957615,  
    "signal_strength_dBm": -99  
},  
{  
    "latitude": 13.06825215,  
    "longitude": 77.56952785,  
    "signal_strength_dBm": -87  
},  
{  
    "latitude": 13.06399985,  
    "longitude": 77.57170065,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.05437225,  
    "longitude": 77.570109,
```

Pretty-print

```
},
{
  "latitude": 13.05681255,
  "longitude": 77.5936446,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.0574998,
  "longitude": 77.5933027,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.07047375,
  "longitude": 77.59231700000001,
  "signal_strength_dBm": -99
},
{
  "latitude": 13.0703137,
  "longitude": 77.5922161,
  "signal_strength_dBm": -58
},
{
  "latitude": 13.07062655,
  "longitude": 77.59244340000001,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.070755550000001,
  "longitude": 77.5922285,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.070649750000001,
  "longitude": 77.5919516,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.07049885,
  "longitude": 77.59185535,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.07038749999999,
  "longitude": 77.5917715,
  "signal_strength_dBm": -84
},
{
  "latitude": 13.07020885,
  "longitude": 77.59180435,
  "signal_strength_dBm": -53
},
{
  "latitude": 13.07024545,
  "longitude": 77.591744,
  "signal_strength_dBm": -44
},
{
  "latitude": 13.0701866,
  "longitude": 77.5918768,
  "signal_strength_dBm": -93
},
{
  "latitude": 13.0701497,
  "longitude": 77.59190095,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.07010659999999,
```

Pretty-print

```
-----  
  "signal_strength_dBm": -58  
,  
{  
  "latitude": 13.0701125,  
  "longitude": 77.5920203,  
  "signal_strength_dBm": -107  
,  
{  
  "latitude": 13.0701308,  
  "longitude": 77.59208705,  
  "signal_strength_dBm": -82  
,  
{  
  "latitude": 13.070167049999998,  
  "longitude": 77.59217455000001,  
  "signal_strength_dBm": -101  
,  
{  
  "latitude": 13.070218,  
  "longitude": 77.59222249999999,  
  "signal_strength_dBm": -78  
,  
{  
  "latitude": 13.07005395,  
  "longitude": 77.59171955,  
  "signal_strength_dBm": -78  
,  
{  
  "latitude": 13.07005365,  
  "longitude": 77.5917048,  
  "signal_strength_dBm": -94  
,  
{  
  "latitude": 13.070068599999999,  
  "longitude": 77.59175095,  
  "signal_strength_dBm": -93  
,  
{  
  "latitude": 13.070058750000001,  
  "longitude": 77.59173545,  
  "signal_strength_dBm": -54  
,  
{  
  "latitude": 13.07007015,  
  "longitude": 77.59176555,  
  "signal_strength_dBm": -96  
,  
{  
  "latitude": 13.07007815,  
  "longitude": 77.59175210000001,  
  "signal_strength_dBm": -102  
,  
{  
  "latitude": 13.0701452,  
  "longitude": 77.59170105,  
  "signal_strength_dBm": -87  
,  
{  
  "latitude": 13.070092299999999,  
  "longitude": 77.59173505,  
  "signal_strength_dBm": -83  
,  
{  
  "latitude": 13.070115900000001,  
  "longitude": 77.5917153,  
  "signal_strength_dBm": -103  
,  
{
```

```
Pretty-print
-----
{
    "longitude": 77.58563835000001,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0630937,
    "longitude": 77.58563835000001,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.0630202,
    "longitude": 77.58579325,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.0630088,
    "longitude": 77.5856605,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0628843,
    "longitude": 77.58566315,
    "signal_strength_dBm": -101
},
{
    "latitude": 13.0627459,
    "longitude": 77.58574635,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.06280075000001,
    "longitude": 77.5856984,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06266285,
    "longitude": 77.58584235000001,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.0627001,
    "longitude": 77.58579475,
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0626061,
    "longitude": 77.58593859999999,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.0626332,
    "longitude": 77.5858915,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.06257305000001,
    "longitude": 77.5859815,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.06250035,
    "longitude": 77.58604605,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0625374,
    "longitude": 77.58601730000001,
    "signal_strength_dBm": -58
},
```

```
Pretty-print
{
    "latitude": 13.06246025,
    "longitude": 77.5860701,
    "signal_strength_dBm": -83
},
{
    "latitude": 13.062405949999999,
    "longitude": 77.5860936,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.06242795,
    "longitude": 77.58608425,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.06238665,
    "longitude": 77.5861079,
    "signal_strength_dBm": -52
},
{
    "latitude": 13.06237105,
    "longitude": 77.58612635,
    "signal_strength_dBm": -110
},
{
    "latitude": 13.0623547,
    "longitude": 77.58616695,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.06236045,
    "longitude": 77.58614645,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.062353,
    "longitude": 77.58618820000001,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0623395,
    "longitude": 77.58624714999999,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.06234960000001,
    "longitude": 77.58621529999999,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.062307350000001,
    "longitude": 77.58629834999999,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.06232505,
    "longitude": 77.586275,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.06228625,
    "longitude": 77.58631845,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.06222055,
    "longitude": 77.58638975,
    "signal_strength_dBm": -90
```

Pretty-print

```
{  
    "latitude": 13.06225585,  
    "longitude": 77.5863475,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.062167200000001,  
    "longitude": 77.58649025,  
    "signal_strength_dBm": -61  
},  
{  
    "latitude": 13.062190699999999,  
    "longitude": 77.58643760000001,  
    "signal_strength_dBm": -59  
},  
{  
    "latitude": 13.062130100000001,  
    "longitude": 77.5866051,  
    "signal_strength_dBm": -46  
},  
{  
    "latitude": 13.062149300000002,  
    "longitude": 77.586547,  
    "signal_strength_dBm": -102  
},  
{  
    "latitude": 13.06210465,  
    "longitude": 77.58666065,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.0620732,  
    "longitude": 77.58671285,  
    "signal_strength_dBm": -50  
},  
{  
    "latitude": 13.06199655,  
    "longitude": 77.5868025,  
    "signal_strength_dBm": -54  
},  
{  
    "latitude": 13.06203695,  
    "longitude": 77.58676025,  
    "signal_strength_dBm": -84  
},  
{  
    "latitude": 13.06195185,  
    "longitude": 77.58683995,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.061903449999999,  
    "longitude": 77.58687215,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.061851650000001,  
    "longitude": 77.58689575,  
    "signal_strength_dBm": -90  
},  
{  
    "latitude": 13.06186915,  
    "longitude": 77.58688895,  
    "signal_strength_dBm": -71  
},  
{  
    "latitude": 13.06183685,  
    "longitude": 77.58690745,  
    "signal_strength_dBm": -53  
}
```

Pretty-print

```
},
{
  "latitude": 13.06182595,
  "longitude": 77.58692305,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.0618199,
  "longitude": 77.58694125,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.061819199999999,
  "longitude": 77.5869604,
  "signal_strength_dBm": -66
},
{
  "latitude": 13.0618368,
  "longitude": 77.5869986,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.061824699999999,
  "longitude": 77.58698025,
  "signal_strength_dBm": -80
},
{
  "latitude": 13.06185415,
  "longitude": 77.58701175,
  "signal_strength_dBm": -97
},
{
  "latitude": 13.0618747,
  "longitude": 77.58701825,
  "signal_strength_dBm": -71
},
{
  "latitude": 13.0632612,
  "longitude": 77.58559070000001,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.0632327,
  "longitude": 77.58562950000001,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0624804,
  "longitude": 77.58654469999999,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.0624643,
  "longitude": 77.5865989,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.06250485,
  "longitude": 77.5864939,
  "signal_strength_dBm": -63
},
{
  "latitude": 13.0625371,
  "longitude": 77.58644785000001,
  "signal_strength_dBm": -76
},
{
  "latitude": 13.062604100000001,
```

```
Pretty-print
-----
    "signal_strength_dBm": -51
},
{
    "latitude": 13.0625709,
    "longitude": 77.58641195000001,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0626402,
    "longitude": 77.5863636,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.0627058,
    "longitude": 77.58634015,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.06267445,
    "longitude": 77.58634885000001,
    "signal_strength_dBm": -86
},
{
    "latitude": 13.06275265,
    "longitude": 77.5863327,
    "signal_strength_dBm": -60
},
{
    "latitude": 13.06277015,
    "longitude": 77.58627899999999,
    "signal_strength_dBm": -102
},
{
    "latitude": 13.062778300000002,
    "longitude": 77.58631255,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.062767699999998,
    "longitude": 77.5862252,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.06276705,
    "longitude": 77.58624965,
    "signal_strength_dBm": -41
},
{
    "latitude": 13.0628001,
    "longitude": 77.58613629999999,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.0627785,
    "longitude": 77.58618715,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.06282555,
    "longitude": 77.58608735,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0628962,
    "longitude": 77.58598585,
    "signal_strength_dBm": -92
},
```

```
Pretty-print
-----
{
    "longitude": 77.58603695,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.06293935,
    "longitude": 77.58593855000001,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.06316615,
    "longitude": 77.58562420000001,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.06527285,
    "longitude": 77.58207265,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.065613500000001,
    "longitude": 77.58211775,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.065331950000001,
    "longitude": 77.58191565,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.05966505,
    "longitude": 77.59018455,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.05965945,
    "longitude": 77.5902325,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.05978605,
    "longitude": 77.59017850000001,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0595715,
    "longitude": 77.59015769999999,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.05953565,
    "longitude": 77.59006425000001,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.05977665,
    "longitude": 77.59000525,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.05993145,
    "longitude": 77.5901102,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.06008035,
    "longitude": 77.5931807,
    "signal_strength_dBm": -76
},
```

```
Pretty-print
{
    "latitude": 13.060077249999999,
    "longitude": 77.59322965,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.06008845,
    "longitude": 77.59313879999999,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.0601228,
    "longitude": 77.59304979999999,
    "signal_strength_dBm": -77
},
{
    "latitude": 13.06010305,
    "longitude": 77.59309285,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.06014755,
    "longitude": 77.59300955,
    "signal_strength_dBm": -104
},
{
    "latitude": 13.06037115,
    "longitude": 77.59280895,
    "signal_strength_dBm": -96
},
{
    "latitude": 13.0601778,
    "longitude": 77.59288535,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.06020475,
    "longitude": 77.59271625,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.060584500000001,
    "longitude": 77.5928292,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.06056035,
    "longitude": 77.5928359,
    "signal_strength_dBm": -89
},
{
    "latitude": 13.0606171,
    "longitude": 77.5928039,
    "signal_strength_dBm": -80
},
{
    "latitude": 13.0606036,
    "longitude": 77.5928178,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.06062725,
    "longitude": 77.5927873,
    "signal_strength_dBm": -76
},
{
    "latitude": 13.06090775,
    "longitude": 77.59306975,
    "signal_strength_dBm": -46
```

Pretty-print

```
{  
    "latitude": 13.06090705,  
    "longitude": 77.5931932,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.0607205,  
    "longitude": 77.59320405,  
    "signal_strength_dBm": -107  
},  
{  
    "latitude": 13.060718099999999,  
    "longitude": 77.5930792,  
    "signal_strength_dBm": -47  
},  
{  
    "latitude": 13.0604284,  
    "longitude": 77.592687,  
    "signal_strength_dBm": -109  
},  
{  
    "latitude": 13.060317399999999,  
    "longitude": 77.5920091,  
    "signal_strength_dBm": -94  
},  
{  
    "latitude": 13.0607418,  
    "longitude": 77.5920795,  
    "signal_strength_dBm": -87  
},  
{  
    "latitude": 13.0606308,  
    "longitude": 77.5914016,  
    "signal_strength_dBm": -78  
},  
{  
    "latitude": 13.06089425,  
    "longitude": 77.5914458,  
    "signal_strength_dBm": -69  
},  
{  
    "latitude": 13.060829550000001,  
    "longitude": 77.59253465,  
    "signal_strength_dBm": -49  
},  
{  
    "latitude": 13.0607887,  
    "longitude": 77.59262849999999,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.06084555,  
    "longitude": 77.59263519999999,  
    "signal_strength_dBm": -100  
},  
{  
    "latitude": 13.06081825,  
    "longitude": 77.5924333,  
    "signal_strength_dBm": -80  
},  
{  
    "latitude": 13.060869100000001,  
    "longitude": 77.5919417,  
    "signal_strength_dBm": -82  
},  
{  
    "latitude": 13.06022785,  
    "longitude": 77.59301235000001,  
    "signal_strength_dBm": -75  
}
```

Pretty-print

```
},
{
  "latitude": 13.0601831,
  "longitude": 77.5929985,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.06027385,
  "longitude": 77.59302075,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.06032055,
  "longitude": 77.5930237,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.060404250000001,
  "longitude": 77.59301515,
  "signal_strength_dBm": -51
},
{
  "latitude": 13.0603642,
  "longitude": 77.5930216,
  "signal_strength_dBm": -94
},
{
  "latitude": 13.0604435,
  "longitude": 77.5930046,
  "signal_strength_dBm": -69
},
{
  "latitude": 13.06054705,
  "longitude": 77.59298749999999,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.0604909,
  "longitude": 77.59299419999999,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.06068105,
  "longitude": 77.59298375,
  "signal_strength_dBm": -86
},
{
  "latitude": 13.0606105,
  "longitude": 77.59298375,
  "signal_strength_dBm": -83
},
{
  "latitude": 13.060812299999998,
  "longitude": 77.5929822,
  "signal_strength_dBm": -56
},
{
  "latitude": 13.060908999999999,
  "longitude": 77.5928528,
  "signal_strength_dBm": -73
},
{
  "latitude": 13.060814,
  "longitude": 77.5932305,
  "signal_strength_dBm": -46
},
{
  "latitude": 13.0607398,
```

```
Pretty-print
-----
  "signal_strength_dBm": -91
},
{
  "latitude": 13.06089335,
  "longitude": 77.5926825,
  "signal_strength_dBm": -92
},
{
  "latitude": 13.06480735,
  "longitude": 77.5741501,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.0627174,
  "longitude": 77.5742483,
  "signal_strength_dBm": -40
},
{
  "latitude": 13.056026899999999,
  "longitude": 77.5935968,
  "signal_strength_dBm": -64
},
{
  "latitude": 13.056145749999999,
  "longitude": 77.59353949999999,
  "signal_strength_dBm": -88
},
{
  "latitude": 13.05620865,
  "longitude": 77.5934707,
  "signal_strength_dBm": -61
},
{
  "latitude": 13.056238,
  "longitude": 77.59339109999999,
  "signal_strength_dBm": -63
},
{
  "latitude": 13.05617205,
  "longitude": 77.5932469,
  "signal_strength_dBm": -60
},
{
  "latitude": 13.056230150000001,
  "longitude": 77.5933254,
  "signal_strength_dBm": -87
},
{
  "latitude": 13.056590400000001,
  "longitude": 77.5938063,
  "signal_strength_dBm": -68
},
{
  "latitude": 13.07038225,
  "longitude": 77.589561,
  "signal_strength_dBm": -107
},
{
  "latitude": 13.07019745,
  "longitude": 77.5900413,
  "signal_strength_dBm": -101
},
{
  "latitude": 13.069750599999999,
  "longitude": 77.58940045,
  "signal_strength_dBm": -45
},
```

```
Pretty-print
{
    "longitude": 77.58920225,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.0687721,
    "longitude": 77.58915305,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.06876595,
    "longitude": 77.5891543,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.068760600000001,
    "longitude": 77.5891585,
    "signal_strength_dBm": -69
},
{
    "latitude": 13.05491495,
    "longitude": 77.59233195,
    "signal_strength_dBm": -105
},
{
    "latitude": 13.0549479,
    "longitude": 77.59229525,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.05502825,
    "longitude": 77.5918966,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05509735,
    "longitude": 77.59149175,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.055091149999999,
    "longitude": 77.59144135,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.05507645,
    "longitude": 77.59140805,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.055070749999999,
    "longitude": 77.59138615,
    "signal_strength_dBm": -91
},
{
    "latitude": 13.055109649999999,
    "longitude": 77.59121075,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0541187,
    "longitude": 77.59121880000001,
    "signal_strength_dBm": -88
},
{
    "latitude": 13.0541463,
    "longitude": 77.59093010000001,
    "signal_strength_dBm": -41
},
```

```
Pretty-print
{
    "latitude": 13.054129,
    "longitude": 77.5913178,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.0541914,
    "longitude": 77.5906837,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.0552268,
    "longitude": 77.5767415,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.05763024999999,
    "longitude": 77.59365600000001,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05731445,
    "longitude": 77.59391915,
    "signal_strength_dBm": -40
},
{
    "latitude": 13.05679985,
    "longitude": 77.59515195,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.05759155,
    "longitude": 77.59385789999999,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.0576167,
    "longitude": 77.59374700000001,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.0631392,
    "longitude": 77.59360855,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.0630163,
    "longitude": 77.5943085,
    "signal_strength_dBm": -75
},
{
    "latitude": 13.06276085,
    "longitude": 77.59423085,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.0625058,
    "longitude": 77.59414480000001,
    "signal_strength_dBm": -42
},
{
    "latitude": 13.06248635,
    "longitude": 77.59413334999999,
    "signal_strength_dBm": -54
},
{
    "latitude": 13.0624741,
    "longitude": 77.59411715,
    "signal_strength_dBm": -99
}
```

Pretty-print

```
{  
    "latitude": 13.070526300000001,  
    "longitude": 77.57980230000001,  
    "signal_strength_dBm": -77  
},  
{  
    "latitude": 13.0707087,  
    "longitude": 77.5786222,  
    "signal_strength_dBm": -55  
},  
{  
    "latitude": 13.07055,  
    "longitude": 77.579393,  
    "signal_strength_dBm": -40  
},  
{  
    "latitude": 13.07123245,  
    "longitude": 77.57803115,  
    "signal_strength_dBm": -60  
},  
{  
    "latitude": 13.071117950000001,  
    "longitude": 77.5780285,  
    "signal_strength_dBm": -93  
},  
{  
    "latitude": 13.0710306,  
    "longitude": 77.57804870000001,  
    "signal_strength_dBm": -97  
},  
{  
    "latitude": 13.070949899999999,  
    "longitude": 77.57807435000001,  
    "signal_strength_dBm": -42  
},  
{  
    "latitude": 13.0708883,  
    "longitude": 77.57811344999999,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.07083635,  
    "longitude": 77.578182,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.0666516,  
    "longitude": 77.58584335,  
    "signal_strength_dBm": -81  
},  
{  
    "latitude": 13.06660705,  
    "longitude": 77.58736175,  
    "signal_strength_dBm": -105  
},  
{  
    "latitude": 13.0665768,  
    "longitude": 77.5873853,  
    "signal_strength_dBm": -110  
},  
{  
    "latitude": 13.0664379,  
    "longitude": 77.5873779,  
    "signal_strength_dBm": -67  
},  
{  
    "latitude": 13.06630385,  
    "longitude": 77.58735415,  
    "signal_strength_dBm": -100  
}
```

Pretty-print

```
},
{
  "latitude": 13.066275950000001,
  "longitude": 77.58733385,
  "signal_strength_dBm": -100
},
{
  "latitude": 13.0662593,
  "longitude": 77.58729930000001,
  "signal_strength_dBm": -42
},
{
  "latitude": 13.0663168,
  "longitude": 77.58699100000001,
  "signal_strength_dBm": -45
},
{
  "latitude": 13.06638205,
  "longitude": 77.58668685,
  "signal_strength_dBm": -78
},
{
  "latitude": 13.0663857,
  "longitude": 77.5866568,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.066381199999999,
  "longitude": 77.58663775,
  "signal_strength_dBm": -89
},
{
  "latitude": 13.066319,
  "longitude": 77.58661945,
  "signal_strength_dBm": -57
},
{
  "latitude": 13.066255250000001,
  "longitude": 77.58660385,
  "signal_strength_dBm": -105
},
{
  "latitude": 13.066243700000001,
  "longitude": 77.58659235,
  "signal_strength_dBm": -72
},
{
  "latitude": 13.066235200000001,
  "longitude": 77.58657525000001,
  "signal_strength_dBm": -96
},
{
  "latitude": 13.06623055,
  "longitude": 77.58650990000001,
  "signal_strength_dBm": -106
},
{
  "latitude": 13.06912575,
  "longitude": 77.58937,
  "signal_strength_dBm": -90
},
{
  "latitude": 13.0690838,
  "longitude": 77.589515,
  "signal_strength_dBm": -102
},
{
  "latitude": 13.069107899999999,
```

```
Pretty-print
-----
    "signal_strength_dBm": -82
},
{
    "latitude": 13.0692332,
    "longitude": 77.5896386,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.06910125,
    "longitude": 77.5897162,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.06941485,
    "longitude": 77.58969375000001,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.06952995,
    "longitude": 77.58974570000001,
    "signal_strength_dBm": -98
},
{
    "latitude": 13.06955305,
    "longitude": 77.58981555,
    "signal_strength_dBm": -81
},
{
    "latitude": 13.069531,
    "longitude": 77.58988944999999,
    "signal_strength_dBm": -106
},
{
    "latitude": 13.06947405,
    "longitude": 77.5899213,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.06924905,
    "longitude": 77.58987305,
    "signal_strength_dBm": -71
},
{
    "latitude": 13.05466570000001,
    "longitude": 77.59372445,
    "signal_strength_dBm": -73
},
{
    "latitude": 13.0548076,
    "longitude": 77.59388899999999,
    "signal_strength_dBm": -51
},
{
    "latitude": 13.05472585,
    "longitude": 77.5939057,
    "signal_strength_dBm": -97
},
{
    "latitude": 13.05861225,
    "longitude": 77.58337365,
    "signal_strength_dBm": -49
},
{
    "latitude": 13.05864705000001,
    "longitude": 77.58342795,
    "signal_strength_dBm": -96
},
```

```
Pretty-print
-----
{
    "longitude": 77.58303535,
    "signal_strength_dBm": -70
},
{
    "latitude": 13.05872435,
    "longitude": 77.58343885,
    "signal_strength_dBm": -95
},
{
    "latitude": 13.057639049999999,
    "longitude": 77.5741481,
    "signal_strength_dBm": -44
},
{
    "latitude": 13.05765495,
    "longitude": 77.57396915,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.057667649999999,
    "longitude": 77.5739906,
    "signal_strength_dBm": -62
},
{
    "latitude": 13.0576556,
    "longitude": 77.57403364999999,
    "signal_strength_dBm": -47
},
{
    "latitude": 13.05763465,
    "longitude": 77.57408054999999,
    "signal_strength_dBm": -78
},
{
    "latitude": 13.05762135,
    "longitude": 77.57411085,
    "signal_strength_dBm": -79
},
{
    "latitude": 13.057618999999999,
    "longitude": 77.5741326,
    "signal_strength_dBm": -55
},
{
    "latitude": 13.062706200000001,
    "longitude": 77.57423195000001,
    "signal_strength_dBm": -67
},
{
    "latitude": 13.062705099999999,
    "longitude": 77.57420690000001,
    "signal_strength_dBm": -94
},
{
    "latitude": 13.0627186,
    "longitude": 77.57410715,
    "signal_strength_dBm": -53
},
{
    "latitude": 13.062743350000002,
    "longitude": 77.5739377,
    "signal_strength_dBm": -99
},
{
    "latitude": 13.062764900000001,
    "longitude": 77.5737984,
    "signal_strength_dBm": -48
},
```

```
Pretty-print
{
    "latitude": 13.0558993,
    "longitude": 77.57882000000001,
    "signal_strength_dBm": -63
},
{
    "latitude": 13.06047789999999,
    "longitude": 77.57559140000001,
    "signal_strength_dBm": -108
},
{
    "latitude": 13.05967929999999,
    "longitude": 77.57379435,
    "signal_strength_dBm": -66
},
{
    "latitude": 13.05966265,
    "longitude": 77.57377220000001,
    "signal_strength_dBm": -59
},
{
    "latitude": 13.059712,
    "longitude": 77.5738158,
    "signal_strength_dBm": -74
},
{
    "latitude": 13.059664,
    "longitude": 77.57374775,
    "signal_strength_dBm": -84
},
{
    "latitude": 13.05978025,
    "longitude": 77.5738399,
    "signal_strength_dBm": -56
},
{
    "latitude": 13.05457725,
    "longitude": 77.5938563,
    "signal_strength_dBm": -48
},
{
    "latitude": 13.05451075,
    "longitude": 77.59385205000001,
    "signal_strength_dBm": -100
},
{
    "latitude": 13.0544853,
    "longitude": 77.59398675,
    "signal_strength_dBm": -107
},
{
    "latitude": 13.0582353,
    "longitude": 77.58946075,
    "signal_strength_dBm": -57
},
{
    "latitude": 13.05839295,
    "longitude": 77.5892532,
    "signal_strength_dBm": -92
},
{
    "latitude": 13.0584041,
    "longitude": 77.58949665,
    "signal_strength_dBm": -45
},
{
    "latitude": 13.05804704999999,
    "longitude": 77.58963985,
    "signal_strength_dBm": -55
}
```

Pretty-print

```
{  
    "latitude": 13.05809115,  
    "longitude": 77.58923580000001,  
    "signal_strength_dBm": -92  
},  
{  
    "latitude": 13.0582537,  
    "longitude": 77.58985275,  
    "signal_strength_dBm": -74  
},  
{  
    "latitude": 13.0584869,  
    "longitude": 77.58971325,  
    "signal_strength_dBm": -48  
},  
{  
    "latitude": 13.05844905,  
    "longitude": 77.58953625000001,  
    "signal_strength_dBm": -63  
},  
{  
    "latitude": 13.0582488,  
    "longitude": 77.58902825000001,  
    "signal_strength_dBm": -47  
}  
]
```