

## Pioneer Lodge Unit Inventory Check List

\* Handover / Takeover

Company Name: SADSADSADF Unit No.: 80-02-002 Date: 19/06/2025

S/NO	DESCRIPTION	QTY	Condition	Defects/Remarks		
	Electrical Items					
1	EXIT light unit	1	Good			
2	Wireless router	1	Good			
3	Ceiling Fan switch (3 G / 1 G)	1	Good			
4	Lighting switch (1 gang)	2	Good			
5	Lighting switches (2 gang)	1	Good			
6	Ceiling Fan		Good			
7	Wall fan	NA	Good			
8	Stand Fan	2	Good			
9	13A Single Wall Socket	4	Good			
10	13A Twin Wall Socket	17	Good			
11	20W LED Tube Lights		Good			
12	2 x 20W LED Tube Lights w Guard		Good			
13	Emergency Light Unit		Good			
		Bedroom	1			
1	Bunk bed w/ladder		Good			
2	Locker w/ accessories		Good			
3	Luggage rack	1	Good			
4	Mattresses		Good			
5	Pillows		Good			
		Toilet				
1	Mirror	2	Good			
2	Wash Basin tap	2	Good			
3	Wash Basin + Drainstopper	2	Good			
4	Wash Basin Bottle Trap (PVC)	2	Good			
5Toil	et cistern w/ lid + seat (Including flushing syst	em)2	Good			
6	Bidet Tap		Good			
7	Floor trap (4" / 6")		Good			
8	Shower head & tap	2	Good			
9	Cubicle door w/lock & hanger hook	4	Good			

10	Partition boards & feet (cubicle/set)	4	Good		
11	Wall & floor tiles	NA	Good		
Kitchen					
1	Washer	1	Good		
2	Tap (washer)	1	Good		
3	Fridge	1	Good		
4	Dining table	1	Good		
5	Chair	2	Good		
6	Induction stove	2	Good		
7	Kettle	2	Good		
8	Wash basin	1	Good		
9	Tap (basin)	1	Good		
10	Prep area (tiles)	NA	Good		
11	Floor trap 6"		Good		
12	Kitchen floor (tiles)	NA	Good		
13	Clothes hanger (above head/over window*)	1	Good		
14	Clothes hanging poles*		Good		
15	Y Stick*		Good		
	Fire	e-Protect	ion		
1	Strobe light		Good		
2	Smoke detector		Good		
		Others			
1	Main door + Cyclinder Lock Handle	1	Good		
2	Main door magnetic holder + unit number plate	e 1	Good		
3	Sliding window w/lock & hook		Good		
4	Awning window w/handle & latch (top)		Good		
5	Casement window w/handle & latch		Good		
6	Curtains with rail		Good		
7	Built-In Shoe Rack		Good		
8	Bathroom exhaust ducting (top)		Good		
9	Sliding doors- GRND floor only*		Good		
10	Dormitory Defect report QR Code		Good		
11	Cleanliness & Wall Paint	NA	Good		

Item	Reading	Sign & Date
Water Meter	22315654	
Electricity Meter		

	Handover	Takeover
Name:		

Signature:	
Date:	