



US0D1092267S

(12) **United States Design Patent** (10) **Patent No.:** **US D1,092,267 S**
Kray et al. (45) **Date of Patent:** **** Sep. 9, 2025**

(54) **VISUAL ALARM INDICATOR HOUSING PORTION**

(71) Applicant: **S.J. Electro Systems, LLC**, Detroit Lakes, MN (US)

(72) Inventors: **Taylor M. Kray**, Detroit Lakes, MN (US); **Corey L. Steinke**, Detroit Lakes, MN (US)

(73) Assignee: **S.J. Electro Systems, LLC**, Detroit Lakes, MN (US)

(**) Term: **15 Years**

(21) Appl. No.: **29/885,828**

(22) Filed: **Mar. 1, 2023**

(51) **LOC (15) Cl.** **10-05**

(52) **U.S. Cl.** **D10/109.1; D10/104.1**
USPC **D10/109.1; D10/104.1**

(58) **Field of Classification Search**
USPC D10/46, 50, 51, 52, 53, 56, 57, 58, 60,
D10/104.1, 106.1, 106.3, 106.95, 109.1,
D10/109.2, 110, 11, 112, 114.1, 114.2,
D10/121
CPC B60Q 1/22; G01F 23/0007; H05K 5/0217;
H05K 5/0226
See application file for complete search history.

(56) **References Cited**

U.S. PATENT DOCUMENTS

D219,711	S	*	1/1971	Sato	374/141
D224,147	S	*	7/1972	Miller	D10/57
D273,944	S	*	5/1984	Koeneman	D10/50
4,751,371	A	*	6/1988	Clinton	B29C 45/78 361/87

(Continued)

OTHER PUBLICATIONS

LX-Light; LED Tail Lights Super Bright 20W Reverse Lights with EMC Compatible with Jeep Wrangler JK&JKU 2007-2017 Brake

Reverse Light Rear Back Up Lights Daytime Running Lamps; first available Nov. 21, 2019; accessed at https://www.amazon.com/gp/product/B071S7PGJB/ref=ppx_yo_dt_b_asin_title_o09_s01?ie=UTF8&th=1 on May 31, 2023; 4 pages.

Primary Examiner — Joseph Kukella

Assistant Examiner — Heather Wencil

(74) *Attorney, Agent, or Firm* — Dicke, Billig & Czaja, PLLC

(57) **CLAIM**

The ornamental design for a visual alarm indicator housing portion as shown and described herein.

DESCRIPTION

FIG. 1 is a front perspective view of a visual alarm indicator housing portion showing our new design.

FIG. 2 is a front view thereof.

FIG. 3 is a top view thereof.

FIG. 4 is a bottom view thereof.

FIG. 5 is a right side view thereof.

FIG. 6 is a left side view thereof; and,

FIG. 7 is a front perspective view of the visual alarm indicator housing portion operatively connected to an alarm assembly.


The visual alarm indicator housing portion depicted in FIGS. 1, 2, and 7 is transparent and has negligible depth.

The broken lines in FIGS. 1-6 show features of the visual alarm indicator housing portion that form no part of the claimed design.

The broken lines shown in FIG. 7 depicting the alarm assembly illustrate environmental structure only and do not form part of the claimed design or of a specified embodiment thereof.

As illustrated in FIG. 7, portions of the visual alarm indicator housing portion are not visible during use of the alarm assembly. Therefore, a rear view of the visual alarm indicator housing portion is not shown in the drawings.

1 Claim, 7 Drawing Sheets



(56)

References Cited

U.S. PATENT DOCUMENTS

5,170,150	A	*	12/1992	Austin		G08B 17/113
						340/630
D338,420	S	*	8/1993	Workman		D10/104.1
D403,445	S	*	12/1998	Talebi		D10/114.1
D451,218	S	*	11/2001	Bernier		D26/28
D545,232	S	*	6/2007	Waldman		D10/125
D589,835	S	*	4/2009	Pokorny		D10/110
D596,962	S	*	7/2009	Okamoto		D10/50
D618,572	S	*	6/2010	Shin		D10/114.1
D679,205	S	*	4/2013	Eyring		D10/50
D705,091	S	*	5/2014	Andersson		D10/50
D947,043	S	*	3/2022	Wu		D10/57

* cited by examiner




Fig. 1




Fig. 2




Fig. 3



Fig. 4




Fig. 5




Fig. 6




Fig. 7